

DAIKIN

DAIKIN AIRCONDITIONING INDIA PVT. LTD.

Authorised Service Provider

AEON AIRCONDITIONING SOLUTIONS

AEON HOUSE, SHOP NO. 6 & 7, BEHIND N CUBE CHINA TOWN

DR. AMBEDKAR ROAD, THANE W 400601 MAHARASHTRA. PHONE :- 02225370101 / 7900097007 / 9322334106



PROJECT :- Blue Dart Jogeshwari Station.

Measurement Sheet

Sr. No.	Location	AC Type	Tonnage	Indoor Unit Details		Outdoor Unit Details		Copper In Rmt	Cable In Rmt	Drain In Rmt	ODU Stand
				Model No.	Sr. No.	Model No.	Sr. No.				
1	JWC Courtyard	split	1.0TR	G-T1cm35UV16WA	10646	12cm35UV16WA	20652	7 mtr	8 m.12	—	—
2											
3											
4											
5											
6											
7											
8											
9											
10											

EXTRA ACTIVITY CARRIED OUT

CIVIL WORK	Stabilizer			TIMER	CASING CAPPING	CABLE TRAY	GAS CHARGING	DISMENTALING		RE-INSTALLATION
	3KVA	4KVA	5KVA					Hi Wall	Cassette	
								1		
OTHERS										

For Customer Details :

Sign :
 Name : Atiya Shaikh (Blue Dart)
 Date : 25/6/25

Stamp :



Vendor Details :

Signature :
 Technician Name : Shoaib A. Gani
 Date : 21-06-25

DAIKIN
012
DAIKIN AIRCONDITIONING INDIA PVT. LTD.
 Service Completion Certificate

AEON AIRCONDITIONING SOLUTIONS

 Office No. 108 & 109, Devashree Garden, Commercial Complex,
 R.W. Swant Marg, above Sheetal Dairy, Rutu Park, Thane - 400 601.
 Mob.: 9322334107 / 9322334109

 Subject: **Installation**

Registration No.		Request Date		Service Engineer		Scheduled Date/Time		Service Order	
				A. Shoaib					
User: 13102 1244				Mobile:		Operation data (Ambient temp. °C)		Fault Diagnosed	
Customer Address: Shop No. 05 Ground Floor Abba						Before repair		After repair	
Base Address: Residency opp Jogeshwari St						HP / T		pslg/ pslg/	
Daikin Invoice:				Date:		SP / T °C		pslg/°C pslg/°C	
Dealer Invoice:				Date:		Current °C		Amps°C Amps°C	
Type		Model No		Manufacturing No.		Voltage		Volts Volts	
Outdoor unit /		121cm35Uv16WA		2065-2		Indoor temperature			
Indoor unit		FT1cm35Uv16WA		10646		Suction		°C °C	
Work Date	No. of S.E.	Work hours	Progress code	Details of the Repair Work		Discharge		°C °C	
21/06/25				A.C Installation Done. Now A.C working cooling fine.		Suction		°C °C	
						Discharge		°C °C	
Compressor manufacturing No.		Defective Compressor		Replacement Compressor		Work No / Parts No		Qty	
								Billing Amount	
Installed date	Warranty	AMC	Using with	Fault location	Phenomena code	Error code			
	Yes / No	Yes / No	Stabilizer Cut off	Yes / No	Yes / No				
Service Engineer Remarks									
Name: Shoaib A. Faiz Signature: [Signature]									
Customer Remarks									
Name: [Signature] Signature: [Signature]									
Customer Impression about Service									
(Please rate on scale of 1 poor, 2, 3, 4 & 5 excellent)									
How is the behavior of visited engineer									
What is the level of your satisfaction									
How is the explanation by Engineer									
a Simple Repair									
b Part Replaced									
c Part Repaired									
d Gas Charging done									
e Routine Service - Wet									
f Routine Service - DRY									
Details of Repair Work Done									
Power Failure									
Phase Reverse									
In door unit PCB Defective									
Out door PCB Defective									
In door unit Fan Motor Defective									
Outdoor Fan Motor Defective									
Comp. taking High Current / Amp									
Compressor Ground / Earth									
Compressor Tripping due to High Temperature									
Compressor tripping due to High Pressure									
Indoor Unit MgsW Defective									
Outdoor Unit MgsW Defective									
Indoor Unit Transformer Faulty									
Out door Unit Transformer Faulty									
Fault of swing Motor									
Defect of Drain Pump									
Expansion Valve Body / Motor Defective									
Defective Temperature Sensor of Indoor Unit									
Defective Temperature Sensor of Outdoor Unit									
Defective Current Sensor In Out door Unit									
Gas Leakage at Indoor Unit									
Gas Leakage at Outdoor Unit									
Blower broken									
Short Cycling of Air at Indoor Unit									
Short Cycling of Air at Outdoor Unit									
Defect in Drain piping System									
Gas Leakage from Flare nut									
Error In Transmission wiring									
Product under capacity									
Rat bite case									
Less cooling problem due to dirty Airfilter									
Remote setting changed									
Clogged Condenser									
Other - Pl. specify									
Details of Repair Work Done									