

DAIKIN

DAIKIN AIRCONDITIONING INDIA PVT. LTD.

Authorised Service Center

AEON AIRCONDITIONING SOLUTIONS

AEON HOUSE, SHOP NO. 6/7, BEHIND N CUBE CHINA TOWN

DR. AMBEDKAR ROAD, THANE W 400601 MAHARASHTRA. PHONE :- 02225370101 / 7900097007



PROJECT :- Cosmos Bank Plot no - 121, S.no.149/2, Masulkar Colony near Ajmera high school Pune 411018.

Measurement Sheet											
Sr. No.	Location	AC Type	Tonnage	Indoor Unit Details		Outdoor Unit Details		Copper In Rmt	Cable In Rmt	Drain In Rmt	ODU Stand
				Model No.	Sr. No.	Model No.	Sr. No.				
1	ATM AC 1	Split	1	FTKL35UV16W3							
2	ATM AC 2	Split	1	FTKL35UV16W3	0032982	RKL35UV16W3	0064898	18	20	10	L Type
3					0032992	RKL35UV16W3	0051685	12	14	10	L Type
4											
5											
6											
7											
8											

CIVIL WORK	Stabilizer			TIMER	CORE CUTTING	CABLE TRAY	GAS CHARGING	DISMENTALING		RE-INSTALLATION
	3KVA	4KVA	5KVA					Hi Wall	Cassette	
				1 Nos.						
OTHERS								3 Nos.		

Rework was carried out for the copper piping of 2 nos. split AC units. Additionally, 2 existing AC units from the ATM area and 1 additional 2 TR split AC unit from the branch were dismantled.

For Customer Details : Cosmos Bank	Vendor Details : AEON AIRCONDITIONING SOLUTIONS
Sign :	Signature :
Name :	Technician Name : Shahrulkh Shaikh
Date :	Date : 25.07.2025
Stamp :	



DAIKIN

DAIKIN AIRCONDITIONING INDIA PVT. LTD.
Service Completion Certificate




AEON AIRCONDITIONING SOLUTIONS

Shop No. 6 & 7, Aeon House, Dr. Ambedkar Rd., Thane (W)
Phone : +91 (9322334107) 9322334109

Subject :

Registration No.		Request Date		Service Engineer		Scheduled Date/Time		Service Order		
				shahzoukh shaikh						
User: COSMOS Bank				Mobile :		Operation data (Ambient temp. °C)		Fault Diagnosed		
Customer Address : masulkar colony Near Ajmera High School Pimpri pune						Before repair		After repair		
I Base Address :						HP / T		psig/		
Daikin Invoice :				Date :		SP / T °C		psig/°C		
Dealer Invoice :				Date :		Current °C		Amps°C		
Type		Model No		Manufacturing No.		Voltage		Volts		
Outdoor unit /		R1CL35UV16W3		0064898		Suction		°C		
Indoor unit		FTK1CL354U16W3		0032982		Discharge		°C		
Work Date	No. of S.E.	Work hours	Progress code	Details of the Repair Work						
25/7/2021										
Compressor manufacturing No.		Defective Compressor		Replacement Compressor		Work No / Parts No		City		
Installed date	Warranty	AMC	Using with		Fault location	Phenomena code	Billing Amount			
	Yes / No	Yes / No	Stabilizer	Cut off						
	Yes / No	Yes / No	Yes / No	Yes / No						
Service Engineer Remarks: Daikin make ITR split AC installation Done now unit working cooling ok										
Name: shahzoukh shaikh				Signature: <i>[Signature]</i>						
Customer Remarks:				Customer Impression about Service						
				(Please rate on scale of 1 poor, 2, 3, 4 & 5 excellent)						
				a Simple Repair						
				b Part Replaced						
				c Part Repaired						
				d Gas Charging done						
				e Routine Service - Wet						
				f Routine Service - DRY						
				How is the behavior of visited engineer						
				What is the level of your satisfaction						
				How is the explanation by Engineer						
				Details of Repair Work Done						



DAIKIN

DAIKIN AIRCONDITIONING INDIA PVT. LTD.
Service Completion Certificate



AEON AIRCONDITIONING SOLUTIONS
Shop No. 6 & 7, Aeon House, Dr. Ambedkar Rd., Thane (W)
Phone : +91 (9322334107) 9322334109

Registration No.		Request Date		Service Engineer		Scheduled Date/Time		Service Order	
				Shahroukh Shaikh					
User: Cosmas Bank				Mobile:		Operation data (Ambient temp. °C)		Fault Diagnosed	
Customer Address: masulkar colony Near Ajmera						Before repair		After repair	
Base Address: High school Pimpry pune						HP / T		pslg/	
Daikin Invoice:				Date:		SP / T °C		pslg/°C	
Dealer Invoice:				Date:		Current °C		Amps °C	
Type		Model No		Manufacturing No.		Voltage		Volts	
Outdoor unit /		AKL35UV16W3		0051685		Indoor temperature		°C	
Indoor unit		FTKL35UV16W3		0032992		Suction		°C	
Work Date		No. of S.E.		Work hours		Discharge		°C	
25/7/2025						Outdoor temperature		°C	
						Suction		°C	
						Discharge		°C	
						Work No / Parts No		Qty	
						Billing Amount			
						Total			
Compressor manufacturing No.		Defective Compressor		Replacement Compressor		Unit		Gas Leakage at Indoor Unit	
Installed date		Warranty		AMC		Using with		Gas Leakage at Outdoor Unit	
						Stabilizer		Blower broken	
						Cut off		Short Cycling of Air at Indoor Unit	
						Fault location		Short Cycling of Air at Outdoor Unit	
						Phenomena code		Defect in Drain piping System	
						Error code		Gas Leakage from Flare nut	
								Error In Transmission wiring	
								Product under capacity	
								Rat bite case	
								Less cooling problem due to dirty Airfilter	
								Remote setting changed	
								Clogged Condenser	
								Other - Pl. specify	
								Details of Repair Work Done	
								a Simple Repair	
								b Part Replaced	
								c Part Repaired	
								d Gas Charging done	
								e Routine Service - Wet	
								f Routine Service - DRY	
Service Engineer Remarks				Daikin make 1TR split AC		Customer Impression about Service		a Simple Repair	
				Installation Done now unit		(Please rate on scale of 1 poor, 2, 3, 4 & 5 excellent)		b Part Replaced	
				working cooling ok		How is the behavior of visited engineer		c Part Repaired	
Name				Shahroukh Shaikh		Signature		d Gas Charging done	
Customer Remarks								e Routine Service - Wet	
								f Routine Service - DRY	
Name									

