

DAIKIN AIRCONDITIONING INDIA PVT. LTD.
Service Completion Certificate

AEON AIRCONDITIONING SOLUTION

Office No. 108 & 109, Devastree Garden, Comm.
R.W. Swarni Marg, above Sheetal Dairy, Rulu Park
Mob.: 9322334107 / 9322334109

Mob.: 9322334107 / 9322334109

24 Apr 2025 7:54:23 pm
6-90 Feet Road
Kandivali West
Mumbai
Konkan Division
Maharashtra

Registration No.		Request Date		Service Engineer		Scheduled Date/Time		Service Order	
		21-4-25		Siddhant Anand		21-4-25			
User :				Mobile :					
Customer Address :									
Base Address :									
Daikin Invoice :				Date :					
Dealer Invoice :				Date :					
Type		Model No.		Manufacturing No.					
Outdoor unit / Indoor unit		RKL60V16V		8017151					
Work Date		FT1460V16V		80091509					
No. of hours		Work Progress code		Details of the Repair Work					
21/4/25				60 + 10 min pipe + 20 min cable + 10 min case + lock		Randy			
Compressor manufacturing No.		Detective Compressor		Replacement Compressor					
Installed date		Warranty		AMC		Using with		Fault location	
		Yes / No		Yes / No		Yes / No		Yes / No	
Service Engineer Remarks									
Name		Signature		Signature					
Customer Remarks									
Name		Signature		Signature					
Operation data (Ambient temp. °C)		Before repair		After repair					
HP / T		pisy		pisy					
SP / T °C		pisy °C		pisy °C					
Current °C		Amps °C		Amps °C					
Voltage		Volts		Volts					
Suction		Indoor temperature		Outdoor temperature					
Discharge		°C		°C					
Suction		°C		°C					
Discharge		°C		°C					
Work No / Parts No		Qty		Billing Amount					
Total									
Customer Impression about Service									
(Please rate on scale of 1 poor, 2, 3, 4 & 5 excellent)									
How is the behavior of visited engineer									
What is the level of your satisfaction									
How is the explanation by Engineer									
Fault Disposition									
Power Failure									
Phase Reverse									
In door unit PCB Defective									
Out door unit PCB Defective									
In door unit Fan Motor Defective									
Outdoor Fan Motor Defective									
Comp. taking High Current / Amp									
Compressor Ground / Earth									
Compressor Tripping due to High Temperature									
Compressor tripping due to High Pressure									
Indoor Unit MGSW Defective									
Outdoor Unit MGSW Defective									
Indoor Unit Transformer Faulty									
Out door unit Transformer Faulty									
Fault of wiring Motor									
Defect of Drain Pump									
Expansion Valve Body / Motor Defective									
Defective Temperature Sensor of Indoor Unit									
Defective Temperature Sensor of Outdoor Unit									
Defective Current Sensor In Out door Unit									
Gas Leakage at Indoor Unit									
Gas Leakage at Outdoor Unit									
Blower Broken									
Short Cycling of Air at Indoor Unit									
Short Cycling of Air at Outdoor Unit									
Defect in Drain piping System									
Gas Leakage from Flare nail									
Error in Transmission wiring									
Product under capacity									
Flat blue case									
Leak cooling problem due to dirty Airtiter									
Remote setting changed									
Clogged Condenser									
Other - Pl. specify									
Details of Repair Work Done									
a Simple Repair									
b Part Replaced									
c Part Replaced									
d Gas Charging done									
e Routine Service - Well									
f Routine Service - DRY									