

DAIKIN
DAIKIN AIRCONDITIONING INDIA PVT. LTD.

Authorised Service Center

AEON AIRCONDITIONING SOLUTIONS

AEON HOUSE, SHOP NO. 6/7, BEHIND N CUBE CHINA TOWN

DR. AMBEDKAR ROAD, THANE W 400601 MAHARASHTRA. PHONE :- 02225370101 / 7900097007


PROJECT :- *Blue Dart Grinigh Park.*
Measurement Sheet

Sr. No.	Location	AC Type	Tonnage	Indoor Unit Details		Outdoor Unit Details		Copper In Rmt	Cable In Rmt	Drain In Rmt	ODU Stand
				Model No.	Sr. No.	Model No.	Sr. No.				
1	CAM Room	Split	1.5TR	ATKM50AV16M	8019431	RKM50XV16M	8034472	5	6	3	—
2											
3											
4											
5											
6											
7											
8											

EXTRA ACTIVITY CARRIED OUT

CIVIL WORK	Stabilizer			TIMER	CASING CAPPING	CABLE TRAY	GAS CHARGING	DISMENTALING		RE-INSTALLATION
	3KVA	4KVA	5KVA					Hi Wall	Cassette	

OTHERS *One old AC Uninstall.*
For Customer Details: *Blue Dart.*
Vendor Details: *AEON AIRCONDITIONING SOLUTIONS*
Sign: *For*
Signature: *Subhjit Babel.*
Name: *Tridip Karm*
Technician Name: *SUBHJIT BABEL*
Date: *13/06/26*
Stamp:
Date: *13/6/26*


DAIKIN AIRCONDITIONING INDIA PVT. LTD.

Service Completion Certificate



AEON AIRCONDITIONING SOLUTIONS

Office No. 108 & 109, Devashree Garden, Commercial Complex,
R.W. Swarnam Marg, above Sheetal Dairy, Phase Park, Thane - 400 601.
Mob: 9322334107 / 9322334109

Subject :

Registration No.		Request Date		Service Engineer		Scheduled Date/Time		Service Center	
Customer Address: Blue Dart Girish Park, Kallala.				Operation data (Ambient temp. °C)				Fault Diagnosed	
Mobile: _____				Before repair		After repair		☒ Power Failure ☐ Phase Reverse ☐ In door unit PCB Defective ☐ Out door PCB Defective ☐ In door unit Fan Motor Defective ☐ Outdoor Fan Motor Defective ☐ Comp. taking High Current / Amp ☐ Compressor Ground / Earth ☐ Compressor Tripping due to High Temperature ☐ Compressor tripping due to High Pressure ☐ Indoor Unit MfgSer Defective ☐ Outdoor Unit MfgSer Defective ☐ Indoor Unit Transformer Faulty ☐ Out door Unit Transformer Faulty ☐ Fault of swing Motor ☐ Defect of Drain Pump ☐ Expansion Valve Body / Motor Defective ☐ Defective Temperature Sensor of Indoor Unit ☐ Defective Temperature Sensor of Outdoor Unit ☐ Defective Current Sensor in Out door Unit ☐ Gas Leakage at Indoor Unit ☐ Gas Leakage at Outdoor Unit ☐ Blower broken ☐ Short Cycling of Air at Indoor Unit ☐ Short Cycling of Air at Outdoor Unit ☐ Defect in Drain piping System ☐ Gas Leakage from Flame nut ☐ Error in Transmission wiring ☐ Product under capacity ☐ Rat bite case ☐ Less cooling problem due to dirty Airfilter ☐ Remote setting changed ☐ Clogged Condenser ☐ Other - PL specify	
				HP / T		psig/			
Date: 13/6/26				SP / T °C		psig/°C			
Date: _____				Current °C		Amps °C			
Type: _____				Voltage		Volts			
Model No: ARK50 XV16MKA				Indoor temperature					
Manufacturing No: 8034477				Suction		°C			
ATK M50 XV16MKB				Discharge		°C			
Details of the Repair Work				Outdoor temperature					
S.E. _____				Suction		°C			
Work hours _____				Discharge		°C			
Progress code _____				Work No / Parts No		Qty		Billing Amount	
Defective Compressor				Replacement Compressor					
Installed date _____				Fault location					
Warranty _____				Phenomena code					
A/MC _____				Error code					
Using with _____									
Stabilizer _____									
Cut off _____									
Yes / No _____									
Yes / No _____									
Yes / No _____									
Yes / No _____									
Engineer Remarks: Installation and Commissioning done cooling OK. Subhash B. Belal.				Total					
Customer Impression about Service									
(Please rate on scale of 1 poor, 2, 3, 4 & 5 excellent)									
How is the behavior of visited engineer									
What is the level of your satisfaction									
a Simple Repair									
b Part Replaced									
c Part Replaced									
d Gas Charging done									
e Replacing Nameplate - Not									
Details of Repair Work Done									