



AEON AIRCONDITIONING SOLUTIONS

Aeon House, Shop No. 6/7, Behind N Cube China Town, Opp. Shishu Dnyan Mandir,
Dr. Ambedkar Rd. Thane 400 601. Maharashtra
Tel. : 022 - 25370101 / 7900097007

103

e-mail : services@aeonacsolutions.com website : www.aeonacsolutions.com

Project: Eat club food Bhayander (w).

Additional Measurement Sheet

Sr. No	Location	AC Type	Tonnage	Indoor Unit Details		Outdoor Unit Details		Copper In Rmt	Cable In Rmt	Drain In Rmt	ODU Stand
				Model No.	Sr. No.	Model No.	Sr. No.				
1	Dining Room	Split	1.5	FTKLSOUV16UAT	8064959	RKLSOUV16UAT	8061639	-	-	-	Fabrication stand
2											
3											
4											
5											
6											
7											
8											

Extra Activity Carried Out

Civil Work	Stabilizer			Timer	Casing Capping	Cable Tray	Gas Charging	Dismantling		Re-installation
	3KVA	4KVA	5KVA					Hi Wall	Cassette	
Others Nitrogen one nos										

For						Vendor Details	
Sign	Krishna Kumar Prajapati					Signature	Aeon AIRCONDITIONING
Name	Krishna Kumar Prajapati					Technician Name	Umar SWAIN
Date	4/07/2025					Date	04/07/25

Subject :

Installation

DAIKIN AIRCONDITIONING INDIA PVT. LTD.
Service Completion Certificate



AEON AIRCONDITIONING SOLUTIONS

Office No. 108 & 109, Devashree Garden, Commercial Complex,
R.W. Sawaant Marg, above Sheetal Dairy, Rutu Park, Thane - 400 601.
Mob.: 9322334107 / 9322334109

Subject: <u>Installation</u>		Registration No.		Request Date		Service Engineer		Scheduled Date/Time		Service Order	
User: <u>Eat Club food</u>		Mobile:		Operation data (Ambient temp. °C)		Before repair		After repair		Fault Diagnosed	
Customer Address: <u>Bayander(w)</u>		Date:		HP / T		psig		psig		✓	
Base Address:		Date:		SP / T °C		psig °C		psig °C		Power Failure	
Daikin Invoice:		Date:		Current °C		Amps °C		Amps °C		Phase Reverse	
Desler Invoice:		Date:		Voltage		Volts		Volts		In door unit PCB Defective	
Type	Model No	Manufacturing No.		Indoor temperature		Suction		°C		°C	
Outdoor unit /	<u>RKLSOUV16VAF</u>	<u>8201699</u>		Discharge		°C		°C		Out door PCB Defective	
Indoor unit	<u>FTKLSO VU 16VAF</u>	<u>8064959</u>		Suction		°C		°C		In door unit Fan Motor Defective	
Work Date	No. of S.E.	Work hours	Progress code	Details of the Repair Work		Discharge		°C		Outdoor Fan Motor Defective	
<u>04</u>				<u>Installation done</u>		Suction		°C		Comp. taking High Current / Amp	
<u>07</u>				<u>colling good.</u>		Discharge		°C		Compressor Ground / Earth	
<u>25</u>						Work No / Parts No		Qty		Compressor Tripping due to High Temperature	
Compressor manufacturing No.				Defective Compressor		Replacement Compressor				Compressor tripping due to High Pressure	
Installed date		Warranty		AMC		Using with		Fault location		Phenomena code	
Yes / No		Yes / No		Yes / No		Yes / No					
Service Engineer Remarks				Signature		Total				Indoor Unit MgSw Defective	
Customer Remarks				Signature						Outdoor Unit Mgsw Defective	
Customer Impression about Service				Signature						Indoor Unit Transformer Faulty	
(Please rate on scale of 1 poor, 2, 3, 4 & 5 excellent)				Signature						Out door Unit Transformer Faulty	
How is the behavior of visited engineer				Signature						Fault of swing Motor	
What is the level of your satisfaction				Signature						Defect of Drain Pump	
How is the explanation by Engineer				Signature						Expansion Valve Body / Motor Defective	
Details of Repair Work Done				Signature						Defective Temperature Sensor of Indoor Unit	
a Simple Repair				Signature						Defective Temperature Sensor of Outdoor Unit	
b Part Replaced				Signature						Defective Current Sensor In Out door Unit	
c Part Repaired				Signature						Gas Leakage at Indoor Unit	
d Gas Charging done				Signature						Gas Leakage at Outdoor Unit	
e Routine Service - Wet				Signature						Blower broken	
f Routine Service - DRY				Signature						Short Cycling of Air at Indoor Unit	
				Signature						Short Cycling of Air at Outdoor Unit	
				Signature						Defect in Drain piping System	
				Signature						Gas Leakage from Flare nut	
				Signature						Error In Transmission wiring	
				Signature						Product under capacity	
				Signature						Rat bite case	
				Signature						Less cooling problem due to dirty Airfilter	
				Signature						Remote setting changed	
				Signature						Clogged Condenser	
				Signature						Other - Pl. specify	