1415

DAIKIN AIRCONDITIONING INDIA PVT. LTD.

Service Completion Certificate

AEON AIRCONDITIONING SOLUTIONS

Office No. 108 & 109, Devashree Garden, Commercial Complex, R.W. Swami Marg, above Sheetal Dairy, Pub : Park, Thane - 400 601. Mob.: 9022204107 / 9022264109

Subject :

Registration No.	Request Date	Service Engineer	Scheduled Date/Time	Service Order
	28/8/26.	Irfan Beg.		

User : OHL Express India. Mobile :

Customer Address : West High Cord Road. OPPDr. Coolidge. Gokulpeth 7202854967

Base Address :

Daikin Invoice : Date : 28-8-26

Dealer Invoice : Date :

Type	Model No	Manufacturing No.
Outdoor unit / Indoor unit	PKM50XV16NKA	8036007
	FTKM50XV16NKB	0026910

Work Date	No. of S.E.	Work hours	Progress code	Details of the Repair Work
28/8/26.	1	1	5	Desmend and Installi' Done. Work Done.

Compressor manufacturing No.	Defective Compressor				Replacement Compressor		
Installed date	Warranty	AMC	Using with Stabilizer	Using with Cut off	Fault location	Phenomena code	Error code
	Yes / No	Yes / No	Yes / No	Yes / No			

Service Engineer Remarks: Work Don. Installation Done

Name: OHL Express (I) Pvt. Ltd. Signature

Customer Remarks: Meena Enclave, W.H.C. Road, Gokulpeth, Nagpur - 10. 0712 - 2638492/93

Name Signature

Operation data (Ambient temp. °C)	Before repair	After repair
HP / T	psig/	psig/
SP / T °C	psig/°C	psig/°C
Current °C	Amps°C	Amps°C
Voltage	Volts	Volts
Indoor temperature		
Suction	°C	°C
Discharge	°C	°C
Outdoor temperature		
Suction	°C	°C
Discharge	°C	°C

Work No / Parts No	Qty	Billing Amount
Dismantal.	1.	Nacy.
Installation	1.	Nacy.
P.V.C. Duct Rep'	5.	Fit.
Total		

Customer Impression about Service

(Please rate on scale of 1 poor, 2, 3, 4 & 5 excellent)

How is the behavior of visted engineer	
What is the level of your satisfaction	
How is the explaination by Engineer	

	Fault Diagnosed	✓
Power	Power Failure	
	Phase Reverse	
PCB	In door unit PCB Defective	
	Out door PCB Defective	
FM	In door unit Fan Motor Defective	
	Outdoor Fan Motor Defective	
Comp	Comp. taking High Current / Amp	
	Compressor Ground / Earth	
	Compressor Tripping due to High Temprature	
	Compressor tripping due to High Pressure	
Electrical	Indoor Unit MgSw Defective	
	Outdoor Unit Mgsw Defective	
	Indoor Unit Transformer Faulty	
	Out door Unit Transformer Faulty	
	Fault of swing Motor	
	Defect of Drain Pump	
	Expansion Valve Body / Motor Defective	
	Defective Temperature Sensor of Indoor Unit	
	Delective Temperature Sensor of Outdoor Unit	
	Defective Current Sensor In Out door Unit	
Unit	Gas Leakage at Indoor Unit	
	Gas Leakage at Outdoor Unit	
	Blower broken	
Installation	Short Cycling of Air at Indoor Unit	
	Short Cycling of Air at Outdoor Unit	
	Defect in Drain piping System	
	Gas Leakage from Flare nut	
	Error In Transmission wiring	
	Product under capacity	
	Rat bite case	
Other	Less cooling problem due to dirty Airfilter	
	Remote setting changed	
	Clogged Condenser	
	Other - Pl. specify	

	Details of Repair Work Done	✓
a	Simple Repair	
b	Part Replaced	
c	Part Repaired	
d	Gas Charging done	
e	Routine Service - Wet	
f	Routine Service - DRY	