DAIKIN AIRCONDITIONING INDIA PVT. LTD.

Authorised Service Center

AEON AIRCONDITIONING SOLUTIONS

AEON HOUSE, SHOP NO. 6/7, BEHIND N CUBE CHINA TOWN

DR. AMBEDKAR ROAD, THANE W 400601 MAHARASHTRA. PHONE :- 02225370101 / 7900097007

PROJECT :- ACC Ltd. Sonarpur. Kalkala West Bengal.

Measurement Sheet

Sr. No.	Location	AC Type	Tonnage	Indoor Unit Details		Outdoor Unit Details		Copper In Rmt	Cable In Rmt	Drain In Rmt	ODU Stand
				Model No.	Sr. No.	Model No.	Sr. No.				
1	PI Room	Split	2 TR	FTKL60XV16VAA	8017155	RKL60XV16VAA	8022623	—	—	4	1
2	HR Room.	Split	2 TR.	FTKL60XV16VAA	8017152	RKL60XV16VAA	8022850	—	—	4	1
3											
4											
5											
6											
7											
8											

EXTRA ACTIVITY CARRIED OUT

CIVIL WORK	Stabilizer			TIMER	CASING CAPPING	CABLE TRAY	GAS CHARGING	DISMENTALING		RE-INSTALLATION
	3KVA	4KVA	5KVA					Hi Wall	Cassette	

OTHERS: Two Core Cutting

For Customer Details : ACC LTD.		Vendor Details : AEON AIRCONDITIONING SOLUTIONS.	
Sign :		Signature :	
Name :		Technician Name :	Subhajit Bakel.
Date :	Stamp : ACC Ltd. Sonarpur	Date :	16/7/26

1415

DAIKIN

DAIKIN AIRCONDITIONING INDIA PVT. LTD.

Service Completion Certificate

AEON AIRCONDITIONING SOLUTIONS
Office No. 108 & 109, Devashree Garden, Commercial Complex,
R.V.L. Sreedevi Marg, above Shantal Dairy, Pokhi Park, Thane - 400 601.
Mob.: 9322334107 / 9322334109

Subject :

Registration No.	Request Date	Service Engineer	Scheduled Date/Time	Service Order

User : ACC Ltd. Sonarpur. Mobile :
Customer Address :
Base Address :

Daikin Invoice : Date : 16/7/26
Dealer Invoice : Date :

Type	Model No	Manufacturing No.
Outdoor unit / Indoor unit	RKL60XV16VAA	8022850
	FTKL60XV16MAA	8017152

Work Date	No. of S.E.	Work hours	Progress code	Details of the Repair Work

Compressor manufacturing No.	Defective Compressor				Replacement Compressor		
Installed date	Warranty	AMC	Using with Stabilizer	Using with Cut off	Fault location	Phenomena code	Error code
	Yes / No	Yes / No	Yes / No	Yes / No			

Service Engineer Remarks : Installation and Commissing done now cooling OK.

Name : Siddhartha Bakshi Signature

Customer Remarks

Name Signature

ACC Limited Sonarpur

Operation data (Ambient temp. °C)

	Before repair	After repair
HP / T	psig/	psig/
SP / T °C	psig/°C	psig/°C
Current °C	Amps°C	Amps°C
Voltage	Volts	Volts
Indoor temperature		
Suction	°C	°C
Discharge	°C	°C
Outdoor temperature		
Suction	°C	°C
Discharge	°C	°C

Work No / Parts No	Qty	Billing Amount
Total		

Customer Impression about Service

(Please rate on scale of 1 poor, 2, 3, 4 & 5 excellent)

How is the behavior of visited engineer	
What is the level of your satisfaction	
How is the explaination by Engineer	

	Fault Diagnosed	✓
Power	Power Failure	
	Phase Reverse	
PCB	In door unit PCB Defective	
	Out door PCB Defective	
FM	In door unit Fan Motor Defective	
	Outdoor Fan Motor Defective	
Comp	Comp. taking High Current / Amp	
	Compressor Ground / Earth	
	Compressor Tripping due of High Temprature	
	Compressor tripping due to High Pressure	
Electrical	Indoor Unit MgSw Defective	
	Outdoor Unit MgSw Defective	
	Indoor Unit Transformer Faulty	
	Out door Unit Transformer Faulty	
	Fault of swing Motor	
	Defect of Drain Pump	
	Expansion Valve Body / Motor Defective	
	Defective Temperature Sensor of Indoor Unit	
	Defective Temperature Sensor of Outdoor Unit	
	Defective Current Sensor in Out door Unit	
Unit	Gas Leakage at Indoor Unit	
	Gas Leakage at Outdoor Unit	
	Blower broken	
Installation	Short Cycling of Air at Indoor Unit	
	Short Cycling of Air at Outdoor Unit	
	Defect in Drain piping System	
	Gas Leakage from Flare nut	
	Error in Transmission wiring	
	Product under capacity	
	Rat bite cause	
Other	Less cooling problem due to dirty Airfilter	
	Remote setting changed	
	Clogged Condenser	
	Other - Pl. specify	

	Details of Repair Work Done	✓
a	Simple Repair	
b	Part Replaced	
c	Part Repaired	
d	Gas Charging done	
e	Routine Service - Wet	
f	Routine Service - DRY	

DAIKIN

DAIKIN AIRCONDITIONING INDIA PVT. LTD.

Service Completion Certificate

1415

AEON AIRCONDITIONING SOLUTIONS

Office No. 108 & 109, Devashree Garden, Commercial Complex, R.W. Swami Marg, above Sheetal Dairy, Pisoi Park, Thane - 400 601. Mob.: 9322334107 / 9322334109

Subject :

Registration No.	Request Date	Service Engineer	Scheduled Date/Time	Service Order

User : ACC LTD. Sonarpur Mobile :

Customer Address :

Base Address :

Daikin Invoice : Date : 16/7/26.

Dealer Invoice : Date :

Type	Model No	Manufacturing No.
Outdoor unit /	RKL60XV16VAA	8022623
Indoor unit	FTKL60XV16VAA	8017155

Work Date	No. of S.E.	Work hours	Progress code	Details of the Repair Work

Operation data (Ambient temp. °C)	Before repair	After repair
HP / T	psig/	psig/
SP / T °C	psig/°C	psig/°C
Current °C	Amps°C	Amps°C
Voltage	Volts	Volts
Indoor temperature		
Suction	°C	°C
Discharge	°C	°C
Outdoor temperature		
Suction	°C	°C
Discharge	°C	°C

Work No / Parts No	Qty	Billing Amount
	Total	

Compressor manufacturing No.	Defective Compressor	Replacement Compressor

Installed date	Warranty	AMC	Using with Stabilizer	Using with Out off	Fault location	Phenomena code	Error code
	Yes / No	Yes / No	Yes / No	Yes / No			

Service Engineer Remarks : Installation and Commissing done Nozo Cooling ok

Name : Siddhanta Bellal. Signature :

Customer Remarks

Name

Customer Impression about Service

(Please rate on scale of 1 poor, 2, 3, 4 & 5 excellent)

How is the behavior of visited engineer	
What is the level of your satisfaction	
How is the explaination by Engineer	

ACC Limited Sonarpur 15/07/26

Fault Diagnosed		✓
Power	Power Failure	
	Phase Reverse	
PCB	In door unit PCB Defective	
	Out door PCB Defective	
Fan	In door unit Fan Motor Defective	
	Outdoor Fan Motor Defective	
Comp	Comp. taking High Current / Amp	
	Compressor Ground / Earth	
	Compressor Tripping due ot High Temprature	
	Compressor tripping due to High Pressure	
Electrical	Indoor Unit MgSw Defective	
	Outdoor Unit Mgsw Defective	
	Indoor Unit Transformer Faulty	
	Out door Unit Transformer Faulty	
	Fault of swing Motor	
	Defect of Drain Pump	
	Expansion Valve Body / Motor Defective	
	Defective Temperature Sensor of Indoor Unit	
	Defective Temperature Sensor of Outdoor Unit	
	Defective Current Sensor In Out door Unit	
Unit	Gas Leakage at Indoor Unit	
	Gas Leakage at Outdoor Unit	
	Blower broken	
Installation	Short Cycling of Air at Indoor Unit	
	Short Cycling of Air at Outdoor Unit	
	Defect in Drain piping System	
	Gas Leakage from Flare nut	
	Error in Transmission wiring	
	Product under capacity	
	Rat bite case	
Other	Less cooling problem due to dirty Airfilter	
	Remote setting changed	
	Clogged Condenser	
	Other - Pl. specify	

Details of Repair Work Done		✓
a	Simple Repair	
b	Part Replaced	
c	Part Repaired	
d	Gas Charging done	
e	Routine Service - Wet	
f	Routine Service - DRY	