DAIKIN

DAIKIN AIRCONDITIONING INDIA PVT. LTD.

Authorised Service Provider

AEON AIRCONDITIONING SOLUTIONS

AEON HOUSE, SHOP NO. 6 & 7, BEHIND N CUBE CHINA TOWN

DR. AMBEDKAR ROAD, THANE W 400601 MAHARASHTRA. PHONE :- 02225370101 / 7900097007 / 9322334106

aeon

PROJECT :- Theobroma Foods Pvt Ltd. Bidhannagar (Saltlake) Kolkata

Measurement Sheet

Sr. No.	Location	AC Type	Tonnage	Indoor Unit Details		Outdoor Unit Details		Copper in Rmt	Cable in Rmt	Drain in Rmt	ODU Stand
				Model No.	Sr. No.	Model No.	Sr. No.				
1	Work Area	Cassette	3Tr	FCNF100CV16	0000829	RZCNF100CV16	0000432	10	12	12	1
2	Work Area.	Cassette	3Tr	FCNF100CV16	0000786	R2CNF100CV16	0000461	10	12	10	1
3	Work Area	Cassette	2 Tr	FCNF50CV16	0000333	R2CNF50CV16	0000169	8	10	13	1
4											
5											
6											
7											
8											
9											
10											

EXTRA ACTIVITY CARRIED OUT

CIVIL WORK	Stabilizer			TIMER	CASING CAPPING	CABLE TRAY	GAS CHARGING	DISMENTALING		RE-INSTALLATION
	3KVA	4KVA	5KVA					Hi Wall	Cassette	
OTHERS	Consultings - 3									

For Customer Details :	Theobroma Foods Pvt Ltd.	Vendor Details :	Aeon Airconditioning Solutions
Sign :		Signature :	
Name :	Tilak Mukherjee	Technician Name :	Jalal Crajeen
Date :	26.10.26 Stamp : THEOBROMA FOODS PVT LTD TILAK MUKHERJEE	Date :	

DAIKIN AIRCONDITIONING INDIA PVT. LTD.

Service Completion Certificate

C-403, Corporate Avenue Andheri Ghatkopar Link Rd, Andheri (E), Mumbai-400093.

AEON AIRCONDITIONING SOLUTIO

Office No. 108 & 109, Devashree Garden Commercial Co
R. W. Sawant Marg, Above Sheetal Dairy, Rutu Park, Thane-
Mob.: 9326311501 / 9322334106

Subject :

Sr.No._____

Registration No.	Request Date	Service Engineer's Name	Scheduled Date	Time	Notification No.	Service Order No.

User Name : Theobroma Foods Pvt. Ltd.

Address : Bidhannagar Kolkata.

Mobile No.: Tel. No.:

Daikin Invoice No.: Date :

Dealer Invoice No.: Date :

Type	Model No.	Manufacturing No.
Outdoor Unit	R2CNF100CV16	0000786
Indoor unit	FCNF100CV16	0000461

Work Date	No. of S.E.	Work Hours	Progress Code	Details of the Repair Work

Compressor Manufacturing No.	Defective Compressor	Replacement Compressor

Installed Date	Warranty	AMC	Using with Stabilizer	Using with Cut off	Fault Location	Phenomen Code	Error Code
	Yes / No	Yes / No	Yes / No	Yes / No			

Service Engineer Remarks Installation and commissing done Now cooling and heating ok.

Name Signature

Customer Remarks THEOBROMA FOODS PVT LTD TILAK MUKHERJEE

Name Signature

Operation data (Ambient temp. °C)	Before Repair	After Repair
HP / T °C	psig/°C	psig/°C
SP / T °C	psig/°C	psig/°C
Current	Amps	Amps
Voltage	Volts	Volts
Indoor Temperature		
Suction	°C	°C
Discharge	°C	°C
Outdoor Temperature		
Suction	°C	°C
Discharge	°C	°C

Work No / Parts No	Qty	Billing Amount
Total		

Customer Impression about Service

(Please rate on scale of 1 poor, 2, 3, 4 & 5 excellent)

How is the behavior of visited engineer	
What is the level of your satisfaction	
How is the explanation by Engineer	

	Fault Diagnosed
Power	Power Failure
	Phase Reverse
PCB	In door unit PCB Defective
	Out door PCB Defective
FM	In door unit Fan Motor Defective
	Outdoor Fan Motor Defective
Comp	Comp. taking Hight Current / Amp
	Compressor Ground / Earth
	Compressor Tripping due to High Temprature
	Compressor Tripping due to Hight Pressure
Electrical	Indoor Unit MgSw Defective
	Outdoor Unit MgSw Defective
	Indoor Unit Transformer Faulty
	Outdoor Unit Transformer Faulty
	Fault of Swing Motor
	Defect of Drain Pump
	Expansion Valve Body / Motor Defective
	Defective Temperature Sensor of Indoor Unit
	Defective Temperature Sensor of Outdoor Unit
	Defective Current Sensor in Out door Unit
Unit	Gas Leakage at Indoor Unit
	Gas Leakage at Outdoor Unit
	Blower Broken
Installation	Short Cycling of Air at Indoor Unit
	Short Cycling of Air at Outdoor Unit
	Defect in Drain Piping System
	Gas Leakage from Flare nut
	Error In Transmission wiring
	Product under capacity
	Rate bite case
Other	Less cooling problem due to dirty Airfilter
	Remote setting changed
	Clogged condenser
	Other - Pl. Specify

	Details of Repair Work Done	✓
a	Simple Repair	
b	Part Replaced	
c	Part Replaced	
d	Gas Charging Done	
e	Routing Service - Wet	
f	Routing Service - Dry	

"We recommend, to take routine maintenance services of your Daikin machine at regular intervals, for its good health"

DAIKIN AIRCONDITIONING INDIA PVT. LTD.

Service Completion Certificate

C-403, Corporate Avenue Andheri Ghatkopar Link Rd, Andheri (E), Mumbai-400093.

AEON AIRCONDITIONING SOLUTION

Office No. 108 & 109, Devashree Garden Commercial Compl
R. W. Sawant Marg, Above Sheetal Dairy, Rutu Park, Thane-400
Mob.: 9326311501 / 9322334106

Subject : **Sr.No.**_____

Registration No.	Request Date	Service Engineer's Name	Scheduled Date	Time	Notification No.	Service Order No.

User Name : Theobroma Foods Pvt Ltd.

Address : Bidhannagar Kolkata

Mobile No.: Tel. No.:

Daikin Invoice No.: Date :

Dealer Invoice No.: Date :

Type	Model No.	Manufacturing No.
Outdoor Unit	RZCNF100CV16	0000432
Indoor unit	FCNF100CV16	0000829.

Work Date	No. of S.E.	Work Hours	Progress Code	Details of the Repair Work

Compressor Manufacturing No.	Defective Compressor			Replacement Compressor		
Installed Date	**Warranty**	**AMC**	**Using with**		**Fault Location**	**Phenomen Code**	**Error Code**
			Stabilizer	**Cut off**			
	Yes / No	Yes / No	Yes / No	Yes / No			

Service Engineer Remarks Instalation and Commissing done Now Cooling and running OK,

Name ..... Signature .....

Customer Remarks

THEOBROMA FOODS PVT LTD Ok.
TILAK MUKHERJEE

Name ..... Signature .....

Operation data (Ambient temp. °C)

	Before Repair	After Repair
HP / T °C	psig/°C	psig/°C
SP / T °C	psig/°C	psig/°C
Current	Amps	Amps
Voltage	Volts	Volts
Indoor Temperature		
Suction	°C	°C
Discharge	°C	°C
Outdoor Temperature		
Suction	°C	°C
Discharge	°C	°C

Work No / Parts No	Qty	Billing Amount

DAIKIN AIRCONDITIONING INDIA PVT. LTD.

Service Completion Certificate
C-403, Corporate Avenue Andheri Ghatkopar Link Rd, Andheri (E), Mumbai-400093.

AEON AIRCONDITIONING SOLUTIONS
Office No. 108 & 109, Devashree Garden Commercial Comple
R. W. Sawant Marg, Above Sheetal Dairy, Rutu Park, Thane-400
Mob.: 9326311501 / 9322334106

Subject : **Sr.No.**_____

Registration No.	Request Date	Service Engineer's Name	Scheduled Date	Time	Notification No.	Service Order No.

User Name :

Address :

Mobile No.: Tel. No.:

Daikin Invoice No.: Date :

Dealer Invoice No.: Date :

Type	Model No.	Manufacturing No.
Outdoor Unit	RZCNF50CV1G	0000333
Indoor unit	FCNF50CV1G	0000169.

Work Date	No. of S.E.	Work Hours	Progress Code	Details of the Repair Work

Compressor Manufacturing No.	Defective Compressor	Replacement Compressor

Installed Date	Warranty	AMC	Using with Stabilizer	Using with Cut off	Fault Location	Phenomen Code	Error Code
	Yes / No	Yes / No	Yes / No	Yes / No			

Service Engineer Remarks

Name Signature

Customer Remarks

THEOBROMA FOODS PVT LTD
TILAK MUKHERJEE

Name Signature

Operation data (Ambient temp. °C)	Before Repair	After Repair
HP / T °C	psig/°C	psig/°C
SP / T °C	psig/°C	psig/°C
Current	Amps	Amps
Voltage	Volts	Volts
Indoor Temperature		
Suction	°C	°C
Discharge	°C	°C
Outdoor Temperature		
Suction	°C	°C
Discharge	°C	°C

Work No / Parts No	Qty	Billing Amount
Total		

Customer Impression about Service

(Please rate on scale of 1 poor, 2, 3, 4 & 5 excellent)

How is the behavior of visited engineer	
What is the level of your satisfaction	
How is the explanation by Engineer	

	Fault Diagnosed	✓
Power	Power Failure	
	Phase Reverse	
PCB	In door unit PCB Defective	
	Out door PCB Defective	
EM	In door unit Fan Motor Defective	
	Outdoor Fan Motor Defective	
Comp	Comp. taking Hight Current / Amp	
	Compressor Ground / Earth	
	Compressor Tripping due to High Temprature	
	Compressor Tripping due to Hight Pressure	
Electrical	Indoor Unit MgSw Defective	
	Outdoor Unit MgSw Defective	
	Indoor Unit Transformer Faulty	
	Outdoor Unit Transformer Faulty	
	Fault of Swing Motor	
	Defect of Drain Pump	
	Expansion Valve Body / Motor Defective	
	Defective Temperature Sensor of Indoor Unit	
	Defective Temperature Sensor of Outdoor Unit	
	Defective Current Sensor in Out door Unit	
Unit	Gas Leakage at Indoor Unit	
	Gas Leakage at Outdoor Unit	
	Blower Broken	
Installation	Short Cycling of Air at Indoor Unit	
	Short Cycling of Air at Outdoor Unit	
	Defect in Drain Piping System	
	Gas Leakage from Flare nut	
	Error In Transmission wiring	
	Product under capacity	
	Rate bite case	
Other	Less cooling problem due to dirty Airfilter	
	Remote setting changed	
	Clogged condenser	
	Other - Pl. Specify	

	Details of Repair Work Done	✓
a	Simple Repair	
b	Part Replaced	
c	Part Replaced	
d	Gas Charging Done	
e	Routing Service - Wet	
f	Routing Service - Dry	

"We recommend, to take routine maintenance services of your Daikin machine at regular intervals, for its good health"