DAIKIN AIRCONDITIONING INDIA PVT. LTD.

Service Completion Certificate
C-403, Corporate Avenue Andheri Ghatkopar Link Rd, Andheri (E), Mumbai-400093.

Subject : Breakdown (out warranty)

Sr.No.

AEON AIRCONDITIONING SOLUTIONS
Office No. 108 & 109, Devashree Garden Commercial Complex,
R. W. Sawant Marg, Above Sheetal Dairy, Rutu Park, Thane-400 601.
Mob.: 9326311501 / 9322334106

Registration No.	Request Date	Service Engineer's Name	Scheduled Date

Time	Notification No.	Service Order No.

User Name : City Union Bank.
Address : DHL Park, Aaveegam.
Mobile No.: Tel. No.:
Daikin Invoice No.: Date :
Dealer Invoice No.: Date :

Type	Model No.	Manufacturing No.
Outdoor Unit	RQ35RRV162.	1202.
Indoor unit	FTQ35RRV162.	1108.

Work Date	No. of S.E.	Work Hours	Progress Code	Details of the Repair Work
07/11/2026			—	I/C Communication wire & Main Supply cut by rat need to be replace. I/C not turn on. Trip issue.

Compressor Manufacturing No.	Defective Compressor	Replacement Compressor

Installed Date	Warranty	AMC	Using with		Fault Location	Phenomen Code	Error Code
			Stabilizer	Cut off			
	Yes / No	Yes / No	Yes / No	Yes / No			

Service Engineer Remarks : Visit Charges pending
Malik Faizan & Muzaffa
Name Signature

Customer Remarks
Name A. Anand Roy. Signature 09/11/26

Operation data (Ambient temp. °C)

	Before Repair	After Repair
HP / T °C	psig/°C	psig/°C
SP / T °C	psig/°C	psig/°C
Current	Amps	Amps
Voltage	Volts	Volts
Indoor Temperature		
Suction	°C	°C
Discharge	°C	°C
Outdoor Temperature		
Suction	°C	°C
Discharge	°C	°C

Work No / Parts No	Qty	Billing Amount
Site visit. Charges	1	500/-
	Total	500/-

Customer Impression about Service
(Please rate on scale of 1 poor, 2, 3, 4 & 5 excellent)
How is the behavior of visited engineer
What is the level of your satisfaction
How is the explanation by Engineer

	Fault Diagnosed	✓
Power	Power Failure	✓
	Phase Reverse	
PCB	In door unit PCB Defective	
	Out door PCB Defective	
EM	In door unit Fan Motor Defective	
	Outdoor Fan Motor Defective	
Comp	Comp. taking Hight Current / Amp	
	Compressor Ground / Earth	
	Compressor Tripping due to High Temprature	
	Compressor Tripping due to Hight Pressure	
Electrical	Indoor Unit MgSw Defective	
	Outdoor Unit MgSw Defective	
	Indoor Unit Transformer Faulty	
	Outdoor Unit Transformer Faulty	
	Fault of Swing Motor	
	Defect of Drain Pump	
	Expansion Valve Body / Motor Defective	
	Defective Temperature Sensor of Indoor Unit	
	Defective Temperature Sensor of Outdoor Unit	
	Defective Current Sensor in Out door Unit	
Unit	Gas Leakage at Indoor Unit	
	Gas Leakage at Outdoor Unit	
	Blower Broken	
Installation	Short Cycling of Air at Indoor Unit	
	Short Cycling of Air at Outdoor Unit	
	Defect in Drain Piping System	
	Gas Leakage from Flare nut	
	Error In Transmission wiring	
	Product under capacity	
	Rate bite case	
Other	Less cooling problem due to dirty Airfilter	
	Remote setting changed	
	Clogged condenser	
	Other - Pl. Specify	

	Details of Repair Work Done	✓
a	Simple Repair	✓
b	Part Replaced	
c	Part Replaced	
d	Gas Charging Done	
e	Routing Service - Wet	
f	Routing Service - Dry	

"We recommend, to take routine maintenance services of your Daikin machine at regular intervals, for its good health"

Daikin Customer Care : Missed Call or SMS <DAIKIN> to 92101 88999 ; Toll Free Number : 1860 180 3900 / 1800 102 9300 ; cs@daikinindia.com / www.daikinindia.com

DAIKIN AIRCONDITIONING INDIA PVT. LTD.

Service Completion Certificate
C-403, Corporate Avenue Andheri Ghatkopar Link Rd, Andheri (E), Mumbai-400093.

AEON AIRCONDITIONING SOLUTIONS
Office No. 108 & 109, Devashree Garden Commercial Complex,
R. W. Sawant Marg, Above Sheetal Dairy, Rutu Park, Thane-400 601.
Mob.: 9326311501 / 9322334106

Subject : Out Warranty AC (Breakdown) Sr.No.

Registration No.	Request Date	Service Engineer's Name	Scheduled Date	Time	Notification No.	Service Order No.

User Name : City Union Bank.

Address : DLH Park, Goregaon, SV Road, Mumbai.

Mobile No.: Tel. No.:

Daikin Invoice No.: Date :

Dealer Invoice No.: Date :

Type	Model No.	Manufacturing No.
Outdoor Unit	RN60QGXV16B	K001384
Indoor unit		

Work Date	No. of S.E.	Work Hours	Progress Code	Details of the Repair Work
07		3:00		Cassette ACs → (2 Nos aging 10 yrs)
11		PM		Condenser coil of ODU is damaged.
26		4:00		Rusting problem. Need to replace both the ACs

Compressor Manufacturing No.	Defective Compressor	Replacement Compressor

Installed Date	Warranty	AMC	Using with Stabilizer	Using with Cut off	Fault Location	Phenomen Code	Error Code
	Yes / No	Yes / No	Yes / No	Yes / No			

Service Engineer Remarks
Suggestion of replacing ACs both cassette
Site visit Charges pending

Name Faizan & Huzaifa Signature

Customer Remarks

Name A. Anand Raj Signature

Operation data (Ambient temp. °C)

	Before Repair	After Repair
HP / T °C	psig/°C	psig/°C
SP / T °C	psig/°C	psig/°C
Current	Amps	Amps
Voltage	Volts	Volts
Indoor Temperature		
Suction	°C	°C
Discharge	°C	°C
Outdoor Temperature		
Suction	°C	°C
Discharge	°C	°C

Work No / Parts No	Qty	Billing Amount
Site visit Charges	1	750/-
	Total	750/-

Customer Impression about Service

(Please rate on scale of 1 poor, 2, 3, 4 & 5 excellent)

How is the behavior of visited engineer	
What is the level of your satisfaction	
How is the explanation by Engineer	

	Fault Diagnosed	✓
Power	Power Failure	
	Phase Reverse	
PCB	In door unit PCB Defective	
	Out door PCB Defective	
EM	In door unit Fan Motor Defective	
	Outdoor Fan Motor Defective	
Comp	Comp. taking Hight Current / Amp	
	Compressor Ground / Earth	
	Compressor Tripping due to High Temprature	
	Compressor Tripping due to Hight Pressure	
Electrical	Indoor Unit MgSw Defective	
	Outdoor Unit MgSw Defective	
	Indoor Unit Transformer Faulty	
	Outdoor Unit Transformer Faulty	
	Fault of Swing Motor	
	Defect of Drain Pump	
	Expansion Valve Body / Motor Defective	
	Defective Temperature Sensor of Indoor Unit	
	Defective Temperature Sensor of Outdoor Unit	
	Defective Current Sensor in Out door Unit	
Unit	Gas Leakage at Indoor Unit	
	Gas Leakage at Outdoor Unit	
	Blower Broken	
Installation	Short Cycling of Air at Indoor Unit	
	Short Cycling of Air at Outdoor Unit	
	Defect in Drain Piping System	
	Gas Leakage from Flare nut	
	Error In Transmission wiring	
	Product under capacity	
	Rate bite case	
Other	Less cooling problem due to dirty Airfilter	
	Remote setting changed	
	Clogged condenser	
	Other - Pl. Specify	

	Details of Repair Work Done	✓
a	Simple Repair	
b	Part Replaced	
c	Part Replaced	
d	Gas Charging Done	
e	Routing Service - Wet	
f	Routing Service - Dry	


"We recommend, to take routine maintenance services of your Daikin machine at regular intervals, for its good health"

Daikin Customer Care : Missed Call or SMS <DAIKIN> to 92101 88999 ; Toll Free Number : 1860 180 3900 / 1800 102 9300 ; cs@daikinindia.com / www.daikinindia.com


AIR CONDITIONER OUTDOOR CONDENSING UNIT
MODEL RQ35RRV162
SER. NO. 0001202
50Hz 230V ~
COOLING CAPACITY 3350W
1100W
CURRENT 4.9A
INPUT
REFRIGERANT R-32 0.60 kg
NET WEIGHT 30 kg
CONDITIONING INDIA PVT




AIR CONDITIONER INDOOR UNIT
MODEL FTQ35RRV162
NET WEIGHT 8kg
SER. NO. 0001108
50Hz 230V ~
DAIKIN AIRCONDITIONING INDIA PVT.LTD.
MADE IN INDIA
2P412668-1B


DAIKIN
Model RN60CGXV16B
S/No. K001384
Rated Power Supply (V/Ph/Hz)
220-240/~/50
Total Rated Power (W)
Total Rated Current (A)
Cooling 2095 / 9.26
Max. Current (A) 12.0
Refrigerant R410A 2.10 kg
Protection IPX1
Max. Allowable Pressure
High Side 41.9 bar (4.19 MPa)
Low Side 25.1 bar (2.51 MPa)
Mass 50 kg
Year of Manufacture 2016
ANPIA5SL26C
B/No. 20592311
DAIKIN INDUSTRIES,LTD.
DAIKIN EUROPE N.V.
MADE IN MALAYSIA
R410A




DTP








S-2
A/C