AEON AIRCONDITIONING SOLUTIONS

Aeon House, Shop No. 6/7, Behind N Cube China Town, Opp. Shishu Dnyan Mandir,
Dr. Ambedkar Rd. Thane 400 601. Maharashtra
Tel.: 022 - 25370101 / 7900097007
e-mail : services@aeonacsolutions.com website : www.aeonacsolutions.com

Project : Samman Capital Ltd - Office No - 401, 4th Flr - Abhimaan II, opp forest office Teen hath Naka

Additional Measurement Sheet

Sr. No	Location	AC Type	Tonnage	Indoor Unit Details		Outdoor Unit Details		Copper In Rmt	Cable In Rmt	Drain In Rmt	ODU Stand
				Model No.	Sr. No.	Model No.	Sr. No.				
1		Split	1.5	FTQ50 XV16VDA	80124 99	RQ50XV16 VDA	80182 902	22 Ft	25ft	2mt	
2											
3											
4		Split	1.5	FTQ50XV16 VDA	80093 18	RQ50XV16V DA	80181882 22	5 Ft	29ft	3mt	
5											
6											
7											
8											

Extra Activity Carried Out

Civil Work	Stabilizer			Timer	Casing Capping	Cable Tray	Gas Charging	Dismentling		Re-installation
	3KVA	4KVA	5KVA					Hi Wall	Cassette	
Others										

For	Cable Wire Supply & US	Vendor Details	
Sign		Signature	
Name	Prashant S. Kotian	Technician Name	Shoaib Adhikari
Date	Stamp	Date	31/5/26

SAMMAAN CAPITAL LIMITED MUMBAI

DAIKIN AIRCONDITIONING INDIA PVT. LTD.

Service Completion Certificate

1415

AEON AIRCONDITIONING SOLUTIONS

Office No. 105 & 106, Devashree Garden, Commercial Complex, R.W. Swami Marg, Jitone Shastri Dairy, Rabodi Park, Thane - 400 601
Mob.: 9922284107 / 9922284109

Subject

Registration No.	Request Date	Service Engineer	Scheduled Date/Time	Service Order

User :

Mobile :

Customer Address

Base Address

Daikin Invoice — Date :

Dealer Invoice — Date :

Type	Model No	Manufacturing No.
Outdoor unit	RQ50XV16VA	80181881
Indoor unit	FTQ50XV16VDA	8009318

Work Date	No. of S.E.	Work hours	Progress code	Details of the Repair Work
26/6				AC fitting done working cooling fine

Compressor manufacturing No.	Defective Compressor				Replacement Compressor		
Installed date	Warranty	AMC	Using with Stabilizer	Using with Cut off	Fault location	Phenomena code	Error code
	Yes / No	Yes / No	Yes / No	Yes / No			

Service Engineer Remarks

Name

Signature

Customer Remarks

Name

Signature

SAMMAAN CAPITAL LIMITED. MUMBAI

Operation data (Ambient temp. °C)	Before repair	After repair
HP / T	psig/	psig/
SP / T °C	psig/°C	psig/°C
Current °C	Amps°C	Amps°C
Voltage	Volts	Volts
Indoor temperature		
Suction	°C	°C
Discharge	°C	°C
Outdoor temperature		
Suction	°C	°C
Discharge	°C	°C

Work No / Parts No	Qty	Billing Amount
Total		

	Fault Diagnosed	✓
Power	Power Failure	
	Phase Reverse	
PCB	In door unit PCB Defective	
	Out door PCB Defective	
FM	In door unit Fan Motor Defective	
	Outdoor Fan Motor Defective	
Comp	Comp. taking High Current / Amp	
	Compressor Ground / Earth	
	Compressor Tripping due of High Temprature	
	Compressor tripping due to High Pressure	
Electrical	Indoor Unit Mcbw Defective	
	Outdoor Unit Mcbw Defective	
	Indoor Unit Transformer Faulty	
	Out door Unit Transformer Faulty	
	Fault of swing Motor	
	Defect of Drain Pump	
	Expansion Valve Body / Motor Defective	
	Defective Temperature Sensor of Indoor Unit	
	Defective Temperature Sensor of Outdoor Unit	
	Defective Current Sensor in Out door Unit	
Unit	Gas Leakage at Indoor Unit	
	Gas Leakage at Outdoor Unit	
	Blower broken	
Installation	Short Cycling of Air at Indoor Unit	
	Short Cycling of Air at Outdoor Unit	
	Defect in Drain piping System	
	Gas Leakage from Flare nut	
	Error in Transmission wiring	
	Product under capacity	
	Rat bite case	
Other	Less cooling problem due to dirty Air filter	
	Remote setting changed	
	Clogged Condenser	
	Other - Pl. specify	

Customer Impression about Service (Please rate on scale of 1 poor, 2, 3, 4 & 5 excellent)	
How is the behavior of visited engineer	
What is the level of your satisfaction	
How is the explanation by Engineer	

Details of Repair Work Done	✓
a	Simple Repair
b	Part Replaced
c	Part Repaired
d	Gas Charging done
e	Routine Service - Wet
f	Routine Service - Dry

1415

DAIKIN AIRCONDITIONING INDIA PVT. LTD.

Service Completion Certificate

AEON AIRCONDITIONING SOLUTIONS

Office No. 108 & 109, Devashree Garden, Commercial Complex, R.W. Swasant Marg, above Sheetal Dairy, Patu Park, Thane - 400 601
Mob.: 9322334107 / 9322334109

Subject :

Registration No.	Request Date	Service Engineer	Scheduled Date/Time	Service Order

User : Mobile :

Customer Address :

Base Address :

Daikin Invoice : Date :

Dealer Invoice : Date :

Type	Model No	Manufacturing No.
Outdoor unit / Indoor unit	RASOXV16PA / FVIGVPA	8018901 / 8012499

Work Date	No. of S.E.	Work hours	Progress code	Details of the Repair Work
3/4/22				AC fitting done. Working in cooling mode

Compressor manufacturing No.	Defective Compressor	Replacement Compressor

Installed date	Warranty	AMC	Using with Stabilizer	Using with Cut off	Fault location	Phenomena code	Error code
	Yes / No	Yes / No	Yes / No	Yes / No			

Service Engineer Remarks :

Name : Signature :

Customer Remarks :

Name : Signature :

SAMMAAN CAPITAL LIMITED. MUMBAI

Operation data (Ambient temp. °C)	Before repair	After repair
HP / T	psig/	psig/
SP / T °C	psig/°C	psig/°C
Current °C	Amps°C	Amps°C
Voltage	Volts	Volts
Indoor temperature		
Suction	°C	°C
Discharge	°C	°C
Outdoor temperature		
Suction	°C	°C
Discharge	°C	°C

Work No / Parts No	Qty	Billing Amount
Total		

Customer Impression about Service

(Please rate on scale of 1 poor, 2, 3, 4 & 5 excellent)

How is the behavior of visted engineer	
What is the level of your satisfaction	
How is the explanation by Engineer	

	Fault Diagnosed	✓
Power	Power Failure	
	Phase Reverse	
PCB	In door unit PCB Defective	
	Out door PCB Defective	
FM	In door unit Fan Motor Defective	
	Outdoor Fan Motor Defective	
Comp	Comp. taking High Current / Amp	
	Compressor Ground / Earth	
	Compressor Tripping due ot High Temprature	
	Compressor tripping due to High Pressure	
Electrical	Indoor Unit MgSw Defective	
	Outdoor Unit Mgsw Defective	
	Indoor Unit Transformer Faulty	
	Out door Unit Transformer Faulty	
	Fault of swing Motor	
	Defect of Drain Pump	
	Expansion Valve Body / Motor Defective	
	Defective Temperature Sensor of Indoor Unit	
	Defective Temperature Sensor at Outdoor Unit	
	Defective Current Sensor In Out door Unit	
Unit	Gas Leakage at Indoor Unit	
	Gas Leakage at Outdoor Unit	
	Blower broken	
Installation	Short Cycling of Air at Indoor Unit	
	Short Cycling of Air at Outdoor Unit	
	Defect in Drain piping System	
	Gas Leakage from Flare nut	
	Error In Transmission wiring	
	Product under capacity	
	Rat bite case	
Other	Less cooling problem due to dirty Airfilter	
	Remote setting changed	
	Clogged Condenser	
	Other - Pl specify	

	Details of Repair Work Done	✓
a	Simple Repair	
b	Part Replaced	
c	Part Repaired	
d	Gas Charging Done	
g	Routine Service - Wet	
f	Routine Service - DRY	