DAIKIN

DAIKIN AIRCONDITIONING INDIA PVT. LTD.

Authorised Service Center

AEON AIRCONDITIONING SOLUTIONS

AEON HOUSE, SHOP NO. 6/7, BEHIND N CUBE CHINA TOWN
DR. AMBEDKAR ROAD, THANE W 400601 MAHARASHTRA. PHONE :- 02225370101 / 7900097007

aeon

PROJECT :- Hotel Ravikant Sy No. 17/1/1, Plot No. 1, Padmavati, Corner, Pune - Satara Rd, Pune, Maharashtra.

Measurement Sheet

Sr. No.	Location	AC Type	Tonnage	Indoor Unit Details		Outdoor Unit Details		Copper In Rmt	Cable In Rmt	Drain In Rmt	ODU Stand
				Model No.	Sr. No.	Model No.	Sr. No.				
1	Open Area	Cassette	4	FCFQ140CV16	0001677	RZCFQ140CY16	0002049	12	14	17	Fabrication
2	Open Area	Cassette	3	FCFQ100CV16	0001210	RZCFQ100C16	0001929	10	12	12	Fabrication
3	Open Area	Cassette	3	FCFQ100CV16	0001530	RZCFQ100C16	0001930	7	9	10	Fabrication
4	Open Area	Cassette	4	FCFQ140CV16	0001562	RZCFQ140CY16	0002176	10	12	12	Fabrication
5	Open Area	Cassette	4	FCFQ140CV16	0001596	RZCFQ140CY16	0002178	27	29	12	Fabrication
6											
7											
8											

CIVIL WORK	Stabilizer			TIMER	CORE CUTTING	CABLE TRAY	DRAIN PUMP	DISMENTALING		RE-INSTALLATION
	3KVA	4KVA	5KVA					Hi Wall	Cassette	Cassette AC (IDU)
–	–	–	–	–	–	–	–	–	–	–

OTHERS	ODU unit Lifting Shifting

For Customer Details	Hotel Ravikant	Vendor Details :	AEON AIRCONDITIONING SOLUTIONS
Sign		Signature :	
Name		Technician Name :	Arif Shaikh
For Custom	Stamp :	Date :	29.09.2026

30-9-2026

DAIKIN AIRCONDITIONING INDIA PVT. LTD.

Service Completion Certificate
C-403, Corporate Avenue Andheri Ghatkopar Link Rd, Andheri (E), Mumbai-400093.

AEON AIRCONDITIONING SOLUTIONS
Office No. 108 & 109, Devashree Garden Commercial Complex,
R. W. Sawant Marg, Above Sheetal Dairy, Rutu Park Thane-400 601
Mob. 9326311501 / 9322334106

Subject :

Sr.No._____

Registration No.	Request Date	Service Engineer's Name	Scheduled Date
		Arif Shaikh	29/09/26

Time	Notification No.	Service Order No.

User Name : Hotel Ravikant,
Address : Padmavati, Corner, Pune - Satara Road -
Mobile No.: Tel. No.:
Daikin Invoice No.: Date :
Dealer Invoice No.: Date :

Type	Model No.	Manufacturing No.
Outdoor Unit		
Indoor unit		

Work Date	No. of S.E.	Work Hours	Progress Code	Details of the Repair Work
29/09/26				3 NOS. 4TR & 2 NOS. 3TR Cassette AC installation work completed.

Compressor Manufacturing No	Defective Compressor	Replacement Compressor

Installed Date	Warranty	AMC	Using with Stabilizer	Using with Cut off	Fault Location	Phenomen Code	Error Code
	Yes / No	Yes / No	Yes / No	Yes / No			

Service Engineer Remarks : All AC unit Testing & Commissioning work completed.

Name ..... Signature

Customer Remarks

Name Signature

Operation data (Ambient temp. °C)	Before Repair	After Repair
HP / T °C	psig/°C	psig/°C
SP / T °C	psig/°C	psig/°C
Current	Amps	Amps
Voltage	Volts	Volts
Indoor Temperature		
Suction	°C	°C
Discharge	°C	°C
Outdoor Temperature		
Suction	°C	°C
Discharge	°C	°C

Work No / Parts No	Qty	Billing Amount
	Total	

Customer Impression about Service

(Please rate on a scale of 1, 2, 3, 4, 5 as applicable)

How is the behavior of visited engineer	
What is the level of your satisfaction	
How is the explanation by Engineer	

	Fault Diagnosed	✓
Power	Power Failure	
	Phase Reverse	
PCB	In door unit PCB Defective	
	Out door PCB Defective	
FM	In door unit Fan Motor Defective	
	Outdoor Fan Motor Defective	
Comp	Comp. taking Hight Current / Amp	
	Compressor Ground / Earth	
	Compressor Tripping due to High Temprature	
	Compressor Tripping due to Hight Pressure	
Electrical	Indoor Unit MgSw Defective	
	Outdoor Unit MgSw Defective	
	Indoor Unit Transformer Faulty	
	Outdoor Unit Transformer Faulty	
	Fault of Swing Motor	
	Defect of Drain Pump	
	Expansion Valve Body / Motor Defective	
	Defective Temperature Sensor of Indoor Unit	
	Defective Temperature Sensor of Outdoor Unit	
	Defective Current Sensor in Out door Unit	
Unit	Gas Leakage at Indoor Unit	
	Gas Leakage at Outdoor Unit	
	Blower Broken	
Installation	Short Cycling of Air at Indoor Unit	
	Short Cycling of Air at Outdoor Unit	
	Defect in Drain Piping System	
	Gas Leakage from Flare nut	
	Error In Transmission wiring	
	Product under capacity	
	Rats bite case	
Other	Less cooling problem due to dirty Air filter	
	Remote setting changed	
	Clogged condenser	
	Other - Pl. Specify	

	Details of Repair Work Done	✓
a	Simple Repair	
b	Part Replaced	
c	Gas Charging Done	
e	Routing Service - Wet	
f	Routing Service - Dry	

"We recommend, to take routine maintenance services of your Daikin machine at regular intervals, for its good health"

Daikin Customer Care : Missed Call or SMS <DAIKIN> to 92101 88999 ; Toll Free Number : 1860 180 3900 / 1800 102 9300 ; cs@daikinindia.com / www.daikinindia.com