AEON AIRCONDITIONING SOLUTIONS

Aeon House, Shop No. 6/7, Behind N Cube China Town, Opp. Shishu Dnyan Mandir,
Dr. Ambedkar Rd. Thane 400 601. Maharashtra
Tel. : 022 - 25370101 / 7900097007
e-mail : services@aeonacsolutions.com website : www.aeonacsolutions.com

307

Project : New York Burritto

Additional Measurement Sheet

Sr. No	Location	AC Type	Tonnage	Indoor Unit Details		Outdoor Unit Details		Copper In Rmt	Cable In Rmt	Drain In Rmt	ODU Stand
				Model No.	Sr. No.	Model No.	Sr. No.				
1	Kitchen Room	Cassette Ahc	3.0Tr	FCVFQ100AVM6	0007942	RZVFQ100AVM6	0009285		~~35mtr~~		
2								35mtr	37mtr	10mtr	
3											
4											
5											
6											
7											
8											

Extra Activity Carried Out

Civil Work	Stabilizer			Timer	Casing Capping	Cable Tray	Gas Charging	Dismentling		Re-installation
	3KVA	4KVA	5KVA					Hi Wall	Cassette	
						7mtr				

Others: Rubber Pad Outdoor Stand & Gas Top up

For		Vendor Details	
Sign		Signature	
Name	Akram	Technician Name	
Date	11-12-25 Stamp	Date	11/12/25

306

DAIKIN AIRCONDITIONING INDIA PVT. LTD.

Service Completion Certificate

Subject :

AEON AIRCONDITIONING SOLUTIONS
Office No. 108 & 109, Devashree Garden, Commercial Complex,
R.W. Swaant Marg, above Sheetal Dairy, Rutu Park, Thane - 400 601.
Mob.: 9322334107 / 9322334109

Registration No.	Request Date	Service Engineer	Scheduled Date/Time	Service Order
		Akram	28-11-25	

User : New York Burrito Mobile :

Customer Address :

I Base Address : Kalina Santacruz East

Daikin Invoice : Date :

Dealer Invoice : Date :

Type	Model No	Manufacturing No.
Outdoor unit / Indoor unit	R2VFQ100AV16	0007942
	FCVFQ100AV16	0009285

Work Date	No. of S.E.	Work hours	Progress code	Details of the Repair Work
28-11-25				3.0 Tr Cassette AHC Installation

Compressor manufacturing No.	Defective Compressor				Replacement Compressor		
Installed date	Warranty	AMC	Using with Stabilizer	Using with Cut off	Fault location	Phenomena code	Error code
	Yes / No	Yes / No	Yes / No	Yes / No			

Service Engineer Remarks : cooling is fine

Name : Akram Signature :

Customer Remarks

Name Signature

Operation data (Ambient temp. °C)	Before repair	After repair
HP / T	psig/	psig/
SP / T °C	psig/°C	psig/°C
Current °C	Amps°C	Amps°C
Voltage	Volts	Volts
Indoor temperature		
Suction	°C	°C
Discharge	°C	°C
Outdoor temperature		
Suction	°C	°C
Discharge	°C	°C

Work No / Parts No	Qty	Billing Amount
Total		

	Fault Diagnosed	✓
Power	Power Failure	
	Phase Reverse	
PCB	In door unit PCB Defective	
	Out door PCB Defective	
EM	In door unit Fan Motor Defective	
	Outdoor Fan Motor Defective	
Comp	Comp. taking High Current / Amp	
	Compressor Ground / Earth	
	Compressor Tripping due ot High Temprature	
	Compressor tripping due to High Pressure	
Electrical	Indoor Unit MgSw Defective	
	Outdoor Unit Mgsw Defective	
	Indoor Unit Transformer Faulty	
	Out door Unit Transformer Faulty	
	Fault of swing Motor	
	Defect of Drain Pump	
	Expansion Valve Body / Motor Defective	
	Defective Temperature Sensor of Indoor Unit	
	Defective Temperature Sensor of Outdoor Unit	
	Defective Current Sensor In Out door Unit	
Unit	Gas Leakage at Indoor Unit	
	Gas Leakage at Outdoor Unit	
	Blower broken	
Installation	Short Cycling of Air at Indoor Unit	
	Short Cycling of Air at Outdoor Unit	
	Defect in Drain piping System	
	Gas Leakage from Flare nut	
	Error In Transmission wiring	
	Product under capacity	
	Rat bite case	
Other	Less cooling problem due to dirty Airfilter	
	Remote setting changed	
	Clogged Condenser	
	Other - Pl. specify	

Customer Impression about Service (Please rate on scale of 1 poor, 2, 3, 4 & 5 excellent)	
How is the behavior of visted engineer	
What is the level of your satisfaction	
How is the explaination by Engineer	

	Details of Repair Work Done	✓
a	Simple Repair	
b	Part Replaced	
c	Part Repaired	
d	Gas Charging done	
e	Routine Service - Wet	
f	Routine Service - DRY	