AEON AIRCONDITIONING SOLUTIONS

Aeon House, Shop No 6/7, Behind N Cube China Town, Opp Shishu Dnyan Mandir
Dr Ambedkar Rd Thane 400 601 Maharashtra
Tel 022 - 25370101 / 7900097007
e-mail services@aeonacsolutions.com website www.aeonacsolutions.com

323

Project : ~~Adani~~ Link Bay Residencies Andheri West

Portsmouth Buildcon Pvt Ltd Additional Measurement Sheet

Sr. No	Location	AC Type	Tonnage	Indoor Unit Details		Outdoor Unit Details		Copper In Rmt	Cable In Rmt	Drain In Rmt	ODU Stand
				Model No.	Sr. No.	Model No.	Sr. No.				
1	Project Room	Hi Wall	1.5TR	FTKL60XV16VAA	8016862	RKL60XV16VAA	8022726	5	7	10	1
2	Ehs Department	Hi Wall	1.5TR	FTKL60XV16VAA	8016813	RKL60XV16VAA	8022788	8	10	6	
3	QA.Q.C Department	Hi Wall	1.5TR	FTKL60XV16VAA	8016732	RKL60XV16VAA	8022718	5	7	11	
4	Execution	Hi Wall	1.5TR	FTKL60XV16VAA	8016841	RKL60XV16VAA	8022679	6	9	8	
5	M.E.P	Hi Wall	1.5TR	FTKL60XV16VAA	8016844	RKL60XV16VAA	8022727	9	11	6	
6	Meeting Room	Hi Wall	1.5TR	FTKL60XV16VAA	8016722	RKL60XV16VAA	8022639	7	9	5	
7	Server Room	Hi Wall	1.5TR	FTKL60XV16VAA	8016860	RKL60XV16VAA	8022636	5	7	4	
8	Billing Room	Hi Wall	1.5TR	FTKL60XV16VAA	8016858	RKL60XV16VAA	8022525	8	10	7	

Extra Activity Carried Out

Civil Work	Stabilizer			Timer	Casing Capping	Cable Tray	Gas Charging	Dismentling		Re-installation
	3KVA	4KVA	5KVA					Hi Wall	Cassette	

Others

For		Vendor Details	
Sign		Signature	
Name	Vijay Gawli	Technician Name	Akram
Date	20/07/2026 Stamp	Date	20/7/26

DAIKIN

DAIKIN AIRCONDITIONING INDIA PVT. LTD.

Authorised Service Provider

AEON AIRCONDITIONING SOLUTIONS

AEON HOUSE, SHOP NO. 6 & 7, BEHIND N CUBE CHINA TOWN

DR. AMBEDKAR ROAD, THANE W 400601 MAHARASHTRA. PHONE :- 02225370101 / 7900097007 / 9322334106

aeon

PROJECT :- Adani - portsmouth Buildcon Pvt. Ltd — Linkbay Residences Amm Nagar Andheri(W)

Measurement Sheet

Sr. No.	Location	AC Type	Tonnage	Indoor Unit Details		Outdoor Unit Details		Copper in Rmt	Cable in Rmt	Drain in Rmt	ODU Stand
				Model No.	Sr. No.	Model No.	Sr. No.				
1	Reserve Room	Split	1.5TR	FTKL60XV16VAA	8016859	RKL60XV16VAA	8D22719	6	8	10	
2	HOD Sir	Split	1.5TR	FTKL60XV16VAA	8016861	RKL60XV16VAA	8D22794	4	6	8	
3	Jaiswal Sir	Split	1.5TR	FTKL60XV16VAA	8016056	RKL60XV16VAA	8D22583	8	10	10	
4	Main Cabin	Split	1.5TR					8	10	10	
5											
6											
7											
8											
9											
10											

EXTRA ACTIVITY CARRIED OUT

CIVIL WORK	Stabilizer			TIMER	CASING CAPPING	CABLE TRAY	GAS CHARGING	DISMENTALING		RE-INSTALLATION
	3KVA	4KVA	5KVA					Hi Wall	Cassette	
OTHERS										

For Customer Details :	Adani - portsmouth Buildcon Pvt. Ltd	Vendor Details :	Aeon Airconditiong Solutions
Sign :		Signature :	
Name :	Vijay Ghugl	Technician Name :	AKram
Date :	20.07.2026	Stamp :	Date : 20/07/26

DAIKIN

386 **DAIKIN AIRCONDITIONING INDIA PVT. LTD.**
Service Completion Certificate

AEON AIRCONDITIONING SOLUTIONS
Office No. 108 & 109, Devashree Garden, Commercial Complex,
R.W. Sawant Marg, above Sheetal Dairy, Ruby Park, Thane - 400 601
Mob : 9022394107 / 9022394109

Subject

Registration No.	Request Date	Service Engineer	Scheduled Date/Time	Service Order
		Akram	20/7/26	

User: Adani Portsmouth Buildcon Pvt Ltd.
Customer Address: Linkbay Residencing
Base Address: Andheri West

Daikin Invoice: Date:
Dealer Invoice: Date:

Type	Model No	Manufacturing No.
Outdoor unit /	RKL60XV16VAP	8022719
Indoor unit	FTKL60XV16VAP	8016859

Work Date	No. of S.E.	Work hours	Progress code	Details of the Repair Work
20/7/26				1.50 TR Daikin A/C Installation Done

Compressor manufacturing No.	Defective Compressor				Replacement Compressor		
Installed date	Warranty	AMC	Using with: Stabilizer	Using with: Cut off	Fault location	Phenomena code	Error code
	Yes / No	Yes / No	Yes / No	Yes / No			

Service Engineer Remarks: Cooling is fine
Name: Akram
Signature:

Customer Remarks:
Name: Vijay Ghugal
Signature:

Operation data (Ambient temp. °C)	Before repair	After repair
HP / T	psig/	psig/
SP / T °C	psig/°C	psig/°C
Current °C	Amps°C	Amps°C
Voltage	Volts	Volts
Indoor temperature		
Suction	°C	°C
Discharge	°C	°C
Outdoor temperature		
Suction	°C	°C
Discharge	°C	°C

Work No / Parts No	Qty	Billing Amount
Total		

Customer Impression about Service
(Please rate on scale of 1 poor, 2, 3, 4 & 5 excellent)

How is the behavior of visited engineer	
What is the level of your satisfaction	
How is the explanation by Engineer	

	Fault Diagnosed	✓
Power	Power Failure	
	Phase Reverse	
PCB	In door unit PCB Defective	
	Out door PCB Defective	
FM	In door unit Fan Motor Defective	
	Outdoor Fan Motor Defective	
Comp	Comp. taking High Current / Amp	
	Compressor Ground / Earth	
	Compressor Tripping due at High Temprature	
	Compressor tripping due to High Pressure	
Electrical	Indoor Unit MgSw Defective	
	Outdoor Unit Mgsw Defective	
	Indoor Unit Transformer Faulty	
	Out door Unit Transformer Faulty	
	Fault of swing Motor	
	Defect of Drain Pump	
	Expansion Valve Body / Motor Defective	
	Defective Temperature Sensor of Indoor Unit	
	Defective Temperature Sensor of Outdoor Unit	
	Defective Current Sensor in Out door Unit	
Unit	Gas Leakage at Indoor Unit	
	Gas Leakage at Outdoor Unit	
	Blower broken	
Installation	Short Cycling of Air at Indoor Unit	
	Short Cycling of Air at Outdoor Unit	
	Defect in Drain piping System	
	Gas Leakage from Flare nut	
	Error in Transmission wiring	
	Product under capacity	
	Rat bite case	
Other	Less cooling problem due to dirty Airfilter	
	Remote setting changed	
	Clogged Condenser	
	Other - Pl. specify	

	Details of Repair Work Done	✓
a	Simple Repair	
b	Part Replaced	
c	Part Repaired	
d	Gas Charging done	
e	Routine Service - Wet	
f	Routine Service - DRY	

DAIKIN

379

DAIKIN AIRCONDITIONING INDIA PVT. LTD.

Service Completion Certificate

Subject

AEON AIRCONDITIONING SOLUTIONS

Office No. 108 & 109, Dewashree Garden, Commercial Complex, R.W. Swami Marg, above Sheetal Dairy, Rutu Park, Thane - 400 601.
Mob: 9322334107 / 9322334109

Registration No.	Request Date	Service Engineer	Scheduled Date/Time	Service Order
		Akram	20-7-26	

User: Adani Portsmouth Mobile: Builder
Customer Address: Link bay Residencies Pvt Ltd.
Base Address: Andheri West

Daikin Invoice: Date:
Dealer Invoice: Date:

Type	Model No	Manufacturing No.
Outdoor unit /	RKL50XV16VAA	8022794
Indoor unit	FTKL50XV16VAA	8016861

Work Date	No. of S.E.	Work hours	Progress code	Details of the Repair Work
20/7/26				7.5 TR Daikin A/C Installation Done

Compressor manufacturing No.	Defective Compressor	Replacement Compressor

Installed date	Warranty	AMC	Using with Stabilizer	Using with Cut off	Fault location	Phenomena code	Error code
	Yes / No	Yes / No	Yes / No	Yes / No			

Service Engineer Remarks: Cooling is fine

Name: Akram Signature:

Customer Remarks:

Name: Vijay Ghugal Signature:

Operation data (Ambient temp. °C)	Before repair	After repair
HP / T	psig/	psig/
SP / T °C	psig/°C	psig/°C
Current °C	Amps°C	Amps°C
Voltage	Volts	Volts
Indoor temperature		
Suction	°C	°C
Discharge	°C	°C
Outdoor temperature		
Suction	°C	°C
Discharge	°C	°C

Work No / Parts No	Qty	Billing Amount
	Total	

Customer Impression about Service
(Please rate on scale of 1 poor, 2, 3, 4 & 5 excellent)

How is the behavior of visted engineer	
What is the level of your satisfaction	
How is the explaination by Engineer	

	Fault Diagnosed	✓
Power	Power Failure	
	Phase Reverse	
PCB	In door unit PCB Defective	
	Out door PCB Defective	
FM	In door unit Fan Motor Defective	
	Outdoor Fan Motor Defective	
Comp	Comp. taking High Current / Amp	
	Compressor Ground / Earth	
	Compressor Tripping due ot High Temprature	
	Compressor tripping due to High Pressure	
Electrical	Indoor Unit MgSw Defective	
	Outdoor Unit Mgsw Defective	
	Indoor Unit Transformer Faulty	
	Out door Unit Transformer Faulty	
	Fault of swing Motor	
	Defect of Drain Pump	
	Expansion Valve Body / Motor Defective	
	Defective Temperature Sensor of Indoor Unit	
	Defective Temperature Sensor of Outdoor Unit	
	Defective Current Sensor In Out door Unit	
Unit	Gas Leakage at Indoor Unit	
	Gas Leakage at Outdoor Unit	
	Blower broken	
Installation	Short Cycling of Air at Indoor Unit	
	Short Cycling of Air at Outdoor Unit	
	Defect in Drain piping System	
	Gas Leakage from Flare nut	
	Error in Transmission wiring	
	Product under capacity	
	Rat bite case	
Other	Less cooling problem due to dirty Airfilter	
	Remote setting changed	
	Clogged Condensar	
	Other - Pl. specify	

	Details of Repair Work Done	✓
a	Simple Repair	
b	Part Replaced	
c	Part Repaired	
d	Gas Charging done	
e	Routine Service - Wet	
f	Routine Service - DRY	

DAIKIN

380

DAIKIN AIRCONDITIONING INDIA PVT. LTD.

Service Completion Certificate

Subject

AEON AIRCONDITIONING SOLUTIONS

Office No. 108 & 109, Devashree Garden, Commercial Complex, R.W. Swami Marg, above Sheetal Dairy, Ruru Park, Thane - 400 601
Mob. 9322334107 / 9322334109

Registration No.	Request Date	Service Engineer	Scheduled Date/Time	Service Order
		Akram	20/7/26	

User: Adani Portsmouth Mobile: Buildcon Pvt Ltd.
Customer Address: Link Bay Residencies
Base Address: Andheri West

Daikin Invoice: Date:
Dealer Invoice: Date:

Type	Model No	Manufacturing No.
Outdoor unit	RKL60XV16VAP	8022583
Indoor unit	FTKL60XV16VAP	8016856

Work Date	No. of S.E.	Work hours	Progress code	Details of the Repair Work
20/7/26				5 TR Daikin A/c Installation Done

Compressor manufacturing No.	Defective Compressor				Replacement Compressor		
Installed date	Warranty	AMC	Using with Stabilizer	Using with Cut off	Fault location	Phenomena code	Error code
	Yes / No	Yes / No	Yes / No	Yes / No			

Service Engineer Remarks: Cooling is fine

Name: Akram Signature:

Customer Remarks:

Name: Vijay Ghugal Signature:

Operation data (Ambient temp. °C)	Before repair	After repair
HP / T	psig/	psig/
SP / T °C	psig/°C	psig/°C
Current °C	Amps°C	Amps°C
Voltage	Volts	Volts
Indoor temperature		
Suction	°C	°C
Discharge	°C	°C
Outdoor temperature		
Suction	°C	°C
Discharge	°C	°C

Work No / Parts No	Qty	Billing Amount
	Total	

Customer Impression about Service

(Please rate on scale of 1 poor, 2, 3, 4 & 5 excellent)

How is the behavior of visited engineer	
What is the level of your satisfaction	
How is the explanation by Engineer	

	Fault Diagnosed	✓
Power	Power Failure	
	Phase Reverse	
PCB	In door unit PCB Defective	
	Out door PCB Defective	
F/M	In door unit Fan Motor Defective	
	Outdoor Fan Motor Defective	
Comp	Comp. taking High Current / Amp	
	Compressor Ground / Earth	
	Compressor Tripping due of High Temprature	
	Compressor tripping due to High Pressure	
Electrical	Indoor Unit Mg/Sw Defective	
	Outdoor Unit Mg/sw Defective	
	Indoor Unit Transformer Faulty	
	Out door Unit Transformer Faulty	
	Fault of swing Motor	
	Defect of Drain Pump	
	Expansion Valve Body / Motor Defective	
	Defective Temperature Sensor of Indoor Unit	
	Defective Temperature Sensor of Outdoor Unit	
	Defective Current Sensor In Out door Unit	
Unit	Gas Leakage at Indoor Unit	
	Gas Leakage at Outdoor Unit	
	Blower broken	
Installation	Short Cycling of Air at Indoor Unit	
	Short Cycling of Air at Outdoor Unit	
	Defect in Drain piping System	
	Gas Leakage from Flare nut	
	Error in Transmission wiring	
	Product under capacity	
	Rat bite case	
Other	Less cooling problem due to dirty Airfilter	
	Remote setting changed	
	Clogged Condenser	
	Other - Pl. specify	

	Details of Repair Work Done	✓
a	Simple Repair	
b	Part Replaced	
c	Part Repaired	
d	Gas Charging done	
e	Routine Service - Wet	
f	Routine Service - DRY	

DAIKIN

381

DAIKIN AIRCONDITIONING INDIA PVT. LTD.

Service Completion Certificate

Subject :

AEON AIRCONDITIONING SOLUTIONS
Office No. 108 & 109, Devashree Garden, Commercial Complex,
R.W. Sawant Marg, above Shrestal Dairy, Rutu Park, Thane - 400 601
Mob. 9322394107 / 9322394109

Registration No.	Request Date	Service Engineer	Scheduled Date/Time	Service Order
		Akram	20/7/26	

User : ~~Adani~~ Portsmouth Mobile : Buildcon Pvt Ltd.

Customer Address : Link bay Residencies

Base Address : Andheri West

Daikin Invoice	Date :
Dealer Invoice	Date :

Type	Model No	Manufacturing No.
Outdoor unit /	RKL60XV16VAA	8022726
Indoor unit	FTKL60XV16VAA	8016862

Work Date	No. of S.E.	Work hours	Progress code	Details of the Repair Work
20/7/26				1.8 TR Daikin Atc Installation Done

Compressor manufacturing No.	Defective Compressor	Replacement Compressor

Installed date	Warranty	AMC	Using with Stabilizer	Using with Cut off	Fault location	Phenomena code	Error code
	Yes / No	Yes / No	Yes / No	Yes / No			

Service Engineer Remarks : Cooling is fine

Name : Akram Signature :

Customer Remarks :

Name : Vijay Ghuge Signature :

Operation data (Ambient temp. °C)	Before repair	After repair
HP / T	psig/	psig/
SP / T °C	psig/°C	psig/°C
Current °C	Amps°C	Amps°C
Voltage	Volts	Volts
Indoor temperature		
Suction	°C	°C
Discharge	°C	°C
Outdoor temperature		
Suction	°C	°C
Discharge	°C	°C

Work No / Parts No	Qty	Billing Amount
Total		

Customer Impression about Service

(Please rate on scale of 1 poor, 2, 3, 4 & 5 excellent)

How is the behavior of visited engineer	
What is the level of your satisfaction	
How is the explanation by Engineer	

Fault Diagnosed		✓
Power	Power Failure	
	Phase Reverse	
PCB	In door unit PCB Defective	
	Out door PCB Defective	
F.M.	In door unit Fan Motor Defective	
	Outdoor Fan Motor Defective	
Comp	Comp. taking High Current / Amp	
	Compressor Ground / Earth	
	Compressor Tripping due of High Temprature	
	Compressor tripping due to High Pressure	
Electrical	Indoor Unit MgSw Defective	
	Outdoor Unit Mgsw Defective	
	Indoor Unit Transformer Faulty	
	Out door Unit Transformer Faulty	
	Fault of swing Motor	
	Defect of Drain Pump	
	Expansion Valve Body / Motor Defective	
	Defective Temperature Sensor of Indoor unit	
	Defective Temperature Sensor of Outdoor Unit	
	Defective Current Sensor in Out door Unit	
Unit	Gas Leakage at Indoor Unit	
	Gas Leakage at Outdoor Unit	
	Blower broken	
Installation	Short Cycling of Air at Indoor Unit	
	Short Cycling of Air at Outdoor Unit	
	Defect in Drain piping System	
	Gas Leakage from Flare nut	
	Error in Transmission wiring	
	Product under capacity	
	Rat bite case	
Other	Less cooling problem due to dirty Airfilter	
	Remote setting changed	
	Clogged Condenser	
	Other - Pl. specify	

Details of Repair Work Done		✓
a	Simple Repair	
b	Part Replaced	
c	Part Repaired	
d	Gas Charging done	
e	Routine Service - Wet	
f	Routine Service - DRY	

DAIKIN

382 DAIKIN AIRCONDITIONING INDIA PVT. LTD.

Service Completion Certificate

Subject

AEON AIRCONDITIONING SOLUTIONS

Office No. 108 & 109, Devashree Garden, Commercial Complex, R.W. Sawant Marg, above Sheetal Dairy, Rutu Park, Thane - 400 601
Mob. 9322334107 / 9322334109

Registration No.	Request Date	Service Engineer	Scheduled Date/Time	Service Order
		Akram	20/7/26	

User
Customer Address: ~~Sdani~~ Portsmouth Mobile: Buildcon Pvt Ltd
Link bay Residencies
Base Address: Andheri West

Daikin Invoice	Date
Dealer Invoice	Date

Type	Model No.	Manufacturing No.
Outdoor unit /	RKL65XV16V44	8022788
Indoor unit	FTKL65XV16VAA	8016813

Work Date	No. of S.E.	Work hours	Progress code	Details of the Repair Work
20/7/26				7.5TR Daikin A/c Installation Done

Compressor manufacturing No.	Defective Compressor	Replacement Compressor

Installed date	Warranty	AMC	Using with Stabilizer	Using with Cut off	Fault location	Phenomena code	Error code
	Yes / No	Yes / No	Yes / No	Yes / No			

Service Engineer Remarks
Cooling is fine
Name: Akram
Signature

Customer Remarks
Name: Vijay Gogal
Signature

Operation data (Ambient temp. °C)	Before repair	After repair
HP / T	psig/	psig
SP / T °C	psig/°C	psig/°C
Current °C	Amps°C	Amps°C
Voltage	Volts	Volts
Indoor temperature		
Suction	°C	°C
Discharge	°C	°C
Outdoor temperature		
Suction	°C	°C
Discharge	°C	°C

Work No. / Parts No	Qty	Billing Amount
	Total	

Customer Impression about Service
(Please rate on scale of 1 poor, 2, 3, 4 & 5 excellent)

How is the behavior of visited engineer	
What is the level of your satisfaction	
How is the explanation by Engineer	

	Fault Diagnosed	✓
Power	Power Failure	
	Phase Reverse	
PCB	In door unit PCB Defective	
	Out door PCB Defective	
FM	In door unit Fan Motor Defective	
	Outdoor Fan Motor Defective	
Comp	Comp. taking High Current / Amp.	
	Compressor Ground / Earth	
	Compressor Tripping due to High Temperature	
	Compressor tripping due to High Pressure	
Electrical	Indoor Unit Mg/Sw Defective	
	Outdoor Unit Mg/sw Defective	
	Indoor Unit Transformer Faulty	
	Out door Unit Transformer Faulty	
	Fault of swing Motor	
	Defect of Drain Pump	
	Expansion Valve Body / Motor Defective	
	Defective Temperature Sensor of Indoor Unit	
	Defective Temperature Sensor of Outdoor Unit	
	Defective Current Sensor in Out door Unit	
Unit	Gas Leakage at Indoor Unit	
	Gas Leakage at Outdoor Unit	
	Blower broken	
Installation	Short Cycling of Air at Indoor Unit	
	Short Cycling of Air at Outdoor Unit	
	Defect in Drain piping System	
	Gas Leakage from Flare nut	
	Error in Transmission wiring	
	Product under capacity	
	Rat bite case	
Other	Less cooling problem due to dirty Air filter	
	Remote setting changed	
	Clogged Condenser	
	Other - Pl. specify	

	Details of Repair Work Done	✓
a	Simple Repair	
b	Part Replaced	
c	Part Repaired	
d	Gas Charging done	
e	Routine Service - Wet	
f	Routine Service - DRY	

DAIKIN

383

DAIKIN AIRCONDITIONING INDIA PVT. LTD.

Service Completion Certificate

Subject

AEON AIRCONDITIONING SOLUTIONS
Office No. 108 & 109, Dwarkadas Garden, Commercial Complex,
R.W. Swami Marg, above Sheetal Dairy, Rutu Park, Thane - 400 601
Mob : 9322334107 / 9322334109

Registration No.	Request Date	Service Engineer	Scheduled Date/Time	Service Order
		Akram	20/7/26	

User: Adani Portsmouth Buildcon Pvt Ltd

Customer Address: Linkway Residencies

Base Address: Andheri West

Daikin Invoice: Date:

Dealer Invoice: Date:

Type	Model No	Manufacturing No.
Outdoor unit :	RKL60XV16VAY	8022718
Indoor unit	FTXL60XV16VAA	8016732

Work Date	No. of S.E.	Work hours	Progress code	Details of the Repair Work
20/7/26				2.0 TR Daikin A/c Installation Done

Compressor manufacturing No.	Defective Compressor	Replacement Compressor

Installed date	Warranty	AMC	Using with Stabilizer	Using with Cut off	Fault location	Phenomena code	Error code
	Yes / No	Yes / No	Yes / No	Yes / No			

Service Engineer Remarks: Cooling is fine

Name: Akram Signature:

Customer Remarks:

Name: Vijay Ghadi Signature:

Operation data (Ambient temp. °C)

	Before repair	After repair
HP / T	psig/	psig/
SP / T °C	psig/°C	psig/°C
Current °C	Amps°C	Amps°C
Voltage	Volts	Volts
Indoor temperature		
Suction	°C	°C
Discharge	°C	°C
Outdoor temperature		
Suction	°C	°C
Discharge	°C	°C

Work No / Parts No	Qty	Billing Amount
	Total	

Customer Impression about Service

(Please rate on scale of 1 poor, 2, 3, 4 & 5 excellent)

How is the behavior of visited engineer	
What is the level of your satisfaction	
How is the explanation by Engineer	

	Fault Diagnosed	✓
Power	Power Failure	
	Phase Reverse	
PCB	In door unit PCB Defective	
	Out door PCB Defective	
FM	In door unit Fan Motor Defective	
	Outdoor Fan Motor Defective	
Comp	Comp. taking High Current / Amp	
	Compressor Ground / Earth	
	Compressor Tripping due ot High Temprature	
	Compressor tripping due to High Pressure	
Electrical	Indoor Unit MpSw Defective	
	Outdoor Unit Mpsw Defective	
	Indoor Unit Transformer Faulty	
	Out door Unit Transformer Faulty	
	Fault of swing Motor	
	Defect of Drain Pump	
	Expansion Valve Body / Motor Defective	
	Defective Temperature Sensor of Indoor Unit	
	Defective Temperature Sensor of Outdoor Unit	
	Defective Current Sensor in Out door Unit	
Unit	Gas Leakage at Indoor Unit	
	Gas Leakage at Outdoor Unit	
	Blower broken	
Installation	Short Cycling of Air at Indoor Unit	
	Short Cycling of Air at Outdoor Unit	
	Defect in Drain piping System	
	Gas Leakage from Flare nut	
	Error in Transmission wiring	
	Product under capacity	
	Rat bite case	
Other	Less cooling problem due to dirty Airfilter	
	Remote setting changed	
	Clogged Condenser	
	Other - Pl. specify	

	Details of Repair Work Done	✓
a	Simple Repair	
b	Part Replaced	
c	Part Repaired	
d	Gas Charging done	
e	Routine Service - Wet	
f	Routine Service - DRY	

DAIKIN

384 DAIKIN AIRCONDITIONING INDIA PVT. LTD.

Service Completion Certificate

AEON AIRCONDITIONING SOLUTIONS
Office No. 108 & 109, Devashree Garden, Commercial Complex,
R.W. Sawant Marg, above Sheetal Dairy, Ritu Park, Thane - 400 601
Mob. 9322334107 / 9322334109

Subject

Registration No.	Request Date	Service Engineer	Scheduled Date/Time	Service Order
		Ahiram	26/7/26	

User
Customer Address: Adani Portsmouth Buildcon Pvt Ltd, Linkbay Residencies
Base Address: Andheri West

Daikin Invoice: Date:
Dealer Invoice: Date:

Type	Model No	Manufacturing No.
Outdoor unit /	RKL60XV1KVAA	8022679
Indoor unit	FTKL60SV16VAA	8016841

Work Date	No. of S.E.	Work hours	Progress code	Details of the Repair Work
26/7/26				1.0 TR Daikin A/c Installation Done

Compressor manufacturing No.	Defective Compressor				Replacement Compressor		
Installed date	Warranty	AMC	Using with Stabilizer	Using with Cut off	Fault location	Phenomena code	Error code
	Yes / No	Yes / No	Yes / No	Yes / No			

Service Engineer Remarks: cooling is fine
Name: Ahiram
Signature:

Customer Remarks:
Name: Vijay Gharpure
Signature:

Operation data (Ambient temp. °C)	Before repair	After repair
HP / T	psig/	psig/
SP / T °C	psig/°C	psig/°C
Current °C	Amps°C	Amps°C
Voltage	Volts	Volts
Indoor temperature		
Suction	°C	°C
Discharge	°C	°C
Outdoor temperature		
Suction	°C	°C
Discharge	°C	°C

Work No / Parts No	Qty	Billing Amount
Total		

Customer Impression about Service
(Please rate on scale of 1 poor, 2, 3, 4 & 5 excellent)

How is the behavior of visted engineer	
What is the level of your satisfaction	
How is the explanation by Engineer	

	Fault Diagnosed	✓
Power	Power Failure	
	Phase Reverse	
PCB	In door unit PCB Defective	
	Out door PCB Defective	
FM	In door unit Fan Motor Defective	
	Outdoor Fan Motor Defective	
Comp	Comp. taking High Current / Amp	
	Compressor Ground / Earth	
	Compressor Tripping due ot High Temprature	
	Compressor tripping due to High Pressure	
Electrical	Indoor Unit MgSw Defective	
	Outdoor Unit Mgsw Defective	
	Indoor Unit Transformer Faulty	
	Out door Unit Transformer Faulty	
	Fault of swing Motor	
	Defect of Drain Pump	
	Expansion Valve Body / Motor Defective	
	Defective Temperature Sensor of Indoor Unit	
	Defective Temperature Sensor of Outdoor Unit	
	Defective Current Sensor in Out door Unit	
Unit	Gas Leakage at Indoor Unit	
	Gas Leakage at Outdoor Unit	
	Blower broken	
Installation	Short Cycling of Air at Indoor Unit	
	Short Cycling of Air at Outdoor Unit	
	Defect in Drain piping System	
	Gas Leakage from Flare nut	
	Error in Transmission wiring	
	Product under capacity	
	Rat bite case	
Other	Less cooling problem due to dirty Airfilter	
	Remote setting changed	
	Clogged Condenser	
	Other - Pl. specify	

	Details of Repair Work Done	✓
a	Simple Repair	
b	Part Replaced	
c	Part Repaired	
d	Gas Charging done	
e	Routine Service - Wet	
f	Routine Service - DRY	

DAIKIN

385 DAIKIN AIRCONDITIONING INDIA PVT. LTD.
Service Completion Certificate

AEON AIRCONDITIONING SOLUTIONS
Office No. 108 & 109, Devashree Garden, Commercial Complex,
R.W. Swami Marg, above Sheetal Dairy, Ruby Park, Thane - 400 601
Mob: 9322334107 / 9322334109

Subject

Registration No.	Request Date	Service Engineer	Scheduled Date/Time	Service Order
		Akram	20/7/26	

User: Adani Portsmouth Buildcon Pvt Ltd
Customer Address: Linkbay Residencies
/ Base Address: Andheri West

Daikin Invoice: Date:
Dealer Invoice: Date:

Type	Model No	Manufacturing No.
Outdoor unit /	RKL60XV16VAA	8022727
Indoor unit	FTKL60XV16VAA	8016844

Work Date	No. of S.E.	Work hours	Progress code	Details of the Repair Work
20/7/26				1.5TR Daikin A/c Installation Done

Compressor manufacturing No.	Defective Compressor	Replacement Compressor

Installed date	Warranty	AMC	Using with Stabilizer	Using with Cut off	Fault location	Phenomena code	Error code
	Yes / No	Yes / No	Yes / No	Yes / No			

Service Engineer Remarks: Cooling is fine
Name: Akram Signature:

Customer Remarks:
Name: Vijay Signature:

Operation data (Ambient temp. °C)	Before repair	After repair
HP / T	psig/	psig/
SP / T °C	psig/°C	psig/°C
Current °C	Amps°C	Amps°C
Voltage	Volts	Volts
Indoor temperature		
Suction	°C	°C
Discharge	°C	°C
Outdoor temperature		
Suction	°C	°C
Discharge	°C	°C

Work No / Parts No	Qty	Billing Amount
	Total	

Customer Impression about Service
(Please rate on scale of 1 poor, 2, 3, 4 & 5 excellent)

How is the behavior of visited engineer	
What is the level of your satisfaction	
How is the explanation by Engineer	

	Fault Diagnosed	✓
Power	Power Failure	
	Phase Reverse	
PCB	In door unit PCB Defective	
	Out door PCB Defective	
F.M	In door unit Fan Motor Defective	
	Outdoor Fan Motor Defective	
Comp	Comp. taking High Current / Amp	
	Compressor Ground / Earth	
	Compressor Tripping due ot High Temprature	
	Compressor tripping due to High Pressure	
Electrical	Indoor Unit Mg/Sw Defective	
	Outdoor Unit Mgsw Defective	
	Indoor Unit Transformer Faulty	
	Out door Unit Transformer Faulty	
	Fault of swing Motor	
	Defect of Drain Pump	
	Expansion Valve Body / Motor Defective	
	Defective Temperature Sensor of Indoor Unit	
	Defective Temperature Sensor of Outdoor Unit	
	Defective Current Sensor In Out door Unit	
Unit	Gas Leakage at Indoor Unit	
	Gas Leakage at Outdoor Unit	
	Blower broken	
Installation	Short Cycling of Air at Indoor Unit	
	Short Cycling of Air at Outdoor Unit	
	Defect in Drain piping System	
	Gas Leakage from Flare nut	
	Error in Transmission wiring	
	Product under capacity	
	Rat bite case	
Other	Less cooling problem due to dirty Airfilter	
	Remote setting changed	
	Clogged Condenser	
	Other - Pl. specify	

	Details of Repair Work Done	✓
a	Simple Repair	
b	Part Replaced	
c	Part Repaired	
d	Gas Charging done	
e	Routine Service - Wet	
f	Routine Service - DRY	

DAIKIN

387

DAIKIN AIRCONDITIONING INDIA PVT. LTD.

Service Completion Certificate

Subject

AEON AIRCONDITIONING SOLUTIONS

Office No. 108 & 109, Devashree Garden, Commercial Complex, R.W. Sawant Marg, above Sheetal Dairy, Rutu Park, Thane - 400 601. Mob. 9322394107 / 9322394109

Registration No	Request Date	Service Engineer	Scheduled Date/Time	Service Order
		Ahran	20/7/26	

User

Customer Address: Adani Portsma Builders Pvt Ltd Linkway Residencies

Base Address: Andheri West

Daikin Invoice: Date:

Dealer Invoice: Date:

Type	Model No	Manufacturing No.
Outdoor unit /	RKL60KVIGVAA	8022633
Indoor unit	FTKL60XV16VAA	8016722

Work Date	No. of S.E.	Work hours	Progress code	Details of the Repair Work
20/7/26				1.0 TR Daikin A/c Installation Done

Compressor manufacturing No.	Defective Compressor	Replacement Compressor

Installed date	Warranty	AMC	Using with Stabilizer	Using with Cut off	Fault location	Phenomena code	Error code
	Yes / No	Yes / No	Yes / No	Yes / No			

Service Engineer Remarks: cooling is fine

Name: Ahran Signature:

Customer Remarks:

Name: Vijay Gharpl Signature: 20/7/26

Operation data (Ambient temp. °C)	Before repair	After repair
HP / T	psig/	psig/
SP / T °C	psig/°C	psig/°C
Current °C	Amps°C	Amps°C
Voltage	Volts	Volts
Indoor temperature		
Suction	°C	°C
Discharge	°C	°C
Outdoor temperature		
Suction	°C	°C
Discharge	°C	°C

Work No / Parts No	Qty	Billing Amount
	Total	

Customer Impression about Service (Please rate on scale of 1 poor, 2, 3, 4 & 5 excellent)	
How is the behavior of visited engineer	
What is the level of your satisfaction	
How is the explanation by Engineer	

	Fault Diagnosed	✓
Power	Power Failure	
	Phase Reverse	
PCB	In door unit PCB Defective	
	Out door PCB Defective	
Fan	In door unit Fan Motor Defective	
	Outdoor Fan Motor Defective	
Comp	Comp. taking High Current / Amp	
	Compressor Ground / Earth	
	Compressor Tripping due ot High Temprature	
	Compressor tripping due to High Pressure	
Electrical	Indoor Unit MgSw Defective	
	Outdoor Unit Mgsw Defective	
	Indoor Unit Trasnformer Faulty	
	Out door Unit Transformer Faulty	
	Fault of swing Motor	
	Defect of Drain Pump	
	Expansion Valve Body / Motor Defective	
	Defective Temperature Sensor of Indoor Unit	
	Defective Temperature Sensor of Outdoor Unit	
	Defective Current Sensor in Out door Unit	
Unit	Gas Leakage at Indoor Unit	
	Gas Leakage at Outdoor Unit	
	Blower broken	
Installation	Short Cycling of Air at Indoor Unit	
	Short Cycling of Air at Outdoor Unit	
	Defect in Drain piping System	
	Gas Leakage from Flare nut	
	Error in Transmission wiring	
	Product under capacity	
	Rat bite case	
Other	Less cooling problem due to dirty Air filter	
	Remote setting changed	
	Clogged Condenser	
	Other - Pl. specify	

	Details of Repair Work Done	✓
a	Simple Repair	
b	Part Replaced	
c	Part Repaired	
d	Gas Charging done	
e	Routine Service - Wet	
f	Routine Service - DRY	

DAIKIN

388

DAIKIN AIRCONDITIONING INDIA PVT. LTD.

Service Completion Certificate

Subject

AEON AIRCONDITIONING SOLUTIONS

Office No. 108 & 109, Devashree Garden, Commercial Complex,
R.W. Sawant Marg, above Sheetal Dairy, Rutu Park, Thane - 400 601
Mob: 9022334107 / 9022334109

Registration No.	Request Date	Service Engineer	Scheduled Date/Time	Service Order
		Akram	20/7/26	

User

Customer Address: ~~Adani Portsmouth Buildcon~~ Pvt Ltd
Linkbay Residencies

Base Address: Andheri West

Daikin Invoice	Date
Dealer Invoice	Date

Type	Model No.	Manufacturing No.
Outdoor unit / Indoor unit	RKL60XV16VAA	8022636
	FTKL60XV16VAA	8016860

Work Date	No. of S.E.	Work hours	Progress code	Details of the Repair Work
20/7/26				1.5 TR Daikin AC Installation Done

Compressor manufacturing No.	Defective Compressor				Replacement Compressor		
Installed date	Warranty	AMC	Using with Stabilizer	Using with Cut off	Fault location	Phenomena code	Error code
	Yes / No	Yes / No	Yes / No	Yes / No			

Service Engineer Remarks: Cooling is fine

Name: Akram

Signature

Customer Remarks

Name: Vijay Chavan

Signature

Operation data (Ambient temp. °C)	Before repair	After repair
HP / T	psig/	psig/
SP / T °C	psig/°C	psig/°C
Current °C	Amps°C	Amps°C
Voltage	Volts	Volts
Indoor temperature		
Suction	°C	°C
Discharge	°C	°C
Outdoor temperature		
Suction	°C	°C
Discharge	°C	°C

Work No / Parts No	Qty	Billing Amount
	Total	

Customer Impression about Service

(Please rate on scale of 1 poor, 2, 3, 4 & 5 excellent)

How is the behavior of visited engineer	
What is the level of your satisfaction	
How is the explanation by Engineer	

	Fault Diagnosed	✓
Power	Power Failure	
	Phase Reverse	
PCB	In door unit PCB Defective	
	Out door PCB Defective	
FM	In door unit Fan Motor Defective	
	Outdoor Fan Motor Defective	
Comp	Comp. taking High Current / Amp	
	Compressor Ground / Earth	
	Compressor Tripping due ot High Temprature	
	Compressor tripping due to High Pressure	
Electrical	Indoor Unit MgSw Defective	
	Outdoor Unit Mgsw Defective	
	Indoor Unit Transformer Faulty	
	Out door Unit Transformer Faulty	
	Fault of swing Motor	
	Defect of Drain Pump	
	Expansion Valve Body / Motor Defective	
	Defective Temperature Sensor of Indoor Unit	
	Defective Temperature Sensor of Outdoor Unit	
	Defective Current Sensor in Out door Unit	
Unit	Gas Leakage at Indoor Unit	
	Gas Leakage at Outdoor Unit	
	Blower broken	
Installation	Short Cycling of Air at Indoor Unit	
	Short Cycling of Air at Outdoor Unit	
	Defect in Drain piping System	
	Gas Leakage from Flare nut	
	Error in Transmission wiring	
	Product under capacity	
	Rat bite case	
Other	Less cooling problem due to dirty Airfilter	
	Remote setting changed	
	Clogged Condenser	
	Other - Pl. specify	

	Details of Repair Work Done	✓
a	Simple Repair	
b	Part Replaced	
c	Part Repaired	
d	Gas Charging done	
e	Housing Service - Wet	
f	Housing Service - DRY	

DAIKIN

378

DAIKIN AIRCONDITIONING INDIA PVT. LTD.

Service Completion Certificate

Subject

AEON AIRCONDITIONING SOLUTIONS
Office No. 108 & 109, Dineshmani Center, Commercial Complex,
R.W. Sawant Marg, above Sheetal Dairy, Pokhu Park, Thane - 400 601
Mob. 9322394107 / 9322394109

Registration No.	Request Date	Service Engineer	Scheduled Date/Time	Service Order
		Akram	20/7/26	

User
Customer Address: ~~Adani~~ Portsmouth Mobile Buildcon Pvt. Ltd. Linkbay Residencies
Base Address: Andheri West

Daikin Invoice: Date:
Dealer Invoice: Date:

Type	Model No.	Manufacturing No.
Outdoor unit :	FXKL50XV1BVAA	8018525
Indoor unit:	FTKL50XV1BVAA	8016858

Work Date	No. of S.E.	Work hours	Progress code	Details of the Repair Work
20/7/26				~~2~~ 1.5 TR Daikin A/c Installation Done

Compressor manufacturing No.	Defective Compressor				Replacement Compressor		
Installed date	Warranty	AMC	Using with Stabilizer	Using with Cut off	Fault location	Phenomena code	Error code
	Yes / No	Yes / No	Yes / No	Yes / No			

Service Engineer Remarks: cooling is fine

Name: Akram Signature:

Customer Remarks:

Name: Vijay Ghuge Signature:

Daikin Customer Care : Missed Call or SMS <DAIKIN> to 92101 88999 , Toll Free Number : 1860 180 3900 / 1800 102 9300 , cs@daikinindia.com / www.daikinindia.com

Operation data (Ambient temp °C)	Before repair	After repair
HP / T	psig/	psig/
SP / T °C	psig/°C	psig/°C
Current °C	Amps/°C	Amps/°C
Voltage	Volts	Volts
Indoor temperature		
Suction	°C	°C
Discharge	°C	°C
Outdoor temperature		
Suction	°C	°C
Discharge	°C	°C

Work No / Parts No	Qty	Billing Amount
Total		

Customer Impression about Service

(Please rate on scale of 1 poor, 2, 3, 4 & 5 excellent)

How is the behavior of visited engineer	
What is the level of your satisfaction	
How is the explanation by Engineer	

	Fault Diagnosed	✓
Power	Power Failure	
	Phase Reverse	
PCB	In door unit PCB Defective	
	Out door PCB Defective	
FM	In door unit Fan Motor Defective	
	Outdoor Fan Motor Defective	
Comp	Comp. taking High Current / Amp	
	Compressor Ground / Earth	
	Compressor Tripping due ot High Temprature	
	Compressor tripping due to High Pressure	
Electrical	Indoor Unit MotSw Defective	
	Outdoor Unit Mtsw Defective	
	Indoor Unit Transformer Faulty	
	Out door Unit Transformer Faulty	
	Fault of swing Motor	
	Defect of Drain Pump	
	Expansion Valve Body / Motor Defective	
	Defective Temperature Sensor of Indoor Unit	
	Defective Temperature Sensor of Outdoor Unit	
	Defective Current Sensor in Out door Unit	
Unit	Gas Leakage at Indoor Unit	
	Gas Leakage at Outdoor Unit	
	Blower broken	
Installation	Short Cycling of Air at Indoor Unit	
	Short Cycling of Air at Outdoor Unit	
	Defect in Drain piping System	
	Gas Leakage from Flare nut	
	Error in Trasmission wiring	
	Product under capacity	
	Rat bite case	
Other	Less cooling problem due to dirty Airfilter	
	Remote setting changed	
	Clogged Condenser	
	Other - PL specify	

	Details of Repair Work Done	✓
a	Simple Repair	
b	Part Replaced	
c	Part Repaired	
d	Gas Charging done	
e	Routine Service - Wet	
f	Routine Service - DRY	