DAIKIN AIRCONDITIONING INDIA PVT. LTD.

Service Completion Certificate
C-403, Corporate Avenue Andheri Ghatkopar Link Rd, Andheri (E), Mumbai-400093.

AEON AIRCONDITIONING SOLUTIONS
Office No. 108 & 109, Devashree Garden Commercial Complex,
R. W. Sawant Marg, Above Sheetal Dairy, Rutu Park, Thane-400 601.
Mob.: 9326311501 / 9322334106

Subject : INSTALLATION

Sr.No.

Registration No.	Request Date	Service Engineer's Name	Scheduled Date	Time	Notification No.
		KHAN GUFRAN			

User Name :

Address : 5th Floor, Tech. wadi Center New Link Road Oshiwara

Mobile No.: Tel. No.:

Daikin Invoice No.: Date :

Dealer Invoice No.: Date :

Type	Model No.	Manufacturing No.
Outdoor Unit	RKL60XV16VAA	8025056
Indoor unit	FTKL60XV16VAA	8016669

Work Date	No. of S.E.	Work Hours	Progress Code	Details of the Repair Work
25 of 2026				Installation done AC working & cooling fine.

Compressor Manufacturing No.	Defective Compressor	Replacement Compressor

Installed Date	Warranty	AMC	Using with Stabilizer	Using with Cut off	Fault Location	Phenomen Code	Error Code
	Yes / No	Yes / No	Yes / No	Yes / No			

Service Engineer Remarks

Name GUFRAN + SAMEER. Signature

Customer Remarks

Name ANIS PATHAN Signature

Operation data (Ambient temp. °C)

	Before Repair	After Repair
HP / T °C	pslg/°C	pslg/°C
SP / T °C	pslg/°C	pslg/°C
Current	Amps	Amps
Voltage	Volts	Volts
Indoor Temperature		
Suction	°C	°C
Discharge	°C	°C
Outdoor Temperature		
Suction	°C	°C
Discharge	°C	°C

Work No / Parts No	Qty	Billing Amount
Total		

Customer Impression about Service

(Please rate on scale of 1 poor, 2, 3, 4 & 5 excellent)

How is the behavior of visited engineer	
What is the level of your satisfaction	
How is the explanation by Engineer	

Service Order No.

	Fault Diagnosed	✓
Power	Power Failure	
	Phase Reverse	
PCB	In door unit PCB Defective	
	Out door PCB Defective	
F/M	In door unit Fan Motor Defective	
	Outdoor Fan Motor Defective	
Comp	Comp. taking Hight Current / Amp	
	Compressor Ground / Earth	
	Compressor Tripping due to High Temprature	
	Compressor Tripping due to Hight Pressure	
Electrical	Indoor Unit MgSw Defective	
	Outdoor Unit MgSw Defective	
	Indoor Unit Transformer Faulty	
	Outdoor Unit Transformer Faulty	
	Fault of Swing Motor	
	Defect of Drain Pump	
	Expansion Valve Body / Motor Defective	
	Defective Temperature Sensor of Indoor Unit	
	Defective Temperature Sensor of Outdoor Unit	
	Defective Current Sensor in Out door Unit	
Unit	Gas Leakage at Indoor Unit	
	Gas Leakage at Outdoor Unit	
	Blower Broken	
Installation	Short Cycling of Air at Indoor Unit	
	Short Cycling of Air at Outdoor Unit	
	Defect in Drain Piping System	
	Gas Leakage from Flare nut	
	Error In Transmission wiring	
	Product under capacity	
	Rate bite case	
Other	Less cooling problem due to dirty Airfilter	
	Remote setting changed	
	Clogged condenser	
	Other - Pl. Specify	

	Details of Repair Work Done	✓
a	Simple Repair	
b	Part Replaced	
c	Part Replaced	
d	Gas Charging Done	
e	Routing Service - Wet	
f	Routing Service - Dry	

"We recommend, to take routine maintenance services of your Daikin machine at regular intervals, for its good health"

Daikin Customer Care : Missed Call or SMS <DAIKIN> to 92101 88999 ; Toll Free Number : 1860 180 3900 / 1800 102 9300 ; cs@daikinindia.com / www.daikinindia.com