DAIKIN

DAIKIN AIRCONDITIONING INDIA PVT. LTD.

Authorised Service Center

AEON AIRCONDITIONING SOLUTIONS

AEON HOUSE, SHOP NO. 6/7, BEHIND N CUBE CHINA TOWN

DR. AMBEDKAR ROAD, THANE W 400601 MAHARASHTRA. PHONE :- 02225370101 / 7900097007

aeon

PROJECT :- The Cliff Garden (The Chatterjee Group Real Estate) Society office & Club house - The Cliff Garden, MIDC Maan Hinjewadi , phase 3, Pune 411057.

Measurement Sheet

Sr. No.	Location	AC Type	Tonnage	Indoor Unit Details		Outdoor Unit Details		Copper In Rmt	Cable In Rmt	Drain In Rmt	ODU Stand
				Model No.	Sr. No.	Model No.	Sr. No.				
1	Office Premises	Split	1.5	FTKC50UV16VF	8093081	RKC50UV16VF	8085583	3	4	6.3	L Type
2	GYM Open Area	Split	2.2	FTKL71UV16M	0025173	RKL71UV16M	0025219	3	3.6	5	Jumbo
3	GYM Open Area	Split	2.2	TKL71UV16M	0025176	RKL71UV16M	0025227	0	0	4	Jumbo
4	MH Open Area	Split	2.2	TKL71UV16M	0025143	RKL71UV16M	0025226	0	0	4	Jumbo
5	AH Open Area	Split	2.2	TKL71UV16M	0025170	RKL71UV16M	0025228	0	0	4	Jumbo
6											
7											
8											

EXTRA ACTIVITY CARRIED OUT

CIVIL WORK	Stabilizer			TIMER	CASING CAPPING	CABLE TRAY	GAS CHARGING	DISMENTALING		RE-INSTALLATION
	3KVA	4KVA	5KVA					Hi Wall	Cassette	
–	–	–	–		–	–	–	–	–	–

OTHERS	Main Power Supply cable used 23.6 RMT

For Customer Details :			Vendor Details :	AEON AIRCONDITIONING SOLUTIONS
Sign :			Signature :	
Name :			Technician Name :	Tanveer Shaikh
Date :		Stamp :	Date :	17.07.2025

3 Pin TOP – 5 NOS.
Rubber Pad – 5 NOS.
Wrapping tape – 5 NOS.
Drain insulation – 4 NOS.

Tanveer Shaikh
21/07/25
9765374941

DAIKIN

DAIKIN AIRCONDITIONING INDIA PVT. LTD.

Service Completion Certificate

AEON AIRCONDITIONING SOLUTIONS
Shop No. 6 & 7, Aeon House, Dr. Ambedkar Rd., Thane (W)
Phone : +91 (9322334107) 9322334109

Subject : The Chatterjee Group - Society Office & Club House

Registration No.	Request Date	Service Engineer	Scheduled Date/Time	Service Order
		Tanveer Shaikh	16/07/2025	

User : The Chatterjee Group Mobile :
Customer Address : Society Office & Club House, The Cliff Garden, MIDC Maan Hinjewadi
Base Address : Phase 3, Pune 411057

Daikin Invoice : Date :
Dealer Invoice : Date :

Type	Model No	Manufacturing No.
Outdoor unit /	RKL71UV16M	0025226
Indoor unit	FTKL71UV16M	0025143

Work Date	No. of S.F.	Work hours	Progress code	Details of the Repair Work
16/07/25				

Compressor manufacturing No.	Defective Compressor	Replacement Compressor

Installed date	Warranty	AMC	Using with Stabilizer	Using with Out off	Fault location	Phenomena code	Error code
	Yes / No	Yes / No	Yes / No	Yes / No			

Service Engineer Remarks
Daikin AC Installation done.
Now AC working & cooling ok.

Name Tanveer Shaikh Signature

Customer Remarks

Name Signature

Operation data (Ambient temp. °C)	Before repair	After repair
HP / T	psig/	psig/
SP / T °C	psig/°C	psig/°C
Current °C	Amps°C	Amps°C
Voltage	Volts	Volts
Indoor temperature		
Suction	°C	°C
Discharge	°C	°C
Outdoor temperature		
Suction	°C	°C
Discharge	°C	°C

Work No / Parts No	Qty	Billing Amount
Total		

Customer Impression about Service
(Please rate on scale of 1 poor, 2, 3, 4 & 5 excellent)

How is the behavior of visited engineer	
What is the level of your satisfaction	
How is the explaination by Engineer	

	Fault Diagnosed	✓
Power	Power Failure	
	Phase Reverse	
PCB	In door unit PCB Defective	
	Out door PCB Defective	
FM	In door unit Fan Motor Defective	
	Outdoor Fan Motor Defective	
Comp	Comp. taking High Current / Amp	
	Compressor Ground / Earth	
	Compressor Tripping due ot High Temprature	
	Compressor tripping due to High Pressure	
Electrical	Indoor Unit MgSw Defective	
	Outdoor Unit Mgsw Defective	
	Indoor Unit Transformer Faulty	
	Out door Unit Transformer Faulty	
	Fault of swing Motor	
	Defect of Drain Pump	
	Expansion Valve Body / Motor Defective	
	Defective Temperature Sensor at Indoor Unit	
	Defective Temperature Sensor of Outdoor Unit	
	Delective Current Sensor in Out door Unit	
Unit	Gas Leakage at Indoor Unit	
	Gas Leakage at Outdoor Unit	
	Blower broken	
Installation	Short Cycling of Air at Indoor Unit	
	Short Cycling of Air at Outdoor Unit	
	Defect in Drain piping System	
	Gas Leakage from Flare nut	
	Error in Transmission wiring	
	Product under capacity	
	Rat bite case	
Other	Less cooling problem due to dirty Airfilter	
	Remote setting changed	
	Clogged Condenser	
	Other - Pl. specify	

	Details of Repair Work Done	✓
a	Simple Repair	
b	Part Replaced	
c	Part Repaired	
d	Gas Charging done	
e	Routine Service - Wet	
f	Routine Service - DRY	

DAIKIN

DAIKIN AIRCONDITIONING INDIA PVT. LTD.

Service Completion Certificate

AEON AIRCONDITIONING SOLUTIONS
Shop No. 6 & 7, Aeon House, Dr. Ambedkar Rd., Thane (W)
Phone : +91 (9322334107) 9322334109

Subject : The Chatterjee Group - Society Office & Club House

Registration No.	Request Date	Service Engineer	Scheduled Date/Time	Service Order
		Tanveer Shaikh	16/07/2025	

User : The Chatterjee Group Mobile :
Customer Address : Society Office & Club House, The Cliff Garden, MIDC Maan Hinjewadi
I Base Address : Phase 3, Pune 411057.

Daikin Invoice : Date :
Dealer Invoice : Date :

Type	Model No	Manufacturing No.
Outdoor unit /	RKL71UV16M	0025228
Indoor unit	FTKL71UV16M	0025170

Work Date	No. of S.E.	Work hours	Progress code	Details of the Repair Work
16/07/25				

Compressor manufacturing No.	Defective Compressor	Replacement Compressor

Installed date	Warranty	AMC	Using with Stabilizer	Using with Cut off	Fault location	Phenomena code	Error code
	Yes / No	Yes / No	Yes / No	Yes / No			

Service Engineer Remarks
Daikin AC Installation done.
Now AC working & cooling ok.

Name Tanveer Shaikh Signature

Customer Remarks

Name Signature

Operation data (Ambient temp. °C)	Before repair	After repair
HP / T	psig/	psig/
SP / T °C	psig/°C	psig/°C
Current °C	Amps°C	Amps°C
Voltage	Volts	Volts
Indoor temperature		
Suction	°C	°C
Discharge	°C	°C
Outdoor temperature		
Suction	°C	°C
Discharge	°C	°C

Work No / Parts No	Qty	Billing Amount
Total		

Fault Diagnosed		✓
Power	Power Failure	
	Phase Reverse	
PCB	In door unit PCB Defective	
	Out door PCB Defective	
FM	In door unit Fan Motor Defective	
	Outdoor Fan Motor Defective	
Comp	Comp. taking High Current / Amp	
	Compressor Ground / Earth	
	Compressor Tripping due ot High Temprature	
	Compressor tripping due to High Pressure	
Electrical	Indoor Unit MgSw Defective	
	Outdoor Unit Mgsw Defective	
	Indoor Unit Transformer Faulty	
	Out door Unit Transformer Faulty	
	Fault of swing Motor	
	Defect of Drain Pump	
	Expansion Valve Body / Motor Defective	
	Defective Temperature Sensor of Indoor Unit	
	Defective Temperature Sensor of Outdoor Unit	
	Defective Current Sensor in Out door Unit	
Unit	Gas Leakage at Indoor Unit	
	Gas Leakage at Outdoor Unit	
	Blower broken	
Installation	Short Cycling of Air at Indoor Unit	
	Short Cycling of Air at Outdoor Unit	
	Defect in Drain piping System	
	Gas Leakage from Flare nut	
	Error in Transmission wiring	
	Product under capacity	
	Rat bite case	
Other	Less cooling problem due to dirty Airfilter	
	Remote setting changed	
	Clogged Condenser	
	Other - Pl. specify	

Customer Impression about Service (Please rate on scale of 1 poor, 2, 3, 4 & 5 excellent)	
How is the behavior of visted engineer	
What is the level of your satisfaction	
How is the explaination by Engineer	

Details of Repair Work Done		✓
a	Simple Repair	
b	Part Replaced	
c	Part Repaired	
d	Gas Charging done	
e	Routine Service - Wet	
f	Routine Service - DRY	

DAIKIN

DAIKIN AIRCONDITIONING INDIA PVT. LTD.

Service Completion Certificate

AEON AIRCONDITIONING SOLUTIONS

Shop No. 6 & 7, Aeon House, Dr. Ambedkar Rd., Thane (W)
Phone : +91 (9322334107) 9322334109

Subject : The Chatterjee Group - Society Office & Club House

Registration No.	Request Date	Service Engineer	Scheduled Date/Time	Service Order
		Tanveer Shaikh	17/07/2025	

User : The Chatterjee Group Mobile :
Customer Address : Society Office & Club House, The Cliff Garden, MIDC Maan Hinjewadi
I Base Address : Phase 3, Pune 411057

Daikin Invoice : Date :
Dealer Invoice : Date :

Type	Model No	Manufacturing No.
Outdoor unit /	RKL71UV16M	0025219
Indoor unit	FTKL71UV16M	0025173

Work Date	No. of S.E.	Work hours	Progress code	Details of the Repair Work
17/07/25				

Compressor manufacturing No.	Defective Compressor				Replacement Compressor		
Installed date	Warranty	AMC	Using with Stabilizer	Using with Cut off	Fault location	Phenomena code	Error code
	Yes / No	Yes / No	Yes / No	Yes / No			

Service Engineer Remarks
Daikin AC Installation done.
Now Ac working & cooling ok.

Name Tanveer Shaikh. Signature

Customer Remarks

Name Signature

Operation data (Ambient temp. °C)	Before repair	After repair
HP / T	psig/	psig/
SP / T °C	psig/°C	psig/°C
Current °C	Amps°C	Amps°C
Voltage	Volts	Volts
Indoor temperature		
Suction	°C	°C
Discharge	°C	°C
Outdoor temperature		
Suction	°C	°C
Discharge	°C	°C

Work No / Parts No	Qty	Billing Amount
Total		

Customer Impression about Service
(Please rate on scale of 1 poor, 2, 3, 4 & 5 excellent)

How is the behavior of visited engineer	
What is the level of your satisfaction	
How is the explaination by Engineer	

	Fault Diagnosed	✓
Power	Power Failure	
	Phase Reverse	
PCB	In door unit PCB Defective	
	Out door PCB Defective	
EM	In door unit Fan Motor Defective	
	Outdoor Fan Motor Defective	
Comp	Comp. taking High Current / Amp	
	Compressor Ground / Earth	
	Compressor Tripping due ot High Temprature	
	Compressor tripping due to High Pressure	
Electrical	Indoor Unit Mg/Sw Defective	
	Outdoor Unit Mgsw Defective	
	Indoor Unit Transformer Faulty	
	Out door Unit Transformer Faulty	
	Fault of swing Motor	
	Defect of Drain Pump	
	Expansion Valve Body / Motor Defective	
	Defective Temperature Sensor of Indoor Unit	
	Defective Temperature Sensor of Outdoor Unit	
	Defective Current Sensor In Out door Unit	
Unit	Gas Leakage at Indoor Unit	
	Gas Leakage at Outdoor Unit	
	Blower broken	
Installation	Short Cycling of Air at Indoor Unit	
	Short Cycling of Air at Outdoor Unit	
	Defect in Drain piping System	
	Gas Leakage from Flare nut	
	Error In Transmission wiring	
	Product under capacity	
	Rat bite case	
Other	Less cooling problem due to dirty Airfilter	
	Remote setting changed	
	Clogged Condenser	
	Other - Pl. specify	

	Details of Repair Work Done	✓
a	Simple Repair	
b	Part Replaced	
c	Part Repaired	
d	Gas Charging done	
e	Routine Service - Wet	
f	Routine Service - DRY	

DAIKIN

DAIKIN AIRCONDITIONING INDIA PVT. LTD.

Service Completion Certificate

AEON AIRCONDITIONING SOLUTIONS
Shop No. 6 & 7, Aeon House, Dr. Ambedkar Rd., Thane (W)
Phone : +91 (9322334107) 9322334109

Subject : The Chatterjee Group - Society Office & Club House

Registration No.	Request Date	Service Engineer	Scheduled Date/Time	Service Order
		Tanveer Shaikh	17/07/2025	

User : The Chatterjee Group Mobile :

Customer Address : Society Office & Club House The Cliff Garden, MIDC Maan Hinjewadi,

Base Address : Phase 3, Pune 411057

Daikin Invoice : Date :

Dealer Invoice : Date :

Type	Model No	Manufacturing No.
Outdoor unit /	RKL71UV16M	0025227
Indoor unit	FTKL71UV16M	0025176

Work Date	No. of S.E.	Work hours	Progress code	Details of the Repair Work
17/07/25				

Compressor manufacturing No.	Defective Compressor	Replacement Compressor

Installed date	Warranty	AMC	Using with Stabilizer	Using with Cut off	Fault location	Phenomena code	Error code
	Yes / No	Yes / No	Yes / No	Yes / No			

Service Engineer Remarks

Daikin AC Installation done.
Now AC working & cooling ok.

Name Tanveer Shaikh. Signature

Customer Remarks

Name Signature

Operation data (Ambient temp. °C)	Before repair	After repair
HP / T	psig/	psig/
SP / T °C	psig/°C	psig/°C
Current °C	Amps°C	Amps°C
Voltage	Volts	Volts
Indoor temperature		
Suction	°C	°C
Discharge	°C	°C
Outdoor temperature		
Suction	°C	°C
Discharge	°C	°C

Work No / Parts No	Qty	Billing Amount

DAIKIN

DAIKIN AIRCONDITIONING INDIA PVT. LTD.

Service Completion Certificate

AEON AIRCONDITIONING SOLUTIONS

Shop No. 6 & 7, Aeon House, Dr. Ambedkar Rd., Thane (W)
Phone : +91 (9322334107) 9322334109

Subject : The Chatterjee Group - Society Office & Club House.

Registration No.	Request Date	Service Engineer	Scheduled Date/Time	Service Order
		Tanveer Shaikh	17/07/2025	

User : The Chatterjee Group Mobile :

Customer Address : Society Office & Club House, The Cliff Garden, MIDC Maan Hinjewadi,

Base Address : Phase 3, Pune 411057.

Daikin Invoice : Date :

Dealer Invoice : Date :

Type	Model No	Manufacturing No.
Outdoor unit /	RKC50UV16VF	8085583
Indoor unit	FTKC50UV16VF	8093081

Work Date	No. of S.E.	Work hours	Progress code	Details of the Repair Work
17/07/25				

Compressor manufacturing No.	Defective Compressor	Replacement Compressor

Installed date	Warranty	AMC	Using with Stabilizer	Using with Cut off	Fault location	Phenomena code	Error code
	Yes / No	Yes / No	Yes / No	Yes / No			

Service Engineer Remarks

Daikin AC Installation done.
Now AC working & cooling ok.

Name Tanveer Shaikh Signature

Customer Remarks

Name Signature

Operation data (Ambient temp. °C)	Before repair	After repair
HP / T	psig/	psig/
SP / T °C	psig/°C	psig/°C
Current °C	Amps°C	Amps°C
Voltage	Volts	Volts
Indoor temperature		
Suction	°C	°C
Discharge	°C	°C
Outdoor temperature		
Suction	°C	°C
Discharge	°C	°C

Work No / Parts No	Qty	Billing Amount
	Total	

Customer Impression about Service

(Please rate on scale of 1 poor, 2, 3, 4 & 5 excellent)

How is the behavior of visited engineer	
What is the level of your satisfaction	
How is the explaination by Engineer	

	Fault Diagnosed	✓
Power	Power Failure	
	Phase Reverse	
PCB	In door unit PCB Defective	
	Out door PCB Defective	
FM	In door unit Fan Motor Defective	
	Outdoor Fan Motor Defective	
Comp	Comp. taking High Current / Amp	
	Compressor Ground / Earth	
	Compressor Tripping due ot High Temprature	
	Compressor tripping due to High Pressure	
Electrical	Indoor Unit MgSw Defective	
	Outdoor Unit Mgsw Defective	
	Indoor Unit Transformer Faulty	
	Out door Unit Transformer Faulty	
	Fault of swing Motor	
	Defect of Drain Pump	
	Expansion Valve Body / Motor Defective	
	Defective Temperature Sensor of Indoor Unit	
	Defective Temperature Sensor of Outdoor Unit	
	Defective Current Sensor In Out door Unit	
Unit	Gas Leakage at Indoor Unit	
	Gas Leakage at Outdoor Unit	
	Blower broken	
Installation	Short Cycling of Air at Indoor Unit	
	Short Cycling of Air at Outdoor Unit	
	Defect in Drain piping System	
	Gas Leakage from Flare nut	
	Error In Transmission wiring	
	Product under capacity	
	Rat bite case	
Other	Less cooling problem due to dirty Airfilter	
	Remote setting changed	
	Clogged Condenser	
	Other - Pl. specify	

	Details of Repair Work Done	✓
a	Simple Repair	
b	Part Replaced	
c	Part Repaired	
d	Gas Charging done	
e	Routine Service - Wet	
f	Routine Service - DRY	