DAIKIN

400

DAIKIN AIRCONDITIONING INDIA PVT. LTD.

Service Completion Certificate

Subject :

AEON AIRCONDITIONING SOLUTIONS

Office No. 108 & 109, Devashree Garden, Commercial Complex, R.W. Swaant Marg, above Sheetal Dairy, Rutu Park, Thane - 400 601.
Mob.: 9322334107 / 9322334109

Registration No.	Request Date	Service Engineer	Scheduled Date/Time	Service Order
		Azam	13/6/26	

User : Azaan Shakeel Mobile :

Customer Address :

I Base Address : Byculla.

Daikin Invoice : Date :

Dealer Invoice : Date :

Type	Model No	Manufacturing No.
Outdoor unit /	RKC50XV16VLA	8019492
Indoor unit	FTKC50XV16VLA	R023078

Work Date	No. of S.E.	Work hours	Progress code	Details of the Repair Work
13/6/26				1.5 TR Daikin AC Installation Done.

Compressor manufacturing No.	Defective Compressor	Replacement Compressor

Installed date	Warranty	AMC	Using with Stabilizer	Using with Cut off	Fault location	Phenomena code	Error code
	Yes / No	Yes / No	Yes / No	Yes / No			

Service Engineer Remarks : Cooling Fine.

Name : Azaan Signature :

Customer Remarks :

Name : Signature :

Operation data (Ambient temp. °C)	Before repair	After repair
HP / T	psig/	psig/
SP / T °C	psig/°C	psig/°C
Current °C	Amps°C	Amps°C
Voltage	Volts	Volts
Indoor temperature		
Suction	°C	°C
Discharge	°C	°C
Outdoor temperature		
Suction	°C	°C
Discharge	°C	°C

Work No / Parts No	Qty	Billing Amount
IAC Uninstall	1	
Total		

Customer Impression about Service

(Please rate on scale of 1 poor, 2, 3, 4 & 5 excellent)

How is the behavior of visted engineer	
What is the level of your satisfaction	
How is the explaination by Engineer	

	Fault Diagnosed	✓
Power	Power Failure	
	Phase Reverse	
PCB	In door unit PCB Defective	
	Out door PCB Defective	
EM	In door unit Fan Motor Defective	
	Outdoor Fan Motor Defective	
Comp	Comp. taking High Current / Amp	
	Compressor Ground / Earth	
	Compressor Tripping due ot High Temprature	
	Compressor tripping due to High Pressure	
Electrical	Indoor Unit MgSw Defective	
	Outdoor Unit Mgsw Defective	
	Indoor Unit Transformer Faulty	
	Out door Unit Transformer Faulty	
	Fault of swing Motor	
	Defect of Drain Pump	
	Expansion Valve Body / Motor Defective	
	Defective Temperature Sensor of Indoor Unit	
	Defective Temperature Sensor of Outdoor Unit	
	Defective Current Sensor In Out door Unit	
Unit	Gas Leakage at Indoor Unit	
	Gas Leakage at Outdoor Unit	
	Blower broken	
Installation	Short Cycling of Air at Indoor Unit	
	Short Cycling of Air at Outdoor Unit	
	Defect in Drain piping System	
	Gas Leakage from Flare nut	
	Error In Transmission wiring	
	Product under capacity	
	Rat bite case	
Other	Less cooling problem due to dirty Airfilter	
	Remote setting changed	
	Clogged Condenser	
	Other - Pl. specify	

	Details of Repair Work Done	✓
a	Simple Repair	
b	Part Replaced	
c	Part Repaired	
d	Gas Charging done	
e	Routine Service - Wet	
f	Routine Service - DRY	