1) Indoor AC was uninstalled and re installed due to damage.
2) 2 remotes are yet to come from daikin and meanwhile they installed wired remote.

AEON AIRCONDITIONING SOLUTIONS

Aeon House, Shop No. 6/7, Behind N Cube China Town, Opp. Shishu Dnyan Mandir,
Dr. Ambedkar Rd. Thane 400 601. Maharashtra
Tel. : 022 - 25370101 / 7900097007
e-mail : services@aeonacsolutions.com website : www.aeonacsolutions.com

CONSOLIDATED PRIVATE LIMITED

Ibrahim Ansari
12/08/2026 @ 04:19pm

Project : I planet 12/08/2026

Powai Andheri (East) Additional Measurement Sheet

Sr. No	Location	AC Type	Tonnage	Indoor Unit Details		Outdoor Unit Details		Copper In Rmt	Cable In Rmt	Drain In Rmt	ODU Stand
				Model No.	Sr. No.	Model No.	Sr. No.				
1	Shop	Cassette	4 Tr	FCFQ140 EV16	000040			32 mtr	37 mtr	21 mtr	Fabricated Tipe
2	Shop	Cassette	4 Tr					〃	〃	〃	Fabricated Pipe
3											
4											
5											
6											
7											
8											

Extra Activity Carried Out

Civil Work	Stabilizer			Timer	Casing Capping	Cable Tray	Gas Charging	Dismentling		Re-installation
	3KVA	4KVA	5KVA					Hi Wall	Cassette	

Others 2 Times A/c unstall and Re installtion

For		Vendor Details	Aeon Air Conditioner
Sign		Signature	
Name	Stamp	Technician Name	Sabir + 3
Date		Date	12/08/2026

Manager Remarks written above.