DAIKIN AIRCONDITIONING INDIA PVT. LTD.

Service Completion Certificate
C-403, Corporate Avenue Andheri Ghatkopar Link Rd, Andheri (E), Mumbai-400093.

AEON AIRCONDITIONING SOLUTIONS
Office No. 108 & 109, Devashree Garden Commercial Complex
R. W. Sawant Marg, Above Sheetal Dairy, Rutu Park, Thane-400 6
Mob.: 9326311501 / 9322334106

Subject : **Sr.No.**_____

Registration No.	Request Date	Service Engineer's Name	Scheduled Date	Time	Notification No.	Service Order No.

User Name : HDFC ERGO

Address : BEHALA KOLKATA.

Mobile No.: Tel. No.:

Daikin Invoice No.: Date :

Dealer Invoice No.: Date :

Type	Model No.	Manufacturing No.
Outdoor Unit	RKM60XV16MAA	0002390
Indoor unit	FTKM60XV16MAA	0000193

Work Date	No. of S.E.	Work Hours	Progress Code	Details of the Repair Work

Compressor Manufacturing No.	Defective Compressor	Replacement Compressor

Installed Date	Warranty	AMC	Using with Stabilizer	Using with Cut off	Fault Location	Phenomen Code	Error Code
	Yes / No	Yes / No	Yes / No	Yes / No			

Service Engineer Remarks Installation and commissing done running cooling ok.

Sabhajit Bala

Name Signature

Customer Remarks

Tukaram Mondal 26-10-26

Name Signature

Operation data (Ambient temp. °C)	Before Repair	After Repair
HP / T °C	psig/°C	psig/°C
SP / T °C	psig/°C	psig/°C
Current	Amps	Amps
Voltage	Volts	Volts
Indoor Temperature		
Suction	°C	°C
Discharge	°C	°C
Outdoor Temperature		
Suction	°C	°C
Discharge	°C	°C

Work No / Parts No	Qty	Billing Amount
	Total	

Customer Impression about Service

(Please rate on scale of 1 poor, 2, 3, 4 & 5 excellent)

How is the behavior of visited engineer	
What is the level of your satisfaction	
How is the explanation by Engineer	

	Fault Diagnosed	✓
Power	Power Failure	
	Phase Reverse	
PCB	In door unit PCB Defective	
	Out door PCB Defective	
EM	In door unit Fan Motor Defective	
	Outdoor Fan Motor Defective	
Comp	Comp. taking Hight Current / Amp	
	Compressor Ground / Earth	
	Compressor Tripping due to High Temprature	
	Compressor Tripping due to Hight Pressure	
Electrical	Indoor Unit MgSw Defective	
	Outdoor Unit MgSw Defective	
	Indoor Unit Transformer Faulty	
	Outdoor Unit Transformer Faulty	
	Fault of Swing Motor	
	Defect of Drain Pump	
	Expansion Valve Body / Motor Defective	
	Defective Temperature Sensor of Indoor Unit	
	Defective Temperature Sensor of Outdoor Unit	
	Defective Current Sensor in Out door Unit	
Unit	Gas Leakage at Indoor Unit	
	Gas Leakage at Outdoor Unit	
	Blower Broken	
Installation	Short Cycling of Air at Indoor Unit	
	Short Cycling of Air at Outdoor Unit	
	Defect in Drain Piping System	
	Gas Leakage from Flare nut	
	Error In Transmission wiring	
	Product under capacity	
	Rate bite case	
Other	Less cooling problem due to dirty Airfilter	
	Remote setting changed	
	Clogged condenser	
	Other - Pl. Specify	

	Details of Repair Work Done	✓
a	Simple Repair	
b	Part Replaced	
c	Part Replaced	
d	Gas Charging Done	
e	Routing Service - Wet	
f	Routing Service - Dry	

"We recommend, to take routine maintenance services of your Daikin machine at regular intervals, for its good health"

DAIKIN AIRCONDITIONING INDIA PVT. LTD.

Service Completion Certificate

C-403, Corporate Avenue Andheri Ghatkopar Link Rd, Andheri (E), Mumbai-400093.

AEON AIRCONDITIONING SOLUTIONS

Office No. 108 & 109, Devashree Garden Commercial Complex
R. W. Sawant Marg, Above Sheetal Dairy, Rutu Park, Thane-400 6
Mob.: 9326311501 / 9322334106

Subject : **Sr.No.**

Registration No.	Request Date	Service Engineer's Name	Scheduled Date	Time	Notification No.	Service Order No.

User Name : HDFC ERGO

Address : BEHALA KOLKATA

Mobile No.: Tel. No.:

Daikin Invoice No.: Date :

Dealer Invoice No.: Date :

Type	Model No.	Manufacturing No.
Outdoor Unit	FTKM60XV16MAA	000
Indoor unit	FTKM60XV16MAA	000 2286

Work Date	No. of S.E.	Work Hours	Progress Code	Details of the Repair Work

Compressor Manufacturing No.	Defective Compressor	Replacement Compressor

Installed Date	Warranty	AMC	Using with Stabilizer	Using with Cut off	Fault Location	Phenomen Code	Error Code
	Yes / No	Yes / No	Yes / No	Yes / No			

Service Engineer Remarks Instalation and Commissing done cooling and running ok.

Name Signature

Customer Remarks

Name Signature

"We recommend, to take routine maintenance services of your Daikin machine at regular intervals, for its good health"

Operation data (Ambient temp. °C)	Before Repair	After Repair
HP / T °C	psig/°C	psig/°C
SP / T °C	psig/°C	psig/°C
Current	Amps	Amps
Voltage	Volts	Volts
Indoor Temperature		
Suction	°C	°C
Discharge	°C	°C
Outdoor Temperature		
Suction	°C	°C
Discharge	°C	°C

Work No / Parts No	Qty	Billing Amount
	Total	

Customer Impression about Service

(Please rate on scale of 1 poor, 2, 3, 4 & 5 excellent)

How is the behavior of visited engineer	
What is the level of your satisfaction	
How is the explanation by Engineer	

	Fault Diagnosed	✓
Power	Power Failure	
	Phase Reverse	
PCB	In door unit PCB Defective	
	Out door PCB Defective	
EM	In door unit Fan Motor Defective	
	Outdoor Fan Motor Defective	
Comp	Comp. taking Hight Current / Amp	
	Compressor Ground / Earth	
	Compressor Tripping due to High Temprature	
	Compressor Tripping due to Hight Pressure	
Electrical	Indoor Unit MgSw Defective	
	Outdoor Unit MgSw Defective	
	Indoor Unit Transformer Faulty	
	Outdoor Unit Transformer Faulty	
	Fault of Swing Motor	
	Defect of Drain Pump	
	Expansion Valve Body / Motor Defective	
	Defective Temperature Sensor of Indoor Unit	
	Defective Temperature Sensor of Outdoor Unit	
	Defective Current Sensor in Out door Unit	
Unit	Gas Leakage at Indoor Unit	
	Gas Leakage at Outdoor Unit	
	Blower Broken	
Installation	Short Cycling of Air at Indoor Unit	
	Short Cycling of Air at Outdoor Unit	
	Defect in Drain Piping System	
	Gas Leakage from Flare nut	
	Error In Transmission wiring	
	Product under capacity	
	Rate bite case	
Other	Less cooling problem due to dirty Airfilter	
	Remote setting changed	
	Clogged condenser	
	Other - Pl. Specify	

	Details of Repair Work Done	✓
a	Simple Repair	
b	Part Replaced	
c	Part Replaced	
d	Gas Charging Done	
e	Routing Service - Wet	
f	Routing Service - Dry	

DAIKIN

DAIKIN AIRCONDITIONING INDIA PVT. LTD.

Authorised Service Provider

AEON AIRCONDITIONING SOLUTIONS

AEON HOUSE, SHOP NO. 6 & 7, BEHIND N CUBE CHINA TOWN

DR. AMBEDKAR ROAD, THANE W 400601 MAHARASHTRA. PHONE :- 02225370101 / 7900097007 / 9322334106

aeon

PROJECT :- HDFC ERGO BEHALA KOLKATA

Measurement Sheet

Sr. No.	Location	AC Type	Tonnage	Indoor Unit Details		Outdoor Unit Details		Copper in Rmt	Cable in Rmt	Drain in Rmt	ODU Stand
				Model No.	Sr. No.	Model No.	Sr. No.				
1	Reception	Split	1.5 TR	FTKM50XV16MKA	0022066	RKM50XV16MKA	0055994	14	16	19	—
2	Hall Area	Split	2 TR	FTKM60XV16MAA	0000193	RKM60XV16MAA	0002390	13	15	18	—
3	Hall Area	Split	2 TR	FTKM60XV16MAA		RKM60XV16MAA	0002286	5	7	10	—
4											
5											
6											
7											
8											
9											
10											

EXTRA ACTIVITY CARRIED OUT

CIVIL WORK	Stabilizer			TIMER	CASING CAPPING	CABLE TRAY	GAS CHARGING	DISMENTALING		RE-INSTALLATION
	3KVA	4KVA	5KVA					HI Wall	Cassette	
OTHERS	3 Drain Pump, 1 Core Cutting, 5 miter Cable tray, One Scrafolding (30 fit by 7 fit).									

For Customer Details : HDFC ERGO		Vendor Details : AEON AIRCONDITIONING SOLUTIONS	
Sign :		Signature :	
Name : Tuhin Mondal		Technician Name :	Subhajit Belel.
Date : 26.10.26	Stamp : HDFC ERGO GENERAL INSURANCE CO. LTD. BEHALA	Date :	26/10/26

DAIKIN AIRCONDITIONING INDIA PVT. LTD.

Service Completion Certificate

C-403, Corporate Avenue Andheri Ghatkopar Link Rd, Andheri (E), Mumbai-400093.

AEON AIRCONDITIONING SOLUTION

Office No. 108 & 109, Devashree Garden Commercial Compl
R. W. Sawant Marg, Above Sheetal Dairy, Rutu Park, Thane-40
Mob.: 9326311501 / 9322334106

Subject : **Sr.No.**_____

Registration No.	Request Date	Service Engineer's Name	Scheduled Date	Time	Notification No.	Service Order No.

User Name : ADFC ERGO

Address : BEHALA KOLKATA.

Mobile No.: Tel. No.:

Daikin Invoice No.: Date :

Dealer Invoice No.: Date :

Type	Model No.	Manufacturing No.
Outdoor Unit	RKM50XV16MKA	0055994
Indoor unit	FTKM50X16MKA	0022066

Work Date	No. of S.E.	Work Hours	Progress Code	Details of the Repair Work

Compressor Manufacturing No.	Defective Compressor	Replacement Compressor

Installed Date	Warranty	AMC	Using with Stabilizer	Using with Cut off	Fault Location	Phenomen Code	Error Code
	Yes / No	Yes / No	Yes / No	Yes / No			

Service Engineer Remarks: Installation and Commissing done Cooling and Heating ok.

Name: Sahil Bilal Signature:

Customer Remarks: THE GENERAL INSURANCE CO. LTD. BEHALA

Name: Signature:

Operation data (Ambient temp. °C)	Before Repair	After Repair
HP / T °C	psig/°C	psig/°C
SP / T °C	psig/°C	psig/°C
Current	Amps	Amps
Voltage	Volts	Volts
Indoor Temperature		
Suction	°C	°C
Discharge	°C	°C
Outdoor Temperature		
Suction	°C	°C
Discharge	°C	°C

Work No / Parts No	Qty	Billing Amount