DAIKIN DAIKIN

Service Completion Certificate

C-403, Corporate Avenue Andheri Ghatkopar Link Rd, Andheri (E), Mumbai-400

Sr.No.

Subject : Installation

Registration No.	Request Date	Service Engineer's Name	Scheduled Date	Time	Notification No.

User Name : Blue dart (DHL)

Address : Soham plaza, Ghodbunder road Thane Tel. No.:

Mobile No.: Date :

Daikin Invoice No.: Date :

Dealer Invoice No.:

	Model No.	Manufacturing No.
Type		
Outdoor Unit		
Indoor unit		

Work Date	No. of S.E.	Work Hours	Progress Code
06/10/26			

Details of the Repair Work

Installation Done. nitrogen flushing, -7 meter 4 Core Wire. 2 meter Copper

Compressor Manufacturing No.	Defective Compressor	Replacement Compressor

Installed Date	Warranty	AMC	Using with		Fault Location	Phenomen Code	Error Code
			Stabilizer	Cut off			
	Yes / No	Yes / No	Yes / No	Yes / No			

Service Engineer Remarks Pipe. PCB Check work, L Type stand Ings Dismentaling Ings

Name Signature

Customer Remarks

Name Signature

DHL EXPRESS (I) PVT. LTD. MUMBAI

Operation data (Ambient temp. °C)

	Before Repair	After Repair
HP / T °C	psig/°C	psig/°C
SP / T °C	psig/°C	psig/°C
Current	Amps	Amps
Voltage	Volts	Volts
Indoor Temperature		
Suction	°C	°C
Discharge	°C	°C
Outdoor Temperature		
Suction	°C	°C
Discharge	°C	°C

Work No / Parts No	Qty	Billing Amount
	Total	

Customer Impression about Service

(Please rate on scale of 1 poor, 2, 3, 4 & 5 excellent)

How is the behavior of visited engineer	
What is the level of your satisfaction	
How is the explanation by Engineer	

	Fault Diagnosed
PCB	Power Failure
	Phase Reverse
	In door unit PCB Defective
	Out door PCB Defective
Fan	In door unit Fan Motor Defective
	Outdoor Fan Motor Defective
Comp	Comp. taking Hight Current / Amp
	Compressor Ground / Earth
	Compressor Tripping due to High Temprature
	Compressor Tripping due to Hight Pressure
Electrical	Indoor Unit MgSw Defective
	Outdoor Unit MgSw Defective
	Indoor Unit Transformer Faulty
	Outdoor Unit Transformer Faulty
	Fault of Swing Motor
	Defect of Drain Pump
	Expansion Valve Body / Motor Defective
	Defective Temperature Sensor of Indoor Unit
	Defective Temperature Sensor of Outdoor Unit
	Defective Current Sensor in Out door Unit
Unit	Gas Leakage at Indoor Unit
	Gas Leakage at Outdoor Unit
	Blower Broken
Installation	Short Cycling of Air at Indoor Unit
	Short Cycling of Air at Outdoor Unit
	Defect in Drain Piping System
	Gas Leakage from Flare nut
	Error In Transmission wiring
	Product under capacity
	Rate bite case
Other	Less cooling problem due to dirty Airfilter
	Remote setting changed
	Clogged condenser
	Other - Pl. Specify

	Details of Repair Work Don
a	Simple Repair
b	Part Replaced
c	Part Replaced
d	Gas Charging Done
e	Routing Service - Wet
f	Routing Service - Dry

me

recommend, to take routine maintenance services of your Daikin machine at regular intervals, for its good health"

DAIKIN to 92101 88999 : Toll Free Number : 1860 180 3900 / 1800 102 9300 ; cs@daikinindia.com / www.daikinin