DAIKIN

DAIKIN AIRCONDITIONING INDIA PVT. LTD.

Authorised Service Provider

AEON AIRCONDITIONING SOLUTIONS

AEON HOUSE, SHOP NO. 6 & 7, BEHIND N CUBE CHINA TOWN

DR. AMBEDKAR ROAD, THANE W 400601 MAHARASHTRA. PHONE :- 02225370101 / 7900097007 / 9322334106

aeon

PROJECT :- Theobroma Foods Pvt. Ltd. Ooria Kolkata.

Measurement Sheet

Sr. No.	Location	AC Type	Tonnage	Indoor Unit Details		Outdoor Unit Details		Copper in Rmt	Cable in Rmt	Drain in Rmt	ODU Stand
				Model No.	Sr. No.	Model No.	Sr. No.				
1	Work Area	Cassette	2Tn	FCQF24ARV16	89449	RQVF24ASV16	0094568	8	10	14	1
2	Work Area	Cassette	2Tn	FCQF24ARV16	88959	RQVF24ASV16	0092184	8	10	15	1
3	Work Area	Cassette	2Tn	FCQF24ARV16	90772	RQVF24ASV16	0094576	7	9	19	1
4											
5											
6											
7											
8											
9											
10											

EXTRA ACTIVITY CARRIED OUT

CIVIL WORK	Stabilizer			TIMER	CASING CAPPING	CABLE TRAY	GAS CHARGING	DISMENTALING		RE-INSTALLATION
	3KVA	4KVA	5KVA					Hi Wall	Cassette	
OTHERS	Corecutting 2,									

For Customer Details : Theobroma Foodds Pvt. Ltd.		Vendor Details : AEON AIRCONDITIONING SOLUTIONS	
Sign :		Signature :	Subhajit Belel
Name : Tilak Mukherjee	THEOBROMA FOODS PVT LTD	Technician Name :	SUBHAJIT BELEL
Date : 26/10/22	Stamp : TILAK MUKHERJEE	Date :	

DAIKIN AIRCONDITIONING INDIA PVT. LTD.

Service Completion Certificate
C-403, Corporate Avenue Andheri Ghatkopar Link Rd, Andheri (E), Mumbai-400093.

AEON AIRCONDITIONING SOLUTIONS
Office No. 108 & 109, Devashree Garden Commercial Complex
R. W. Sawant Marg, Above Sheetal Dairy, Rutu Park, Thane-400 6
Mob.: 9326311501 / 9322334106

Subject :

Sr.No._____

Registration No.	Request Date	Service Engineer's Name	Scheduled Date	Time	Notification No.	Service Order No.

User Name : Theobroma Foods Pvt Ltd.

Address : Garia Kolkata

Mobile No.: Tel. No.:

Daikin Invoice No.: Date :

Dealer Invoice No.: Date :

Type	Model No.	Manufacturing No.
Outdoor Unit	RKVF24ASV1G	0092184
Indoor unit	FCQF24ARV1G	88959

Work Date	No. of S.E.	Work Hours	Progress Code	Details of the Repair Work

Operation data (Ambient temp. °C)	Before Repair	After Repair
HP / T °C	psig/°C	psig/°C
SP / T °C	psig/°C	psig/°C
Current	Amps	Amps
Voltage	Volts	Volts
Indoor Temperature		
Suction	°C	°C
Discharge	°C	°C
Outdoor Temperature		
Suction	°C	°C
Discharge	°C	°C

Work No / Parts No	Qty	Billing Amount
Total		

Compressor Manufacturing No.	Defective Compressor	Replacement Compressor

Installed Date	Warranty	AMC	Using with Stabilizer	Using with Cut off	Fault Location	Phenomen Code	Error Code
	Yes / No	Yes / No	Yes / No	Yes / No			

Service Engineer Remarks Installation and Commissing done Nose coolling and running OK.

Name Signature

Customer Remarks THEOBROMA FOODS PVT LTD TILAK MUKHERJEE Ok.

Name Signature

	Fault Diagnosed	✓
Power	Power Failure	
	Phase Reverse	
PCB	In door unit PCB Defective	
	Out door PCB Defective	
FM	In door unit Fan Motor Defective	
	Outdoor Fan Motor Defective	
Comp	Comp. taking Hight Current / Amp	
	Compressor Ground / Earth	
	Compressor Tripping due to High Temprature	
	Compressor Tripping due to Hight Pressure	
Electrical	Indoor Unit MgSw Defective	
	Outdoor Unit MgSw Defective	
	Indoor Unit Transformer Faulty	
	Outdoor Unit Transformer Faulty	
	Fault of Swing Motor	
	Defect of Drain Pump	
	Expansion Valve Body / Motor Defective	
	Defective Temperature Sensor of Indoor Unit	
	Defective Temperature Sensor of Outdoor Unit	
	Defective Current Sensor in Out door Unit	
Unit	Gas Leakage at Indoor Unit	
	Gas Leakage at Outdoor Unit	
	Blower Broken	
Installation	Short Cycling of Air at Indoor Unit	
	Short Cycling of Air at Outdoor Unit	
	Defect in Drain Piping System	
	Gas Leakage from Flare nut	
	Error in Transmission wiring	
	Product under capacity	
	Rate bite case	
Other	Less cooling problem due to dirty Airfilter	
	Remote setting changed	
	Clogged condenser	
	Other - Pl. Specify	

	Details of Repair Work Done	✓
a	Simple Repair	
b	Part Replaced	
c	Part Replaced	
d	Gas Charging Done	
e	Routing Service - Wet	
f	Routing Service - Dry	

Customer Impression about Service

(Please rate on scale of 1 poor, 2, 3, 4 & 5 excellent)

How is the behavior of visited engineer	
What is the level of your satisfaction	
How is the explanation by Engineer	

"We recommend, to take routine maintenance services of your Daikin machine at regular intervals, for its good health"

DAIKIN AIRCONDITIONING INDIA PVT. LTD.

Service Completion Certificate

C-403, Corporate Avenue Andheri Ghatkopar Link Rd, Andheri (E), Mumbai-400093.

AEON AIRCONDITIONING SOLUTIONS

Office No. 108 & 109, Devashree Garden Commercial Complex
R. W. Sawant Marg, Above Sheetal Dairy, Rutu Park, Thane-400 6
Mob.: 9326311501 / 9322334106

Subject :

Sr.No._____

Registration No.	Request Date	Service Engineer's Name	Scheduled Date	Time	Notification No.	Service Order No.

User Name : Theobroma Foods Pvt Ltd.

Address : Garia Kolkata

Mobile No.: Tel. No.:

Daikin Invoice No.: Date :

Dealer Invoice No.: Date :

Type	Model No.	Manufacturing No.
Outdoor Unit	RKVF24ASV1G	0094576
Indoor unit	FCQF24ARV1G	90772

Work Date	No. of S.E.	Work Hours	Progress Code	Details of the Repair Work

Compressor Manufacturing No.	Defective Compressor	Replacement Compressor

Installed Date	Warranty	AMC	Using with Stabilizer	Using with Cut off	Fault Location	Phenomen Code	Error Code
	Yes / No	Yes / No	Yes / No	Yes / No			

Service Engineer Remarks Installation and commissing done now cooling and servicing ok.

Name Signature

Customer Remarks
THEOBROMA FOODS PVT LTD
TILAK MUKHERJEE
Ok

Name Signature

Operation data (Ambient temp. °C)

	Before Repair	After Repair
HP / T °C	psig/°C	psig/°C
SP / T °C	psig/°C	psig/°C
Current	Amps	Amps
Voltage	Volts	Volts
Indoor Temperature		
Suction	°C	°C
Discharge	°C	°C
Outdoor Temperature		
Suction	°C	°C
Discharge	°C	°C

Work No / Parts No	Qty	Billing Amount
Total		

Customer Impression about Service

(Please rate on scale of 1 poor, 2, 3, 4 & 5 excellent)

How is the behavior of visited engineer	
What is the level of your satisfaction	
How is the explanation by Engineer	

	Fault Diagnosed	✓
Power	Power Failure	
	Phase Reverse	
PCB	In door unit PCB Defective	
	Out door PCB Defective	
FM	In door unit Fan Motor Defective	
	Outdoor Fan Motor Defective	
Comp	Comp. taking Hight Current / Amp	
	Compressor Ground / Earth	
	Compressor Tripping due to High Temprature	
	Compressor Tripping due to Hight Pressure	
Electrical	Indoor Unit MgSw Defective	
	Outdoor Unit MgSw Defective	
	Indoor Unit Transformer Faulty	
	Outdoor Unit Transformer Faulty	
	Fault of Swing Motor	
	Defect of Drain Pump	
	Expansion Valve Body / Motor Defective	
	Defective Temperature Sensor of Indoor Unit	
	Defective Temperature Sensor of Outdoor Unit	
	Defective Current Sensor in Out door Unit	
Unit	Gas Leakage at Indoor Unit	
	Gas Leakage at Outdoor Unit	
	Blower Broken	
Installation	Short Cycling of Air at Indoor Unit	
	Short Cycling of Air at Outdoor Unit	
	Defect in Drain Piping System	
	Gas Leakage from Flare nut	
	Error In Transmission wiring	
	Product under capacity	
	Rate bite case	
Other	Less cooling problem due to dirty Airfilter	
	Remote setting changed	
	Clogged condenser	
	Other - Pl. Specify	

	Details of Repair Work Done	✓
a	Simple Repair	
b	Part Replaced	
c	Part Replaced	
d	Gas Charging Done	
e	Routing Service - Wet	
f	Routing Service - Dry	

"We recommend, to take routine maintenance services of your Daikin machine at regular intervals, for its good health"

DAIKIN AIRCONDITIONING INDIA PVT. LTD.

Service Completion Certificate

C-403, Corporate Avenue Andheri Ghatkopar Link Rd, Andheri (E), Mumbai-400093.

AEON AIRCONDITIONING SOLUTI

Office No. 108 & 109, Devashree Garden Commercial C
R. W. Sawant Marg, Above Sheetal Dairy, Rutu Park, Thane
Mob.: 9326311501 / 9322334106

Subject :

Sr.No._____

Registration No.	Request Date	Service Engineer's Name	Scheduled Date	Time	Notification No.	Service Order No.

User Name : Theobroma Foods Pvt Ltd.

Address : Garia Kolkata

Mobile No.: Tel. No.:

Daikin Invoice No.: Date :

Dealer Invoice No.: Date :

Type	Model No.	Manufacturing No.
Outdoor Unit	RGVF24ASV16	0094568
Indoor unit	FCQF24ARV16	89449.

Work Date	No. of S.E.	Work Hours	Progress Code	Details of the Repair Work

Compressor Manufacturing No.	Defective Compressor	Replacement Compressor

Installed Date	Warranty	AMC	Using with Stabilizer	Using with Cut off	Fault Location	Phenomen Code	Error Code
	Yes / No	Yes / No	Yes / No	Yes / No			

Service Engineer Remarks: Installation and Commissioning done now Cooling and running OK.

Name: Subhajit Bakl. Signature:

Customer Remarks: THEOBROMA FOODS PVT LTD. TILAK MUKHERJEE OK

Name: Signature:

Operation data (Ambient temp. °C)

	Before Repair	After Repair
HP / T °C	psig/°C	psig/°C
SP / T °C	psig/°C	psig/°C
Current	Amps	Amps
Voltage	Volts	Volts
Indoor Temperature		
Suction	°C	°C
Discharge	°C	°C
Outdoor Temperature		
Suction	°C	°C
Discharge	°C	°C

Work No / Parts No	Qty	Billing Amount
	Total	

Customer Impression about Service

(Please rate on scale of 1 poor, 2, 3, 4 & 5 excellent)

How is the behavior of visited engineer	
What is the level of your satisfaction	
How is the explanation by Engineer	

	Fault Diagnosed
Power	Power Failure
	Phase Reverse
PCB	In door unit PCB Defective
	Out door PCB Defective
FM	In door unit Fan Motor Defective
	Outdoor Fan Motor Defective
Comp	Comp. taking Hight Current / Amp
	Compressor Ground / Earth
	Compressor Tripping due to High Temprature
	Compressor Tripping due to Hight Pressure
Electrical	Indoor Unit MgSw Defective
	Outdoor Unit MgSw Defective
	Indoor Unit Transformer Faulty
	Outdoor Unit Transformer Faulty
	Fault of Swing Motor
	Defect of Drain Pump
	Expansion Valve Body / Motor Defective
	Defective Temperature Sensor of Indoor Unit
	Defective Temperature Sensor of Outdoor Unit
	Defective Current Sensor in Out door Unit
Unit	Gas Leakage at Indoor Unit
	Gas Leakage at Outdoor Unit
	Blower Broken
Installation	Short Cycling of Air at Indoor Unit
	Short Cycling of Air at Outdoor Unit
	Defect in Drain Piping System
	Gas Leakage from Flare nut
	Error In Transmission wiring
	Product under capacity
	Rate bite case
Other	Less cooling problem due to dirty Airfilter
	Remote setting changed
	Clogged condenser
	Other - Pl. Specify

	Details of Repair Work Done	✓
a	Simple Repair	
b	Part Replaced	
c	Part Replaced	
d	Gas Charging Done	
e	Routing Service - Wet	
f	Routing Service - Dry	

"We recommend, to take routine maintenance services of your Daikin machine at regular intervals for its good health."