DAIKIN AIRCONDITIONING INDIA PVT. LTD.

Service Completion Certificate
C-403, Corporate Avenue Andheri Ghatkopar Link Rd, Andheri (E), Mumbai-40093

ECOVISTA MEP SOLUTIONS PRIVATE LIMITED
Shop No. 06, Shastri Dayan Mandir, Thane - 400601
Mob.: 9322534107 / 9322534106

Subject : Installation

Sr.No.

Registration No.	Request Date	Service Engineer's Name	Scheduled Date
		Ganesh	

User Name: Allana - MIDC Taloja

Address:

Mobile No.:

Daikin Invoice No.: Sl. No.:

Dealer Invoice No.: Date:

Date:

Type	Model No.	Manufacturing No.
Outdoor Unit	RZ 35KV16WAA	21450
Indoor Unit	FTKJ35KV16WAA	8522

Work Date	No. of S.E	Work Hours	Completed Code
26/ 26/ 28/			

Details of the Repair Work

Installation done not
Acid blowing Cooling
Fine

Compressor Manufacturing No.	Defective Compressor	Replacement Compressor

Installed Date	Warranty	AMC	Using with		Fault Location	Flowchart Code	Error Code
	Yes / No	Yes / No	Gas Leak	Oil Leak			
			Yes / No	Yes / No			

Service Engineer Remarks

Upto

Name: Signature:

Customer Remarks

Ganesh Patil

Name: Signature:

"We recommend, to take routine maintenance services of your Daikin machine at regular intervals, for its good health"

Daikin Customer Care : Missed Call or SMS <Daikin> to 92101 69999, Toll Free Number : 1800 180 3000/ 1800 102 0300 , csc@daikinindia.com / www.daikinindia.com

Date	Notification No.	Service Order No.

Operation data (Ambient temp. °C)

	Before Repair	After Repair
Hp / °C	psig/°C	psig/°C
Lp / °C	psig/°C	psig/°C
Current	Amps	Amps
Voltage	Volts	Volts
Indoor Temperature		
Suction	°C	°C
Discharge	°C	°C
Condenser Temperature		
Liquid	°C	°C
Discharge	°C	°C

Work No / Parts No	Qty	Billing Amount
Total		

Customer Impression about Service

Please rate on scale of 1 poor, 2, 3, 4 & 5 excellent	
How is the behavior of service engineer	
What is the level of their satisfaction	
How is the punctuality of Engineer	

	Fault Diagnosed	✓
Power	Power Failure	
	Phase Reversal	
PCB	In door unit PCB Defective	
	Out door PCB Defective	
Fan	In door unit Fan Motor Defective	
	Outdoor Fan Motor Defective	
Comp.	Comp. Safety High Current / Amp	
	Compressor Ground / Earth	
	Compressor Tripping due to High Temperature	
	Compressor Tripping due to High Pressure	
Electrical	Indoor Unit Mother Detective	
	Outdoor Unit Mother Detective	
	Indoor Unit Transformer Faulty	
	Outdoor Unit Transformer Faulty	
	Fault of Swing Motor	
	Defect in Drain Pump	
	Defect in Vane Body / Motor Defective	
	Defective Temperature Sensor of Indoor Unit	
	Defective Temperature Sensor of Outdoor Unit	
	Defective Current Sensor in Elt. Box Unit	
Unit	Gas Leakage at Indoor Unit	
	Gas Leakage at Outdoor Unit	
	Blower Broken	
Installation	Short Cycling of Air at Indoor Unit	
	Short Cycling of Air at Outdoor Unit	
	Defect in Drain Piping System	
	Gas Leakage from Flare nut	
	Error in Transmission wiring	
	Product power capacity	
	Rate low case	
Other	Less Cooling (reason due to dirty Airfilter	
	Remote setting changed	
	Charged carryforward	
	Other - PK Specify	

	Details of Repair Work Done	✓
R	Repair Repair	
P	Part Replaced	
C	Part Recharged	
G	Gas Charging Done	
N	Nothing Service - Yes	
T	Nothing Service - Dry	