DAIKIN

DAIKIN AIRCONDITIONING INDIA PVT. LTD.

Service Completion Certificate

713

AEON AIRCONDITIONING SOLUTIONS

Office No. 108 & 109, Devashree Garden, Commercial Complex, R.W. Swaant Marg, above Sheetal Dairy, Rutu Park, Thane - 400 601. Mob.: 9322334107 / 9322334109

Subject :

Registration No.	Request Date	Service Engineer	Scheduled Date/Time	Service Order

User :

Customer Address : Pradeep Karnik 6/Sai Ambika Society / Tarodi Naka near Bank of India Mulund (W) 400 080

Mobile :

I Base Address :

Daikin Invoice : Date :

Dealer Invoice : Date :

Type	Model No	Manufacturing No.
Outdoor unit / Indoor unit	RKC50UV16VF / FTKC50UV16VF	8049571 / SER. NO. 8031054

Work Date	No. of S.E.	Work hours	Progress code	Details of the Repair Work
22/4/2025				Installation : Done and Cabling : Done

Compressor manufacturing No.	Defective Compressor	Replacement Compressor

Installed date	Warranty	AMC	Using with		Fault location	Phenomena code	Error code
			Stabilizer	Cut off			
	Yes / No	Yes / No	Yes / No	Yes / No			

Service Engineer Remarks

Name Azeem Signature

Customer Remarks

Name Pradeep Karnik Signature

Operation data (Ambient temp. °C)	Before repair	After repair
HP / T	psig/	psig/
SP / T °C	psig/°C	psig/°C
Current °C	Amps°C	Amps°C
Voltage	Volts	Volts
Indoor temperature		
Suction	°C	°C
Discharge	°C	°C
Outdoor temperature		
Suction	°C	°C
Discharge	°C	°C

Work/No / Parts No	Qty	Billing Amount
Installation	1	
Drain Pipe	13	
Piping tape	1	
Jet and 3 Blanket	1	
	10	
Total		

Fault Diagnosed		✓
Power	Power Failure	
	Phase Reverse	
PCB	In door unit PCB Defective	
	Out door PCB Defective	
EM	In door unit Fan Motor Defective	
	Outdoor Fan Motor Defective	
Comp	Comp. taking High Current / Amp	
	Compressor Ground / Earth	
	Compressor Tripping due ot High Temprature	
	Compressor tripping due to High Pressure	
Electrical	Indoor Unit MgSw Defective	
	Outdoor Unit Mgsw Defective	
	Indoor Unit Transformer Faulty	
	Out door Unit Transformer Faulty	
	Fault of swing Motor	
	Defect of Drain Pump	
	Expansion Valve Body / Motor Defective	
	Defective Temperature Sensor of Indoor Unit	
	Defective Temperature Sensor of Outdoor Unit	
	Defective Current Sensor In Out door Unit	
Unit	Gas Leakage at Indoor Unit	
	Gas Leakage at Outdoor Unit	
	Blower broken	
Installation	Short Cycling of Air at Indoor Unit	
	Short Cycling of Air at Outdoor Unit	
	Defect in Drain piping System	
	Gas Leakage from Flare nut	
	Error In Transmission wiring	
	Product under capacity	
	Rat bite case	
Other	Less cooling problem due to dirty Airfilter	
	Remote setting changed	
	Clogged Condenser	
	Other - Pl. specify	

Customer Impression about Service (Please rate on scale of 1 poor, 2, 3, 4 & 5 excellent)	
How is the behavior of visted engineer	
What is the level of your satisfaction	
How is the explaination by Engineer	

Details of Repair Work Done		✓
a	Simple Repair	
b	Part Replaced	
c	Part Repaired	
d	Gas Charging done	
e	Routine Service - Wet	
f	Routine Service - DRY	