DAIKIN

DAIKIN AIRCONDITIONING INDIA PVT. LTD.

Authorised Service Center

AEON AIRCONDITIONING SOLUTIONS

AEON HOUSE, SHOP NO. 6/7, BEHIND N CUBE CHINA TOWN

DR. AMBEDKAR ROAD, THANE W 400601 MAHARASHTRA. PHONE :- 02225370101 / 7900097007

aeon

PROJECT :- BLUE DART, RAJBANDH, DURGAPUR

Measurement Sheet

Sr. No.	Location	AC Type	Tonnage	Indoor Unit Details		Outdoor Unit Details		Copper in Rmt	Cable in Rmt	Drain in Rmt	ODU Stand
				Model No.	Sr. No.	Model No.	Sr. No.				
1	Manager Room	Split	1.5 T.C	FTKM50XV16 MKB	0021875	RKM50XV16 MKB	8057795	12 Mt	4 Mt	3 Mt	1
2											
3											
4											
5											
6											
7											
8											

EXTRA ACTIVITY CARRIED OUT

CIVIL WORK	Stabilizer			TIMER	CASING CAPPING	CABLE TRAY	GAS CHARGING	DISMENTALING		RE-INSTALLATION
	3KVA	4KVA	5KVA					Hi Wall	Cassette	
					1					

OTHERS: one Cutting and one Electrical Top

For Customer Details :			Vendor Details : AEON AIRCONDITIONING SOLUTIONS
Sign :	Apu Das		Signature :
Name :	APU DAS		Technician Name : Sk Nojibul Hossain
Date :	31/10/26	Stamp :	Date : 31/10/26

DAIKIN AIRCONDITIONING INDIA PVT. LTD.

Service Completion Certificate
C-403, Corporate Avenue Andheri Ghatkopar Link Rd, Andheri (E), Mumbai-400093.

AEON AIRCONDITIONING SOLUTIONS
Office No. 106 & 109, Devashree Garden Commercial Complex, R. W. Sawant Marg, Above Bhagat Dairy, Ruta Park, Thane-400 601.
Mob.: 9029311901 / 9322334108

Subject :

Registration No.	Request Date	Service Engineer's Name	Scheduled Date

Time	Notification No.	Service Order No.

User Name : Blue Dart
Address : Dunsapur - Rajbandh
Mobile No. : Tel. No. :
Daikin Invoice No. : Date : 31/10/25
Dealer Invoice No. : Date :

Type	Model No.	Manufacturing No.
Outdoor Unit	RKM50RVJMAH	8057775
Indoor unit	FTKM50RVJMKB	8024875

Work Date	No. of S.E.	Work Hours	Progress Code	Details of the Repair Work

Compressor Manufacturing No.	Defective Compressor	Replacement Compressor

Installed Date	Warranty	AMC	Using with Stabilizer	Using with Cut off	Fault Location	Phenomen Code	Error Code
	Yes / No	Yes / No	Yes / No	Yes / No			

Service Engineer Remarks : Installation and commissioning done power supply & cooling ok

Name : SK Nasirul Signature :

Customer Remarks :

Name : MD DAS Signature :

Operation data (Ambient temp. °C)	Before Repair	After Repair
HP / T °C	psig/°C	psig/°C
SP / T °C	psig/°C	psig/°C
Current	Amps	Amps
Voltage	Volts	Volts
Indoor Temperature		
Suction	°C	°C
Discharge	°C	°C
Outdoor Temperature		
Suction	°C	°C
Discharge	°C	°C

Work No / Parts No	Qty	Billing Amount
Total		

Customer Impression about Service
(Please rate on scale of 1 poor, 2, 3, 4 & 5 excellent)

How is the behavior of visited engineer	
What is the level of your satisfaction	
How is the explanation by Engineer	

	Fault Diagnosed	✓
Power	Power Failure	
	Phase Reverse	
PCB	In door unit PCB Defective	
	Out door PCB Defective	
Fan	In door unit Fan Motor Defective	
	Outdoor Fan Motor Defective	
Comp.	Comp. taking High Current / Amp	
	Compressor Ground / Earth	
	Compressor Tripping due to High Temperature	
	Compressor Tripping due to High Pressure	
Blocked	Indoor Unit MgSw Defective	
	Outdoor Unit MgSw Defective	
	Indoor Unit Transformer Faulty	
	Outdoor Unit Transformer Faulty	
	Fault of Swing Motor	
	Defect of Drain Pump	
	Expansion Valve Body / Motor Defective	
	Defective Temperature Sensor of Indoor Unit	
	Defective Temperature Sensor of Outdoor Unit	
	Defective Current Sensor in Out door Unit	
Gas	Gas Leakage at Indoor Unit	
	Gas Leakage at Outdoor Unit	
	Blower Broken	
Installation	Short Cycling of Air at Indoor Unit	
	Short Cycling of Air at Outdoor Unit	
	Defect in Drain Piping System	
	Gas Leakage from Pipe Joint	
	Error in Transmission wiring	
	Product under capacity	
	Rats bite case	
Other	Less cooling problem due to dirty Air filter	
	Remote setting changed	
	Clogged condenser	
	Other - Pl. Specify	

	Details of Repair Work Done	✓
a	Simple Repair	
b	Part Replaced	
c	Part Replaced	
d	Gas Charging Done	
e	Routine Service - Wet	
f	Routine Service - Dry	

"We recommend, to take routine maintenance services of your Daikin machine at regular intervals, for its good health"
Daikin Customer Care : Missed Call or SMS <DAIKIN> to 92101 88999 ; Toll Free Number : 1860 180 3600 / 1800 102 9300 ; cs@daikinindia.com / www.daikinindia.com

DPG
BLUE DART EXPRESS