



AEON AIRCONDITIONING SOLUTIONS

Aeon House, Shop No. 6/7, Behind N Cube China Town, Opp. Shishu Dnyan Mandir,
Dr. Ambedkar Rd, Thane 400 601, Maharashtra
Tel : 022 - 25370101 / 7900097007
e-mail : services@aeonacsolutions.com website : www.aeonacsolutions.com

Project :

Eat club. Shop no 50 & 5c Kolshet Road (Thane)

Additional Measurement Sheet

Sr. No	Location	AC Type	Tonnage	Indoor Unit Details		Outdoor Unit Details		Copper In Rmt	Cable In Rmt	Drain In Rmt	ODU Stand
				Model No.	Sr. No.	Model No.	Sr. No.				
1	Dining Room	Splite	1.5	FTRL50UV16	806375	RK50UV16VAD	8123810	-	-	1 mt	1
2	Dining Room	Splite	1.5	FTRL50UV16	8112018	RK50UV16VAG	8112018	-	-	1 mt	1
3											
4											
5											
6											
7											
8											

Extra Activity Carried Out

Civil Work	Stabilizer			Timer	Casing Capping	Cable Tray	Gas Charging	Dismantling		Re-installation
	3KVA	4KVA	5KVA					Hi Wall	Cassette	
2 Core cutting	-	-	-	-	-	-	-	-	-	-
Others	Nitrogen Flush.									

Vendor Details

For		Signature	
Sign		Technician Name	Umar SHAIKH.
Name		Date	24/04/25.
Date		Stamp	

DAIKIN

DAIKIN AIRCONDITIONING INDIA PVT. LTD. Service Completion Certificate


AEON AIRCONDITIONING SOLUTION

 Office No. 108 & 109, Devashree Garden, Commercial Complex
 R.W. Swarn Marg, above Sheetal Dairy, Fulu Park, Thane - 400
 Mob.: 9322334107 / 9322334109

1282

Subject: <u>Installation</u>		Request Date		Service Engineer		Scheduled Date/Time		Service Order	
Registration No.				Umar SHASKH					
User: <u>Eat Club</u>				Mobile:		Operation data (Ambient temp. °C)		Fault Diagnosed	
Customer Address: <u>Shop No 50, & 52 Ground floor</u>						Before repair		After repair	
Base Address: <u>Kolshet Road (Thane).</u>						HP / T		psig/	
Daikin Invoice:				Date:		SP / T °C		psig °C	
Dealer Invoice:				Date:		Current °C		Amps °C	
Type				Model No		Manufacturing No.		Voltage	
Outdoor unit /				RKL50UV16VAT		8123810		Volts	
Indoor unit				FTKL50UV16VAT		8063751		Volts	
Work Date				No. of S.E.		Work hours		Progress code	
24									
04									
25									
Details of the Repair Work						Discharge		°C	
Installation done.						Suction		°C	
Colling good.						Discharge		°C	
Compressor manufacturing No.				Defective Compressor		Replacement Compressor		Work No / Parts No	
Installed date				Warranty		AMC		Qty	
Yes / No				Yes / No		Yes / No		Billing Amount	
Service Engineer Remarks				Using with Stabilizer		Cut off		Fault location	
Umar SHASKH + Arsalan				Yes / No		Yes / No		Phenomena code	
Signature				Yes / No		Yes / No		Error code	
Customer Remarks				Service Engineer Signature		Total		Unit	
Name				Signature				Electrical	
								Defect of Drain Pump	
								Expansion Valve Body / Motor Defective	
								Defective Temperature Sensor of Indoor Unit	
								Defective Temperature Sensor of Outdoor Unit	
								Defective Current Sensor In Outdoor Unit	
								Gas Leakage at Indoor Unit	
								Gas Leakage at Outdoor Unit	
								Blower broken	
								Short Cycling of Air at Indoor Unit	
								Short Cycling of Air at Outdoor Unit	
								Defect in Drain piping System	
								Gas Leakage from Flare nut	
								Error in Transmission wiring	
								Product under capacity	
								Rat bite case	
								Less cooling problem due to dirty Airfilter	
								Remote setting changed	
								Clogged Condenser	
								Other - Pl. specify	
								Details of Repair Work Done	
								a Simple Repair	
								b Part Replaced	
								c Part Repaired	
								d Gas Charging done	
								e Routine Service - Wet	
								f Routine Service - DRY	
								Customer Impression about Service	
								(Please rate on scale of 1 poor, 2, 3, 4 & 5 excellent)	
								How is the behavior of visited engineer	
								What is the level of your satisfaction	
								How is the explanation by Engineer	



DAIKIN AIRCONDITIONING INDIA PVT. LTD.
Service Completion Certificate

Subject: Installation.



AEON AIRCONDITIONING SOLUTIONS

Office No. 108 & 109, Devashree Garden, Commercial Complex,
R.W. Swaant Marg, above Sheetal Dairy, Rutu Park, Thane - 400 601.
Mob.: 9322334107 / 9322334109

1283

Registration No.				Request Date		Service Engineer		Scheduled Date/Time		Service Order	
						UMAR SHAKH.					
User : Eat Club.				Mobile :		Operation data (Ambient temp. °C)				Fault Diagnosed	
Customer Address : Shop No 50, 52, around corner								Before repair		After repair	
Base Address : Kolshet Road (Thane)-						HP / T		psig/°C		psig/°C	
Daikin Invoice :				Date :		SP / T °C		psig/°C		psig/°C	
Dealer Invoice :				Date :		Current °C		Amps°C		Amps°C	
Type	Model No			Manufacturing No.							
Outdoor unit / Indoor unit	RKL50UVI6UAF			8123509.							
	FTKLS0VVI6UAH			8063752.							
Work Date	No. of S.E.	Work hours	Progress code	Details of the Repair Work				Discharge		°C °C	
24				Installation done.				Suction		°C °C	
04				Colling good.				Discharge		°C °C	
25								Work No / Parts No		Qty Billing Amount	
Compressor manufacturing No.				Defective Compressor				Replacement Compressor			
Installed date		Warranty	AMC	Using with		Fault location	Phenomena code	Error code			
		Yes / No	Yes / No	Stabilizer Cut off							
Service Engineer Remarks											
Name Umar Hassan.											
Signature [Signature]											
Total											
Other											
Less cooling problem due to dirty Airfilter											
Remote setting changed											
Clogged Condenser											
Other - Pl. specify											
Details of Repair Work Done											
a	Simple Repair										
b	Part Replaced										
c	Part Repaired										
d	Gas Charging done										
e	Routine Service - Wet										
f	Routine Service - DRY										
Customer Impression about Service											
(Please rate on scale of 1 poor, 2, 3, 4 & 5 excellent)											
How is the behavior of visited engineer											
What is the level of your satisfaction											
How is the explanation by Engineer											
Name Signature											