

DAIKIN
DAIKIN AIRCONDITIONING INDIA PVT. LTD.

Authorised Service Center

AEON AIRCONDITIONING SOLUTIONS

AEON HOUSE, SHOP NO. 6/7, BEHIND N CUBE CHINA TOWN

DR. AMBEDKAR ROAD, THANE W-400601 MAHARASHTRA. PHONE : 02225370101 / 7900097007


 PROJECT -> GUWAHATI BANDHAN BANK KAHILI PARA
Measurement Sheet

Sr. No.	Location	AC Type	Tonnage	Indoor Unit Details		Outdoor Unit Details		Copper In Rmt	Cable In Rmt	Drain In Rmt	ODU Stand
				Model No.	Sr. No.	Model No.	Sr. No.				
1	WATER MACHIN ROOM	SPLIT	1.5(T)	FK150UV16	8097363	RKL50UV16VAF	8269637	12. M	12. M	12. M	1
2	WORK AREA	CASSETTE	2. (T)	FCQF24AR	0075591	RGVF24AS	0075685	18. M	10. M	8. M	1
3	II	II	2. (T)	FCQF24AR	0075594	RGVF24AS	0078080	14. M	15. M	7. M	1
4	II	II	2. (T)	FCQF24AR	0075593	RGVF24AS	0075691	11. M	12. M	9. M	1
5											
6											
7											
8											

EXTRA ACTIVITY CARRIED OUT

CIVIL WORK	Stabilizer			TIMER	CASING CAPPING	CABLE TRAY	GAS CHARGING	DISMENTALING		RE-INSTALLATION
	3KVA	4KVA	5KVA					H. Wall	Cassette	

OTHERS

Three Cassette and one Split ac installations and one water pump. Three core capping and 2m wall capping and filling.

 Vendor Details: Aeon Airconditioning Solutions

For Customer Details:

 Sign: SUDIP HAZRA

Signature:

 Name: SUDIP HAZRA

Technician Name:

SK. Noxibul

 Date: 16.10.2025

Stamp:

Date:

DAIKIN

DAIKIN AIRCONDITIONING INDIA PVT. LTD. Service Completion Certificate


AEON AIRCONDITIONING SOLUTIONS

 Office No. 105 & 106, Durgam Chaudhary Complex,
 4th Floor, 1st Main, 1st Cross, 1st Stage, 4th Cross, 4th Stage,
 Bangalore - 560025.

1415

Serial No.

Registration No.		Request Date		Service Engineer		Service Date/Time		Service Center	
BANDHAN BANK		At: UWAHATI KALLIRARA		Excavation & Installation of Unit		Unit Type		Unit Capacity	
Customer Address		Date: 17/10/25		Unit Type		Unit Type		Unit Capacity	
Type: A/C		Date: 17/10/25		Unit Type		Unit Type		Unit Capacity	
Model No.		Manufacturer's No.		Unit Type		Unit Type		Unit Capacity	
RGVF24ASY16		0072080		Unit Type		Unit Type		Unit Capacity	
FCQF24AR16		0075594		Unit Type		Unit Type		Unit Capacity	
Work Done		Remarks		Unit Type		Unit Type		Unit Capacity	
COPPER PIPE 1/4" (M) and main		COPPER PIPE 1/4" (M) and main		Unit Type		Unit Type		Unit Capacity	
CABLE (1/2" M) and drain (1/2" M)		CABLE (1/2" M) and drain (1/2" M)		Unit Type		Unit Type		Unit Capacity	
and one outdoor stand.		and one outdoor stand.		Unit Type		Unit Type		Unit Capacity	
Machine wiring colling OK.		Machine wiring colling OK.		Unit Type		Unit Type		Unit Capacity	
Signature: Zunaib Shaiikh		Signature: Z.S		Unit Type		Unit Type		Unit Capacity	
Signature: Sudip Hazra		Signature: Sudip Hazra		Unit Type		Unit Type		Unit Capacity	
Customer Signature		Customer Signature		Unit Type		Unit Type		Unit Capacity	
Signature: Sudip Hazra		Signature: Sudip Hazra		Unit Type		Unit Type		Unit Capacity	



DAIKIN AIRCONDITIONING INDIA PVT. LTD.
Service Completion Certificate

AEDN AIRCONDITIONING SOLUTIONS

AEON JAPAN CO., LTD.
1-1-1, Higashi-Shinjyuku, Shinjyuku-Ku, Tokyo 162-8601, Japan
Tel: 03-3342-1111 Fax: 03-3342-1112

1415

Customer Name		Model No.		Service Engineer		Scheduled Date/Time		Service Order	
BANDHAN BANK				BANK				Fast Tag/Model	
MUMBAHATI KAHILIPARA								✓	
Basic Machine				Electrical (Wiring/Control)		Mechanical (Parts/Assembly)		Safety (Guarding)	
Date of Purchase				Date of Installation		Date of Service		Date of Completion	
17/10/25				17/10/25		17/10/25		17/10/25	
Machine No.				Serial No.		Model No.		Capacity	
RGVF24ASV16 0075691				ECQF24ARV16 0075593					
Description of Work				Faults/Defects		Cause of Faults		Remedy/Action	
COPPER PAIR (12m) and wire cable 12(m) and drain pair 9m and one outdoor stand machine panning colling box				No Faults		No Cause		No Action	
Work Done/Remarks				Time Spent		Cost of Materials		Total Cost	
Zunaid Shaikh				2.5					
SUDIP HAZRA									
Sudip Hazra									

DAIKIN

DAIKIN AIRCONDITIONING INDIA PVT. LTD. Service Completion Certificate


AEON AIRCONDITIONING SOLUTIONS

 Office No. 106 & 108, Tawakkul Garden, Commercial Complex,
 P.W. Quarters Marg, above Sharda City, Pusa Park, Thane - 400001
 Mob: 9822341017 / 9822341018

1415

Subject:

Registration No.	Repair Date	Service Engineer	Scheduled Date/Time	Service Order
------------------	-------------	------------------	---------------------	---------------

 User: **BANDHAN BANK**
 Customer Address: **GUWAHATI KAMILIPARA**

(Bank Address)

DAIKIN Invoice:

Dealer Invoice:

Type:

Model No:

Manufacturing No:

Outdoor unit:

RKL50UV16VAF
826963

Indoor unit:

FTKL50UV16VAF
8097363

Work Date:

No. of S.S:

Work hours:

Progress code:

Details of the Repair Work:

 copper pipe 28m and drain pipe
 cable (2m) and drain pipe
 12(m) and one outdoor stand
 machine piping colling ok.

Compressor manufacturing No:

Defective Compressor:

Replacement Compressor:

Installed date:

Warranty:

AMC:

Usage with:

Fault location:

Phenomena code:

Error code:

Yes / No:

Yes / No:

Yes / No:

Yes / No:

Yes / No:

Yes / No:

Yes / No:

Service Engineer Remarks:

Name:

Zunaid Shaikh

Signature:

Z.S

Customer Remarks:

SUDIP HAZRA

Name:

Sudip Hazra

Customer Impression about Service

(Please rate on scale of 1 point 2, 3, 4 & 5 excellent)

How is the behavior of service engineer?

What is the level of your satisfaction?

How is the explanation by Engineer?

a) Single Repair

b) Part Replaced

c) Part Replaced

d) Gas Charging Done

e) Routine Service - 1st

f) Routine Service - 2nd

Details of Repair Work Done

Fault Checked:

☒

Power Failure

Phase Reverse

In door unit PCB Defective

Out door PCB Defective

In door unit Fan Motor Defective

Outdoor Fan Motor Defective

Comp taking High Current / Amp

Compressor Ground / Earth

Compressor tripping due to High Temperature

Compressor tripping due to high pressure

Indoor Unit Midge Defective

Outdoor Unit Midge Defective

Indoor Unit Transformer Faulty

Outdoor Unit Transformer Faulty

Fault of swing Motor

Defect of Drain Pump

Expansion Valve Body / Motor Defective

Defective Temperature Sensor of Indoor Unit

Defective Temperature Sensor of Outdoor Unit

Defective Current Sensor in Out door Unit

Gas Leakage at Indoor Unit

Gas Leakage at Outdoor Unit

Blower broken

Short Cycling of Air at Indoor Unit

Short Cycling of Air at Outdoor Unit

Defect in Drain piping system

Gas leakage from Panel nut

Error in Transmission wiring

Product under capacity

Rat bite case

Leak cooling problem due to dirty Airfilter

Remote setting changed

Clogged Compressor

Other - If specify