



AEON AIRCONDITIONING SOLUTIONS

Aeon House, Shop No. 6/7, Behind N Cube China Town, Opp. Shishu Dnyan Mandir,
 Dr. Ambedkar Rd. Thane 400 601. Maharashtra
 Tel. : 022 - 25370101 / 7900097007
 e-mail : services@aeonacsolutions.com website : www.aeonacsolutions.com

415

Project : Indusind Nippon Life Insurance Co. Ltd.

Additional Measurement Sheet

Sr. No	Location	AC Type	Tonnage	Indoor Unit Details		Outdoor Unit Details		Copper In Rmt	Cable In Rmt	Drain In Rmt	ODU Stand
				Model No.	Sr. No.	Model No.	Sr. No.				
1	SND.	CASSETTE	3.5	FCQF42ARV16	3703	RGVF42BSY16	2002	12.1	25	02	—
2											
3											
4											
5											
6											
7											
8											

Extra Activity Carried Out


Civil Work	Stabilizer			Timer	Casing Capping	Cable Tray	Gas Charging	Dismantling		Re-installation
	3KVA	4KVA	5KVA					Hi Wall	Cassette	
									01	

Others nitrogen testing and Flaring and vacuum / Gas charging in existing

For				Vendor Details	<u>AEON</u>
Sign	<u>[Signature]</u>			Signature	<u>[Signature]</u>
Name	<u>Seema K</u>			Technician Name	<u>Fir02</u>
Date	<u>25/02/2026</u>			Date	<u>25/02/2026</u>



Stamp



Subject: Installation

Registration No.		Request Date		Service Engineer		Scheduled Date/Time		Service Order	
				Firoz					
User: <u>Indusind Nippon Life</u> Mobile:				Operation data (Ambient temp. °C)		Fault Diagnosed			
Customer Address: <u>1004 10th floor opal square</u>				Before repair		After repair		Power	
I Base Address: <u>C-1 waghle Estate Thane</u>				HP/T		psig/		PSB	
Daikin Invoice: Date:				SP/T °C		psig/°C		EM	
Dealer Invoice: Date:				Current °C		Amps °C		Comp	
Type	Model No		Manufacturing No.		Voltage		Indoor temperature		Electrical
Outdoor unit /	<u>RG6F42BSY16</u>		<u>2002</u>		Volts		°C		
Indoor unit	<u>FCQE42ARV16</u>		<u>3703</u>		Suction		°C		
Work Date	No. of S.E.	Work hours	Progress code	Details of the Repair Work		Discharge		°C	
<u>25</u>				<u>Installation done now A/C working cooling fine.</u>		Outdoor temperature		°C	
<u>02</u>						Suction		°C	
<u>26</u>						Discharge		°C	
Compressor manufacturing No.		Defective Compressor		Replacement Compressor		Work No / Parts No		Qty	
Installed date	Warranty	AMC	Using with		Fault location	Phenomena code	Error code		
	Yes / No	Yes / No	Stabilizer	Cut off					
			Yes / No	Yes / No					
Service Engineer Remarks									
Name: <u>Firoz + Naem</u>									
Signature:									
Customer Remarks									
Name: <u>Seema k</u>									
Signature:									
Customer Impression about Service									
(Please rate on scale of 1 poor, 2, 3, 4 & 5 excellent)									
How is the behavior of visited engineer					a Simple Repair				
What is the level of your satisfaction					b Part Replaced				
How is the explanation by Engineer					c Part Repaired				
					d Gas Charging done				
					e Routine Service - Wet				
					f Routine Service - DRY				
Total									
Coder: <u>Coder</u>									
Details of Repair Work Done									
Gas Leakage at Indoor Unit									
Gas Leakage at Outdoor Unit									
Blower broken									
Short Cycling of Air at Indoor Unit									
Short Cycling of Air at Outdoor Unit									
Defect in Drain piping System									
Gas Leakage from Flare nut									
Error in Transmission wiring									
Product under capacity									
Rat bite case									
Less cooling problem due to dirty Airfilter									
Remote setting changed									
Clogged Condenser									
Other - Pl. specify									

