



AEON AIRCONDITIONING SOLUTIONS
Aeon House, Shop No. 6/7, Behind H Cube Chye Town, Opp. Shishu Dhyani Mandir,
Dr. Ambedkar Rd. Thane - 400 001, Maharashtra
Tel : 022 - 25310101 / 2500091001
e-mail : services@aeonacsolutions.com website : www.aeonacsolutions.com

Project :

Additional Measurement Sheet

Sr. No	Location	AC Type	Tonnage	Indoor Unit Details		Outdoor Unit Details		Copper In Rmt	Cable In Rmt	Drain In Rmt	ODU Stand
				Model No.	Sr. No.	Model No.	Sr. No.				
1		Split		RKM60V	0042823	FTKM60UV	0033477	15	16	6	1
2				V16U		16U					
3											
4											
5											
6											
7											
8											

Extra Activity Carried Out

Civil Work	Stabilizer			Timer	Casing Capping	Cable Tray	Gas Charging	Dismantling		Re-installation
	3KVA	4KVA	5KVA					Hi Wall	Cassette	
	4							1		
Others	4	MRACON TAP								

For						Vendor Details	
Sign						Signature	
Name	munesh mehan Sawant					Technician Name	Ajeet
Date	23/01/25					Date	23-1-2025



DAIKIN AIRCONDITIONING INDIA PVT. LTD.

Service Completion Certificate



AEON AIRCONDITIONING SOLUTIONS

Office No. 108 & 109, Dewshree Garden, Commercial Complex,
R.W. Swami Marg, above Shree Sai, Raju Park, Thane - 400 601.
Mob: 922234107 / 922234108

712

Subject:

Registration No.		Request Date		Service Engineer		Scheduled Date/Time		Service Order	
User: Nitesh Hiraji blue dart express		Customer Address: blue dart express navneet education		Operation data (Ambient temp. °C)		28-3-2025		Fault Diagnosed	
Base Address: 32 Lianie infra road M.I.D.C. andheri (E) 400093		Date: 28/3/25		Before repair		After repair		Power Failure	
Dealer Invoice:		Date:		HP/T		HP/T		Phase Reverse	
Dealer Invoice:		Date:		SP/T °C		SP/T °C		In door unit PCB Defective	
Type:		Model No:		Current °C		Amps °C		Out door PCB Defective	
Outdoor unit: R32 R160V16U		Manufacturing No: 0042823		Voltage		Voltage		In door unit Fan Motor Defective	
Indoor unit: EKFTKM60U16U		Manufacturing No: 0029477		Indoor temperature		Indoor temperature		Outdoor Fan Motor Defective	
Work Date: 28/3/25		No. of E.E.		Discharge		Discharge		Comp. taking High Current / Amp	
Work hours:		Progress code:		Section		Section		Compressor Ground / Earth	
Details of the Repair Work:		Installation : Done		Outdoor temperature		Outdoor temperature		Compressor tripping due to High Temperature	
		and calling : Done		Discharge		Discharge		Compressor tripping due to High Pressure	
Compressor manufacturing No:		Defective Compressor		Work No / Parts No		Qty		Billing Amount	
Installed date:		Warranty		Fault location		Fault location		Fault location	
Yes / No		Yes / No		Yes / No		Yes / No		Yes / No	
Service Engineer Remarks:		Signature: [Signature]		Total		Total		Total	
Customer Remarks:		A/C working fine		Customer Impression about Service		Customer Impression about Service		Customer Impression about Service	
Signature: [Signature]		Signature: [Signature]		How is the behavior of visited engineer		How is the behavior of visited engineer		How is the behavior of visited engineer	
				What is the level of your satisfaction		What is the level of your satisfaction		What is the level of your satisfaction	
				How is the explanation by Engineer		How is the explanation by Engineer		How is the explanation by Engineer	