

314 DAIKIN AIRCONDITIONING INDIA PVT. LTD.
Service Completion Certificate



AEON AIRCONDITIONING SOLUTIONS

Office No. 108 & 109, Devashree Garden, Commercial Complex,
R.W. Swarn Marg, above Sheetal Dairy, Rulu Park, Thane - 400 601.
Mob: 9322334107 / 9322334109

Subject :

Registration No.		Request Date		Service Engineer		Scheduled Date/Time		Service Order	
		11/12/25		Akram					
User: Cosmos Bank				Mobile:					
Customer Address: Santacruz East				Operation data (Ambient temp. °C)					
I Base Address:				Before repair		After repair		Fault Diagnosed	
Daikin Invoice:				HP / T	psig'	psig'	Power	Power Failure	
Dealer Invoice:				SP / T °C	psig"°C	psig"°C	PCB	Phase Reverse	
Type				Current °C	Amps°C	Amps°C	EM	In door unit PCB Defective	
Outdoor unit / Indoor unit				Voltage	Volts	Volts	Comp	Out door PCB Defective	
Model No. Manufacturing No.				Indoor temperature				In door unit Fan Motor Defective	
RKL600V16V 8031613				Suction °C °C				Outdoor Fan Motor Defective	
F+K600V16V 8022923				Discharge °C °C				Comp. taking High Current / Amp	
Work Date No. of S.E. Work hours Progress code				Outdoor temperature				Compressor Ground / Earth	
11				Suction °C °C				Compressor tripping due to High Temperature	
12				Discharge °C °C				Compressor tripping due to High Pressure	
25				Suction °C °C				Indoor Unit MgsW Defective	
Details of the Repair Work				Discharge °C °C				Outdoor Unit MgsW Defective	
200 Ton Daikin A/c Installation				Outdoor temperature				Indoor Unit Transformer Faulty	
Compressor manufacturing No.				Suction °C °C				Out door Unit Transformer Faulty	
Defective Compressor Replacement Compressor				Discharge °C °C				Fault of swing Motor	
Installed date Warranty AMC Using with Stabilizer Cut off Fault location Phenomena code Error code				Work No / Parts No Qty Billing Amount				Defect of Drain Pump	
Yes / No Yes / No Yes / No Yes / No				Installation 1				Expansion Valve Body / Motor Defective	
				Uninstallation 1				Defective Temperature Sensor of Indoor Unit	
				Copper 6 mtr				Defective Temperature Sensor of Outdoor Unit	
				Cable 6 mtr				Defective Current Sensor In Outdoor Unit	
Service Engineer Remarks				Total				Gas Leakage at Indoor Unit	
cooling is fine								Gas Leakage at Outdoor Unit	
Name Akram Signature								Blower broken	
								Short Cycling of Air at Indoor Unit	
								Short Cycling of Air at Outdoor Unit	
								Defect in Drain piping System	
								Gas Leakage from Flare nut	
								Error in Transmission wiring	
								Product under capacity	
								Rat bite case	
								Less cooling problem due to dirty Airfilter	
								Remote setting changed	
								Clogged Condenser	
								Other - Pl. specify	
Customer Remarks				Customer Impression about Service				Details of Repair Work Done	
Installation done				(Please rate on scale of 1 poor, 2, 3, 4 & 5 excellent)				a Simple Repair	
				How is the behavior of visited engineer				b Part Replaced	
				What is the level of your satisfaction				c Part Repaired	
				How is the explanation by Engineer				d Gas Charging done	
								e Routine Service - Wet	
								f Routine Service - DRY	

Mithun Pawar
Signature
PMV 4440