



AEON AIRCONDITIONING SOLUTIONS

Aeon House, Shop No. 6/7, Behind N Cube China Town, Opp. Shishu Dnyan Mandir,
Dr. Ambedkar Rd. Thane 400 601. Maharashtra
Tel. : 022 - 25370101 / 7900097007
e-mail : services@aeonacsolutions.com website : www.aeonacsolutions.com

048

Project : Blue Dart - Nariman point, Mumbai.

Additional Measurement Sheet

Sr. No	Location	AC Type	Tonnage	Indoor Unit Details		Outdoor Unit Details		Copper In Rmt	Cable In Rmt	Drain In Rmt	ODU Stand
				Model No.	Sr. No.	Model No.	Sr. No.				
1	Work Area	SPLIT	1.5	FTKM50V16V	8195713	RKM50V16V	8257891	45ft	45ft		fabricated
2	Work Area	SPLIT	2.0	M7KM60VV	0001567	RKM60V16V	0034270	40ft	44ft	40ft	fabricated
3				16V							Cage
4											
5											
6											
7											
8											

Extra Activity Carried Out

Civil Work	Stabilizer			Timer	Casing Capping	Cable Tray	Gas Charging	Dismantling		Re-installation
	3KVA	4KVA	5KVA					Hi Wall	Cassette	
								02 nos		

Others

For

Sign

Name

Date

Blue Dart
Sunil Jadhav



Stamp

Vendor Details

Signature

Technician Name

Date

Aeon Airconditioning Solutions

Shoeb Adhikari

05/11/2025



IKIN

968 DAIKIN AIRCONDITIONING INDIA PVT. LTD.

Service Completion Certificate

BeOn

AEON AIRCONDITIONING SOLUTIONS

Office No. 108 & 109, Devashree Garden, Commercial Complex,
R.W. Swaant Marg, above Sheetal Dairy, Ritu Park, Thane - 400 601.
Mob.: 9322334107 / 9322334109

Subject :

Registration No.		Request Date		Service Engineer		Scheduled Date/Time		Service Order	
User :				Mobile :				Operation data (Ambient temp. °C)	
Customer Address : <i>Q/116 Datt Express Ltd</i>				HP / T				Before repair	After repair
I Base Address : <i>910 EMBASSY CENTRE Nariman Point Mumbai</i>				SP / T °C				psig/	psig/
Daikin Invoice :				Date :				psig/°C	psig/°C
Dealer Invoice :				Date :				Current °C	Amps °C
Type		Model No		Manufacturing No.		Voltage		Volts	Volts
Outdoor unit /		RKM50W16VH 8257891				Suction		°C	°C
Indoor unit		ETK050W16VH 8195713				Discharge		°C	°C
Work Date	No. of S.E.	Work hours	Progress code	Details of the Repair Work					
6/11/25				COPPER PIPE 45FT Added Cable wire wrapping Tape 3 piece					
Compressor manufacturing No.		Defective Compressor		Replacement Compressor		Work No / Parts No		Qty	Billing Amount
Installed date	Warranty	AMC	Using with	Fault location	Phenomena code	Error code			
Yes / No	Yes / No	Yes / No	Yes / No						
Service Engineer Remarks									
<i>Chaitan Adhikari</i> Name: _____ Signature: _____									
Customer Remarks									
<i>Sunil Jadhav</i> Name: _____ Signature: _____									
Customer Impression about Service									
(Please rate on scale of 1 poor, 2, 3, 4 & 5 excellent)									
How is the behavior of visited engineer									
What is the level of your satisfaction									
How is the explanation by Engineer									
a Simple Repair b Part Replaced c Part Repaired d Gas Charging done e Routine Service - Wet f Routine Service - DRY									
Fault Diagnosed Power Failure Phase Reverse In door unit PCB Defective Out door PCB Defective In door unit Fan Motor Defective Outdoor Fan Motor Defective Comp. taking High Current / Amp Compressor Ground / Earth Compressor Tripping due to High Temperature Compressor tripping due to High Pressure Indoor Unit MgSw Defective Outdoor Unit Mgsw Defective Indoor Unit Transformer Faulty Out door Unit Transformer Faulty Fault of swing Motor Defect of Drain Pump Expansion Valve Body / Motor Defective Defective Temperature Sensor of Indoor Unit Defective Temperature Sensor of Outdoor Unit Defective Current Sensor In Out door Unit Gas Leakage at Indoor Unit Gas Leakage at Outdoor Unit Blower broken Short Cycling of Air at Indoor Unit Short Cycling of Air at Outdoor Unit Defect in Drain piping System Gas Leakage from Flare nut Error In Transmission wiring Product under capacity Rat bite case Less cooling problem due to dirty Airfilter Remote setting changed Clogged Condenser Other - Pl. specify									
Details of Repair Work Done a Simple Repair b Part Replaced c Part Repaired d Gas Charging done e Routine Service - Wet f Routine Service - DRY									

Daikin Customer Care : Missed Call or SMS <DAIKIN> to 92101 88999 ; Toll Free Number : 1860 180 3900 / 1800 102 9300 ; cs@daikinindia.com / www.daikinindia.com



Scanned with OKEN Scanner