



DAIKIN AIRCONDITIONING INDIA PVT. LTD.

Authorised Service Center

AEON AIRCONDITIONING SOLUTIONS

AEON HOUSE, SHOP NO. 6/7, BEHIND N CUBE CHINA TOWN

DR. AMBEDKAR ROAD, THANE W 400601 MAHARASHTRA. PHONE :- 02225370101 / 7900097007



PROJECT :- Bandhan Bank, Abhayapuri, Dist- Bongaigaon stn- Assam pin- 781384

Measurement Sheet

Sr. No.	Location	AC Type	Tonnage	Indoor Unit Details		Outdoor Unit Details		Copper In Rmt	Cable In Rmt	Drain In Rmt	ODU Stand
				Model No.	Sr. No.	Model No.	Sr. No.				
1	Assistant Branch	SPLIT	1.5 TR	FTKL50UV16V AF	8101033	RKL50UV16V AF	8270435	5 (m)	8 (m)	8 (m)	1 PCS
2	Customer Relation	SPLIT	1.5 TR	FTKL50UV16V AF	8109174	RKL50UV16V AF	8270001	2 (m)	4 (m)	8 (m)	1 PCS
3	Branch Head	SPLIT	1.5 TR	FTKL50UV16V AF	8121311	RKL50UV16V AF	8269634	2 (m)	4 (m)	8 (m)	1 PCS
4	Teller Room	SPLIT	1.5 TR	FTKL50UV16V AF	8109175	RKL50UV16V AF	8269638	2 (m)	4 (m)	8 (m)	1 PCS
5											
6											
7											
8											

EXTRA ACTIVITY CARRIED OUT

CIVIL WORK	Stabilizer			TIMER	CASING CAPPING	CABLE TRAY	GAS CHARGING	DISMENTALING		RE-INSTALLATION
	3KVA	4KVA	5KVA					Hi Wall	Cassette	
								✓		
OTHERS	2 corthing, 142 Kg... IRON CAGE,									

For Customer Details:

Vendor Details: AEON AIRCONDITIONING SOLUTIONS

Sign: Jiten Das 104998

Signature: Jalal Gayen

Name: JITEN DAS

Technician Name: JALAL GAYEN

Date: 9/12/25

Stamp:



Date: 9/12/25

WORLD

Office No. 105 & 109, Dewangan Garden, Commercial Complex,
F.W. Daudat Marg, above Shreeast Dairy, Paldi Park, Thane - 405 001
Mob: 9822234107 / 9822234100

Subject

Registration No.		Request Date		Service Engineer		Scheduled Date/Time		Service Order	
User : Bandhan Bank		Mobile :		Operation date (Ambient temp. °C)		Fault Diagnosed			
Customer Address : Abhayapuri				Before repair		After repair		☒	
Basic Address :				HP / T		psig/		psig/	
Daksh Invoice :		Date :		SP / T °C		psig°C		psig°C	
Dealer Invoice :		Date :		Current °C		Amps°C		Amps°C	
Type	Model No.	Manufacturing No.		Voltage	Volts	Volts			
Outdoor unit /	RK250UVI6VAF	8269634		Indoor temperature					
Indoor unit	FTKL50UVI6VAF	8121311		Suction	°C		°C		
Work Date	No. of S.E.	Work hours	Progress code	Details of the Repair Work		Discharge	°C		
						Outdoor temperature			
						Suction	°C		
						Discharge	°C		
						Work No / Parts No	Qty	Billing Amount	
Compressor manufacturing No.				Defective Compressor		Replacement Compressor			
Installed date		Warranty	AMC	Using with Stabilizer	Cut off	Fault location	Phenomena code	Error code	
Yes / No		Yes / No	Yes / No	Yes / No	Yes / No				
Service Engineer Remarks : Installation commission and Rainy add calling Ok.									
Name : JALAL GHAYEN Signature : Jalal									
Customer Remarks : Station 104998									
Signature : [Circular Stamp: Bandhan Bank Ltd. Abhayapuri Branch]									
Customer Impression about Service (Please rate on scale of 1 poor, 2, 3, 4 & 5 excellent)									
How is the behavior of visited engineer									
What is the level of your satisfaction									
How is the explanation by Engineer									
a Simple Repair									
b Part Replaced									
c Part Repaired									
d Gas Charging done									
e Routine Service - Well									
f Routine Service - DRY									
Details of Repair Work Done									
☒									

DAIKIN

DAIKIN AIRCONDITIONING INDIA PVT. LTD. Service Completion Certificate

aeon
1415
AEON AIRCONDITIONING SOLUTIONS

 Office No. 105 & 106, Deveshree Garden, Commercial Complex,
 F.W. Dey Road, above Shree Dey, Pusa Park, Thane - 400 021
 Mobile : 932234107 / 932234108

Subject:

Registration No.		Request Date		Service Engineer		Scheduled Date/Time		Service Order			
User: Banbhan Bank				Mobile:		Operation data (Ambient temp. °C)		Fault Diagnosed			
Customer Address: Abhayopuri						Before repair After repair HP / T poly/ poly/ SP / T °C poly°C poly°C Current °C Amps°C Amps°C Voltage Volts Volts		Power Failure Phase Reverse In door unit PCB Defective Out door PCB Defective In door unit Fan Motor Defective Outdoor Fan Motor Defective Comp. taking High Current / Amp Compressor Ground / Earth Compressor Tripping due to High Temperature Compressor tripping due to high pressure Indoor Unit Mgrw Defective Outdoor Unit Mgrw Defective Indoor Unit Transformer Faulty Out door Unit Transformer Faulty Fault of swing Motor Defect of Drain Pump Expansion Valve Body / Motor Defective Defective Temperature Sensor of Indoor Unit Defective Temperature Sensor of Outdoor Unit Defective Current Sensor in Out door Unit Gas Leakage at Indoor Unit Gas Leakage at Outdoor Unit Blower broken Short Cycling of Air at Indoor Unit Short Cycling of Air at Outdoor Unit Defect in Drain piping System Gas Leakage from Flare nut Error in Transmission wiring Product under capacity Rat bite case Less cooling problem due to dirty Airfilter Remote setting changed Clogged Condenser Other - Pl. specify			
Base Address:						Indoor temperature Suction °C °C Discharge °C °C Outdoor temperature Suction °C °C Discharge °C °C		PCB EM Compo Electrical Unit Installation Other			
Daikin Invoice:		Date:		Current °C		Amps°C					
Dealer Invoice:		Date:		Voltage		Volts					
Type	Model No.		Manufacturing No.		Suction		°C				
Outdoor unit /	R R K L 50 U V I 6 V A F		827000 /		Discharge		°C				
Indoor unit	F T K L 50 U V I 6 V A F		8109174		Work No / Parts No		Qty		Billing Amount		
Work Date	No. of S.E.	Work hours	Progress code	Details of the Repair Work		Total					
Compressor manufacturing No.		Defective Compressor		Replacement Compressor							
Installed date	Warranty	AMC	Using with Stabilizer	Fault location	Phenomena code						
	Yes / No	Yes / No	Yes / No	Yes / No							
Service Engineer Remarks: Installation commissioning and Raising and calling ok.											
Name: JALAL GAYEN											
Customer Remarks: Signature											
Name: 104998											
Customer Impression about Service (Please rate on scale of 1 poor, 2, 3, 4 & 5 excellent)											
How is the behavior of visited engineer											
What is the level of your satisfaction											
How is the explanation by Engineer											
a Simple Repair b Part Replaced c Part Replaced d Gas Charging done e Routine Service - Well f Routine Service - DRY											
Details of Repair Work Done											

DAIKIN

DAIKIN AIRCONDITIONING INDIA PVT. LTD. Service Completion Certificate

AEON AIRCONDITIONING SOLUTIONS
1415

 Office No. 105 & 106, Dewashree Garden, Commercial Complex,
 N.W. Sweets Marg, above Shree Lal Ganga, Pusa Park, Thane - 400 001
 Mob.: 9322204107 / 9322204108

Subject:

Registration No.	Request Date	Service Engineer	Scheduled Date/Time	Service Order
------------------	--------------	------------------	---------------------	---------------

 User: **Bandhan Bank**
 Customer Address: **Abhayapuri**

Mobile:

Base Address:

Daikin Invoice:

Date:

Dealer Invoice:

Date:

Type	Model No.	Manufacturing No.
Outdoor unit /	RKL50UV16VAF	8270435
Indoor unit	FTKL50UV16VAF	8101033

Work Date	No. of S.E.	Work hours	Progress code

Details of the Repair Work

Operation data (Ambient temp. °C)

	Before repair	After repair
HP / T	psig	psig
SP / T °C	psig°C	psig°C
Current °C	Amps°C	Amps°C
Voltage	Volts	Volts

Fault Diagnosed

PCB	Power Failure	☒
	Phase Reverse	
	Indoor unit PCB Defective	
	Out door PCB Defective	
	In door unit Fan Motor Defective	
	Outdoor Fan Motor Defective	
	Comp. taking High Current / Amp	
	Compressor Ground / Earth	
	Compressor tripping due to High Temperature	
	Compressor tripping due to High Pressure	
EM	Indoor Unit M/Sw Defective	
	Outdoor Unit M/Sw Defective	
	Indoor Unit Transformer Faulty	
	Out door Unit Transformer Faulty	
	Fault of wiring Motor	
	Defect of Drain Pump	
	Expansion Valve Body / Motor Defective	
	Defective Temperature Sensor of Indoor Unit	
	Defective Temperature Sensor of Outdoor Unit	
	Defective Current Sensor in Out door Unit	
Comp	Gas Leakage at Indoor Unit	
	Gas Leakage at Outdoor Unit	
	Blower broken	
	Short Cycling of Air at Indoor Unit	
	Short Cycling of Air at Outdoor Unit	
	Defect in Drain piping System	
	Gas Leakage from Flare nut	
	Error in Transmission wiring	
	Product under capacity	
	Flat bite case	
Electrical	Less cooling problem due to dirty Airfilter	
	Remote setting changed	
	Clogged Condenser	
	Other - PL specify	
Unit		
Installation		
Other		

Work No / Parts No Qty Billing Amount

Total

Details of Repair Work Done

Compressor manufacturing No.		Defective Compressor		Replacement Compressor	
Installed date	Warranty	AMC	Using with	Fault location	Phenomena code
			Stabilizer Cut off		
	Yes / No	Yes / No	Yes / No	Yes / No	

 Service Engineer Remarks: **Installation Commissioning and Running and calling OK.**

Name

JALPINDER SINGH

Signature

Customer Remarks

Name

Signature



Customer Impression about Service

(Please rate on scale of 1 poor, 2, 3, 4 & 5 excellent)

How is the behavior of visited engineer	
What is the level of your satisfaction	
How is the explanation by Engineer	

a	Simple Repair	
b	Part Replaced	
c	Part Repaired	
d	Gas Charging done	
e	Routine Service - Wet	
f	Routine Service - DRY	

DAIKIN

DAIKIN AIRCONDITIONING INDIA PVT. LTD. Service Completion Certificate

Reg
AEON AIRCONDITIONING SOLUTIONS
1415

 Office No. 108 & 109, Commercial Garden, Commercial Complex
 P.W. Sagar Marg, Above Shree Ganga Park, Thane - 401 001
 Mob. : 922234 107 / 922234 108

Subject:

Registration No.	Request Date	Service Engineer	Scheduled Date/Time	Service Order
------------------	--------------	------------------	---------------------	---------------

 User: **Bandhan Bank**
 Customer Address: **Ab halapuri**

Mobile:

Operation data (Ambient temp. °C)

Fault Diagnosis

I Bank Address:

Before repair After repair

Power

Phase Reverse

In door unit PCB Defective

Out door PCB Defective

In door unit Fan Motor Defective

Outdoor Fan Motor Defective

Comp. taking High Current / Amp

Compressor Ground / Earth

Compressor Tripping due to High Temperature

Compressor tripping due to High Pressure

Indoor Unit Mfg. Defective

Outdoor Unit Mfg. Defective

Indoor Unit Transformer Faulty

Out door Unit Transformer Faulty

Fault of swing Motor

Defect of Drain Pump

Expansion Valve Body / Motor Defective

Defective Temperature Sensor of Indoor Unit

Defective Temperature Sensor of Outdoor Unit

Defective Current Sensor in Out door Unit

DAIKIN Product:

Date:

Dealer Invoice:

Date:

Type:

Model No.

Manufacturing No.

Outdoor unit /

RK250UV16 VAF
826938

Indoor unit

FTKL50UV16 VAF
8109175

Work Date:

No. of S.E.

Work hours:

Progress code:

Details of the Repair Work

Suction

°C

°C

Discharge

°C

°C

Outdoor temperature

Suction

°C

°C

Discharge

°C

°C

Work No / Parts No

Qty

Billing Amount

Unit

Gas Leakage at Indoor Unit

Gas Leakage at Outdoor Unit

Blower broken

Short Cycling of Air at Indoor Unit

Short Cycling of Air at Outdoor Unit

Defect in Drain piping System

Gas Leakage from Flare nut

Error in Transmission wiring

Product under capacity

Rat bite case

Less cooling problem due to dirty A/C filter

Remote setting changed

Clogged Condenser

Other - Pl. specify

Other

Details of Repair Work Done

✓

Compressor manufacturing No.

Defective Compressor

Replacement Compressor

Installed date

Warranty

AMC

Using with

Fault location

Phenomena code

Error code

Yes / No

Yes / No

Yes / No

Yes / No

Yes / No

Yes / No

Yes / No

Service Engineer Remarks

Installation
commission and Repairing calling OK.

Name

JALAL GIDYEN

Signature

Jalal

Customer Remarks

Get on 104998

Signature

Customer Impression about Service

(Please rate on scale of 1 poor, 2, 3, 4 & 5 excellent)

How is the behavior of visited engineer

What is the level of your satisfaction

How is the explanation by Engineer

a Simple Repair

b Part Replaced

c Part Repaired

d Gas Charging done

e Routine Service - Wet

f Routine Service - Dry