



# AEON AIRCONDITIONING SOLUTIONS

Aeon House, Shop No. 6/7, Behind N Cube China Town, Opp. Shishu Dnyan Mandir,  
Dr. Ambedkar Rd. Thane 400 601. Maharashtra  
Tel. : 022 - 25370101 / 7900097007

313

e-mail : services@aeonacsolutions.com website : www.aeonacsolutions.com

Project : City Union Bank - Shankar Darghan CHS 15th Road Chembur East

## Additional Measurement Sheet

Sr. No	Location	AC Type	Tonnage	Indoor Unit Details		Outdoor Unit Details		Copper In Rmt	Cable In Rmt	Drain In Rmt	ODU Stand
				Model No.	Sr. No.	Model No.	Sr. No.				
1	WORK AREA	Cassett	2TR	FCVF0100AV16	0008432	RZVF0100AV16	0010177	30	32	14	} Double Decker Stand
2	WORK AREA	Cassett	2TR	FCVF71ARV169	0003136	RZVF71BRV169	0004925	28	30	20	
3	Manages	Hi Wall	1. TR	FTKC35XV16WAA	8000120	RKC35XV16WAA	8001010	30	32	18	} Fabricated Stand
4	ATM	Hi Wall	1. TR	FTKC35XV16WAA	8000125	RKC35XV16WAA	80010102	35	37	16	
5											02 nos.
6											
7											
8											

### Extra Activity Carried Out

Civil Work	Stabilizer			Timer	Casing Capping	Cable Tray	Gas Charging	Dismantling		Re-installation
	3KVA	4KVA	5KVA					Hi Wall	Cassette	
Core Cutting										
05 nos.										
Others	2 Drain Motor									2 Double Decker Fabrication Stand.

For

Sign

Name

Date

Stamp



Vendor Details

Signature

Technician Name

Date

*[Signature]*

AZAN

4/4/26

**DAIKIN**

339

**DAIKIN AIRCONDITIONING INDIA PVT. LTD.**  
Service Completion Certificate



**AEON AIRCONDITIONING SOLUTIONS**

Office No. 108 & 109, Devashree Garden, Commercial Complex,  
R.W. Swaant Marg, above Sheetal Dairy, Rutu Park, Thane - 400 601.  
Mob.: 9322334107 / 9322334109

Subject :

Registration No.		Request Date		Service Engineer		Scheduled Date/Time		Service Order	
				A. Zam		4/4/26			
User: City Union Bank				Mobile:		Operation data (Ambient temp. °C)			
Customer Address:						Before repair		After repair	
I Base Address: Chembur.						HP / T		pslg/ pslg/	
Daikin Invoice:				Date:		SP / T °C		pslg °C pslg °C	
Dealer Invoice:				Date:		Current °C		Amps °C Amps °C	
Type		Model No		Manufacturing No.		Voltage		Volts Volts	
Outdoor unit /		R2VF@100AV16		0010177		Indoor temperature			
Indoor unit		FCVF@100AV16		0008432		Suction		°C °C	
Work Date	No. of S.E.	Work hours	Progress code	Details of the Repair Work				Discharge	
4				3. TR casset A/c				°C °C	
4				Installation Done.				°C °C	
26								°C °C	
Compressor manufacturing No.		Defective Compressor		Replacement Compressor		Work No / Parts No		Qty Billing Amount	
Installed date	Warranty	AMC	Using with		Fault location	Phenomena code	Error code		
	Yes / No	Yes / No	Stabilizer	Cut off					
			Yes / No	Yes / No					
Service Engineer Remarks				Cooling Fine.					
Name				Signature					
Customer Remarks				Customer Impression about Service					
Vaibhav				(Please rate on scale of 1 poor, 2, 3, 4 & 5 excellent)					
Name				How is the behavior of visited engineer					
				What is the level of your satisfaction					
				How is the explanation by Engineer					
				a		Simple Repair			
				b		Part Replaced			
				c		Part Repaired			
				d		Gas Charging done			
				e		Routine Service - Wet			
				f		Routine Service - DRY			
				Details of Repair Work Done					



**DAIKIN**

342

**DAIKIN AIRCONDITIONING INDIA PVT. LTD.**  
Service Completion Certificate**AEON AIRCONDITIONING SOLUTIONS**Office No. 108 & 109, Devashree Garden, Commercial Complex,  
R.W. Svaant Marg, above Sheetal Dairy, Flutu Park, Thane - 400 601.  
Mob.: 9322334107 / 9322334109

Subject:

Registration No.		Request Date		Service Engineer		Scheduled Date/Time		Service Order	
				Azan		4/14/26			
User: City Union Bank				Mobile:		Operation data (Ambient temp. °C)			
Customer Address:						Before repair		After repair	
I Base Address: Chembur				HP / T		pslg/		pslg/	
Daikin Invoice:				Date:		SP / T °C		pslg/°C	
Dealer Invoice:				Date:		Current °C		Amps°C	
Type		Model No		Manufacturing No.		Voltage		Volts	
Outdoor unit /		RKC35XV16WAA		8001012		Indoor temperature			
Indoor unit		FTKC95XV16WAA		8000125		Suction		°C	
Work Date		No. of S.E.		Work hours		Progress code		Details of the Repair Work	
4/4/26								1-TR Daikin A/C installation done.	
Compressor manufacturing No.		Defective Compressor		Replacement Compressor		Discharge		°C	
Installed date		Warranty		AMC		Using with		Fault location	
		Yes / No		Yes / No		Stabilizer		Phenomena code	
						Cut off		Error code	
Service Engineer Remarks: cooling fine.									
Name: Azan				Signature:					
Customer Remarks:				Customer Impression about Service					
Name: Vaibhav				(Please rate on scale of 1 poor, 2, 3, 4 & 5 excellent)					
				How is the behavior of visited engineer		a		Simple Repair	
				What is the level of your satisfaction		b		Part Replaced	
				How is the explanation by Engineer		c		Part Repaired	
						d		Gas Charging done	
						e		Routine Service - Wet	
						f		Routine Service - DRY	
				Details of Repair Work Done					
				Blower broken					
				Short Cycling of Air at Indoor Unit					
				Short Cycling of Air at Outdoor Unit					
				Defect in Drain piping System					
				Gas Leakage from Flare nut					
				Error in Transmission wiring					
				Product under capacity					
				Rat bite case					
				Less cooling problem due to dirty Airfilter					
				Remote setting changed					
				Clogged Condenser					
				Other - PL specify					



**DAIKIN**

**341 DAIKIN AIRCONDITIONING INDIA PVT. LTD.**  
Service Completion Certificate



**AEON AIRCONDITIONING SOLUTIONS**

Office No. 108 & 109, Devashree Garden, Commercial Complex,  
R.W. Swaant Marg, above Sheetal Dairy, Rutu Park, Thane - 400 601.  
Mob.: 9322334107 / 9322334109

Subject :

Registration No.		Request Date		Service Engineer		Scheduled Date/Time		Service Order	
				Azeem		4/4/26			
User: City Union Bank				Mobile:		Operation data (Ambient temp. °C)		Fault Diagnosed	
Customer Address:								✓	
I Base Address: Chembur.				HP / T		Before repair After repair		Power	
Daikin Invoice:				Date:		SP / T °C		PCB	
Dealer Invoice:				Date:		pslg/°C pslg/°C		Power Failure	
Type				Model No		Amps°C		Phase Reverse	
Outdoor unit /				RKC35XV16WAA8001010		pslg/°C		In door unit PCB Defective	
Indoor unit				FTKC35XV16WAA8000120		Amps°C		Out door PCB Defective	
Work Date				No. of S.E.		Voltage		In door unit Fan Motor Defective	
4						Volts		Outdoor Fan Motor Defective	
4						Indoor temperature		Comp. taking High Current / Amp	
26				1:TR Daikin A/C		Suction °C °C		Compressor Ground / Earth	
Details of the Repair Work				Discharge °C °C		Outdoor temperature		Compressor Tripping due to High Temperature	
Installation Done				Suction °C °C		Suction °C °C		Compressor Tripping due to High Pressure	
				Discharge °C °C		Discharge °C °C		Indoor Unit MgSw Defective	
Compressor manufacturing No.				Defective Compressor		Work No / Parts No Qty		Outdoor Unit Mgsw Defective	
				Replacement Compressor		Billing Amount		Indoor Unit Transformer Faulty	
Installed date				Warranty				Out door Unit Transformer Faulty	
Yes / No				Yes / No				Fault of swing Motor	
Service Engineer Remarks				Cooling Fine.				Defect of Drain Pump	
Name Azeem				Signature				Expansion Valve Body / Motor Defective	
								Defective Temperature Sensor of Indoor Unit	
Customer Remarks								Defective Temperature Sensor of Outdoor Unit	
Vaibhav				Signature				Defective Current Sensor In Out door Unit	
								Gas Leakage at Indoor Unit	
Customer Impression about Service								Gas Leakage at Outdoor Unit	
a Simple Repair								Blower broken	
b Part Replaced								Short Cycling of Air at Indoor Unit	
c Part Repaired								Short Cycling of Air at Outdoor Unit	
d Gas Charging done								Defect in Drain piping System	
e Routine Service - Wet								Gas Leakage from Flare nut	
f Routine Service - DRY								Error In Transmission wiring	
								Product under capacity	
								Rat bite case	
								Less cooling problem due to dirty Airfilter	
								Remote setting changed.	
								Clogged Condenser	
								Other - Pl. specify	
								Details of Repair Work Done	
								✓	



