



AEON AIRCONDITIONING SOLUTIONS

Aeon House, Shop No. 6/7, Behind N Cube China Town, Opp. Shishu Dnyan Mandir,
Dr. Ambedkar Rd. Thane 400 601. Maharashtra
Tel. : 022 - 25370101 / 7900097007

038

e-mail : services@aeonacsolutions.com website : www.aeonacsolutions.com



Project : Cosmos Bank matunga East
Additional Measurement Sheet

Sr. No	Location	AC Type	Tonnage	Indoor Unit Details		Outdoor Unit Details		Copper In Rmt	Cable In Rmt	Drain In Rmt	ODU Stand
				Model No.	Sr. No.	Model No.	Sr. No.				
1	BM Cabin	split	1.0	FTKL35UV16WA	27846	RKL354V16WA	81162	15.2	17.0	1.8	01
2	1st Floor	split	1.5	FTKL60UV16V	8017814	RKL60UV16V	8030185	4.5	6.4	3.9	
3	GF open Area	Cassette	3.0	FCLF100ARV169	1590	R2LF100BRV169	1706	11.2	14.3	3.6	
4	GF open Area	Cassette	3.0	FCLF100ARV169	1721	R2LF100BRV169	1589	8.5	11.5	3.6	
5	ATM 1 Hitachi	split	1.5	RSG312EAD	ES0727	RSG312EAD	D60761	3.6	5.4	1.8	
6	ATM 2 Hitachi	split	1.5	RSG312EAD	ES0717	RSG312EAD	E63293	10.0	11.8	1.8	
7								53	66.4	16.5	01
8											

Extra Activity Carried Out outdoor stand modification 02

Civil Work	Stabilizer			Timer	Casing Capping	Cable Tray	Gas Charging	Dismantling		Re-installation
	3KVA	4KVA	5KVA					Hi Wall	Cassette	
				01			1.5	✓		02

Others Nitrogen flushing and Hold. Vacuum. Remote coil 08, Fan capacitor 01, 3 core wire 2.5mm, 13 meter.

For				Vendor Details	AEON
Sign	 30.09.2028			Signature	
Name				Stamp	
Date				Date	30/09/2028

DAIKIN

072

DAIKIN AIRCONDITIONING INDIA PVT. LTD.
Service Completion Certificate



AEON AIRCONDITIONING SOLUTIONS

Office No. 108 & 109, Devashree Garden, Commercial Complex,
R.W. Svaant Marg, above Sheetal Dairy, Rutu Park, Thane - 400 601.
Mob.: 9322334107 / 9322334109

Subject: Installation

Registration No.	Request Date	Service Engineer	Scheduled Date/Time	Service Order
		<u>Firoz</u>		

User: <u>Cosmos Ban /i</u>	Mobile:	Operation data (Ambient temp. °C)			Fault Diagnosed		✓
Customer Address: <u>G.F, Plot No. 32, Pali Residency</u>		Before repair	After repair	Power	Power Failure		
Base Address: <u>HSC matunga East mumbai</u>		HP / T	psig/	PCB	In door unit PCB Defective		
			psig/	EM	Out door PCB Defective		

Daikin Invoice:	Date:	SP / T °C	psig/°C	psig/°C	EM	In door unit Fan Motor Defective	
Dealer Invoice:	Date:	Current °C	Amps°C	Amps°C	Comp	Outdoor Fan Motor Defective	
Type	Model No	Manufacturing No.	Voltage	Volts	Volts	Comp. taking High Current / Amp	
Outdoor unit /	<u>R2VF100BRV169</u>	<u>1706</u>	Indoor temperature			Compressor Ground / Earth	
Indoor unit	<u>FCLV100ARV169</u>	<u>1590</u>	Suction	°C	°C	Compressor Tripping due to High Temperature	

Work Date	No. of S.E.	Work hours	Progress code	Details of the Repair Work				Discharge	°C	°C	Electrical	Indoor Unit MgSw Defective	
<u>30</u>				<u>Installation Done</u> <u>Now Air working</u> <u>cooling fine.</u>				Outdoor temperature			Outdoor Unit Mgsw Defective		
<u>09</u>								Suction	°C	°C	Defective Temperature Sensor of Indoor Unit		
<u>25</u>								Discharge	°C	°C	Defective Temperature Sensor of Outdoor Unit		
								Work No / Parts No	Qty	Billing Amount	Defective Current Sensor In Out door Unit		

Compressor manufacturing No.		Defective Compressor		Replacement Compressor		Work No / Parts No		Qty	Billing Amount	Unit	Gas Leakage at Indoor Unit	
Installed date	Warranty	AMC	Using with		Fault location	Phenomena code	Error code			Installation	Gas Leakage at Outdoor Unit	
	Yes / No	Yes / No	Stabilizer	Cut off						Other	Blower broken	
			Yes / No	Yes / No							Short Cycling of Air at Indoor Unit	

Service Engineer Remarks		Name		Signature		Code:		Total		Other		Details of Repair Work Done	
<u>Firoz + Belal</u>		<u>Firoz</u>				<u>Code:</u>				Less cooling problem due to dirty Airfilter		✓	

Customer Remarks		Name		Signature		Customer Impression about Service		a		Simple Repair		✓	
		<u>Belal</u>				(Please rate on scale of 1 poor, 2, 3, 4 & 5 excellent)		b		Part Replaced			
								c		Part Repaired			
								d		Gas Charging done			
								e		Routine Service - Wet			
						f		Routine Service - DRY					

070

DAIKIN AIRCONDITIONING INDIA PVT. LTD.
Service Completion Certificate



AEON AIRCONDITIONING SOLUTIONS

Office No. 108 & 109, Devashree Garden, Commercial Complex,
R.W. Swam Marg, above Sheetal Dairy, Rutu Park, Thane - 400 601.
Mob.: 9322334107 / 9322334109

Subject: Installation

Registration No.		Request Date		Service Engineer		Scheduled Date/Time		Service Order			
				<u>Firoz</u>							
User: <u>Cosmos Bank</u>			Mobile:			Operation data (Ambient temp. °C)			Fault Diagnosed		
Customer Address: <u>GF, Plot No. 32, Palai Residency</u>									<input checked="" type="checkbox"/> Power Failure <input type="checkbox"/> Phase Reverse <input type="checkbox"/> In door unit PCB Defective <input type="checkbox"/> Out door PCB Defective <input type="checkbox"/> In door unit Fan Motor Defective <input type="checkbox"/> Outdoor Fan Motor Defective <input type="checkbox"/> Comp. taking High Current / Amp <input type="checkbox"/> Compressor Ground / Earth <input type="checkbox"/> Compressor Tripping due to High Temperature <input type="checkbox"/> Compressor tripping due to High Pressure <input type="checkbox"/> Indoor Unit MgSw Defective <input type="checkbox"/> Outdoor Unit Mgsw Defective <input type="checkbox"/> Indoor Unit Transformer Faulty <input type="checkbox"/> Outdoor Unit Transformer Faulty <input type="checkbox"/> Fault of swing Motor <input type="checkbox"/> Defect of Drain Pump <input type="checkbox"/> Expansion Valve Body / Motor Defective <input type="checkbox"/> Defective Temperature Sensor of Indoor Unit <input type="checkbox"/> Defective Temperature Sensor of Outdoor Unit <input type="checkbox"/> Defective Current Sensor In Out door Unit <input type="checkbox"/> Gas Leakage at Indoor Unit <input type="checkbox"/> Gas Leakage at Outdoor Unit <input type="checkbox"/> Blower broken <input type="checkbox"/> Short Cycling of Air at Indoor Unit <input type="checkbox"/> Short Cycling of Air at Outdoor Unit <input type="checkbox"/> Defect in Drain piping System <input type="checkbox"/> Gas Leakage from Flare nut <input type="checkbox"/> Error in Transmission wiring <input type="checkbox"/> Product under capacity <input type="checkbox"/> Rat bite case <input type="checkbox"/> Less cooling problem due to dirty Airfilter <input type="checkbox"/> Remote setting changed <input type="checkbox"/> Clogged Condenser <input type="checkbox"/> Other - PL specify		
Base Address: <u>CHS matunga East. Mumbai</u>											
Daikin Invoice:		Date:		SP / T °C		psig/°C		psig/°C		EMI	
Dealer Invoice:		Date:		Current °C		Amps°C		Amps°C		Comp	
Type		Model No		Manufacturing No.		Voltage		Volts		Volts	
Outdoor unit /		<u>R1CLG04V16V</u>		<u>8030185</u>		Indoor temperature					
Indoor unit		<u>F1CLG04V16V</u>		<u>8017814</u>		Suction		°C		°C	
Work Date	No. of S.E.	Work hours	Progress code	Details of the Repair Work							
<u>30</u>				<u>Installation Done now A/C working cooling fine</u>							
<u>09</u>											
<u>25</u>											
Compressor manufacturing No.		Defective Compressor		Replacement Compressor		Work No / Parts No		Qty		Billing Amount	
Installed date	Warranty	AMC	Using with		Fault location	Phenomena code	Error code				
	Yes / No	Yes / No	Yes / No	Cut off							
Service Engineer Remarks											
<u>Firoz + Belal</u>											
Name										Signature	
Customer Remarks											
<u>Code:</u>											
Name										Signature	
Customer Impression about Service											
(Please rate on scale of 1 poor, 2, 3, 4 & 5 excellent)											
How is the behavior of visited engineer						a Simple Repair					
What is the level of your satisfaction						b Part Replaced					
How is the explanation by Engineer						c Part Repaired					
						d Gas Charging done					
						e Routine Service - Wet					
						f Routine Service - DRY					



