



AEON AIRCONDITIONING SOLUTIONS

Aeon House, Shop No. 6/7, Behind N Cube China Town, Opp. Shishu Dnyan Mandir,
 Dr. Ambedkar Rd. Thane 400 601. Maharashtra
 Tel. : 022 - 25370101 / 7900097007
 e-mail : services@aeonacsolutions.com website : www.aeonacsolutions.com

416

Project : Eterclub Kopar Khaihe Nave MUMBAI

Additional Measurement Sheet

| Sr. No | Location | AC Type | Tonnage | Indoor Unit Details | | Outdoor Unit Details | | Copper In Rmt | Cable In Rmt | Drain In Rmt | ODU Stand |
|--------|----------|---------|---------|---------------------|---------|----------------------|---------|---------------|--------------|--------------|-----------|
| | | | | Model No. | Sr. No. | Model No. | Sr. No. | | | | |
| 1 | Shop | SPLIT | 1.5 | FTKL60XV16VAA | B006496 | KKL60XV16VAA | B007417 | 7.6 | 9.1 | 4.2 | 01 |
| 2 | Shop | SPLIT | 1.5 | FTKL60XV16VAA | B006462 | KKL60XV16VAA | B007418 | - | - | 2.4 | 01 |
| 3 | | | | | | | | | | | |
| 4 | | | | | | | | 7.6 | 9.1 | 6.6 | 02 |
| 5 | | | | | | | | | | | |
| 6 | | | | | | | | | | | |
| 7 | | | | | | | | | | | |
| 8 | | | | | | | | | | | |

Extra Activity Carried Out

| Civil Work | Stabilizer | | | Timer | Casing Capping | Cable Tray | Gas Charging | Dismantling | | Re-installation |
|------------|------------|------|------|-------|----------------|------------|--------------|-------------|----------|-----------------|
| | 3KVA | 4KVA | 5KVA | | | | | Hi Wall | Cassette | |
| | | | | | | | | | | |

Others Nitrogen/Steels/Fishing Veem

| | | |
|------|---------------------|------------|
| For | Vendor Details Aeon | |
| Sign | Signature | |
| Name | Technician Name | FIROZ |
| Date | Date | 11/03/2021 |

RAMIZ PATEL
 11/03/2026

Stamp

DAIKIN AIRCONDITIONING INDIA PVT. LTD.



AEON AIRCONDITIONING SOLUTIONS

Service Completion Certificate

C-403, Corporate Avenue Andheri Ghatkopar Link Rd, Andheri (E), Mumbai-400093.

Office No. 108 & 109, Devashree Garden Commercial Complex,
R. W. Sawant Marg, Above Sheetal Dairy, Rutu Park, Thane-400 601
Mob.: 9326311501 / 9322334106

Subject: Installation

Sr.No. 517


| Registration No. | | Request Date | | Service Engineer's Name | | Scheduled Date | | Time | | Notification No. | | Service Order No. | | |
|---|----------------------|--------------|---------------|--|--|----------------|--|-----------------------------------|---------|------------------|---------------------------------|-------------------|--|--|
| | | | | Firoz | | | | | | | | | | |
| User Name: <u>EaDClub</u> | | | | | | | | Operation data (Ambient temp. °C) | | | Fault Diagnosed | | | |
| Address: <u>Shop No. 7. B Ground floor Koparkhairne Navi Mumbai</u> | | | | | | | | Before Repair | | After Repair | | Power | | |
| Mobile No.: | | | | Tel. No.: | | | | HP / T °C | pslg °C | pslg °C | PCB | | | |
| Daikin Invoice No.: | | | | Date: | | | | SP / T °C | pslg °C | pslg °C | EM | | | |
| Dealer Invoice No.: | | | | Date: | | | | Current | Amps | Amps | Comp | | | |
| Type | Model No. | | | Manufacturing No. | | | | Voltage | Volts | Volts | Electrical | | | |
| Outdoor Unit | <u>RKL60XV16VAA</u> | | | <u>8007417</u> | | | | Indoor Temperature | | | Indoor Unit MgSw Defective | | | |
| Indoor unit | <u>FTKL60XV16VAA</u> | | | <u>8006496</u> | | | | Suction | °C | °C | Outdoor Unit MgSw Defective | | | |
| Work Date | No. of S.E. | Work Hours | Progress Code | Details of the Repair Work | | | | Discharge | °C | °C | Indoor Unit Transformer Faulty | | | |
| <u>11/3/25</u> | | | | <u>Installation Done now AC working Cooling Fine</u> | | | | Outdoor Temperature | | | Outdoor Unit Transformer Faulty | | | |
| | | | | | | | | Suction | °C | °C | Fault of Swing Motor | | | |
| | | | | | | | | Discharge | °C | °C | Defect of Drain Pump | | | |
| | | | | | | | | Work No / Parts No | | Qty | Billing Amount | | Unit | |
| | | | | | | | | | | | | | Gas Leakage at Indoor Unit | |
| | | | | | | | | | | | | | Gas Leakage at Outdoor Unit | |
| | | | | | | | | | | | | | Blower Broken | |
| | | | | | | | | | | | | | Short Cycling of Air at Indoor Unit | |
| | | | | | | | | | | | | | Short Cycling of Air at Outdoor Unit | |
| | | | | | | | | | | | | | Defect in Drain Piping System | |
| | | | | | | | | | | | | | Gas Leakage from Flare nut | |
| | | | | | | | | | | | | | Error in Transmission wiring | |
| | | | | | | | | | | | | | Product under capacity | |
| | | | | | | | | | | | | | Rate bite case | |
| | | | | | | | | | | | | | Less cooling problem due to dirty Airfilter | |
| | | | | | | | | | | | | | Remote setting changed | |
| | | | | | | | | | | | | | Clogged condenser | |
| | | | | | | | | | | | | | Other - Pl. Specify | |
| | | | | | | | | | | | | | Total | |
| | | | | | | | | | | | | | Details of Repair Work Done | |
| | | | | | | | | | | | | | a Simple Repair | |
| | | | | | | | | | | | | | b Part Replaced | |
| | | | | | | | | | | | | | c Part Replaced | |
| | | | | | | | | | | | | | d Gas Charging Done | |
| | | | | | | | | | | | | | e Routing Service - Wet | |
| | | | | | | | | | | | | | f Routing Service - Dry | |
| | | | | | | | | | | | | | Customer Impression about Service | |
| | | | | | | | | | | | | | (Please rate on scale of 1 poor, 2, 3, 4 & 5 excellent) | |
| | | | | | | | | | | | | | How is the behavior of visited engineer | |
| | | | | | | | | | | | | | What is the level of your satisfaction | |
| | | | | | | | | | | | | | How is the explanation by Engineer | |
| | | | | | | | | | | | | | Name: <u>Firoz + Betal</u> Signature: <u>[Signature]</u> | |
| | | | | | | | | | | | | | Customer Remarks | |
| | | | | | | | | | | | | | Name: <u>RAMIZ PATEL</u> Signature: <u>[Signature]</u> | |

"We recommend, to take routine maintenance services of your Daikin machine at regular intervals, for its good health"

Daikin Customer Care : Missed Call or SMS <DAIKIN> to 92101 88999 ; Toll Free Number : 1860 180 3900 / 1800 102 9300 ; cs@daikinindia.com / www.daikinindia.com

DAIKIN AIRCONDITIONING INDIA PVT. LTD.

Service Completion Certificate
C-403, Corporate Avenue Andheri Ghatkopar Link Rd, Andheri (E), Mumbai-400093.



AEON AIRCONDITIONING SOLUTIONS

Office No. 108 & 109, Devashree Garden Commercial Complex,
R. W. Sawant Marg, Above Sheetal Dairy, Rutu Park, Thane-400 601
Mob.: 9326311501 / 9322334106

Subject :

Sr.No. **518**

| Registration No. | Request Date | Service Engineer's Name | Scheduled Date | Time | Notification No. | Service Order No. | |
|--|---------------------|-------------------------|----------------|---|------------------|---|---|
| | | FIROZ | | | | | |
| User Name : Hotelub | | | | Operation data (Ambient temp. °C) | | Fault Diagnosed <input checked="" type="checkbox"/> | |
| Address : Shop No 7-B Ground Floor Koparkhane Nov/ Mumbai | | | | Before Repair | After Repair | | Power Failure |
| Mobile No.: _____ Tel. No.: _____ | | | | HP / T °C | pslg/°C | pslg/°C | Phase Reverse |
| Daikin Invoice No.: _____ Date: _____ | | | | SP / T °C | pslg/°C | pslg/°C | In door unit PCB Defective |
| Dealer Invoice No.: _____ Date: _____ | | | | Current | Amps | Amps | Out door PCB Defective |
| Type | Model No. | Manufacturing No. | | Voltage | Volts | Volts | In door unit Fan Motor Defective |
| Outdoor Unit | RKLG0XU/CVAA | B007428 | | Indoor Temperature | | | Outdoor Fan Motor Defective |
| Indoor unit | FKLG0XU/CVAA | B006462 | | Suction | °C | °C | Comp. taking High Current / Amp |
| Work Date | No. of S.E. | Work Hours | Progress Code | Details of the Repair Work | | | Compressor Ground / Earth |
| 11/3/26 | | | | Installation Done how AC working cooling fine | | | Compressor Tripping due to High Temperature |
| Compressor Manufacturing No. | | | | Defective Compressor | | Replacement Compressor | |
| Installed Date | Warranty | AMC | Using with | | Fault Location | Phenomen Code | Error Code |
| | Yes / No | Yes / No | Stabilizer | Cut off | | | |
| Service Engineer Remarks | | | | Work No / Parts No | | Qty | Billing Amount |
| | | | | | | | |
| Name FIROZ + Belal | | | | Signature | | Code | |
| Customer Remarks | | | | Customer Impression about Service | | | Unit |
| | | | | (Please rate on scale of 1 poor, 2, 3, 4 & 5 excellent) | | | Gas Leakage at Indoor Unit |
| | | | | How is the behavior of visited engineer | | | Gas Leakage at Outdoor Unit |
| | | | | What is the level of your satisfaction | | | Blower Broken |
| | | | | How is the explanation by Engineer | | | Short Cycling of Air at Indoor Unit |
| | | | | | | | Short Cycling of Air at Outdoor Unit |
| | | | | | | | Defect in Drain Piping System |
| | | | | | | | Gas Leakage from Flare nut |
| | | | | | | | Error in Transmission wiring |
| | | | | | | | Product under capacity |
| | | | | | | | Rate bite case |
| | | | | | | | Less cooling problem due to dirty Airfilter |
| | | | | | | | Remote setting changed |
| | | | | | | | Clogged condenser |
| | | | | | | | Other - Pl. Specify |
| | | | | | | | Details of Repair Work Done <input checked="" type="checkbox"/> |
| | | | | | | | a Simple Repair |
| | | | | | | | b Part Replaced |
| | | | | | | | c Part Replaced |
| | | | | | | | d Gas Charging Done |
| | | | | | | | e Routing Service - Wet |
| | | | | | | | f Routing Service - Dry |

"We recommend, to take routine maintenance services of your Daikin machine at regular intervals, for its good health"

Daikin Customer Care : Missed Call or SMS <DAIKIN> to 92101 88999 ; Toll Free Number : 1860 180 3900 / 1800 102 9300 ; cs@daikinindia.com / www.daikinindia.com