



AEON AIRCONDITIONING SOLUTIONS

Aeon House, Shop No. 6/7, Behind N Cube China Town, Opp. Shishu Dnyan Mandir,

Dr. Ambedkar Rd. Thane 400 601. Maharashtra

Tel. : 022 - 25370101 / 7900097007

e-mail : services@aeonacsolutions.com website : www.aeonacsolutions.com

Project : Shreeing Mature Trails - Durshek, Khopoli.

Additional Measurement Sheet

Sr. No	Location	AC Type	Tonnage	Indoor Unit Details		Outdoor Unit Details		Copper In Rmt	Cable In Rmt 4 Core	Drain In Rmt	ODU Stand
				Model No.	Sr. No.	Model No.	Sr. No.				
1	Contanter. A-1	Split	1.5	4TKLS00V	119085	RKLS00V16	8065744	1.5	2.5	2.3	—
2	Contanter. A-2	Split	1.5	4TKLS00V	0118983	RKLS00V16	0252794	1.5	2.5	2.3	—
3											
4											
5							03 Core 2.5mm poly carb wire		4.8		
6									4.8		
7											
8											

Extra Activity Carried Out

Civil Work	Stabilizer			Timer	Casing Capping	Cable Tray	Gas Charging	Dismantling		Re-installation
	3KVA	4KVA	5KVA					Hi Wall	Cassette	
Others										

For	Vendor Details				
Sign	Signature				
Name	Technician Name				
Date	Date				

For Shree Shreeing Mature Trails
Shri. Shri. V. Satpat
Stamp

Aeon Airconditioning Solutions
Haresh
Haresh & Umesh
12/01/2025.

DAIKIN AIRCONDITIONING INDIA PVT. LTD. Service Completion Certificate


AEON AIRCONDITIONING SOLUTIONS

1248

 Office No. 108 & 109, Devashree Garden, Commercial Complex,
 R.W. Swam Marg, above Sheetal Dairy, Ratu Park, Thane - 400 601.
 Mob.: 9322334107 / 9322334109

 Subject: Installation

Registration No.		Request Date		Service Engineer		Scheduled Date/Time		Service Order	
User: <u>Shetling Nature Trails</u> Mobile: _____ Customer Address: <u>Dutshet Nature Trails,</u> <u>Khopoli.</u> Base Address: _____									
Daikin Invoice: _____				Date: _____		SP / T °C		pslg/°C	
Dealer Invoice: _____				Date: _____		Current °C		Amps°C	
Type		Model No.		Manufacturing No.		Voltage		Volts	
Outdoor unit /		<u>RKL50UV16VA4</u>		<u>8065744.</u>		Suction		°C	
Indoor unit		<u>4TKL50UV16V3</u>		<u>0119085.</u>		Discharge		°C	
Work Date	No. of S.E.	Work hours	Progress code	Details of the Repair Work					
<u>12/01/2025</u>				<u>A/C Installation done. Now a/c working & cooling fine.</u>					
Compressor manufacturing No.		Defective Compressor		Replacement Compressor					
Installed date	Warranty	AMC	Using with	Fault location	Phenomena code	Error code			
	Yes / No	Yes / No	Yes / No	Yes / No					
Service Engineer Remarks									
Name <u>Harish & Umar</u>		Signature <u>[Signature]</u>							
Customer Remarks									
Name		Signature							
Customer Impression about Service									
(Please rate on scale of 1 poor, 2, 3, 4 & 5 excellent)									
How is the behavior of visited engineer									
What is the level of your satisfaction									
How is the explanation by Engineer									
Fault Diagnosed Power Failure Phase Reverse In door unit PCB Defective Out door PCB Defective In door unit Fan Motor Defective Outdoor Fan Motor Defective Comp. taking High Current / Amp Compressor Ground / Earth Compressor Tripping due to High Temperature Compressor tripping due to High Pressure Indoor Unit MgsW Defective Outdoor Unit MgsW Defective Indoor Unit Transformer Faulty Out door Unit Transformer Faulty Fault of swing Motor Defect of Drain Pump Expansion Valve Body / Motor Defective Defective Temperature Sensor of Indoor Unit Defective Temperature Sensor of Outdoor Unit Defective Current Sensor In Out door Unit Gas Leakage at Indoor Unit Gas Leakage at Outdoor Unit Blower broken Short Cycling of Air at Indoor Unit Short Cycling of Air at Outdoor Unit Defect in Drain piping System Gas Leakage from Flare nut Error In Transmission wiring Product under capacity Rat bite case Less cooling problem due to dirty Airfilter Remote setting changed Clogged Condenser Other - Pl. specify Details of Repair Work Done									
a Simple Repair b Part Replaced c Part Repaired d Gas Charging done e Routine Service - Wet f Routine Service - DRY									

DAIKIN

DAIKIN AIRCONDITIONING INDIA PVT. LTD. Service Completion Certificate


AEON AIRCONDITIONING SOLUTIONS

 Office No. 108 & 109, Devashree Garden, Commercial Complex,
 R.W. Swant Marg, above Sheetal Dairy, Ritu Park, Thane - 400 601.
 Mob.: 9322334107 / 9322334109

1249

 Subject: Installation

Registration No.		Request Date		Service Engineer		Scheduled Date/Time		Service Order				
User: <u>Sterling Nature Trails</u> Mobile: _____ Customer Address: <u>Durshet. Nature Trails, Khopoli.</u> Base Address: _____												
Daikin Invoice:		Date:		SP / T °C		psig/°C		psig/°C				
Dealer Invoice:		Date:		Current °C		Amps°C		Amps°C				
Type	Model No		Manufacturing No.		Voltage		Volts		Volts			
Outdoor unit /	<u>RKL500V1G03</u>		<u>0252794</u>		Suction		°C		°C			
Indoor unit	<u>4TKL500V1G03</u>		<u>0118983</u>		Discharge		°C		°C			
Work Date	No. of S.E.	Work hours	Progress code	Details of the Repair Work		Suction		°C		°C		
<u>12</u>				<u>A/C Installation done</u>		Discharge		°C		°C		
<u>01</u>				<u>Now a/c working & Cooling fine</u>		Suction		°C		°C		
<u>2025</u>						Discharge		°C		°C		
Compressor manufacturing No.		Defective Compressor		Replacement Compressor		Work No / Parts No		Qty		Billing Amount		
Installed date	Warranty	AMC	Using with	Fault location	Phenomena code	Error code						
	Yes / No	Yes / No	Yes / No	Yes / No								
Service Engineer Remarks												
Name		<u>Faizan & Umair</u>		Signature		<u>Faizan</u>						
Customer Remarks												
Name		<u>For Budget</u>		Signature								
Operation data (Ambient temp. °C) Before repair After repair HP / T psig/ psig/ SP / T °C psig/°C psig/°C Current °C Amps°C Amps°C Voltage Volts Volts Indoor temperature Suction °C °C Discharge °C °C Outdoor temperature Suction °C °C Discharge °C °C Work No / Parts No Qty Billing Amount Total												
Fault Diagnosed Power Failure Phase Reverse In door unit PCB Defective Out door PCB Defective In door unit Fan Motor Defective Outdoor Fan Motor Defective Comp. taking High Current / Amp Compressor Ground / Earth Compressor Tripping due to High Temperature Compressor tripping due to High Pressure Indoor Unit MgsW Defective Outdoor Unit MgsW Defective Indoor Unit Transformer Faulty Out door Unit Transformer Faulty Fault of swing Motor Defect of Drain Pump Expansion Valve Body / Motor Defective Defective Temperature Sensor of Indoor Unit Defective Temperature Sensor of Outdoor Unit Defective Current Sensor In Out door Unit Gas Leakage at Indoor Unit Gas Leakage at Outdoor Unit Blower broken Short Cycling of Air at Indoor Unit Short Cycling of Air at Outdoor Unit Defect in Drain piping System Gas Leakage from Flare nut Error in Transmission wiring Product under capacity Rat bite case Less cooling problem due to dirty Airfilter Remote setting changed Clogged Condenser Other - Pl. specify												
Details of Repair Work Done a Simple Repair b Part Replaced c Part Repaired d Gas Charging done e Routine Service - Wet f Routine Service - DRY												
Customer Impression about Service (Please rate on scale of 1 poor, 2, 3, 4 & 5 excellent) How is the behavior of visted engineer What is the level of your satisfaction How is the explanation by Engineer												