



AEON AIRCONDITIONING SOLUTIONS

Aeon House, Shop No. 6/7, Behind N Cube China Town, Opp. Shishu Dnyan Mandir,
Dr. Ambedkar Rd. Thane 400 601. Maharashtra
Tel. : 022 - 25370101 / 7900097007

e-mail : services@aeonacsolutions.com website : www.aeonacsolutions.com

010

Project : Blue Dart Express Ltd (Bhiwandi)

Additional Measurement Sheet

Sr. No	Location	AC Type	Tonnage	Indoor Unit Details		Outdoor Unit Details		Copper In Rmt	Cable In Rmt	Drain In Rmt	ODU Stand
				Model No.	Sr. No.	Model No.	Sr. No.				
1	Blue Dart office	split	1.8	MTKM60UV16U	1725	RKM60UV16U	43498	—	3.0	3.0	wall stand
2	Blue Dart office	split	1.8	MTKM60UV16U	1572	RKM60UV16U	43463	—	3.0	3.0	wall stand
3	Blue Dart office	split	1.5	—	—	—	—	2.5	2.5	3.0	—
4											
5											
6											
7											
8											

Extra Activity Carried Out

Civil Work	Stabilizer			Timer	Casing Capping	Cable Tray	Gas Charging	Dismantling		Re-installation
	3KVA	4KVA	5KVA					Hi Wall	Cassette	
								02 nos.		01 nos.

Others Nitrogen flushing, Nitrogen holding, Vacuum.

For	Vendor Details Aeon				
Sign	Signature				
Name	Technician Name				
Date	Date				

[Signature]

Girish Pandhe

3/07/25



Aeon

[Signature]

Firoz Abid

03.07.2025

DAIKIN

824

DAIKIN AIRCONDITIONING INDIA PVT. LTD. Service Completion Certificate


AEON AIRCONDITIONING SOLUTIONS

 Office No. 108 & 109, Devashree Garden, Commercial Complex,
 R.W. Swarn Marg, above Sheetal Dairy, Ratu Park, Thane - 400 601.
 Mob.: 9322334107 / 9322334109

 Subject: **Installation**

Registration No.		Request Date		Service Engineer		Scheduled Date/Time		Service Order	
				Firoz					
User: Blue Dart Express Ltd				Mobile:		Operation data (Ambient temp. °C)			
Customer Address: Hissa no 424 A/B survey no						Before repair		After repair	
Base Address: 122 house no 215, Bhiwandi						HP / T		psig/ psig/	
Daikin Invoice:				Date:		SP / T °C		psig/°C psig/°C	
Dealer Invoice:				Date:		Current °C		Amps°C Amps°C	
Type		Model No		Manufacturing No.		Voltage		Volts Volts	
Outdoor unit /		RKM60UV16U		43448		Indoor temperature			
Indoor unit		MTKM60UV16U		1725		Suction		°C °C	
Work Date	No. of S.E.	Work hours	Progress code	Details of the Repair Work		Discharge		°C °C	
03				Installation Done.		Outdoor temperature			
07				Nitrogen Flushing,		Suction		°C °C	
25				Nitrogen holding,		Discharge		°C °C	
				Vacuum Done.		Work No / Parts No		Qty Billing Amount	
Compressor manufacturing No.				Defective Compressor		Replacement Compressor			
Installed date		Warranty		AMC		Using with		Fault Phenomena Error	
						Stabilizer Cut off		location code code	
Yes / No		Yes / No		Yes / No		Yes / No			
Service Engineer Remarks									
Firoz + Abid									
Name									
Signature									
Customer Remarks									
Gurish Rande.									
Name									
Signature									
Customer Impression about Service									
(Please rate on scale of 1 poor, 2, 3, 4 & 5 excellent)									
How is the behavior of visited engineer									
What is the level of your satisfaction									
How is the explanation by Engineer									
a Simple Repair									
b Part Replaced									
c Part Repaired									
d Gas Charging done									
e Routine Service - Wet									
f Routine Service - DRY									
Fault Diagnosed									
Power Failure									
Phase Reverse									
In door unit PCB Defective									
Out door PCB Defective									
In door unit Fan Motor Defective									
Outdoor Fan Motor Defective									
Comp. taking High Current / Amp									
Compressor Ground / Earth									
Compressor Tripping due to High Temperature									
Compressor tripping due to High Pressure									
Indoor Unit MgsW Defective									
Outdoor Unit MgsW Defective									
Indoor Unit Transformer Faulty									
Out door Unit Transformer Faulty									
Fault of swing Motor									
Defect of Drain Pump									
Expansion Valve Body / Motor Defective									
Defective Temperature Sensor of Indoor Unit									
Defective Temperature Sensor of Outdoor Unit									
Defective Current Sensor In Out door Unit									
Gas Leakage at Indoor Unit									
Gas Leakage at Outdoor Unit									
Blower broken									
Short Cycling of Air at Indoor Unit									
Short Cycling of Air at Outdoor Unit									
Defect in Drain piping System									
Gas Leakage from Flare nut									
Error In Transmission wiring									
Product under capacity									
Rat bite case									
Less cooling problem due to dirty Airfilter									
Remote setting changed									
Clogged Condenser									
Other - Pl. specify									
Details of Repair Work Done									
a Simple Repair									
b Part Replaced									
c Part Repaired									
d Gas Charging done									
e Routine Service - Wet									
f Routine Service - DRY									

DAIKIN

825 DAIKIN AIRCONDITIONING INDIA PVT. LTD.

Service Completion Certificate

Subject: Installation


AEON AIRCONDITIONING SOLUTIONS

Office No. 108 & 109, Devashree Garden, Commercial Complex,
R.W. Swam Marg, above Sheetal Dairy, Ritu Park, Thane - 400 601.
Mob: 9322334107 / 9322334109

Registration No.		Request Date		Service Engineer		Scheduled Date/Time		Service Order	
				Firoz					
User: Blue Dart Epress Ltd				Mobile:		Operation data (Ambient temp. °C)			
Customer Address: Hissa no 424 AIB survey no						Before repair		After repair	
Base Address: 122 house no 215, Bhiwandi						HP / T		psig/	
Daikin Invoice:				Date:		SP / T °C		psig/°C	
Dealer Invoice:				Date:		Current °C		Amps°C	
Type		Model No		Manufacturing No.		Voltage		Volts	
Outdoor unit /		RKM60UV16U		43463		Indoor temperature			
Indoor unit		MTKM60UV16U		1572		Suction		°C	
Work Date	No. of S.E.	Work hours	Progress code	Details of the Repair Work		Discharge		°C	
03				Installation Done. Nitrogen		Suction		°C	
07				Flushing, nitrogen holding		Discharge		°C	
25				Vacuum Done.		Work No / Parts No		Qty	
Compressor manufacturing No.				Defective Compressor		Replacement Compressor		Billing Amount	
Installed date	Warranty	AMC	Using with	Fault location	Phenomena code	Error code			
	Yes / No	Yes / No	Stabilizer Cut off						
Service Engineer Remarks									
Firoz + Abid									
Name									
Signature									
Customer Remarks									
Girish Remdhe									
Name									
Signature									
Customer Impression about Service									
(Please rate on scale of 1 poor, 2, 3, 4 & 5 excellent)									
How is the behavior of visited engineer									
What is the level of your satisfaction									
How is the explanation by Engineer									
Fault Diagnosed									
Power Failure									
Phase Reverse									
In door unit PCB Defective									
Out door PCB Defective									
In door unit Fan Motor Defective									
Outdoor Fan Motor Defective									
Comp. taking High Current / Amp									
Compressor Ground / Earth									
Compressor Tripping due to High Temperature									
Compressor tripping due to High Pressure									
Indoor Unit MgsW Defective									
Outdoor Unit MgsW Defective									
Indoor Unit Transformer Faulty									
Out door Unit Transformer Faulty									
Fault of swing Motor									
Defect of Drain Pump									
Expansion Valve Body / Motor Defective									
Defective Temperature Sensor of Indoor Unit									
Defective Temperature Sensor of Outdoor Unit									
Defective Current Sensor In Out door Unit									
Gas Leakage at Indoor Unit									
Gas Leakage at Outdoor Unit									
Blower broken									
Short Cycling of Air at Indoor Unit									
Short Cycling of Air at Outdoor Unit									
Defect in Drain piping System									
Gas Leakage from Flare nut									
Error In Transmission wiring									
Product under capacity									
Rat bite case									
Less cooling problem due to dirty Airlitter									
Remote setting changed									
Clogged Condenser									
Other - Pl. specify									
Details of Repair Work Done									
Simple Repair									
Part Replaced									
Part Repaired									
Gas Charging done									
Routine Service - Wet									
Routine Service - DRY									