



AEON AIRCONDITIONING SOLUTIONS

Aeon House, Shop No. 6/7, Behind N Cube China Town, Opp. Shishu Dnyan Mandir,

Dr. Ambedkar Rd. Thane 400 601, Maharashtra

Tel : 022 - 25370101 / 7900097007

e-mail : services@aeonacsolutions.com website : www.aeonacsolutions.com

Project : Eat Club - kandivali

Additional Measurement Sheet

Sr. No	Location	AC Type	Tonnage	Indoor Unit Details		Outdoor Unit Details		Copper In Rmt	Cable In Rmt	Drain In Rmt	ODU Stand
				Model No.	Sr. No.	Model No.	Sr. No.				
1	lobby	1.8	1.8	FTKL60V16	55533	RKL60V16	122933				1
2											
3	lobby	Split	1.8	FTKL60V16	55536	RKL60V16	122927				1
4				16U		16U					
5											
6											
7											
8											

Extra Activity Carried Out

Civil Work	Stabilizer			Timer	Casing Capping	Cable Tray	Gas Charging	Dismantling		Re-installation
	3KVA	4KVA	5KVA					Hi Wall	Cassette	
Others										

Nitrogen Testing, Flushing, vacuuming Done

For	Vendor Details			
Sign			Signature	M. E. Khar.
Name			Technician Name	
Date	Stamp		Date	07-01-2025



DAIKIN

DAIKIN AIRCONDITIONING INDIA PVT. LTD.

Service Completion Certificate

B2B

AEON AIRCONDITIONING SOLUTIONS

Office No. 106 & 109, Devashree Garden, Commercial Complex,
R.V. Swarn Marg, above Sheetal Dairy, Pudu Park, Thane - 400 601.
Mob: 9322334107 / 9322334199

1415

Subject :

Registration No.		Request Date		Service Engineer		Scheduled Date/Time		Service Order	
User: <i>Eat Club Food Ltd</i>				Mobile:		Fault Diagnosed			
Customer Address: <i>Shop No 34 ground Floor Axiom</i>				Operation data (Ambient temp. °C)		✓			
Base Address: <i>Majara motor godhale Road Near Datta Mandir</i>				Before repair		After repair			
Daikin Invoice:				Date:		HP/T		Power Failure	
Dealer Invoice:				Date:		SP/T °C		Phase Reverse	
Type				Model No		Manufacturing No.		In door unit PCB Defective	
Outdoor unit /				R1/L60W/6U		0122933		Out door PCB Defective	
Indoor unit				FTIRL60W/6U		0055513		In door unit Fan Motor Defective	
Work Date				No. of S.E.		Work hours		Progress code	
7/9/25									
Details of the Repair Work				Suction		°C		°C	
2 AC installation 2 L bracket				Discharge		°C		°C	
Nitrogen flushing pressure				Suction		°C		°C	
testing and vacuumizing done				Discharge		°C		°C	
AC working fine				Work No / Parts No		Qty		Billing Amount	
Compressor manufacturing No.				Defective Compressor		Replacement Compressor			
Installed date				Warranty		AMC		Using with	
Yes / No				Yes / No		Yes / No		Yes / No	
Service Engineer Remarks				Fault location		Phenomena code		Error code	
Shobha Bhalakare									
Signature				Total					
Customer Remarks				Customer Impression about Service		a Simple Repair			
Name: <i>medha shankar</i>				(Please rate on scale of 1 poor, 2, 3, 4 & 5 excellent)		b Part Replaced			
Signature: <i>medha shankar</i>				How is the behavior of visited engineer		c Part Repaired			
				What is the level of your satisfaction		d Gas Charging done			
				How is the explanation by Engineer		e Routine Service - Wet			
						f Routine Service - DRY			
								Details of Repair Work Done	
								✓	

Daikin Customer Care : Missed Call or SMS «DAIKIN» to 92101 86999 ; Toll Free Number : 1880 180 3900 / 1800 102 9300 ; cs@daikinindia.com / www.daikinindia.com



DAIKIN

DAIKIN AIRCONDITIONING INDIA PVT. LTD.

Service Completion Certificate

1418

**AEON AIRCONDITIONING SOLUTIONS**

Office No. 108 & 109, Devashree Garden, Commercial Complex,
R.W. Swaant Marg, above Sheetal Dairy, Ratu Park, Thane - 400 601.
Mob.: 9322334107 / 9322334109

Subject :

Registration No.		Request Date		Service Engineer		Scheduled Date/Time		Service Order		
User: <i>East Club Food Ltd</i>		Mobile :		Operation data (Ambient temp. °C)		Fault Diagnosed		✓		
Customer Address: <i>Shop No 384 Ground Floor Axiom miller</i>				Before repair		After repair				
Base Address: <i>Mildan Gokhale Road NEAR Datta margdar</i>				pslg/		pslg/				
Daikin Invoice :		Date :		SP / T °C		pslg/°C		pslg/°C		
Dealer Invoice :		Date :		Current °C		Amps °C		Amps °C		
Type	Model No	Manufacturing No.		Voltage		Volts		Volts		
Outdoor unit /	<i>R1L60W160</i>	<i>0122929</i>		Indoor temperature						
Indoor unit	<i>BT1L60W160</i>	<i>0055536</i>		Suction		°C		°C		
Work Date	No. of S.E.	Work hours	Progress code	Details of the Repair Work		Discharge		°C		
<i>2/1/25</i>				<i>2/1C installation on 22 bracket</i>		Suction		°C		
				<i>Nitrogen flushing pressure</i>		Discharge		°C		
				<i>testing and vacuumizing done</i>		Outdoor temperature				
				<i>AC working fine</i>		Work No / Parts No		Qty		
Compressor manufacturing No.		Defective Compressor		Replacement Compressor		Billing Amount				
Installed date	Warranty	AMC	Using with	Fault location	Phenomena code	Error code				
	Yes / No	Yes / No	Stabilizer	Cut off						
Service Engineer Remarks							Total			
<i>Shodh Adhikari</i>							Signature			
Customer Remarks							Customer Impression about Service			
<i>medhan jkhare</i>							(Please rate on scale of 1 poor, 2, 3, 4 & 5 excellent)			
Name							How is the behavior of visited engineer			
Signature							What is the level of your satisfaction			
							How is the explanation by Engineer			
							a Simple Repair			
							b Part Replaced			
							c Part Repaired			
							d Gas Charging done			
							e Routine Service - Wet			
							f Routine Service - DRY			
							Details of Repair Work Done			
							✓			

Daikin Customer Care : Missed Call or SMS <DAIKIN> to 92101 88999 ; Toll Free Number : 1860 180 3900 / 1800 102 9300 ; cs@daikinindia.com / www.daikinindia.com



Scanned with OKEN Scanner