

DAIKIN

DAIKIN AIRCONDITIONING INDIA PVT. LTD.

Authorised Service Center

AEON AIRCONDITIONING SOLUTIONS

AEON HOUSE, SHOP NO. 6/7, BEHIND N CUBE CHINA TOWN

DR. AMBEDKAR ROAD, THANE W 400601 MAHARASHTRA. PHONE :- 02225370101 / 7900097007



PROJECT :- BANDHAN BANK (ISLAMPUR)

Measurement Sheet

Sr. No.	Location	AC Type	Tonnage	Indoor Unit Details		Outdoor Unit Details		Copper In Rmt	Cable In Rmt	Drain In Rmt	ODU Stand
				Model No.	Sr. No.	Model No.	Sr. No.				
1	Work Area	Casest	2. TON	FCQF24ARVIG	007295	RUVF24ASVIG	0078284	32(m)	34(m)	7(m)	1
2	"	"	"	FCQF24ARVIG	0074644	RUVF24ASVIG	0078071	27(m)	29(m)	7(m)	1
3	"	"	"	FCQF24ARVIG	0074941	RUVF24ASVIG	0078278	24(m)	26(m)	7(m)	1
4	"	"	"	FCQF24ARVIG	0074914	RUVF24ASVIG	0078076	20(m)	22(m)	7(m)	1
5											
6											
7											
8											

EXTRA ACTIVITY CARRIED OUT

CIVIL WORK	Stabilizer			TIMER	CASING CAPPING	CABLE TRAY	GAS CHARGING	DISMENTALING		RE-INSTALLATION
	3KVA	4KVA	5KVA					Hi Wall	Cassette	
						✓			✓	

OTHERS

22(m) cable tray, one scaffolding (20ft x 12 ft), Two cone cutting, 164 kg Iron cage.

Vendor Details:

AEON AIRCONDITIONING SOLUTIONS

For Customer Details:

Sign :

Name :

Date :

Signature :

Technician Name :

Date :

25

Zamir Shaikh,

18.12.25

Stamp :



DAIKIN

DAIKIN AIRCONDITIONING INDIA PVT. LTD.
Service Completion Certificate

08/09/2019

AECM AIRCONDITIONING SOLUTIONS

Office: 885, 108 & 109, Newsworld Garden, Commercial Complex,
H.W. Chow Road, above Shing Lee Dairy, Poko Park, Tsim Sha Tsui - 407 600
Fax: 407 634 1028 / 407 634 1029

Subjects

Subject :												
Registration No.		Request Date		Service Engineer		Scheduled Date/Time		Service Center				
User:	BANDHAN BANK	Mobil:		Operator date (Ambient temp. °C)			Fault Diagnosed					
Customer Address:	ISLAMPUR							☒				
I Base Address:												
Cash Invoice:	Date:	GP / T °C			Before repair			After repair				
Dealer Invoice:	Date:	Current °C			Amps °C			Amps °C				
Type	Model No.	Manufacturing No.		Voltage	Volts	Volts	Compressor					
Outdoor unit / Indoor unit	RUVF24ASVIB FCAF24ARVIG	0078281 007295		Indoor temperature			Electrical					
Work Done	No. of S.E.	Work hours	Progress code	Details of the Repair Work			Discharge			°C		
				Installations done painting calling done e.			Outdoor temperature			°C		
							Suction			°C		
							Discharge			°C		
							Work No / Parts No			Qty	Billing Amount	
Compressor manufacturing No.				Defective Compressor			Replacement Compressor					
Installed date		Warranty	AAC	Using with		Fault location	Parameters code	Error code				
Yes / No		Yes / No	Yes / No	Yes / No								
Service Engineer Remarks												
Name	Zuraid Shairah	Signature Z.S										
Customer Remarks						Customer Impression about Service						
(Please rate on scale of 1 poor, 2, 3, 4 & 5 excellent)												
How is the behavior of visited engineer						d Gas Charging done						
What is the level of your satisfaction						e Routine Service - Well						
How is the explanation by Engineer						f Routine Service - DPH						
Other						Less cooling problem due to dirty fan coil						
Remote setting changed												
Charged Condenser												
Other - Pl specify												
Total												
Details of Repair Work Done						☒						
a	Single Repair					b	Part Replaced					
c	Part Repaired					d	Gas Charging done					
e	Routine Service - Well					f	Routine Service - DPH					

Dial-in Customer Care : Missed Call or SMS «DAKIN» to 82101 88099 ; Toll Free Number : 1600 160 3900 / 1800 102 8300 ; cs@dakinindia.com / www.dakinindia.com

DAIKIN

DAIKIN AIRCONDITIONING INDIA PVT. LTD.

Service Completion Certificate



AEON AIRCONDITIONING SOLUTIONS

Office No. 108 & 109, Chaudhary Garden, Commercial Complex,
K. K. Sweets Marg, above Shree Durg Puja Park, Thane - 400 001.
Mob. 922234102 / 922234109

1415

Subject:		Registration No.		Request Date		Service Engineer		Scheduled Date/Time		Service Order	
User: Bandhan Bank		Mobile:		Operation (Indoor temp. °C)		Before repair		After repair		Fault Diagnosed	
Customer Address: ISLAMPUR		Base Address:		Indoor temperature		Suction		Discharge		✓	
Date:		Date:		Voltage		Vib		Vib		✓	
Dealer Invoice:		Date:		Current °C		Ampere °C		Ampere °C		✓	
Type:		Model No.		Manufacturing No.		Voltage		Vib		Vib	
Outdoor unit / Indoor unit		R410F 24ASV16		0078076		Suction		Discharge		✓	
Work Date		No. of S.C.		Work Issues		Progress made		Details of the Repair Work		✓	
								Installations done wiring & charging OK.		✓	
Compressor manufacturing No.		Defective Compressor		Replacement Compressor		Work No / Parts No		Qty		Billing Amount	
Installed date		Warranty		A.M.C.		Using with		Fault location		Error code	
Yes / No		Yes / No		Yes / No		Yes / No		Yes / No		Yes / No	
Service Engineer Remarks		Name		Signature		Total				Details of Repair Work Done	
Customer Remarks		Name		Signature		Customer Impression about Service				✓	
						(Please rate on scale of 1 point, 2, 3, 4 & 5 enclosed)					
						How is the behavior of visited engineer				a) Single Repair	
						What is the level of your satisfaction				b) Part Replaced	
						How is the explanation by Engineer				c) Part Repaired	
										d) Gas Charging done	
										e) Routine Service - Yes	
										f) Routine Service - DPF	

DAIKIN

DAIKIN AIRCONDITIONING INDIA PVT. LTD.

Service Completion Certificate

1415

AEON AIRCONDITIONING SOLUTIONS
Office No. 106 & 108, Dewdree Garden, Commercial Complex,
Plot Street Marg, above Shree Lal Ganga Park, Thane - 401 006
Tel: 922234102 / 922234103

Subject:

Registration No.		Request Date		Service Engineer		Scheduled Date/Time		Service Order	
User: BANDHAN BANK		Mobile:		Operation data (Ambient temp. °C)		Fault Diagnosed		✓	
Customer Address: ISLAMPUR									
(Base Address):				1P / 2		Before repair		After repair	
Daikin Invoice:		Date:		1P / 2 °C		p/g/g		p/g/g	
Dealer Invoice:		Date:		Current °C		Amps °C		Amps °C	
Type	Model No.	Manufacturing No.		Voltage		Volts		Volts	
Outdoor unit /	RHVF2H4SV16	0078071		Indoor temperature					
Indoor unit	FCBF2H4RV16	0074644		Suction		°C		°C	
Work Date	No. of S.C.	Work Failure	Progress code	Details of the Repair Work		Discharge		°C	
				Installations done piping colling done		Suction		°C	
						Discharge		°C	
Compressor manufacturing No.				Defective Compressor		Replacement Compressor			
Installed date	Warranty	AMC	Using with	Fault location	Remarks	Error code			
	Yes / No	Yes / No	Yes / No	Yes / No					
Service Engineer Remarks									
Name: Zunaid Swainch				Signature: Z.S					
Customer Remarks				Customer Impression about Service					
				(Please rate on scale of 1 poor, 2, 3, 4 & 5 excellent)					
				How is the behavior of visited engineer					
				What is the level of your satisfaction					
				How is the explanation by Engineer					
				a) Single Repair					
				b) Part Replaced					
				c) Part Replaced					
				d) Gas Charging done					
				e) Routine Service - Yes					
				f) Routine Service - No					
				g) Other - If specify					
				Details of Repair Work Done					
				✓					

DAIKIN
DAIKIN AIRCONDITIONING INDIA PVT. LTD.
 Service Completion Certificate

1415

AEON AIRCONDITIONING SOLUTIONS
 100/101, 102 & 103, Dhanush Garden, Commercial Complex,
 RMC Sector Marg, above Shree Durg, Pali Park, Thane - 405 005
 Mob: 922234101 / 922234102

Registration No.		Request Date		Service Engineer		Scheduled Date/Time		Billing Center	
User: GANDHAN BANK		Module:		Operation mode (Ambient temp. °C)		Fault Diagnosed		☒	
Customer Address: ISLAMPUR									
(Room Address):				Before repair		After repair			
Chiller Inlet:		Date:		SP/°C		SP/°C			
Chiller Outlet:		Date:		Current °C		After °C			
Type:		Model No.		Manufacturing No.		Voltage		Volts	
Customer Unit:		RVVF24ASV16		0078278		Indoor temperature			
Indoor Unit:		FCAF24ARV16		0074942		Before		°C	
Work Order		No. of E.P.		Work hours		Progress code		Details of the Repair Work	
								Discharge	
								Before	
								°C	
								Discharge	
								°C	
								Discharge	
								°C	
								Discharge	
								°C	
								Discharge	
								°C	
								Discharge	
								°C	
								Discharge	
								°C	
								Discharge	
								°C	
								Discharge	
								°C	
								Discharge	
								°C	
								Discharge	
								°C	
								Discharge	
								°C	
								Discharge	
								°C	
								Discharge	
								°C	
								Discharge	
								°C	
								Discharge	
								°C	
								Discharge	
								°C	
								Discharge	
								°C	
								Discharge	
								°C	
								Discharge	
								°C	
								Discharge	
								°C	
								Discharge	
								°C	
								Discharge	
								°C	
								Discharge	
								°C	
								Discharge	
								°C	
								Discharge	
								°C	
								Discharge	
								°C	
								Discharge	
								°C	
								Discharge	
								°C	
								Discharge	
								°C	
								Discharge	
								°C	
								Discharge	
								°C	
								Discharge	
								°C	
								Discharge	
								°C	
								Discharge	
								°C	
								Discharge	
								°C	
								Discharge	
								°C	
								Discharge	
								°C	
								Discharge	
								°C	
								Discharge	
								°C	
								Discharge	
								°C	
								Discharge	
								°C	
								Discharge	
								°C	
								Discharge	
								°C	
								Discharge	
								°C	
								Discharge	
								°C	
								Discharge	
								°C	
								Discharge	
								°C	
								Discharge	
								°C	
								Discharge	
								°C	
								Discharge	
								°C	
								Discharge	
								°C	
								Discharge	
								°C	
								Discharge	
								°C	
								Discharge	
								°C	
								Discharge	
								°C	
								Discharge	
								°C	
								Discharge	
								°C	
								Discharge	
								°C	
								Discharge	
								°C	
								Discharge	
								°C	
								Discharge	
								°C	
								Discharge	
								°C	
								Discharge	
								°C	
								Discharge	
								°C	
								Discharge	
								°C	
								Discharge	
								°C	
								Discharge	
								°C	
								Discharge	
								°C	
								Discharge	
								°C	
								Discharge	
								°C	
								Discharge	
								°C	
								Discharge	
								°C	
								Discharge	
								°C	
								Discharge	
								°C	
								Discharge	
								°C	
								Discharge	
								°C	
								Discharge	
								°C	
								Discharge	
								°C	
								Discharge	
								°C	
								Discharge	
								°C	
								Discharge	
								°C	
								Discharge	
								°C	
								Discharge	
								°C	
								Discharge	
								°C	
								Discharge	
								°C	
								Discharge	
								°C	
								Discharge	
								°C	
								Discharge	
								°C	
								Discharge	
								°C	
								Discharge	
								°C	
								Discharge	
								°C	
								Discharge	
								°C	
								Discharge	
								°C	
								Discharge	
								°C	
								Discharge	
								°C	
								Discharge	
								°C	
								Discharge	
								°C	
								Discharge	
								°C	
								Discharge	
								°C	
								Discharge	
								°C	
								Discharge	
								°C	
								Discharge	
								°C	
								Discharge	
								°C	
								Discharge	
								°C	
								Discharge	
								°C	
								Discharge	
								°C	
								Discharge	
								°C	
								Discharge	
								°C	
								Discharge	
								°C	
								Discharge	
								°C	
								Discharge	
								°C	
								Discharge	
								°C	
								Discharge	