

DAIKIN AIRCONDITIONING INDIA PVT. LTD.



AEON AIRCONDITIONING SOLUTIONS

Service Completion Certificate
 C-483, Corporate Avenue Andheri Ghatkopar Link Rd, Andheri (E), Mumbai-400093.

Office No. 105 & 109, Durgamacheri Garden Commercial Complex,
 R. W. Sarwat Marg, Above Shree Dairy, Plot Park, Thane-400 001
 Mba: 9328111591 / 9222354105

Sr.No. 173

Subject: installation

Registration No.	Request Date	Service Engineer's Name	Scheduled Date	Time	Notification No.	Service Order No.
		Assalan.				
User Name: <u>Stealling</u>				Operation data (Ambient temp. °C)		Fault Diagnosed
Address: <u>Thomas Cook Nature topics Kundalika</u>				Before Repair	After Repair	
Mobile No. _____ Tel. No. _____				HP / T °C	psig/°C	Power Failure
Dealer Invoice No.:		Date:		SP / T °C	psig/°C	Phase Reverse
Dealer Invoice No.:		Date:		Current	Amps	In door unit PCB Defective
Type	Model No.	Manufacturing No.		Voltage	Volts	Out door PCB Defective
Outdoor Unit	<u>RKLS0VV16VAF</u>	<u>8290807</u>		Indoor Temperature		In door unit Fan Motor Defective
Indoor unit	<u>RFTRKLS0VV16VAF</u>	<u>8140964</u>		Suction	°C	Outdoor Fan Motor Defective
Work Date	No. of S.E.	Work Hours	Progress Code	Discharge	°C	Comp. taking High Current / Amp
Details of the Repair Work				Outdoor Temperature		Compressor Ground / Earth
<u>1/24/20</u> installation done A.c working and cooling Fine				Suction	°C	Compressor Tripping due to High Temperature
				Discharge	°C	Compressor Tripping due to High Pressure
				Suction	°C	Indoor Unit MgSw Defective
				Discharge	°C	Outdoor Unit MgSw Defective
Compressor Manufacturing No.		Defective Compressor		Replacement Compressor		Indoor Unit Transformer Faulty
Installed Date	Warranty	AMC	Using with	Fault Location	Phenomenon Code	Error Code
	Yes / No	Yes / No	Stabilizer			
Service Engineer Remarks: <u>Man supply 3-meter wire, stand - 1nos</u>				Work No / Parts No		Qty
Name: <u>Assalan + Belal</u>				Billing Amount		1
Signature: _____				Total		1
Customer Remarks				Installation		Gas Leakage at Indoor Unit
Name: <u>Pranil Halk</u>				Other		Gas Leakage at Outdoor Unit
Signature: _____				Details of Repair Work Done		Blower Broken
Customer Impression about Service				a Simple Repair		Short Cycling of Air at Indoor Unit
(Please rate on scale of 1 poor, 2, 3, 4 & 5 excellent)				b Part Replaced		Short Cycling of Air at Outdoor Unit
How is the behavior of visited engineer				c Part Replaced		Defect in Drain Piping System
What is the level of your satisfaction				d Gas Charging Done		Gas Leakage from Flare nut
How is the explanation by Engineer				e Routing Service - Wet		Error In Transmission wiring
				f Routing Service - Dry		Product under capacity
						Rate bite case
						Less cooling problem due to dirty Airfilter
						Remote setting changed
						Clogged condenser
						Other - Pl. Specify



"We recommend, to take routine maintenance services of your Daikin machine at regular intervals, for its good health"
 Daikin Customer Care : Missed Call or SMS <DAIKIN> to 92101 88999 ; Toll Free Number : 1860 180 3900 / 1800 102 9300 ; cs@daikinindia.com / www.daikinindia.com