

DAIKIN

309

DAIKIN AIRCONDITIONING INDIA PVT. LTD.
Service Completion Certificate



AEON AIRCONDITIONING SOLUTIONS

Office No. 108 & 109, Devashree Garden, Commercial Complex,
R.W. Swaant Marg, above Sheetal Dairy, Putu Park, Thane - 400 601.
Mob.: 9322334107 / 9322334109

Subject :

Registration No.		Request Date		Service Engineer		Scheduled Date/Time		Service Order		
				Akram		20/12/25				
User: Blue Dayt EXPRESS. Mobile:				Operation data (Ambient temp. °C)			Fault Diagnosed			
Customer Address:				Before repair			After repair			
I Base Address: Andheri				HP / T	pslg/	pslg/	Power Failure			
Daikin Invoice: Date:				SP / T °C	pslg°C	pslg°C	Phase Reverse			
Dealer Invoice: Date:				Current °C	Amps°C	Amps°C	In door unit PCB Defective			
Type	Model No	Manufacturing No.		Voltage	Volts	Volts	Out door PCB Defective			
Outdoor unit /	RKM60UV16M	0004669		Indoor temperature			In door unit Fan Motor Defective			
Indoor unit	FTKM60UV16M	0005001		Suction	°C	°C	Outdoor Fan Motor Defective			
Work Date	No. of S.E.	Work hours	Progress code	Details of the Repair Work			Comp. taking High Current / Amp			
20				2-TR Daikin ALC			Compressor Ground / Earth			
10				Installation Done.			Compressor Tripping due to High Temperature			
25							Compressor Tripping due to High Pressure			
Compressor manufacturing No.				Defective Compressor		Replacement Compressor		Indoor Unit MgSw Defective		
Installed date	Warranty	AMC	Using with Stabilizer	Fault location	Phenomena code	Error code	Outdoor Unit Mgsw Defective			
	Yes / No	Yes / No	Yes / No	Yes / No			Indoor Unit Transformer Faulty			
Service Engineer Remarks				Discharge		°C	°C	Out door Unit Transformer Faulty		
Cooling Fine				Outdoor temperature			Fault of swing Motor			
Name: Akram				Suction		°C	°C	Defect of Drain Pump		
Signature: [Signature]				Discharge		°C	°C	Expansion Valve Body / Motor Defective		
Customer Remarks				Work No / Parts No		Qty	Billing Amount	Defective Temperature Sensor of Indoor Unit		
Name: Nilesh Hirani				Total				Defective Temperature Sensor of Outdoor Unit		
Signature: [Signature]				Unit				Defective Current Sensor In Out door Unit		
Customer Impression about Service				Unit				Gas Leakage at Indoor Unit		
(Please rate on scale of 1 poor, 2, 3, 4 & 5 excellent)				Installation				Gas Leakage at Outdoor Unit		
How is the behavior of visited engineer				Blower broken				Short Cycling of Air at Indoor Unit		
What is the level of your satisfaction				Short Cycling of Air at Outdoor Unit				Short Cycling of Air at Outdoor Unit		
How is the explanation by Engineer				Defect in Drain piping System				Defect in Drain piping System		
a) Simple Repair				Gas Leakage from Flare nut				Gas Leakage from Flare nut		
b) Part Replaced				Error In Transmission wiring				Error In Transmission wiring		
c) Part Repaired				Product under capacity				Product under capacity		
d) Gas Charging done				Rat bite case				Rat bite case		
e) Routine Service - Wet				Less cooling problem due to dirty Airfilter				Less cooling problem due to dirty Airfilter		
f) Routine Service - DRY				Remote setting changed				Remote setting changed		
				Clogged Condenser				Clogged Condenser		
				Other - Pl. specify				Other - Pl. specify		
				Details of Repair Work Done				Details of Repair Work Done		

DAIKIN

308

DAIKIN AIRCONDITIONING INDIA PVT. LTD.
Service Completion Certificate



AEON AIRCONDITIONING SOLUTIONS
Office No. 108 & 109, Devashree Garden, Commercial Complex,
R.V. Svaant Marg, above Sheetal Dairy, Pudu Park, Thane - 400 601.
Mob.: 9322334107 / 9322334109

Subject :

Registration No.		Request Date		Service Engineer		Scheduled Date/Time		Service Order	
				Akram		20/10/25			
User: Blue Dart Express				Mobile:					
Customer Address:				Operation data (Ambient temp. °C)					
Base Address: Andheri				Before repair		After repair		Fault Diagnosed	
Daikin Invoice:				HP / T		pslg/		Power Failure	
Dealer Invoice:				SP / T °C		pslg/°C		Phase Reverse	
Type				Current °C		Amps°C		In door unit PCB Defective	
Model No				Voltage		Volts		Out door PCB Defective	
Manufacturing No.				Indoor temperature				In door unit Fan Motor Defective	
Outdoor unit /		RKM60UV16M		Suction		°C		Outdoor Fan Motor Defective	
Indoor unit		FT16M60UV16M		Discharge		°C		Comp. taking High Current / Amp	
Work Date	No. of S.E.	Work hours	Progress code	Details of the Repair Work					
20/10/25				2. TR Daikin AC installation done.					
Compressor manufacturing No.				Defective Compressor		Replacement Compressor			
Installed date	Warranty	AMC	Using with		Fault location	Phenomena code	Error code		
	Yes / No	Yes / No	Yes / No	Yes / No					
Service Engineer Remarks				Cooling fine.					
Name: Sultan				Signature: [Signature]					
Customer Remarks				Customer Impression about Service					
Name: Nilesh Kiraji				Signature: [Signature]					
				a		Simple Repair		✓	
				b		Part Replaced			
				c		Part Repaired			
				d		Gas Charging done			
				e		Routine Service - Wet			
				f		Routine Service - DRY			

DAIKIN

307

DAIKIN AIRCONDITIONING INDIA PVT. LTD.
Service Completion Certificate



AEON AIRCONDITIONING SOLUTIONS

Office No. 108 & 109, Devashree Garden, Commercial Complex,
R.W. Swaant Marg, above Sheetal Dairy, Ritu Park, Thane - 400 601.
Mob.: 9322334107 / 9322334109

Subject :

Registration No.		Request Date		Service Engineer		Scheduled Date/Time		Service Order	
				AKG		26/10/25			
User: RIME Dart Express Mobile:				Operation data (Ambient temp. °C)			Fault Diagnosed		
Customer Address:				Before repair			After repair		
I Base Address: Anaher				HP / T	psig/	psig/	Power Failure		
Daikin Invoice: Date:				SP / T °C	psig/°C	psig/°C	Phase Reverse		
Dealer Invoice: Date:				Current °C	Amps°C	Amps°C	In door unit PCB Defective		
Type	Model No	Manufacturing No.		Voltage	Volts	Volts	Out door PCB Defective		
Outdoor unit /	RKM60UV16M	0004668		Indoor temperature			In door unit Fan Motor Defective		
Indoor unit	FTKM60UV16M	0005070		Suction	°C	°C	Outdoor Fan Motor Defective		
Work Date	No. of S.E.	Work hours	Progress code	Discharge			Comp. taking High Current / Amp		
20/10/25				Outdoor temperature			Compressor Ground / Earth		
Details of the Repair Work				Suction	°C	°C	Compressor Tripping due to High Temperature		
2-TR Daikin AC installation done.				Discharge	°C	°C	Compressor tripping due to High Pressure		
				Work No / Parts No		Qty	Billing Amount		Electrical
									Indoor Unit MgsW Defective
									Outdoor Unit MgsW Defective
									Indoor Unit Transformer Faulty
									Out door Unit Transformer Faulty
									Fault of swing Motor
									Defect of Drain Pump
									Expansion Valve Body / Motor Defective
									Defective Temperature Sensor of Indoor Unit
									Defective Temperature Sensor of Outdoor Unit
									Defective Current Sensor In Out door Unit
									Gas Leakage at Indoor Unit
									Gas Leakage at Outdoor Unit
									Blower broken
									Short Cycling of Air at Indoor Unit
									Short Cycling of Air at Outdoor Unit
									Defect in Drain piping System
									Gas Leakage from Flare nut
									Error in Transmission wiring
									Product under capacity
									Rat bite case
									Less cooling problem due to dirty Airfilter
									Remote setting changed
									Clogged Condenser
									Other - Pl. specify
Service Engineer Remarks									Unit
cooling fine.									Installation
Name: Anaher Signature: Anaher									Other
Customer Remarks									Details of Repair Work Done
									a Simple Repair
									b Part Replaced
									c Part Repaired
									d Gas Charging done
									e Routine Service - Wet
									f Routine Service - DRY
Customer Impression about Service									
(Please rate on scale of 1 poor, 2, 3, 4 & 5 excellent)									
Name: Nikhil Mishra Signature: Nikhil Mishra									
How is the behavior of visited engineer									
What is the level of your satisfaction									
How is the explanation by Engineer									



AEON AIRCONDITIONING SOLUTIONS

Aeon House, Shop No. 6/7, Behind N Cube China Town, Opp. Shishu Dnyan Mandir,
 Dr. Ambedkar Rd. Thane 400 601. Maharashtra
 Tel. : 022 - 25370101 / 7900097007
 e-mail : services@aeonacsolutions.com website : www.aeonacsolutions.com

302

Project : <u>Blue Dart Express Ltd.</u>											
Additional Measurement Sheet											
Sr. No	Location	AC Type	Tonnage	Indoor Unit Details		Outdoor Unit Details		Copper In Rmt	Cable In Rmt	Drain In Rmt	ODU Stand
				Model No.	Sr. No.	Model No.	Sr. No.				
1	work Area	split	2TR	FTKM 60UV16	0004987	RKM 60UV16M	0004670	18	20	10	1
2	work Area	split	2TR	FTKM 60UV16M	0005001	RKM 60UV16M	0004669	16	18	8	1
3	work Area	split	2TR	FTKM 60UV16M	0005070	RKM 60UV16M	0004668	20	22	12	1
4											
5											
6											
7											
8											
Extra Activity Carried Out											
Civil Work	Stabilizer			Timer	Casing Capping	Cable Tray	Gas Charging	Dismantling		Re-installation	
	3KVA	4KVA	5KVA					Hi Wall	Cassette		
								3			
Others											
For						Vendor Details					
Sign	<i>Mitesh Hirani</i>					Signature	<i>[Signature]</i>				
Name	Mitesh Hirani					Technician Name	AK Ram				
Date	20/10/2025 Stamp					Date	20/10/25				

