

DAIKIN

DAIKIN AIRCONDITIONING INDIA PVT. LTD.

Authorised Service Center

AEON AIRCONDITIONING SOLUTIONS

AEON HOUSE, SHOP NO. 6/7, BEHIND N CUBE CHINA TOWN

DR. AMBEDKAR ROAD, THANE W 400601 MAHARASHTRA. PHONE :- 02225370101 / 7900097007



PROJECT :- Eat Club Food Ltd / Alandi Road Moshi Chikhi Pune - 411062											
Measurement Sheet											
Sr. No.	Location	AC Type	Tonnage	Indoor Unit Details		Outdoor Unit Details		Copper In Rmt	Cable In Rmt	Drain In Rmt	ODU Stand
				Model No.	Sr. No.	Model No.	Sr. No.				
1	Open Area	Split	1.4	FTKL60UV16V	8004642	RKL60UV16V	8010180	12	15	-	L-type
2											
3											
4											
5											
6											
7											
8											
EXTRA ACTIVITY CARRIED OUT											
CIVIL WORK		Stabilizer		TIMER		CASING CAPPING	CABLE TRAY	GAS CHARGING	DISMENTALING		RE-INSTALLATION
		3KVA	4KVA	5KVA					Hi Wall	Cassette	
3-6 RMT											
OTHERS											
For Customer Details : Eat club Food Ltd						Vendor Details : Aeon Airconditioning Solutions					
Sign :						Signature :					
Name :						Technician Name : Tanveer Sheikh					
Date :						Date : 08/03/2025					
Stamp :											

DAIKIN
DAIKIN AIRCONDITIONING INDIA PVT. LTD.
 Service Completion Certificate

AEON AIRCONDITIONING SOLUTIONS

 Shop No. 6 & 7, Aeon House, Dr. Ambedkar Rd., Thane (W)
 Phone : +91 (022) 34107 / 032234109

 Subject: **Eat Club Food Ltd**

Registration No.		Request Date		Service Engineer		Scheduled Date/Time		Service Order	
				Tanveer Shaikh		06/03/2025			
User: Jadhavwadi, De No: Alandi Customer Address: Road, Moshi chikhdi Pune I Ease Address: 411062				Operation data (Ambient temp. °C)			Fault Diagnosed		
				Before repair After repair			Power Failure		
				HP / T pslg/ pslg/			Phase Reverse		
Daikin Invoice: Date: SP / T °C pslg/°C pslg/°C				Current °C Amps °C Amps °C			In door unit PCB Defective		
Dealer Invoice: Date:				Voltage Volts Volts			Out door PCB Defective		
Type Model No Manufacturing No.				Indoor temperature			In door unit Fan Motor Defective		
Outdoor unit / Indoor unit				Suction °C °C			Outdoor Fan Motor Defective		
Work Date No. of S.E. Work hours Progress code Details of the Repair Work				Discharge °C °C			Comp. taking High Current / Amp		
				Outdoor temperature			Compressor Ground / Earth		
				Suction °C °C			Compressor Tripping due to High Temperature		
				Discharge °C °C			Compressor tripping due to High Pressure		
				Work No / Parts No Qty Billing Amount			Indoor Unit M/SW Defective		
Compressor manufacturing No. Defective Compressor Replacemant Compressor				Unit			Outdoor Unit M/SW Defective		
Installed date Warranty AMC Using with Stabilizer Cut off Fault location Phenomena code Error code				Installation			Outdoor Unit Transformer Faulty		
Yes / No Yes / No Yes / No Yes / No				Other			Outdoor Unit Transformer Faulty		
Service Engineer Remarks				Total			Fault of swing Motor		
Tanveer Shaikh				Details of Repair Work Done			Defect of Drain Pump		
Name Signature				a Simple Repair			Expansion Valve Body / Motor Defective		
Customer Remarks				b Part Replaced			Defective Temperature Sensor of Indoor Unit		
Name Signature				c Part Repaired			Defective Temperature Sensor of Outdoor Unit		
Customer Impression about Service				d Gas Charging done			Defective Current Sensor In Out door Unit		
(Please rate on scale of 1 poor, 2, 3, 4 & 5 excellent)				e Routine Service - Wet			Gas Leakage at Indoor Unit		
How is the behavior of visited engineer				f Routine Service - DRY %			Gas Leakage at Outdoor Unit		
What is the level of your satisfaction							Blower broken		
How is the explanation by Engineer							Short Cycling of Air at Indoor Unit		