



AEON AIRCONDITIONING SOLUTIONS

Aeon House, Shop No. 6/7, Behind N Cube China Town, Opp. Shishu Dnyan Mandir,
Dr. Ambedkar Rd. Thane 400 601. Maharashtra

Tel.: 022 - 25370101 / 7900097007

e-mail: services@aeonacsolutions.com website: www.aeonacsolutions.com

490

Project : Allana Sanpada

Additional Measurement Sheet

Sr. No	Location	AC Type	Tonnage	Indoor Unit Details		Outdoor Unit Details		Copper In Rmt	Cable In Rmt	Drain In Rmt	ODU Stand
				Model No.	Sr. No.	Model No.	Sr. No.				
1	Canteen	Split	1.8	FTKL71XV16MAA	11281	RKL71XV16MAA	11390			3.0	01
2	Canteen	Split	1.8	FTKL71XV16MAA	11641	RKL71XV16MAA	11379			3.0	01
3								1.8	2.4	6.0	02
4										10.6	
5										16.6	
6											
7											
8											

Extra Activity Carried Out

Civil Work	Stabilizer			Timer	Casing Capping	Cable Tray	Gas Charging	Dismantling		Re-installation
	3KVA	4KVA	5KVA					Hi Wall	Cassette	
					3.2 met					
Others										

For	Vendor Details <u>AEON</u>			
Sign	<u>[Signature]</u>		Signature	
Name	<u>M. Avinash</u>		Technician Name	<u>Fir02</u>
Date	<u>8-6-26</u>		Date	<u>27/05/2026</u>

Stamp

DAIKIN DAIKIN AIRCONDITIONING INDIA PVT. LTD.

Service Completion Certificate

C-403, Corporate Avenue Andhri Challenger Link Rd, Andhri (E), Mumbai-400053



AEON AIRCONDITIONING SOLUTIONS

Office No. 101 & 102, Deveshwar Garden Commercial Complex,
A, 10, Tansen Marg, Above Shree Datta, Ruby Park, Thane-400 021
Mob. 9220111501 / 922234408

Subject: Installation

Sr.No. 580

Registration No.	Request Date	Service Engineer's Name	Scheduled Date	Type	Notification No.	Service Order No.															
		<u>F102</u>																			
User Name:	<u>Aduna</u>			Operation data (Ambient temp. °C)																	
Address:	<u>Plot No: 28 maha vad</u>			<table border="1"> <tr> <th></th><th>Before Repair</th><th>After Repair</th></tr> <tr> <td>HP/°C</td><td><u>34°C</u></td><td><u>34°C</u></td></tr> <tr> <td>SP/°C</td><td><u>34°C</u></td><td><u>34°C</u></td></tr> <tr> <td>Current</td><td><u>18A</u></td><td><u>18A</u></td></tr> <tr> <td>Voltage</td><td><u>240V</u></td><td><u>240V</u></td></tr> </table>				Before Repair	After Repair	HP/°C	<u>34°C</u>	<u>34°C</u>	SP/°C	<u>34°C</u>	<u>34°C</u>	Current	<u>18A</u>	<u>18A</u>	Voltage	<u>240V</u>	<u>240V</u>
	Before Repair	After Repair																			
HP/°C	<u>34°C</u>	<u>34°C</u>																			
SP/°C	<u>34°C</u>	<u>34°C</u>																			
Current	<u>18A</u>	<u>18A</u>																			
Voltage	<u>240V</u>	<u>240V</u>																			
Machine No.	<u>5000000000</u>			<table border="1"> <tr> <th></th><th>Before Repair</th><th>After Repair</th></tr> <tr> <td>Room</td><td><u>24°C</u></td><td><u>24°C</u></td></tr> <tr> <td>Outside</td><td><u>34°C</u></td><td><u>34°C</u></td></tr> </table>				Before Repair	After Repair	Room	<u>24°C</u>	<u>24°C</u>	Outside	<u>34°C</u>	<u>34°C</u>						
	Before Repair	After Repair																			
Room	<u>24°C</u>	<u>24°C</u>																			
Outside	<u>34°C</u>	<u>34°C</u>																			
Order Invoice No.	<u>5000000000</u>			<table border="1"> <tr> <th></th><th>Before Repair</th><th>After Repair</th></tr> <tr> <td>Room</td><td><u>24°C</u></td><td><u>24°C</u></td></tr> <tr> <td>Outside</td><td><u>34°C</u></td><td><u>34°C</u></td></tr> </table>				Before Repair	After Repair	Room	<u>24°C</u>	<u>24°C</u>	Outside	<u>34°C</u>	<u>34°C</u>						
	Before Repair	After Repair																			
Room	<u>24°C</u>	<u>24°C</u>																			
Outside	<u>34°C</u>	<u>34°C</u>																			
Order Invoice No.	<u>5000000000</u>			<table border="1"> <tr> <th></th><th>Before Repair</th><th>After Repair</th></tr> <tr> <td>Room</td><td><u>24°C</u></td><td><u>24°C</u></td></tr> <tr> <td>Outside</td><td><u>34°C</u></td><td><u>34°C</u></td></tr> </table>				Before Repair	After Repair	Room	<u>24°C</u>	<u>24°C</u>	Outside	<u>34°C</u>	<u>34°C</u>						
	Before Repair	After Repair																			
Room	<u>24°C</u>	<u>24°C</u>																			
Outside	<u>34°C</u>	<u>34°C</u>																			
Type	<u>Split</u>			<table border="1"> <tr> <th></th><th>Before Repair</th><th>After Repair</th></tr> <tr> <td>Room</td><td><u>24°C</u></td><td><u>24°C</u></td></tr> <tr> <td>Outside</td><td><u>34°C</u></td><td><u>34°C</u></td></tr> </table>				Before Repair	After Repair	Room	<u>24°C</u>	<u>24°C</u>	Outside	<u>34°C</u>	<u>34°C</u>						
	Before Repair	After Repair																			
Room	<u>24°C</u>	<u>24°C</u>																			
Outside	<u>34°C</u>	<u>34°C</u>																			
Customer Unit	<u>RTCL 3.5 TL MPA</u>			<table border="1"> <tr> <th></th><th>Before Repair</th><th>After Repair</th></tr> <tr> <td>Room</td><td><u>24°C</u></td><td><u>24°C</u></td></tr> <tr> <td>Outside</td><td><u>34°C</u></td><td><u>34°C</u></td></tr> </table>				Before Repair	After Repair	Room	<u>24°C</u>	<u>24°C</u>	Outside	<u>34°C</u>	<u>34°C</u>						
	Before Repair	After Repair																			
Room	<u>24°C</u>	<u>24°C</u>																			
Outside	<u>34°C</u>	<u>34°C</u>																			
Order unit	<u>RTCL 3.5 TL MPA</u>			<table border="1"> <tr> <th></th><th>Before Repair</th><th>After Repair</th></tr> <tr> <td>Room</td><td><u>24°C</u></td><td><u>24°C</u></td></tr> <tr> <td>Outside</td><td><u>34°C</u></td><td><u>34°C</u></td></tr> </table>				Before Repair	After Repair	Room	<u>24°C</u>	<u>24°C</u>	Outside	<u>34°C</u>	<u>34°C</u>						
	Before Repair	After Repair																			
Room	<u>24°C</u>	<u>24°C</u>																			
Outside	<u>34°C</u>	<u>34°C</u>																			
Work No. of Day	1	2	3	Details of the Repair Work																	
23				Installation Done																	
24				New AC Working																	
25				Coding Fine																	
26																					
Compressor Manufacturing No.				<table border="1"> <tr> <th></th><th>Before Repair</th><th>After Repair</th></tr> <tr> <td>Room</td><td><u>24°C</u></td><td><u>24°C</u></td></tr> <tr> <td>Outside</td><td><u>34°C</u></td><td><u>34°C</u></td></tr> </table>				Before Repair	After Repair	Room	<u>24°C</u>	<u>24°C</u>	Outside	<u>34°C</u>	<u>34°C</u>						
	Before Repair	After Repair																			
Room	<u>24°C</u>	<u>24°C</u>																			
Outside	<u>34°C</u>	<u>34°C</u>																			
Installed Date	Year/Mo	Day	Hour	<table border="1"> <tr> <th></th><th>Before Repair</th><th>After Repair</th></tr> <tr> <td>Room</td><td><u>24°C</u></td><td><u>24°C</u></td></tr> <tr> <td>Outside</td><td><u>34°C</u></td><td><u>34°C</u></td></tr> </table>				Before Repair	After Repair	Room	<u>24°C</u>	<u>24°C</u>	Outside	<u>34°C</u>	<u>34°C</u>						
	Before Repair	After Repair																			
Room	<u>24°C</u>	<u>24°C</u>																			
Outside	<u>34°C</u>	<u>34°C</u>																			
Service Engineer Remarks				<table border="1"> <tr> <th></th><th>Before Repair</th><th>After Repair</th></tr> <tr> <td>Room</td><td><u>24°C</u></td><td><u>24°C</u></td></tr> <tr> <td>Outside</td><td><u>34°C</u></td><td><u>34°C</u></td></tr> </table>				Before Repair	After Repair	Room	<u>24°C</u>	<u>24°C</u>	Outside	<u>34°C</u>	<u>34°C</u>						
	Before Repair	After Repair																			
Room	<u>24°C</u>	<u>24°C</u>																			
Outside	<u>34°C</u>	<u>34°C</u>																			
Name	<u>Chitwan Wadhwa</u>			<table border="1"> <tr> <th></th><th>Before Repair</th><th>After Repair</th></tr> <tr> <td>Room</td><td><u>24°C</u></td><td><u>24°C</u></td></tr> <tr> <td>Outside</td><td><u>34°C</u></td><td><u>34°C</u></td></tr> </table>				Before Repair	After Repair	Room	<u>24°C</u>	<u>24°C</u>	Outside	<u>34°C</u>	<u>34°C</u>						
	Before Repair	After Repair																			
Room	<u>24°C</u>	<u>24°C</u>																			
Outside	<u>34°C</u>	<u>34°C</u>																			
Customer Remarks				<table border="1"> <tr> <th></th><th>Before Repair</th><th>After Repair</th></tr> <tr> <td>Room</td><td><u>24°C</u></td><td><u>24°C</u></td></tr> <tr> <td>Outside</td><td><u>34°C</u></td><td><u>34°C</u></td></tr> </table>				Before Repair	After Repair	Room	<u>24°C</u>	<u>24°C</u>	Outside	<u>34°C</u>	<u>34°C</u>						
	Before Repair	After Repair																			
Room	<u>24°C</u>	<u>24°C</u>																			
Outside	<u>34°C</u>	<u>34°C</u>																			
Name	<u>M. D. ...</u>			<table border="1"> <tr> <th></th><th>Before Repair</th><th>After Repair</th></tr> <tr> <td>Room</td><td><u>24°C</u></td><td><u>24°C</u></td></tr> <tr> <td>Outside</td><td><u>34°C</u></td><td><u>34°C</u></td></tr> </table>				Before Repair	After Repair	Room	<u>24°C</u>	<u>24°C</u>	Outside	<u>34°C</u>	<u>34°C</u>						
	Before Repair	After Repair																			
Room	<u>24°C</u>	<u>24°C</u>																			
Outside	<u>34°C</u>	<u>34°C</u>																			

"We recommend, to take routine maintenance services of your Daikin machine at regular intervals, for its good health"

Daikin Customer Care : 1800 180 1800 / 1800 101 2000 : info@daikinindia.com / www.daikinindia.com

C-401, Corporate Avenue Anaheim (Duke's) Link Rd. Anaheim (CA) 92701

Sr.No. 579

*We recommend, to take routine maintenance services of your Datsun machine at regular intervals, for its good health.
Datsun Customer Care: Missed Call or SMS -DARON- to 92101 82290. Toll Free Number : 1550 180 3900 / 1800 102 9004; cs@datsun.co.in / www.datsun.co.in