



DAIKIN AIRCONDITIONING INDIA PVT. LTD.

Authorised Service-Center

AEON AIRCONDITIONING SOLUTIONS

AEON HOUSE, SHOP NO. 6/7, BEHIND N CUBE CHINA TOWN

DR. AMBEDKAR ROAD, THANE W 400601 MAHARASHTRA. PHONE :- 02225370101 / 7900097007



PROJECT :- CIECL Mahatma Phule Road (40 ft road) Indapur

Measurement Sheet											
Sr. No.	Location	AC Type	Tonnage	Indoor Unit Details		Outdoor Unit Details		Copper In Rmt	Cable In Rmt	Drain In Rmt	ODU Stand
				Model No.	Sr. No.	Model No.	Sr. No.				
1	Office Area Split	1.5									
2	Office Area Split	1.5									
3											
4											
5											
6											
7											
8											
EXTRA ACTIVITY CARRIED OUT											
CIVIL WORK	Stabilizer			TIMER	CASING CAPPING	CABLE TRAY	GAS CHARGING	DISMANTLING		RE-INSTALLATION	
	3KVA	4KVA	5KVA					Hi Wall	Cassette		
OTHERS											
For Customer Details : CIECL						Vendor Details : Aeon Airconditioning Solutions					
Sign :						Signature :					
Name :						Technician Name : Tanveer Shaikh					
Date :						Date : 12-02-2025					

Visited the Site where 2 NOS. AC unit has been dismantled & kept in the office. We checked both AC unit, Both AC units copper pipe missing, Found gas leakage, PCB card & Motor missing. Also outer body damaged. So we suggest Both AC replacement with new one.

Note: Both AC units need to be replaced as new ACs are required. The existing units are 6 to 7 years old and have already undergone repairs in the past. Even if they are repaired again and reinstalled, their lifespan will be limited to a maximum of 1 to 2 years. Therefore, we strongly recommend installing new AC units for long-term efficiency and reliability.



Vaibhav Thakur
(Coe Indapur Branch)