



AEON AIRCONDITIONING SOLUTIONS

Aeon House, Shop No. 6/7, Behind N Cube China Town, Opp. Shishu Dnyan Mandir,

Dr. Ambedkar Rd. Thane 400 601, Maharashtra

Tel. : 022 - 25370101 / 7900097007

e-mail : services@aeonacsolutions.com website : www.aeonacsolutions.com

85.8

Project: ICICI Bank Tower - BKC.

Additional Measurement Sheet

Sr. No	Location	AC Type	Tonnage	Indoor Unit Details		Outdoor Unit Details		Copper In Rmt	Cable In Rmt	Drain In Rmt	ODU Stand
				Model No.	Sr. No.	Model No.	Sr. No.				
1	North Lift RM.	Split	1.8	RKMG00V	37127	RKMG00V	39608	5.7	7.7	7.9	Bumbo Stand
2	South Lift RM	Split	1.8	RKMG00V	37109	RKMG00V	3907	5.2	7.7	7.8	Bumbo Stand
3	South Lift RM	Split	1.8	RKMG00V	37141	RKMG00V	39615	11.5	13.5	—	Bumbo Stand.
4	South Lift RM.	Cass.	3.0	ACM100AR	2098	RZM100BR	1598	17.4	18.4	02.	Bumbo Stand.
5	LT Elec. RM	Ductable	5.5	4DR65RRNIG	6563	RR65RRYIG	15058	21.3	—	2.5	Fabricated.
6	LT Elec. RM.	Ductable	5.5	4DR65RRNIG	6564	RR65RRYIG	14460	22.4	—	2.5	Stand modification.
7	CCTV RM	Split	1.8	RKMG00VIG	37402	RKMG00VIG	39694	23.6	25.6	—	—
8	North Lift RM	Split	1.8	RKMG00VIG	37375	RKMG00VIG	39698	6.8	8.8	—	Bumbo Stand.

Extra Activity Carried Out

Civil Work	Stabilizer			Timer	Casing Capping	Cable Tray	Gas Charging	Dismantling		Duct - Uninstallation Re-installation
	3KVA	4KVA	5KVA					Hi Wall	Cassette	
Ductable - 04	Cable 1.5 4mm 2	54mtr	54mtr							
Ductable - 02	Cable 2.5 8mm 2	54mtr	54mtr							
Others	03 Cable 2.5 mm Plain	Supply =	85.8					03.	01 nos	02 nos.

For

Sign

Name

Date

Vendor Details

Signature

Technician Name

Date

Paul 9819844812

Rupam Auelkar

13/12/2024.

Stamp

Aeon Airconditioning Solutions

Harsan, Umar & Riaz.

13/12/2024.





DAIKIN AIRCONDITIONING INDIA PVT. LTD.
Service Completion Certificate



AEON AIRCONDITIONING SOLUTIONS

Office No. 108 & 109, Devashree Garden, Commercial Complex,
R.W. Swam Marg, above Sheetal Dairy, Ratu Park, Thane - 400 601.
Mob.: 9322334107 / 9322334109

562

Subject: Installation Ductable A/C 5.5 TR.

Registration No.		Request Date		Service Engineer		Scheduled Date/Time		Service Order				
User: ICICI Bank				Mobile:		Operation data (Ambient temp. °C)				Fault Diagnosed		✓
Customer Address: ICICI Bank Tower, BKC.												
Base Address:												
Daikin Invoice:				Date:		SP / T °C		pslg/°C		pslg/°C		
Dealer Invoice:				Date:		Current °C		Amps °C		Amps °C		
Type		Model No		Manufacturing No.		Voltage		Volts		Volts		
Outdoor unit /		RR654R716		15058.		Suction		°C		°C		
Indoor unit		4DR654RV16		06563.		Discharge		°C		°C		
Work Date	No. of S.E.	Work hours	Progress code	Details of the Repair Work		Suction		°C		°C		
30/11/2024				Ductable a/c Installation done. Now a/c working & cooling fine.		Discharge		°C		°C		
Compressor manufacturing No.		Defective Compressor		Replacement Compressor		Work No / Parts No		Qty		Billing Amount		
Installed date	Warranty	AMC	Using with	Fault location	Phenomena code	Error code						
	Yes / No	Yes / No	Yes / No	Yes / No								
Service Engineer Remarks												
Name: Umar & Feizan				Signature: [Signature]								
Customer Remarks: Good												
Name: Rishabh Guleria				Signature: [Signature]								
Customer Impression about Service						Details of Repair Work Done						✓
(Please rate on scale of 1 poor, 2, 3, 4 & 5 excellent)												
How is the behavior of visited engineer						a Simple Repair						
What is the level of your satisfaction						b Part Replaced						
How is the explanation by Engineer						c Part Repaired						
						d Gas Charging done						
						e Routine Service - Wet						
						f Routine Service - DRY						

Daikin Customer Care : Missed Call or SMS <DAIKIN> to 92101 88999 ; Toll Free Number : 1860 180 3900 / 1800 102 9300 ; cs@daikinindia.com / www.daikinindia.com



Scanned with OKEN Scanner



DAIKIN AIRCONDITIONING INDIA PVT. LTD.

Service Completion Certificate



AEON AIRCONDITIONING SOLUTIONS

Office No. 108 & 109, Devashree Garden, Commercial Complex,
R.W. Swaant Marg, above Sheetal Dairy, Ratu Park, Thane - 400 601.
Mob.: 9322334107 / 9322334109

561

Subject: Installation Ductable A/C 5.5 TR

Registration No.		Request Date		Service Engineer		Scheduled Date/Time		Service Order	
User: ICICI Bank.		Mobile:		Operation data (Ambient temp. °C)		Fault Diagnosed		✓	
Customer Address: ICICI Bank Tower, BKC.									
I Base Address:									
Daikin Invoice:		Date:		SP / T °C		pslg/		pslg/	
Dealer Invoice:		Date:		Current °C		Amps °C		Amps °C	
Type		Model No		Manufacturing No.		Voltage		Volts	
Outdoor unit /		RR65TR416.		14460..		Indoor temperature			
Indoor unit		4DR65TR416.		06564.		Suction		°C	
Work Date		No. of S.E.		Work hours		Progress code		Details of the Repair Work	
02								Ductable A/C Installation	
12								done. Now all working	
2024.								& Cooling fine.	
Compressor manufacturing No.		Defective Compressor		Replacement Compressor		Work No / Parts No		Qty	
Installed date		Warranty		AMC		Using with		Fault location	
						Stabilizer		Phenomena code	
						Cut off		Error code	
		Yes / No		Yes / No		Yes / No		Yes / No	
Service Engineer Remarks									
Name Umair & Faizan.									
Signature									
Customer Remarks									
Name									
Signature									
981954812									
Customer Impression about Service									
(Please rate on scale of 1 poor, 2, 3, 4 & 5 excellent)									
How is the behavior of visited engineer									
What is the level of your satisfaction									
How is the explanation by Engineer									
a Simple Repair									
b Part Replaced									
c Part Repaired									
d Gas Charging done									
e Routine Service - Wet									
f Routine Service - DRY									

Daikin Customer Care : Missed Call or SMS <DAIKIN> to 92101 88999 ; Toll Free Number : 1860 180 3900 / 1800 102 9300 ; cs@daikinindia.com / www.daikinindia.com



Scanned with OKEN Scanner

DAIKIN AIRCONDITIONING INDIA PVT. LTD. Service Completion Certificate



AEON AIRCONDITIONING SOLUTIONS
Office No. 108 & 109, Devashree Garden, Commercial Complex,
R.W. Swant Marg, above Sheetal Dairy, Ratu Park, Thane - 400 601.
Mob.: 9322334107 / 9322334109

560

Subject: Installation Class A/C. 3.0TR.

Registration No.		Request Date		Service Engineer		Scheduled Date/Time		Service Order	
User: ICICI Bank				Mobile:		Operation data (Ambient temp. °C)			
Customer Address: ICICI Bank Tower, BKC.						Before repair		After repair	
I Base Address:						HP / T		pslg/ pslg/	
Daikin Invoice:				Date:		SP / T °C		pslg °C pslg °C	
Dealer Invoice:				Date:		Current °C		Amps °C Amps °C	
Type		Model No		Manufacturing No.		Voltage		Volts Volts	
Outdoor unit /		R2M1100BRV169.		1598.		Indoor temperature			
Indoor unit		HCM1100ARV169.		2098.		Suction		°C °C	
Work Date	No. of S.E.	Work hours	Progress code	Details of the Repair Work		Discharge		°C °C	
26				Cassette A/C Installation		Suction		°C °C	
11				Done. Now A/C		Discharge		°C °C	
2024				working & Cooling OK.		Outdoor temperature			
Compressor manufacturing No.		Defective Compressor		Replacement Compressor		Work No / Parts No		Qty	
Installed date		Warranty		AMC		Using with		Fault location	
		Yes / No		Yes / No		Stabilizer		Phenomena code	
						Cut off		Error code	
Service Engineer Remarks									
Name: Umar & Faizan				Signature: [Signature]					
Customer Remarks				Customer Impression about Service					
				(Please rate on scale of 1 poor, 2, 3, 4 & 5 excellent)					
Name: [Signature]				How is the behavior of visited engineer					
				What is the level of your satisfaction					
				How is the explanation by Engineer					
Fault Diagnosed									
Power Failure									
Phase Reverse									
In door unit PCB Defective									
Out door PCB Defective									
In door unit Fan Motor Defective									
Outdoor Fan Motor Defective									
Comp. taking High Current / Amp									
Compressor Ground / Earth									
Compressor Tripping due to High Temperature									
Compressor tripping due to High Pressure									
Indoor Unit MgsW Defective									
Outdoor Unit MgsW Defective									
Indoor Unit Transformer Faulty									
Out door Unit Transformer Faulty									
Fault of swing Motor									
Defect of Drain Pump									
Expansion Valve Body / Motor Defective									
Defective Temperature Sensor of Indoor Unit									
Defective Temperature Sensor of Outdoor Unit									
Defective Current Sensor in Out door Unit									
Gas Leakage at Indoor Unit									
Gas Leakage at Outdoor Unit									
Blower broken									
Short Cycling of Air at Indoor Unit									
Short Cycling of Air at Outdoor Unit									
Defect in Drain piping System									
Gas Leakage from Flare nut									
Error In Transmission wiring									
Product under capacity									
Rat bite case									
Less cooling problem due to dirty Airfilter									
Remote setting changed									
Clogged Condenser									
Other - PL specify									
Details of Repair Work Done									
a Simple Repair									
b Part Replaced									
c Part Repaired									
d Gas Charging done									
e Routine Service - Wet									
f Routine Service - DRY									



DAIKIN AIRCONDITIONING INDIA PVT. LTD.
Service Completion Certificate



AEON AIRCONDITIONING SOLUTIONS
Office No. 108 & 109, Devashree Garden, Commercial Complex,
R.W. Swarni Marg, above Sheetal Dairy, Ratu Park, Thane - 400 601.
Mob: 9322334107 / 9322334109

559

Subject: Installation. Split A/C.

Registration No.		Request Date		Service Engineer		Scheduled Date/Time		Service Order				
User: ICICI Bank.				Mobile:		Operation data (Ambient temp. °C)				Fault Diagnosed		✓
Customer Address: ICICI Bank Tower, BKC												
I Base Address:												
Daikin Invoice:				Date:		SP / T °C		pslg/				
Dealer Invoice:				Date:		Current °C		Amps °C				
Type		Model No		Manufacturing No.		Voltage		Volts				
Outdoor unit /		RKRIG00VIGU		39615.		Suction		°C				
Indoor unit		LTKRIG00VIGU		37141.		Discharge		°C				
Work Date	No. of S.E.	Work hours	Progress code	Details of the Repair Work		Suction		°C				
24				A/C Installation done.		Discharge		°C				
11				How air working		Suction		°C				
2024				& Cooling fine.		Discharge		°C				
Compressor manufacturing No.		Defective Compressor		Replacement Compressor		Work No / Parts No		Qty		Billing Amount		
						↑		↑				
Installed date	Warranty	AMC	Using with Stabilizer	Out off	Fault location	Phenomena code	Error code					
	Yes / No	Yes / No	Yes / No	Yes / No								
Service Engineer Remarks												
Name Umar & Jaison.												
Signature [Signature]												
Customer Remarks												
Name												
Signature [Signature]												
Customer Impression about Service												
(Please rate on scale of 1 poor, 2, 3, 4 & 5 excellent)												
How is the behavior of visited engineer												
What is the level of your satisfaction												
How is the explanation by Engineer												
a Simple Repair												
b Part Replaced												
c Part Repaired												
d Gas Charging done												
e Routine Service - Wet												
f Routine Service - DRY												
Details of Repair Work Done												✓

Daikin Customer Care : Missed Call or SMS <DAIKIN> to 92101 88999 ; Toll Free Number : 1860 1803900 / 1800 102 9300 ; cs@daikinindia.com / www.daikinindia.com

DAIKIN AIRCONDITIONING INDIA PVT. LTD. Service Completion Certificate



AEON AIRCONDITIONING SOLUTIONS

Office No. 108 & 109, Devashree Garden, Commercial Complex,
R.W. Swaant Marg, above Sheetal Dairy, Ratu Park, Thane - 400 601.
Mob.: 9322334107 / 9322334109

558

Subject: Installation. Split A/C

Registration No.		Request Date		Service Engineer		Scheduled Date/Time		Service Order	
User: ICICI Bank		Mobile:		Operation data (Ambient temp. °C)		Fault Diagnosed		✓	
Customer Address: ICICI Bank Tower, BKC.				Before repair		After repair			
I Base Address:				HP / T		pslg/		pslg/	
Daikin Invoice:		Date:		SP / T °C		pslg/°C		pslg/°C	
Dealer Invoice:		Date:		Current °C		Amps°C		Amps°C	
Type	Model No	Manufacturing No.		Voltage		Volts		Volts	
Outdoor unit /	RTK160UV16U	3907		Indoor temperature					
Indoor unit	RTK160UV16U	37109		Suction		°C		°C	
Work Date	No. of S.E.	Work hours	Progress code	Details of the Repair Work		Discharge		°C	
24/11/2024				A/C installation done Now a/c working & cooling fine		Suction		°C	
				Outdoor temperature		Discharge		°C	
				Work No / Parts No		Qty		Billing Amount	
				Defective Compressor		Replacement Compressor			
				Installed date		Warranty		AMC	
				Using with Stabilizer		Cut off		Fault location	
				Phenomena code		Error code			
				Service Engineer Remarks		Name		Signature	
				Umar & Faizan		Faizan			
				Customer Remarks		Customer Impression about Service			
				(Please rate on scale of 1 poor, 2, 3, 4 & 5 excellent)		a Simple Repair			
				How is the behavior of visited engineer		b Part Replaced			
				What is the level of your satisfaction		c Part Repaired			
				How is the explanation by Engineer		d Gas Charging done			
						e Routine Service - Wet			
						f Routine Service - DRY			
						Details of Repair Work Done		✓	

Daikin Customer Care : Missed Call or SMS <DAIKIN> to 92101 88999 ; Toll Free Number : 1860 180 3900 / 1800 102 9300 ; cs@daikinindia.com / www.daikinindia.com

Subject: R. V.
Registration No.
DAIKIN
Owner Address

557

DAIKIN AIRCONDITIONING INDIA PVT. LTD. Service Completion Certificate



AEON AIRCONDITIONING SOLUTIONS

Office No. 108 & 109, Devashree Garden, Commercial Complex,
R.W. Swam Marg, above Sheetal Dairy, Ratu Park, Thane - 400 601.
Mob.: 9322334107 / 9322334109

Subject: Installation RPUK AIC

Registration No.		Request Date		Service Engineer		Scheduled Date/Time		Service Order	
User: ICICI Bank.		Mobile:		Operation data (Ambient temp. °C)		Fault Diagnosed		✓	
Customer Address: ICICI Bank Tower, BKC.				Before repair		After repair			
I Base Address:				HP / T		pslg/		pslg/	
Daikin Invoice:		Date:		SP / T °C		pslg °C		pslg °C	
Dealer Invoice:		Date:		Current °C		Amps °C		Amps °C	
Type	Model No	Manufacturing No.		Voltage	Volts	Volts			
Outdoor unit /	RKRM60U16U.	39608		Indoor temperature					
Indoor unit	RTKRM60U16U.	37127.		Suction	°C	°C			
Work Date	No. of S.E.	Work hours	Progress code	Details of the Repair Work		Discharge	°C	°C	
23				AIC Installation done.		Outdoor temperature			
11				Now all working		Suction	°C	°C	
2024				& Cooling fine.		Discharge	°C	°C	
Compressor manufacturing No.		Defective Compressor		Replacement Compressor		Work No / Parts No		Qty	Billing Amount
Installed date	Warranty	AMC	Using with	Fault location	Phenomena code	Error code			
	Yes / No	Yes / No	Yes / No	Yes / No					
Service Engineer Remarks						Total			
Name: Umair & Faizan						Signature: Faizan.			
Customer Remarks						Customer Impression about Service			
						(Please rate on scale of 1 poor, 2, 3, 4 & 5 excellent)			
Name: Pulke						How is the behavior of visited engineer			
981984812						What is the level of your satisfaction			
						How is the explanation by Engineer			
						a Simple Repair			
						b Part Replaced			
						c Part Repaired			
						d Gas Charging done			
						e Routine Service - Wet			
						f Routine Service - DRY			
						Details of Repair Work Done		✓	

Daikin Customer Care : Missed Call or SMS <DAIKIN> to 92101 88999 ; Toll Free Number : 1860 180 3900 / 1800 102 9300 ; cs@daikinindia.com / www.daikinindia.com



Scanned with OKEN Scanner

DAIKIN AIRCONDITIONING INDIA PVT. LTD. Service Completion Certificate

Subject: Installation. Split A/C C.C.T.V. R.R.



AEON AIRCONDITIONING SOLUTIONS

Office No. 108 & 109, Devashree Garden, Commercial Complex,
R.W. Swam Marg, above Sheetal Dairy, Ritu Park, Thane - 400 601.
Mob.: 9322334107 / 9322334109

Registration No.		Request Date		Service Engineer		Scheduled Date/Time		Service Order	
User: ICICI Bank		Mobile :		Operation data (Ambient temp. °C)		Fault Diagnosed		✓	
Customer Address: ICICI Bank Tower, BKC.				Before repair		After repair			
I Base Address :				HP / T		pslg/		pslg/	
Daikin Invoice :		Date :		SP / T °C		pslg/°C		pslg/°C	
Dealer Invoice :		Date :		Current °C		Amps°C		Amps°C	
Type		Model No		Manufacturing No.		Voltage		Volts	
Outdoor unit /		RRTM60UUV16U.		39694.		Suction		°C	
Indoor unit		RTRM60UUV16U.		37402.		Discharge		°C	
Work Date		No. of S.E.		Work hours		Progress code		Details of the Repair Work	
07/12/2024								A/C Installation done. Now all working & cooling fine	
Compressor manufacturing No.		Defective Compressor		Replacement Compressor		Work No / Parts No		Qty	
Installed date		Warranty		AMC		Using with		Fault location	
		Yes / No		Yes / No		Stabilizer		Phenomena code	
						Cut off		Error code	
Service Engineer Remarks									
Name: Umair & Anwar									
Signature: [Signature]									
Customer Remarks									
Name: [Signature]									
Signature: [Signature]									
921984812									
Customer Impression about Service									
(Please rate on scale of 1 poor, 2, 3, 4 & 5 excellent)									
How is the behavior of visited engineer									
What is the level of your satisfaction									
How is the explanation by Engineer									
a Simple Repair									
b Part Replaced									
c Part Repaired									
d Gas Charging done									
e Routine Service - Wet									
f Routine Service - DRY									
Details of Repair Work Done									
Less cooling problem due to dirty Airfilter									
Remote setting changed									
Clogged Condenser									
Other - Pl. specify									

DAIKIN AIRCONDITIONING INDIA PVT. LTD. Service Completion Certificate



AEON AIRCONDITIONING SOLUTIONS

Office No. 108 & 109, Devashree Garden, Commercial Complex,
R.W. Swarn Marg, above Sheetal Dairy, Ratu Park, Thane - 400 601.
Mob.: 9322334107 / 9322334109

Subject: Installation Split A/C. North left dm.

Registration No.		Request Date		Service Engineer		Scheduled Date/Time		Service Order	
User: ICICI Bank.		Mobile:		Operation data (Ambient temp. °C)		Fault Diagnosed		✓	
Customer Address: ICICI Bank Tower - BKC.				Before repair		After repair			
I Base Address:				HP / T		pslg/		pslg/	
Daikin Invoice:		Date:		SP / T °C		pslg °C		pslg °C	
Dealer Invoice:		Date:		Current °C		Amps °C		Amps °C	
Type	Model No	Manufacturing No.		Voltage		Volts		Volts	
Outdoor unit /	RKM160UV16U	39698		Indoor temperature					
Indoor unit	4TKM160UV16U	37375		Suction		°C		°C	
Work Date	No. of S.E.	Work hours	Progress code	Details of the Repair Work		Discharge		°C	
08				A/C Installation done.		Outdoor temperature			
12				Now a/c working		Suction		°C	
2024				& Cooling fine.		Discharge		°C	
Compressor manufacturing No.		Defective Compressor		Replacement Compressor		Work No / Parts No		Qty	
Installed date	Warranty	AMC	Using with	Fault location	Phenomena code	Error code	Billing Amount		
	Yes / No	Yes / No	Yes / No	Yes / No					
Service Engineer Remarks							Total		
Name: Umair & Farzan.							Signature: [Signature]		
Customer Remarks							Customer Impression about Service		
							(Please rate on scale of 1 poor, 2, 3, 4 & 5 excellent)		
Name: [Signature]							How is the behavior of visited engineer		
Signature: [Signature]							What is the level of your satisfaction		
9219844812							How is the explanation by Engineer		
							a Simple Repair		✓
							b Part Replaced		
							c Part Repaired		
							d Gas Charging done		
							e Routine Service - Wet		
							f Routine Service - DRY		
							Details of Repair Work Done		✓