


DAIKIN AIRCONDITIONING INDIA PVT. LTD.

Service Completion Certificate



1281
AEON AIRCONDITIONING SOLUTIONS
Office No. 108 & 109, Devashree Garden, Commercial Complex,
R.W. Swant Marg, above Sheetal Dairy, Ratu Park, Thane - 400 601.
Mob.: 9322334107 / 9322334109

Subject: Installation

Registration No.		Request Date		Service Engineer		Scheduled Date/Time		Service Order	
				Umar					
User: <u>Eat Club - Badlapur</u>				Mobile: _____				Operation data (Ambient temp. °C)	
Customer Address: <u>Shop No 6, 7, 8, Ground Floor</u>								Before repair	
Base Address: <u>Prapti Heritage Manjari Bar</u>								After repair	
Daikin Invoice: _____				Date: _____				HP / T	
Dealer Invoice: _____				Date: _____				SP / T °C	
Type				Model No				Manufacturing No.	
Outdoor unit /				<u>RKLS0UV16VAF</u>				<u>8183597</u>	
Indoor unit				<u>FTQLS0UV16VAF</u>				<u>8112018</u>	
Work Date	No. of S.E.	Work hours	Progress code	Details of the Repair Work					
<u>22/04/25</u>				<u>Installation</u>					
				<u>Colling Good</u>					
Compressor manufacturing No.				Defective Compressor				Replacement Compressor	
Installed date				Warranty				AMC	
Using with				Fault location				Phenomena code	
Stabilizer				Cut off				Error code	
Yes / No				Yes / No				Yes / No	
Service Engineer Remarks									
<u>Umar</u>									
<u>+ Arslan</u>									
<u>Samajeet</u>									
Signature <u>2291622842</u>									
Name									
Customer Remarks									
<u>Samajeet</u>									
Signature									
Customer Impression about Service									
(Please rate on scale of 1 poor, 2, 3, 4 & 5 excellent)									
How is the behavior of visted engineer									
What is the level of your satisfaction									
How is the explanation by Engineer									
a Simple Repair									
b Part Replaced									
c Part Repaired									
d Gas Charging done									
e Routine Service - Wet									
f Routine Service - DRY									
Fault Diagnosed									
Power Failure									
Phase Reverse									
In door unit PCB Defective									
Out door PCB Defective									
In door unit Fan Motor Defective									
Outdoor Fan Motor Defective									
Comp. taking High Current / Amp									
Compressor Ground / Earth									
Compressor Tripping due ot High Temperature									
Compressor tripping due to High Pressure									
Indoor Unit MgSw Defective									
Outdoor Unit Mgsw Defective									
Indoor Unit Transformer Faulty									
Out door Unit Transformer Faulty									
Fault of swing Motor									
Defect of Drain Pump									
Expansion Valve Body / Motor Defective									
Defective Temperature Sensor of Indoor Unit									
Defective Temperature Sensor of Outdoor Unit									
Defective Current Sensor In Out door Unit									
Gas Leakage at Indoor Unit									
Gas Leakage at Outdoor Unit									
Blower broken									
Short Cycling of Air at Indoor Unit									
Short Cycling of Air at Outdoor Unit									
Defect in Drain piping System									
Gas Leakage from Flare nut									
Error In Transmission wiring									
Product under capacity									
Rat bite case									
Less cooling problem due to dirty Airlfilter									
Remote setting changed									
Clogged Condenser									
Other - Pl. specify									
Details of Repair Work Done									