



AEON AIRCONDITIONING SOLUTIONS

Aeon House, Shop No. 6/7, Behind N Cube China Town, Opp. Shishu Dnyan Mandir,

Dr. Ambedkar Rd. Thane 400 601. Maharashtra

Tel : 022 - 25370101 / 7900097007

e-mail : services@aeonacsolutions.com website : www.aeonacsolutions.com

Project: Bajaj Finance Ltd - Vile Parle

Additional Measurement Sheet

Sr. No	Location	AC Type	Tonnage	Indoor Unit Details		Outdoor Unit Details		Copper In Rmt	Cable In Rmt	Drain In Rmt	ODU Stand
				Model No.	Sr. No.	Model No.	Sr. No.				
1	Office - Working Area	4-Way	1.5	FCVFQ50	0002	RZVFQ50	0003	10Mtr	13.5	6	01
2		Cassette		AV16	341	ARV16	264				
3											
4											
5											
6											
7											
8											

Extra Activity Carried Out

Civil Work	Stabilizer			Timer	Casing Capping	Cable Tray	Gas Charging	Dismantling		Re-installation
	3KVA	4KVA	5KVA					Hi Wall	Cassette	
						11Mtr		01		
Others										

Indoor Fabricated frame for Cassette unit - 26Kg.

For

Sign

Name

Date



Vendor Details

Signature

Technician Name

Date

Aeon Airconditioning

Attab Alam

08.03.2025

DAIKIN AIRCONDITIONING INDIA PVT. LTD. Service Completion Certificate


AEON AIRCONDITIONING SOLUTIONS
1867

 Office No 108 & 109, Omvashree Garden, Commercial Complex,
 A W Swarnat Marg, above Shree Lal Dairy, Flau Park, Thane - 400 601
 Mob : 9322334107 / 9322334109

 Subject: **Installation**

Registration No.		Request Date		Service Engineer		Scheduled Date/Time		Service Order			
User: Bajaj Finance Ltd		Mobile:		Operation data (Ambient temp. °C)		Fault Diagnosed					
Customer Address: Vileparle				Before repair		After repair		✓			
Base Address:				HP / T		psig/		psig/			
Daikin Invoice:		Date:		SP / T °C		psig/°C		psig/°C			
Dealer Invoice:		Date:		Current °C		Amps/°C		Amps/°C			
Type	Model No	Manufacturing No.		Voltage		Volts		Volts			
Outdoor unit /	RZVFQ50ARV16	0003264		Indoor temperature							
Indoor unit	FCVFG50AV16	0002341		Suction		°C		°C			
Work Date	No. of S.E.	Work hours	Progress code	Details of the Repair Work		Discharge		°C			
08				Installation Work done.		Outdoor temperature					
03						Suction		°C		°C	
25						Discharge		°C		°C	
Compressor manufacturing No.		Defective Compressor		Replacement Compressor		Work No / Parts No		Qty			
Installed date	Warranty	AMC	Using with	Fault location	Phenomena code	Error code	Billing Amount				
	Yes / No	Yes / No	Yes / No	Yes / No							
Service Engineer Remarks							Total				
Aftab Akum Name:							Signature				
Customer Remarks							Customer Impression about Service				
							(Please rate on scale of 1 poor, 2, 3, 4 & 5 excellent)				
							How is the behavior of visited engineer				
							What is the level of your satisfaction				
							How is the explanation by Engineer				
							a Simple Repair				
							b Part Replaced				
							c Part Repaired				
							d Gas Charging done				
							e Routine Service - Wet				
							f Routine Service - DRY				
							Details of Repair Work Done		✓		