



350 DAIKIN AIRCONDITIONING INDIA PVT. LTD.
Service Completion Certificate



AEON AIRCONDITIONING SOLUTIONS

Office No. 108 & 109, Devashree Garden, Commercial Complex,
R.W. Swaant Marg, above Sheetal Dairy, Ritu Park, Thane - 400 601.
Mob: 9322334107 / 9322334109

Subject :

Registration No.		Request Date		Service Engineer		Scheduled Date/Time		Service Order				
				Azam		17/4/26						
User: COSMOS BANK				Mobile :		Operation data (Ambient temp. °C)						
Customer Address :						Before repair		After repair				
I Base Address : Zaveri Bazar						HP / T	pslg	pslg	Fault Diagnosed			
Daikin Invoice :				Date :		SP / T °C	pslg °C	pslg °C	Power Failure			
Dealer Invoice :				Date :		Current °C	Amps °C	Amps °C	Phase Reverse			
Type	Model No	Manufacturing No.		Voltage	Volts	Volts	In door unit PCB Defective					
Outdoor unit /	RKL35UV16WA	0102119		Indoor temperature			Out door PCB Defective					
Indoor unit	FTKL35UV16WA	0039049		Suction	°C	°C	In door unit Fan Motor Defective					
Work Date	No. of S.E.	Work hours	Progress code	Details of the Repair Work			Discharge	°C	°C	Outdoor Fan Motor Defective		
17	4			1 TR Daikin A/C			Outdoor temperature			Comp. taking High Current / Amp		
26				Installation Done.			Suction	°C	°C	Compressor Ground / Earth		
Compressor manufacturing No.				Defective Compressor		Replacement Compressor		Discharge	°C	°C	Compressor Tripping due to High Temperature	
Installed date	Warranty	AMC	Using with		Fault location	Phenomena code	Error code	Electrical			Compressor tripping due to High Pressure	
	Yes / No	Yes / No	Yes / No	Yes / No				Indoor Unit MgSw Defective			Indoor Unit Transformer Faulty	
Service Engineer Remarks				Cooling fine.				Unit			Out door Unit Transformer Faulty	
Name	Azam	Signature						Gas Leakage at Indoor Unit			Fault of swing Motor	
Customer Remarks				Umesh Purandare		Signature		Other			Defect of Drain Pump	
				Asst. Manager		Signature		Gas Leakage at Outdoor Unit			Expansion Valve Body / Motor Defective	
								Blower broken			Defective Temperature Sensor of Indoor Unit	
								Short Cycling of Air at Indoor Unit			Defective Temperature Sensor of Outdoor Unit	
								Short Cycling of Air at Outdoor Unit			Defective Current Sensor In Out door Unit	
								Defect in Drain piping System			Gas Leakage from Flare nut	
								Error In Transmission wiring			Error In Transmission wiring	
								Product under capacity			Product under capacity	
								Rat bite case			Rat bite case	
								Less cooling problem due to dirty Airfilter			Less cooling problem due to dirty Airfilter	
								Remote setting changed			Remote setting changed	
								Clogged Condenser			Clogged Condenser	
								Other - Pl. specify			Other - Pl. specify	
								Total			Total	
								Details of Repair Work Done			Details of Repair Work Done	
								a Simple Repair			a Simple Repair	
								b Part Replaced			b Part Replaced	
								c Part Repaired			c Part Repaired	
								d Gas Charging done			d Gas Charging done	
								e Routine Service - Wet			e Routine Service - Wet	
								f Routine Service - DRY			f Routine Service - DRY	
								Customer Impression about Service			Customer Impression about Service	
								(Please rate on scale of 1 poor, 2, 3, 4 & 5 excellent)			(Please rate on scale of 1 poor, 2, 3, 4 & 5 excellent)	
								How is the behavior of visited engineer			How is the behavior of visited engineer	
								What is the level of your satisfaction			What is the level of your satisfaction	
								How is the explanation by Engineer			How is the explanation by Engineer	

DAIKIN

351

DAIKIN AIRCONDITIONING INDIA PVT. LTD.
Service Completion Certificate



AEON AIRCONDITIONING SOLUTIONS

Office No. 108 & 109, Davashree Garden, Commercial Complex,
R.W. Svaant Marg, above Sheetal Dairy, Rutu Park, Thane - 400 601.
Mob.: 9322334107 / 9322334109

Subject :

Registration No.		Request Date		Service Engineer		Scheduled Date/Time		Service Order			
				Azeem		17/4/26					
User: Cosmos Bank Customer Address:				Mobile:		Operation data (Ambient temp. °C)			Fault Diagnosed		
I Base Address: Zaveri Bazar.						Before repair		After repair		<input checked="" type="checkbox"/> Power Failure <input type="checkbox"/> Phase Reverse <input type="checkbox"/> In door unit PCB Defective <input type="checkbox"/> Out door PCB Defective <input type="checkbox"/> In door unit Fan Motor Defective <input type="checkbox"/> Outdoor Fan Motor Defective <input type="checkbox"/> Comp. taking High Current / Amp <input type="checkbox"/> Compressor Ground / Earth <input type="checkbox"/> Compressor Tripping due to High Temperature <input type="checkbox"/> Compressor Tripping due to High Pressure <input type="checkbox"/> Indoor Unit MgsW Defective <input type="checkbox"/> Outdoor Unit MgsW Defective <input type="checkbox"/> Indoor Unit Transformer Faulty <input type="checkbox"/> Out door Unit Transformer Faulty <input type="checkbox"/> Fault of swing Motor <input type="checkbox"/> Defect of Drain Pump <input type="checkbox"/> Expansion Valve Body / Motor Defective <input type="checkbox"/> Defective Temperature Sensor of Indoor Unit <input type="checkbox"/> Defective Temperature Sensor of Outdoor Unit <input type="checkbox"/> Defective Current Sensor In Out door Unit <input type="checkbox"/> Gas Leakage at Indoor Unit <input type="checkbox"/> Gas Leakage at Outdoor Unit <input type="checkbox"/> Blower broken <input type="checkbox"/> Short Cycling of Air at Indoor Unit <input type="checkbox"/> Short Cycling of Air at Outdoor Unit <input type="checkbox"/> Defect in Drain piping System <input type="checkbox"/> Gas Leakage from Flare nut <input type="checkbox"/> Error in Transmission wiring <input type="checkbox"/> Product under capacity <input type="checkbox"/> Rat bite case <input type="checkbox"/> Less cooling problem due to dirty Airfilter <input type="checkbox"/> Remote setting changed <input type="checkbox"/> Clogged Condenser <input type="checkbox"/> Other - Pl. specify	
Daikin Invoice:		Date:		SP / T °C		pslg/°C		pslg/°C		Power	
Dealer Invoice:		Date:		Current °C		Amps°C		Amps°C		PCB	
Type		Model No		Manufacturing No.		Voltage		Volts		EM	
Outdoor unit /		R1L 60UV16WA		8032235		Indoor temperature				Comp	
Indoor unit		ATU 60UV16WA		8012474		Suction		°C		Electrical	
Work Date		No. of S.E.		Work hours		Progress code		Details of the Repair Work		Unit	
17		4		26				2-TR Daikin A/C		Installation	
								Installation Done		Other	
										<input type="checkbox"/> Defective Compressor <input type="checkbox"/> Replacement Compressor <input type="checkbox"/> Blower broken <input type="checkbox"/> Short Cycling of Air at Indoor Unit <input type="checkbox"/> Short Cycling of Air at Outdoor Unit <input type="checkbox"/> Defect in Drain piping System <input type="checkbox"/> Gas Leakage from Flare nut <input type="checkbox"/> Error in Transmission wiring <input type="checkbox"/> Product under capacity <input type="checkbox"/> Rat bite case <input type="checkbox"/> Less cooling problem due to dirty Airfilter <input type="checkbox"/> Remote setting changed <input type="checkbox"/> Clogged Condenser <input type="checkbox"/> Other - Pl. specify	
Compressor manufacturing No.		Defective Compressor		Replacement Compressor		Work No / Parts No		Qty		Billing Amount	
Installed date		Warranty		AMC		Using with		Fault location		Phenomena code	
		Yes / No		Yes / No		Stabilizer		Cut off		Error code	
Service Engineer Remarks: cooling fine										Total	
Name: Azeem				Signature:							
Customer Remarks:				Customer Impression about Service							
				(Please rate on scale of 1 poor, 2, 3, 4 & 5 excellent)							
Name: Umesh Purandare				Asst. Manager				Signature:			
				How is the behavior of visited engineer				a Simple Repair			
				What is the level of your satisfaction				b Part Replaced			
				How is the explanation by Engineer				c Part Repaired			
								d Gas Charging done			
								e Routine Service - Wet			
								f Routine Service - DRY			
Details of Repair Work Done										<input checked="" type="checkbox"/>	

DAIKIN

352 DAIKIN AIRCONDITIONING INDIA PVT. LTD.
Service Completion Certificate



AEON AIRCONDITIONING SOLUTIONS

Office No. 108 & 109, Devashree Garden, Commercial Complex,
R.W. Svaant Marg, above Sheetal Dairy, Rutu Park, Thane - 400 601.
Mob.: 9322334107 / 9322334109

Subject :

Registration No.		Request Date		Service Engineer		Scheduled Date/Time		Service Order		
				A. Zam		17/4/26				
User: Cosmos Bank Customer Address:				Mobile:		Operation data (Ambient temp. °C)				
I Base Address: Zaveri Bazar						Before repair		After repair		
Daikin Invoice:				Date:		HP / T	psig/	psig/	Fault Diagnosed	
Dealer Invoice:				Date:		SP / T °C	psig°C	psig°C		Power Failure
Type		Model No		Manufacturing No.		Voltage		Amps°C		
Outdoor unit /		R1K60UV16V		8032212		Volts		Volts		
Indoor unit		ATK160UV16V		8012482		Indoor temperature				
Work Date	No. of S.E.	Work hours	Progress code	Details of the Repair Work				Discharge	°C	
17/4/26				2-TR Daikin A/C installation Done.				Suction	°C	
Compressor manufacturing No.		Defective Compressor		Replacement Compressor		Work No / Parts No		Qty	Billing Amount	
Installed date	Warranty	AMC	Using with		Fault location	Phenomena code	Error code		Unit	
Yes / No	Yes / No	Yes / No	Stabilizer	Cut off						
Service Engineer Remarks: cooling size.										
Name: [Signature]				Signature: [Signature]						
Customer Remarks: Umesh Purandare Asst. Manager				Customer Impression about Service				Total		Installation
				(Please rate on scale of 1 poor, 2, 3, 4 & 5 excellent)						
Name: [Signature]				Signature: [Signature]						
				How is the behavior of visited engineer						
				What is the level of your satisfaction						
				How is the explanation by Engineer						
Details of Repair Work Done										
a Simple Repair										
b Part Replaced										
c Part Repaired										
d Gas Charging done										
e Routine Service - Wet										
f Routine Service - DRY										

DAIKIN

353

DAIKIN AIRCONDITIONING INDIA PVT. LTD.
Service Completion Certificate



AEON AIRCONDITIONING SOLUTIONS

Office No. 108 & 109, Devashree Garden, Commercial Complex,
R.W. Svaant Marg, above Sheetal Dairy, Rutu Park, Thane - 400 601.
Mob.: 9322334107 / 9322334109

Subject :

Registration No.		Request Date		Service Engineer		Scheduled Date/Time		Service Order	
				Azeem		17/4/26			
User: COSMOS BANK				Mobile :		Operation data (Ambient temp. °C)			
Customer Address :						Before repair		After repair	
I Base Address : Zaveri Bazar						HP / T		psig/ psig/	
Daikin Invoice :				Date :		SP / T °C		psig/°C psig/°C	
Dealer Invoice :				Date :		Current °C		Amps°C Amps°C	
Type		Model No		Manufacturing No.		Voltage		Volts Volts	
Outdoor unit /		RKL60UV16V		8032157		Indoor temperature			
Indoor unit		ATKL60UV16V		8012470		Suction		°C °C	
Work Date	No. of S.E	Work hours	Progress code	Details of the Repair Work					
17	4			2 TR DAIKIN A/C					
26				Installation Done.					
Compressor manufacturing No.		Defective Compressor		Replacement Compressor		Work No / Parts No		Qty Billing Amount	
Installed date	Warranty	AMC	Using with		Fault location	Phenomena code	Error code		
	Yes / No	Yes / No	Yes / No	Cut off					
Service Engineer Remarks									
Cooling fine.									
Name AS					Signature				
Customer Remarks					Customer Impression about Service				
					(Please rate on scale of 1 poor, 2, 3, 4 & 5 excellent)				
Name Umesh Purandare					a Simple Repair				
Asst. Manager					b Part Replaced				
Signature					c Part Replaced				
					d Gas Charging done				
					e Routine Service - Wet				
					f Routine Service - DRY				
Details of Repair Work Done									
Power Failure <input checked="" type="checkbox"/>									
Phase Reverse <input type="checkbox"/>									
In door unit PCB Defective <input type="checkbox"/>									
Out door PCB Defective <input type="checkbox"/>									
In door unit Fan Motor Defective <input type="checkbox"/>									
Outdoor Fan Motor Defective <input type="checkbox"/>									
Comp. taking High Current / Amp <input type="checkbox"/>									
Compressor Ground / Earth <input type="checkbox"/>									
Compressor Tripping due of High Temperature <input type="checkbox"/>									
Compressor tripping due to High Pressure <input type="checkbox"/>									
Indoor Unit MgsW Defective <input type="checkbox"/>									
Outdoor Unit MgsW Defective <input type="checkbox"/>									
Indoor Unit Transformer Faulty <input type="checkbox"/>									
Out door Unit Transformer Faulty <input type="checkbox"/>									
Fault of swing Motor <input type="checkbox"/>									
Defect of Drain Pump <input type="checkbox"/>									
Expansion Valve Body / Motor Defective <input type="checkbox"/>									
Defective Temperature Sensor of Indoor Unit <input type="checkbox"/>									
Defective Temperature Sensor of Outdoor Unit <input type="checkbox"/>									
Defective Current Sensor In Out door Unit <input type="checkbox"/>									
Gas Leakage at Indoor Unit <input type="checkbox"/>									
Gas Leakage at Outdoor Unit <input type="checkbox"/>									
Blower broken <input type="checkbox"/>									
Short Cycling of Air at Indoor Unit <input type="checkbox"/>									
Short Cycling of Air at Outdoor Unit <input type="checkbox"/>									
Defect in Drain piping System <input type="checkbox"/>									
Gas Leakage from Flare nut <input type="checkbox"/>									
Error In Transmission wiring <input type="checkbox"/>									
Product under capacity <input type="checkbox"/>									
Rat bite case <input type="checkbox"/>									
Less cooling problem due to dirty Airfilter <input type="checkbox"/>									
Remote setting changed <input type="checkbox"/>									
Clogged Condenser <input type="checkbox"/>									
Other - Pl. specify <input type="checkbox"/>									

DAIKIN

354 DAIKIN AIRCONDITIONING INDIA PVT. LTD.
Service Completion Certificate



AEON AIRCONDITIONING SOLUTIONS

Office No. 108 & 109, Devashree Garden, Commercial Complex,
R.W. Sawaat Marg, above Sheetal Dairy, Ratu Park, Thane - 400 601.
Mob.: 9322334107 / 9322334109

Subject :

Registration No.		Request Date		Service Engineer		Scheduled Date/Time		Service Order						
				Azam		17/11/26								
User: Cosmos Bank			Mobile:			Operation data (Ambient temp. °C)			Fault Diagnosed					
Customer Address:									✓					
I Base Address: Zaverji Bazar														
Daikin Invoice:			Date:			SP / T °C			PSlg/°C					
Dealer Invoice:			Date:			Current °C			Amps°C					
Type		Model No		Manufacturing No.		Voltage		Volts		Volts				
Outdoor unit /		R1CL35UV16W4		0102124		Suction		°C		°C				
Indoor unit		FTKL35UV16WA		0041714		Discharge		°C		°C				
Work Date	No. of S.E.	Work hours	Progress code	Details of the Repair Work										
17	4			1. TR Daikin A/C										
26				Installation Done.										
Compressor manufacturing No.		Defective Compressor		Replacement Compressor		Work No / Parts No		Qty		Billing Amount				
Installed date	Warranty	AMC	Using with		Fault location	Phenomena code	Error code							
	Yes / No	Yes / No	Yes / No	Cut off										
Service Engineer Remarks														
Cooling fine.														
Name: Azam			Signature:											
Customer Remarks						Customer Impression about Service								
Umesh Purandare Asst. Manager						(Please rate on scale of 1 poor, 2, 3, 4 & 5 excellent)								
						How is the behavior of visited engineer			a Simple Repair			d Gas Charging done		
						What is the level of your satisfaction			b Part Replaced			e Routine Service - Wet		
						How is the explanation by Engineer			c Part Repaired			f Routine Service - DRY		
Name: Umesh Purandare						Signature:								
Details of Repair Work Done														
✓														

DAIKIN

355

DAIKIN AIRCONDITIONING INDIA PVT. LTD.
Service Completion Certificate



AEON AIRCONDITIONING SOLUTIONS

Office No. 108 & 109, Devashree Garden, Commercial Complex,
R.W. Swaant Marg, above Sheetal Dairy, Puna Park, Thane - 400 601.
Mob.: 9322334107 / 9322334109

Subject :

Registration No.		Request Date		Service Engineer		Scheduled Date/Time		Service Order																					
				Azeem		17/4/26																							
User: Cosmos Bank			Mobile:			Operation data (Ambient temp. °C)			Fault Diagnosed																				
Customer Address:			I Base Address: Zaveri Road			Date:			Date:																				
Daikin Invoice:			Date:			SP / T °C			pslg/°C																				
Dealer Invoice:			Date:			Current °C			Amps°C																				
Type		Model No		Manufacturing No.		Voltage			Volts																				
Outdoor unit / Indoor unit		RK260UV16V		8032234		Indoor temperature			Suction °C																				
Work Date		No. of S.E.		Work hours		Progress code		Details of the Repair Work																					
17		4		26				2 TR Daikin A/c																					
								insulation Done																					
Compressor manufacturing No.		Defective Compressor		Replacement Compressor		Work No / Parts No			Qty																				
Installed date		Warranty		AMC		Using with		Fault location		Phenomena code																			
Yes / No		Yes / No		Yes / No		Stabilizer Cut off				Error code																			
Yes / No		Yes / No		Yes / No		Yes / No																							
Service Engineer Remarks: cooling fine.																													
Name: [Signature]						Signature: [Signature]																							
Customer Remarks:						Customer Impression about Service																							
Name: Umesh Purandare						Signature: [Signature]																							
Asst. Manager						Name: [Signature]																							
						<table border="1"> <tr> <td>a</td> <td>Simple Repair</td> <td></td> </tr> <tr> <td>b</td> <td>Part Replaced</td> <td></td> </tr> <tr> <td>c</td> <td>Part Repaired</td> <td></td> </tr> <tr> <td>d</td> <td>Gas Charging done</td> <td></td> </tr> <tr> <td>e</td> <td>Routine Service - Wet</td> <td></td> </tr> <tr> <td>f</td> <td>Routine Service - DRY</td> <td></td> </tr> </table>						a	Simple Repair		b	Part Replaced		c	Part Repaired		d	Gas Charging done		e	Routine Service - Wet		f	Routine Service - DRY	
a	Simple Repair																												
b	Part Replaced																												
c	Part Repaired																												
d	Gas Charging done																												
e	Routine Service - Wet																												
f	Routine Service - DRY																												



AEON AIRCONDITIONING SOLUTIONS

Aeon House, Shop No. 6/7, Behind N Cube China Town, Opp. Shishu Dnyan Mandir,
Dr. Ambedkar Rd. Thane 400 601. Maharashtra
Tel. : 022 - 25370101 / 7900097007
e-mail : services@aeonacsolutions.com website : www.aeonacsolutions.com

316

Project : <u>COSMOS BANK</u> <u>Zaveri Bazar</u>											
Additional Measurement Sheet											
Sr. No	Location	AC Type	Tonnage	Indoor Unit Details		Outdoor Unit Details		Copper In Rmt	Cable In Rmt	Drain In Rmt	ODU Stand
				Model No.	Sr. No.	Model No.	Sr. No.				
1	Work Area	Split	2-TR	ATKL60UV16A	8012474	RKL60UV16A	8032238	16	18	14	Fabrication stand
2	Work Area	split	2-TR	ATKL60UV16A	8012482	RKL60UV16A	8032212	13	15	12	Fabrication stand
3	Work Area	Split	2-TR	ATKL60UV16A	8012470	RKL60UV16A	8032157	20	22	18	1
4	Work Area	Split	2-TR	ATKL60UV16A		RKL60UV16A	8032234	18	20	16	1
5	Manager	Split	1-TR	FTKL35UV16WA	0039057	RKL35UV16WA	0102118	12	14	10	1
6	ATM	Split	1-TR	FTKL35UV16WA	0039049	RKL35UV16WA	0102119	10	12	14	1
7	ATM	split	1-TR	FTKL35UV16WA	0041714	RKL35UV16WA	0102124	16	18	10	1
8											
Extra Activity Carried Out											
Civil Work	Stabilizer			Timer	Casing Capping	Cable Tray	Gas Charging	Dismantling		Re-installation	
	3KVA	4KVA	5KVA					Hi Wall	Cassette		
				1							
Others <u>code cutting & ins. Hold</u>				Fabrication stand							
For						Vendor Details					
Sign	 Umesh Purandare Asst. Manager Stamp					Signature	 Technician Name A Zaveri Date 17/4/26				
Name						Signature					
Date						Signature					