



# AEON AIRCONDITIONING SOLUTIONS

Aeon House, Shop No. 6/7, Behind N Cube China Town, Opp. Shishu Dnyan Mandir,  
Dr. Ambedkar Rd. Thane 400 601. Maharashtra  
Tel. : 022 - 25370101 / 7900097007

e-mail : services@aeonacsolutions.com website : www.aeonacsolutions.com

Project : Torrent Diagnostics. (Turbhe).

## Additional Measurement Sheet

| Sr. No | Location        | AC Type | Tonnage | Indoor Unit Details |         | Outdoor Unit Details |         | Copper In Rmt | Cable In Rmt | Drain In Rmt | ODU Stand |
|--------|-----------------|---------|---------|---------------------|---------|----------------------|---------|---------------|--------------|--------------|-----------|
|        |                 |         |         | Model No.           | Sr. No. | Model No.            | Sr. No. |               |              |              |           |
| 1      | 1 floor office. | Splitte | 1.5.    | FTK50UV16K 8020495  |         | RK50UV16K 8024700    |         | 3 mt          | 4 mt         | -            | 1         |
| 2      |                 |         |         |                     |         |                      |         |               |              |              |           |
| 3      |                 |         |         |                     |         |                      |         |               |              |              |           |
| 4      |                 |         |         |                     |         |                      |         |               |              |              |           |
| 5      |                 |         |         |                     |         |                      |         |               |              |              |           |
| 6      |                 |         |         |                     |         |                      |         |               |              |              |           |
| 7      |                 |         |         |                     |         |                      |         |               |              |              |           |
| 8      |                 |         |         |                     |         |                      |         |               |              |              |           |

## Extra Activity Carried Out

| Civil Work | Stabilizer |      |      | Timer | Casing Capping | Cable Tray | Gas Charging | Dismantling |          | Re-installation |
|------------|------------|------|------|-------|----------------|------------|--------------|-------------|----------|-----------------|
|            | 3KVA       | 4KVA | 5KVA |       |                |            |              | Hi Wall     | Cassette |                 |
| -          | -          | -    | -    | -     | -              | -          | -            | -           | -        | -               |
| Others     |            |      |      |       |                |            |              |             |          |                 |

|      |             |  |  |  |  |                 |                |
|------|-------------|--|--|--|--|-----------------|----------------|
| For  |             |  |  |  |  | Vendor Details  |                |
| Sign |             |  |  |  |  | Signature       |                |
| Name | Rahul Nalho |  |  |  |  | Technician Name | Vendor SHAIKH. |
| Date | 17/04/25    |  |  |  |  | Date            | 17/04/25       |

Stamp

**DAIKIN**

# DAIKIN AIRCONDITIONING INDIA PVT. LTD. Service Completion Certificate


**AEON AIRCONDITIONING SOLUTIONS**

 Office No. 108 & 109, Devashree Garden, Commercial Complex,  
 R.W. Swant Marg, above Sheetal Dairy, Ratu Park, Thane - 400 601.  
 Mob.: 9322334107 / 9322334109

1269

 Subject: Installation.

|                                                        |  |              |  |                                                         |  |                     |                                              |               |  |
|--------------------------------------------------------|--|--------------|--|---------------------------------------------------------|--|---------------------|----------------------------------------------|---------------|--|
| Registration No.                                       |  | Request Date |  | Service Engineer                                        |  | Scheduled Date/Time |                                              | Service Order |  |
|                                                        |  |              |  | Umar SHAKH                                              |  |                     |                                              |               |  |
| User: <u>Torrent Diagnostics</u> Mobile:               |  |              |  | Operation data (Ambient temp. °C)                       |  |                     | Fault Diagnosed                              |               |  |
| Customer Address: <u>C-531 D shirt Company, Sevi</u>   |  |              |  |                                                         |  |                     | ✓                                            |               |  |
| Base Address: <u>Chemical Rad MIDC Pawane (Turbhe)</u> |  |              |  |                                                         |  |                     |                                              |               |  |
| Daikin Invoice:                                        |  |              |  | Date:                                                   |  |                     | Power                                        |               |  |
| Dealer Invoice:                                        |  |              |  | Date:                                                   |  |                     | Phase Reverse                                |               |  |
| Type                                                   |  |              |  | Model No                                                |  |                     | PCB                                          |               |  |
| Outdoor unit /                                         |  |              |  | RKC50UV16VF                                             |  |                     | In door unit PCB Defective                   |               |  |
| Indoor unit                                            |  |              |  | fTRKC50UV16VF                                           |  |                     | Out door PCB Defective                       |               |  |
| Work Date                                              |  |              |  | No. of S.E.                                             |  |                     | EM                                           |               |  |
| 17/04/25                                               |  |              |  |                                                         |  |                     | In door unit Fan Motor Defective             |               |  |
| Work hours                                             |  |              |  | Progress code                                           |  |                     | Outdoor Fan Motor Defective                  |               |  |
| Details of the Repair Work                             |  |              |  | SP / T °C                                               |  |                     | Comp. taking High Current / Amp              |               |  |
| Installation done                                      |  |              |  | Current °C                                              |  |                     | Compressor Ground / Earth                    |               |  |
| Celling good.                                          |  |              |  | Amps °C                                                 |  |                     | Compressor Tripping due to High Temperature  |               |  |
|                                                        |  |              |  | Voltage                                                 |  |                     | Compressor tripping due to High Pressure     |               |  |
|                                                        |  |              |  | Volts                                                   |  |                     | Indoor Unit MgSw Defective                   |               |  |
|                                                        |  |              |  | Volts                                                   |  |                     | Outdoor Unit Mgsw Defective                  |               |  |
|                                                        |  |              |  | Suction                                                 |  |                     | Indoor Unit Transformer Faulty               |               |  |
|                                                        |  |              |  | °C                                                      |  |                     | Out door Unit Transformer Faulty             |               |  |
|                                                        |  |              |  | Discharge                                               |  |                     | Fault of swing Motor                         |               |  |
|                                                        |  |              |  | °C                                                      |  |                     | Defect of Drain Pump                         |               |  |
|                                                        |  |              |  | °C                                                      |  |                     | Expansion Valve Body / Motor Defective       |               |  |
|                                                        |  |              |  | °C                                                      |  |                     | Defective Temperature Sensor of Indoor Unit  |               |  |
|                                                        |  |              |  | °C                                                      |  |                     | Defective Temperature Sensor of Outdoor Unit |               |  |
|                                                        |  |              |  | °C                                                      |  |                     | Defective Current Sensor In Out door Unit    |               |  |
|                                                        |  |              |  | Work No / Parts No                                      |  |                     | Unit                                         |               |  |
|                                                        |  |              |  | Qty                                                     |  |                     | Gas Leakage at Indoor Unit                   |               |  |
|                                                        |  |              |  | Billing Amount                                          |  |                     | Gas Leakage at Outdoor Unit                  |               |  |
|                                                        |  |              |  | Stand                                                   |  |                     | Blower broken                                |               |  |
|                                                        |  |              |  | 1                                                       |  |                     | Short Cycling of Air at Indoor Unit          |               |  |
|                                                        |  |              |  |                                                         |  |                     | Short Cycling of Air at Outdoor Unit         |               |  |
|                                                        |  |              |  |                                                         |  |                     | Defect in Drain piping System                |               |  |
|                                                        |  |              |  |                                                         |  |                     | Gas Leakage from Flare nut                   |               |  |
|                                                        |  |              |  |                                                         |  |                     | Error In Transmission wiring                 |               |  |
|                                                        |  |              |  |                                                         |  |                     | Product under capacity                       |               |  |
|                                                        |  |              |  |                                                         |  |                     | Rat bite case                                |               |  |
|                                                        |  |              |  |                                                         |  |                     | Less cooling problem due to dirty Airfilter  |               |  |
|                                                        |  |              |  |                                                         |  |                     | Remote setting changed                       |               |  |
|                                                        |  |              |  |                                                         |  |                     | Clogged Condenser                            |               |  |
|                                                        |  |              |  |                                                         |  |                     | Other - PL specify                           |               |  |
|                                                        |  |              |  | Total                                                   |  |                     | Details of Repair Work Done                  |               |  |
|                                                        |  |              |  |                                                         |  |                     | ✓                                            |               |  |
| Compressor manufacturing No.                           |  |              |  | Defective Compressor                                    |  |                     | Replacement Compressor                       |               |  |
| Installed date                                         |  |              |  | Warranty                                                |  |                     | AMC                                          |               |  |
| Yes / No                                               |  |              |  | Yes / No                                                |  |                     | Yes / No                                     |               |  |
| Using with                                             |  |              |  | Stabilizer                                              |  |                     | Cut off                                      |               |  |
| Yes / No                                               |  |              |  | Yes / No                                                |  |                     | Yes / No                                     |               |  |
| Fault location                                         |  |              |  | Phenomena code                                          |  |                     | Error code                                   |               |  |
| Service Engineer Remarks                               |  |              |  | Umar                                                    |  |                     | Signature                                    |               |  |
| Name                                                   |  |              |  | Ahsan                                                   |  |                     |                                              |               |  |
| Customer Remarks                                       |  |              |  | Rahul Nath                                              |  |                     | Signature                                    |               |  |
| Name                                                   |  |              |  |                                                         |  |                     |                                              |               |  |
| Customer Impression about Service                      |  |              |  | (Please rate on scale of 1 poor, 2, 3, 4 & 5 excellent) |  |                     |                                              |               |  |
| How is the behavior of visted engineer                 |  |              |  |                                                         |  |                     | a Simple Repair                              |               |  |
| What is the level of your satisfaction                 |  |              |  |                                                         |  |                     | b Part Replaced                              |               |  |
| How is the explanation by Engineer                     |  |              |  |                                                         |  |                     | c Part Repaired                              |               |  |
|                                                        |  |              |  |                                                         |  |                     | d Gas Charging done                          |               |  |
|                                                        |  |              |  |                                                         |  |                     | e Routine Service - Wet                      |               |  |
|                                                        |  |              |  |                                                         |  |                     | f Routine Service - DRY                      |               |  |