

DAIKIN

DAIKIN AIRCONDITIONING INDIA PVT. LTD.
 Authorised Service Provider



AEON AIRCONDITIONING SOLUTIONS

AEON HOUSE, SHOP NO. 6 & 7, BEHIND N CUBE CHINA TOWN

DR. AMBEDKAR ROAD, THANE W 400601 MAHARASHTRA. PHONE :- 02225370101 / 7900097007 / 9322334106

PROJECT :- M/S. Sivaaram - Sikk Sikk Mills Ltd. H-3/1 Midc Tarapur Buisong 401506

Measurement Sheet

Sr. No.	Location	AC Type	Tonnage	Indoor Unit Details		Outdoor Unit Details		Copper In Rmt	Cable In Rmt	Drain In Rmt	ODU Stand
				Model No.	Sr. No.	Model No.	Sr. No.				
1	R.O. OFF. SP. 114.1.9		1.5 ton	FTKL600V16V	8022 642	RKLG00V16V	8033 684				01
2											
3											
4											
5											
6											
7											
8											
9											
10											

EXTRA ACTIVITY CARRIED OUT

CIVIL WORK	Stabilizer			TIMER	CASING CAPPING	CABLE TRAY	GAS CHARGING	DISMENTALING		RE-INSTALLATION
	3KVA	4KVA	5KVA					Hi Wall	Cassette	
								01		
OTHERS										

Customer Details: Work completed under observation
 22/07/2026

Vendor Details:
 Signature:
 Technician Name:
 Date: 07.01.2026

AB. Sheikh
 Aswif Sheikh



DAIKIN

DAIKIN AIRCONDITIONING INDIA PVT. LTD. Service Completion Certificate

AEON AIRCONDITIONING SOLUTIONS

1415

Office No. 106 & 109, Dabholkar Complex, Chhatrapati Shivaji Maharaj Marg, above Shivajinagar, Pune-411 004. Mob: 9822341313 / 9822334199

Subject: **Installation**

Registration No. _____ Received Date _____ Service Engineer _____ Scheduled Date/Time _____ Service Order _____

User: **M/S. Siyaram Silk Mills**

Customer Address: **Boisar, MIDC - H-3/1**

Daikin Invoice: _____ Date: _____

Dealer Invoice: _____ Date: _____

Type	Model No.	Manufacturing No.
Outdoor unit /	RAL60UV16V-8033684	
Indoor unit	FTKL60UM6V-8022642	

Work Date	No. of S.E.	Work hours	Progress code	Details of the Repair Work
07				AC. installation work done cooling OK.
01				
20/25				

Compressor manufacturing No.	Defective Compressor	Replacement Compressor

Installed date	Warranty	AMC	Using with Silacitzat	Cut off	Fault location	Phenomena code	Error code
	Yes / No	Yes / No	Yes / No	Yes / No			

Service Engineer Remarks: _____

Name: **Ashif Shukh** Signature: **AS. Shukh**

Customer Remarks: **Remote handed to the customer**

Name: _____ Signature: _____

Customer Impression about Service (Please rate on scale of 1 poor, 2, 3, 4 & 5 excellent)

How is the behavior of visited engineer	What is the level of your satisfaction	How is the explanation by Engineer

Unit	Details of Repair Work Done
Electrical	<input checked="" type="checkbox"/> Power failure
	<input type="checkbox"/> Phase Reversal
	<input type="checkbox"/> Indoor unit PCB Defective
	<input type="checkbox"/> Outdoor PCB Defective
	<input type="checkbox"/> Indoor unit Fan Motor Defective
	<input type="checkbox"/> Outdoor Fan Motor Defective
	<input type="checkbox"/> Comp. Working High Current / Amps
	<input type="checkbox"/> Compressor Overload / Error
	<input type="checkbox"/> Compressor Tripping due to High Temperature
	<input type="checkbox"/> Compressor Tripping due to High Pressure
Mechanical	<input type="checkbox"/> Indoor Unit Motor Defective
	<input type="checkbox"/> Outdoor Unit Transformer Faulty
	<input type="checkbox"/> Indoor Unit Transformer Faulty
	<input type="checkbox"/> Fault of swing Motor
	<input type="checkbox"/> Defect of Drain Pump
	<input type="checkbox"/> Expansion Valve Body / Motor Defective
	<input type="checkbox"/> Defective Temperature Sensor of indoor Unit
	<input type="checkbox"/> Defective Temperature Sensor of outdoor Unit
	<input type="checkbox"/> Defective Current Sensor in Outdoor Unit
	<input type="checkbox"/> Gas Leakage at Indoor Unit
Installation	<input type="checkbox"/> Gas Leakage at Outdoor Unit
	<input type="checkbox"/> Blower broken
	<input type="checkbox"/> Short Cycling of Air at Indoor Unit
	<input type="checkbox"/> Short Cycling of Air at Outdoor Unit
	<input type="checkbox"/> Defect in Drain piping System
	<input type="checkbox"/> Gas Leakage from Flare nut
	<input type="checkbox"/> Error in Transmission wiring
	<input type="checkbox"/> Product under capacity
	<input type="checkbox"/> Rat bite case
	<input type="checkbox"/> Less cooling problem due to dirty Airfilter
Other	<input type="checkbox"/> Remote setting changed
	<input type="checkbox"/> Glogged Condenser
	<input type="checkbox"/> Other - Pl. specify

Daikin, Customer Care : Missed Call or SMS <DAIKIN> to 92101 88999 ; Toll Free Number : 1880 180 3900 / 1800 102 9300 ; cs@daikinindia.com / www.daikinindia.com

Ro panel Room AC installation work completed working under observation



Handwritten signature and date: Ashif 07/10/20