



AEON AIRCONDITIONING SOLUTIONS

Aeon House, Shop No. 6/7, Behind N Cube China Town, Opp. Shishu Dnyan Mandir,
Dr. Ambedkar Rd. Thane 400 601. Maharashtra
Tel. : 022 - 25370101 / 7900097007
e-mail : services@aeonacsolutions.com website : www.aeonacsolutions.com

112

Project : City Union Bank - Khar.

Additional Measurement Sheet

Sr. No	Location	AC Type	Tonnage	Indoor Unit Details		Outdoor Unit Details		Copper In Rmt	Cable In Rmt	Drain In Rmt	ODU Stand
				Model No.	Sr. No.	Model No.	Sr. No.				
1	Lobby	Casaset	2.0.	RCVF071AV16	1282	RZVF071AV16	12626	7.62	8.5	4.5	1 Big
2	Lobby	Split	1.0.	FTKc35UV16W	29127	RKc35UV16W	27057	8.2	9.1	4.5	1
3	ATM	Split	1.0.	FTKc35UV16W	29126	RKc35UV16W	27026	10.6	11.5	4.5	1
4	Manager cabin.	Split	1.0.	FTKc35UV16W	29131	RKc35UV16W	27037	9.1	10.3	4.5	1
5	Up cabin.	Split	1.0.	FTKc35UV16W	29133	RKc35UV16W	27036	15.2	16.4	4.5	1
6	Server Room	Split	1.0.	FTKc35UV16W	29136	RKc35UV16W	27063	10.6	11.5	4.5	1
7											
8											

Extra Activity Carried Out

Civil Work	Stabilizer			Timer	Casing Capping	Cable Tray	Gas Charging	Dismantling		Re-installation
	3KVA	4KVA	5KVA					Hi Wall	Cassette	
3mt seasoning	-	-	-	-	-	-	-	-	-	-

Others 1 drain pump. Core Cutting - 02 nos

For				Vendor Details	
Sign				Signature	Aeon - AIRCONDITIONING.
Name				Technician Name	Umar SHAIKH.
Date				Date	9/12/25



09/12/2025
Hijeshwarand



DAIKIN AIRCONDITIONING INDIA PVT. LTD.
Service Completion Certificate

AEON AIRCONDITIONING SOLUTIONS

Office No. 101 & 102, Devasthanam Garden, Commercial Complex,
FLV, Bowand Mang, Above Shastri Circle, Puli Park, Thane - 400 001
Mob: 932234101 / 932234102

Installation

1415

Registration No.		Request Date		Service Engineer		Scheduled Date/Time		Service Center	
User: City Union Bank.		Mobile:		Operation data (Ambient temp. °C)		Fault Description		✓	
Customer Address: — Khar.				Before repair		After repair			
Base Address:				HP / T		psig/		psig/	
Date In Invoice:		Date:		SP / T °C		psig/°C		psig/°C	
Dealer Invoice:		Date:		Current °C		Amps °C		Amps °C	
Type		Model No		Manufacturing No.		Voltage		Volts	
Outdoor unit / Indoor unit		RZVF071AV16 FTEVF071AV16		12626 1282		Indoor temperature			
Work Date		No. of S.E.		Work hours		Progress code		Details of the Repair Work	
09/12/25								Installation done. Colling good.	
Compressor manufacturing No.		Defective Compressor		Replacement Compressor		Work No / Parts No		Qty	
Installed date		Warranty		AMC		Using with		Fault location	
		Yes / No		Yes / No		Stabilizer		Phenomena code	
						Cut off		Error code	
Service Engineer Remarks		Umar		Signature		Total		Billing Amount	
Customer Remarks		Signature		Signature		Other		Details of Repair Work Done	
Name		Signature		Signature		Other		✓	
Customer Impression about Service		(Please rate on scale of 1 poor, 2, 3, 4 & 5 excellent)		a Simple Repair		b Part Replaced		c Part Repaired	
How is the behavior of visited engineer				d Gas Charging done		e Routine Service - Wet		f Routine Service - DRY	
What is the level of your satisfaction									
How is the explanation by Engineer									

Daikin Customer Care : Missed Call or SMS <DAIKIN> to 92101 88999 ; Toll Free Number : 1860 180 3000 / 1800 102 9300 ; cs@daikinindia.com / www.daikinindia.com



DAIKIN AIRCONDITIONING INDIA PVT. LTD.

Service Completion Certificate

Subject: Installation.



AEON AIRCONDITIONING SOLUTIONS
Office No. 108 & 109, Denashree Garden, Commercial Complex,
H. Sward Marg, above Sheetal Dairy, Pudu Park, Thane - 400 601
Mob : 9322334107 / 9322334109

1415

Registration No.		Request Date		Service Engineer		Scheduled Date/Time		Service Order	
User: City Union Bank		Mobile: Umar							
Customer Address: — khar.				Operation data (Ambient temp. °C)				Fault Diagnosis	
Base Address:				Before repair		After repair		Power Failure	
				HP / T		psig/		psig/	
Outdoor unit /				SP / T °C		psig/°C		psig/°C	
Indoor unit				Current °C		Amps °C		Amps °C	
Work Date				Voltage		Volts		Volts	
No. of S.E.				Indoor temperature					
Work hours				Suction		°C		°C	
Progress code				Discharge		°C		°C	
Details of the Repair Work				Outdoor temperature					
Installation done. Colling good.				Suction		°C		°C	
				Discharge		°C		°C	
Compressor manufacturing No.				Work No / Parts No		Qty		Billing Amount	
Installed date				Total					
Warranty									
AMC									
Stabilizer									
Cut off									
Fault location									
Phenomena code									
Error code									
Service Engineer Remarks									
Name									
Signature									
Customer Remarks									
Name									
Signature									
Customer Impression about Service									
(Please rate on scale of 1 poor, 2, 3, 4 & 5 excellent)									
How is the behavior of visited engineer									
What is the level of your satisfaction									
How is the explanation by Engineer									
a Simple Repair									
b Part Replaced									
c Part Repaired									
d Gas Charging done									
e Routine Service - Wet									
f Routine Service - DRY									

DAIKIN

DAIKIN AIRCONDITIONING INDIA PVT. LTD.
Service Completion Certificate



AEON AIRCONDITIONING SOLUTIONS

Office No. 108 & 109, Connaught Garden, Connaught Place, New Delhi - 110028
R.V. Sharma Marg, above Shanti Park, Puna Park, Thane - 400 001
Mob: 9322334101 / 9322334102

1415

Subject: Installation

Registration No.		Request Date		Service Engineer		Scheduled Date/Time		Service Center																																																																					
				Umar																																																																									
User: <u>City Union Bank.</u>				Mobile:		Operation data (Ambient temp. °C)																																																																							
Customer Address:						<table border="1"> <tr> <td></td> <td>Before repair</td> <td>After repair</td> </tr> <tr> <td>HP / T</td> <td>psig/</td> <td>psig/</td> </tr> <tr> <td>SP / T °C</td> <td>psig/°C</td> <td>psig/°C</td> </tr> <tr> <td>Current °C</td> <td>Amps°C</td> <td>Amps°C</td> </tr> <tr> <td>Voltage</td> <td>Volts</td> <td>Volts</td> </tr> </table>					Before repair	After repair	HP / T	psig/	psig/	SP / T °C	psig/°C	psig/°C	Current °C	Amps°C	Amps°C	Voltage	Volts	Volts																																																					
	Before repair	After repair																																																																											
HP / T	psig/	psig/																																																																											
SP / T °C	psig/°C	psig/°C																																																																											
Current °C	Amps°C	Amps°C																																																																											
Voltage	Volts	Volts																																																																											
I Base Address:						Fault Charge/No.																																																																							
Daikin Invoice:				Date:		<table border="1"> <tr> <td>Power Failure</td> <td></td> </tr> <tr> <td>Phase Reversal</td> <td></td> </tr> <tr> <td>In door unit PCB Defective</td> <td></td> </tr> <tr> <td>Out door PCB Defective</td> <td></td> </tr> <tr> <td>In door unit Fan Motor Defective</td> <td></td> </tr> <tr> <td>Outdoor Fan Motor Defective</td> <td></td> </tr> <tr> <td>Comp. taking High Current / Amp</td> <td></td> </tr> <tr> <td>Compressor Ground / Earth</td> <td></td> </tr> <tr> <td>Compressor Tripping due to High Temperature</td> <td></td> </tr> <tr> <td>Compressor tripping due to High Pressure</td> <td></td> </tr> <tr> <td>Indoor Unit M/Sw Defective</td> <td></td> </tr> <tr> <td>Outdoor Unit M/Sw Defective</td> <td></td> </tr> <tr> <td>Indoor Unit Transformer Faulty</td> <td></td> </tr> <tr> <td>Out door Unit Transformer Faulty</td> <td></td> </tr> <tr> <td>Fault of swing Motor</td> <td></td> </tr> <tr> <td>Defect of Drain Pump</td> <td></td> </tr> <tr> <td>Expansion Valve Body / Motor Defective</td> <td></td> </tr> <tr> <td>Defective Temperature Sensor of Indoor Unit</td> <td></td> </tr> <tr> <td>Defective Temperature Sensor of Outdoor Unit</td> <td></td> </tr> <tr> <td>Defective Current Sensor in Out door Unit</td> <td></td> </tr> <tr> <td>Gas Leakage at Indoor Unit</td> <td></td> </tr> <tr> <td>Gas Leakage at Outdoor Unit</td> <td></td> </tr> <tr> <td>Blower broken</td> <td></td> </tr> <tr> <td>Short Cycling of Air at Indoor Unit</td> <td></td> </tr> <tr> <td>Short Cycling of Air at Outdoor Unit</td> <td></td> </tr> <tr> <td>Defect in Drain piping System</td> <td></td> </tr> <tr> <td>Gas Leakage from Flare nut</td> <td></td> </tr> <tr> <td>Error in Transmission wiring</td> <td></td> </tr> <tr> <td>Product under capacity</td> <td></td> </tr> <tr> <td>Rat bite case</td> <td></td> </tr> <tr> <td>Less cooling problem due to dirty Airfilter</td> <td></td> </tr> <tr> <td>Remote setting changed</td> <td></td> </tr> <tr> <td>Clogged Condenser</td> <td></td> </tr> <tr> <td>Other - PL specify</td> <td></td> </tr> </table>				Power Failure		Phase Reversal		In door unit PCB Defective		Out door PCB Defective		In door unit Fan Motor Defective		Outdoor Fan Motor Defective		Comp. taking High Current / Amp		Compressor Ground / Earth		Compressor Tripping due to High Temperature		Compressor tripping due to High Pressure		Indoor Unit M/Sw Defective		Outdoor Unit M/Sw Defective		Indoor Unit Transformer Faulty		Out door Unit Transformer Faulty		Fault of swing Motor		Defect of Drain Pump		Expansion Valve Body / Motor Defective		Defective Temperature Sensor of Indoor Unit		Defective Temperature Sensor of Outdoor Unit		Defective Current Sensor in Out door Unit		Gas Leakage at Indoor Unit		Gas Leakage at Outdoor Unit		Blower broken		Short Cycling of Air at Indoor Unit		Short Cycling of Air at Outdoor Unit		Defect in Drain piping System		Gas Leakage from Flare nut		Error in Transmission wiring		Product under capacity		Rat bite case		Less cooling problem due to dirty Airfilter		Remote setting changed		Clogged Condenser		Other - PL specify	
Power Failure																																																																													
Phase Reversal																																																																													
In door unit PCB Defective																																																																													
Out door PCB Defective																																																																													
In door unit Fan Motor Defective																																																																													
Outdoor Fan Motor Defective																																																																													
Comp. taking High Current / Amp																																																																													
Compressor Ground / Earth																																																																													
Compressor Tripping due to High Temperature																																																																													
Compressor tripping due to High Pressure																																																																													
Indoor Unit M/Sw Defective																																																																													
Outdoor Unit M/Sw Defective																																																																													
Indoor Unit Transformer Faulty																																																																													
Out door Unit Transformer Faulty																																																																													
Fault of swing Motor																																																																													
Defect of Drain Pump																																																																													
Expansion Valve Body / Motor Defective																																																																													
Defective Temperature Sensor of Indoor Unit																																																																													
Defective Temperature Sensor of Outdoor Unit																																																																													
Defective Current Sensor in Out door Unit																																																																													
Gas Leakage at Indoor Unit																																																																													
Gas Leakage at Outdoor Unit																																																																													
Blower broken																																																																													
Short Cycling of Air at Indoor Unit																																																																													
Short Cycling of Air at Outdoor Unit																																																																													
Defect in Drain piping System																																																																													
Gas Leakage from Flare nut																																																																													
Error in Transmission wiring																																																																													
Product under capacity																																																																													
Rat bite case																																																																													
Less cooling problem due to dirty Airfilter																																																																													
Remote setting changed																																																																													
Clogged Condenser																																																																													
Other - PL specify																																																																													
Type				Model No		Manufacturing No.																																																																							
Outdoor unit /				RKC35UV16W		27037																																																																							
Indoor unit				FTKC35UV16W		29131																																																																							
Work Date				No. of S.E.		Work hours		Progress code																																																																					
09/12/25																																																																													
Details of the Repair Work																																																																													
Installation done.																																																																													
Colling good.																																																																													
Compressor manufacturing No.				Defective Compressor		Replacement Compressor																																																																							
Installed date				Warranty		AMC		Using with																																																																					
								Stabilizer Cut off																																																																					
Yes / No				Yes / No		Yes / No		Yes / No																																																																					
Service Engineer Remarks				Umar		Signature																																																																							
Customer Remarks																																																																													
Name																																																																													
Signature																																																																													
Customer Impression about Service																																																																													
(Please rate on scale of 1 poor, 2, 3, 4 & 5 excellent)																																																																													
How is the behavior of visited engineer																																																																													
What is the level of your satisfaction																																																																													
How is the explanation by Engineer																																																																													
a Simple Repair																																																																													
b Part Replaced																																																																													
c Part Repaired																																																																													
d Gas Charging done																																																																													
e Routine Service - Wet																																																																													
f Routine Service - DRY																																																																													
Details of Repair Work Done																																																																													

Daikin Customer Care : Missed Call or SMS <DAIKIN> to 92101 88999 ; Toll Free Number : 1860 180 3900 / 1800 102 9300 ; cs@daikinindia.com / www.daikinindia.com



Scanned with OKEN Scanner

DAIKIN

DAIKIN AIRCONDITIONING INDIA PVT. LTD. Service Completion Certificate


AEON AIRCONDITIONING SOLUTIONS

 Office No. 108 & 109, Dhanashree Garden, Commercial Complex,
 R.V. Swarni Marg, above Shree Lal Dairy, Pusa Park, Thane - 400 601.
 Mob.: 9322334107 / 9322334109

1415

 Subject: *Installation*

Registration No.		Request Date		Service Engineer		Scheduled Date/Time		Service Order																																																																																																										
				<i>Umar</i>																																																																																																														
User: <i>city Union Bank</i>				Mobile:		Operation data (Ambient temp. °C)																																																																																																												
Customer Address: <i>- Kher.</i>						<table border="1"> <tr> <th></th> <th>Before repair</th> <th>After repair</th> </tr> <tr> <td>HP / T</td> <td>psig/</td> <td>psig/</td> </tr> <tr> <td>SP / T °C</td> <td>psig/°C</td> <td>psig/°C</td> </tr> <tr> <td>Current °C</td> <td>Amps°C</td> <td>Amps°C</td> </tr> <tr> <td>Voltage</td> <td>Volts</td> <td>Volts</td> </tr> </table>					Before repair	After repair	HP / T	psig/	psig/	SP / T °C	psig/°C	psig/°C	Current °C	Amps°C	Amps°C	Voltage	Volts	Volts																																																																																										
	Before repair	After repair																																																																																																																
HP / T	psig/	psig/																																																																																																																
SP / T °C	psig/°C	psig/°C																																																																																																																
Current °C	Amps°C	Amps°C																																																																																																																
Voltage	Volts	Volts																																																																																																																
I Base Address:						<table border="1"> <tr> <th colspan="2">Fault Diagnosed</th> <th>✓</th> </tr> <tr> <td>Power Failure</td> <td></td> <td></td> </tr> <tr> <td>Phase Reversal</td> <td></td> <td></td> </tr> <tr> <td>In door unit PCB Defective</td> <td></td> <td></td> </tr> <tr> <td>Out door PCB Defective</td> <td></td> <td></td> </tr> <tr> <td>In door unit Fan Motor Defective</td> <td></td> <td></td> </tr> <tr> <td>Outdoor Fan Motor Defective</td> <td></td> <td></td> </tr> <tr> <td>Comp. taking High Current / Amp</td> <td></td> <td></td> </tr> <tr> <td>Compressor Ground / Earth</td> <td></td> <td></td> </tr> <tr> <td>Compressor Tripping due to High Temperature</td> <td></td> <td></td> </tr> <tr> <td>Compressor tripping due to High Pressure</td> <td></td> <td></td> </tr> <tr> <td>Indoor Unit MfgSw Defective</td> <td></td> <td></td> </tr> <tr> <td>Outdoor Unit MfgSw Defective</td> <td></td> <td></td> </tr> <tr> <td>Indoor Unit Transformer Faulty</td> <td></td> <td></td> </tr> <tr> <td>Out door Unit Transformer Faulty</td> <td></td> <td></td> </tr> <tr> <td>Fault of swing Motor</td> <td></td> <td></td> </tr> <tr> <td>Defect of Drain Pump</td> <td></td> <td></td> </tr> <tr> <td>Expansion Valve Body / Motor Defective</td> <td></td> <td></td> </tr> <tr> <td>Defective Temperature Sensor of Indoor Unit</td> <td></td> <td></td> </tr> <tr> <td>Defective Temperature Sensor of Outdoor Unit</td> <td></td> <td></td> </tr> <tr> <td>Defective Current Sensor In Out door Unit</td> <td></td> <td></td> </tr> <tr> <td>Gas Leakage at Indoor Unit</td> <td></td> <td></td> </tr> <tr> <td>Gas Leakage at Outdoor Unit</td> <td></td> <td></td> </tr> <tr> <td>Blower broken</td> <td></td> <td></td> </tr> <tr> <td>Short Cycling of Air at Indoor Unit</td> <td></td> <td></td> </tr> <tr> <td>Short Cycling of Air at Outdoor Unit</td> <td></td> <td></td> </tr> <tr> <td>Defect in Drain piping System</td> <td></td> <td></td> </tr> <tr> <td>Gas Leakage from Flare nut</td> <td></td> <td></td> </tr> <tr> <td>Error in Transmission wiring</td> <td></td> <td></td> </tr> <tr> <td>Product under capacity</td> <td></td> <td></td> </tr> <tr> <td>Rat bite case</td> <td></td> <td></td> </tr> <tr> <td>Less cooling problem due to dirty Airfilter</td> <td></td> <td></td> </tr> <tr> <td>Remote setting changed</td> <td></td> <td></td> </tr> <tr> <td>Clogged Condenser</td> <td></td> <td></td> </tr> <tr> <td>Other - Pl. specify</td> <td></td> <td></td> </tr> </table>				Fault Diagnosed		✓	Power Failure			Phase Reversal			In door unit PCB Defective			Out door PCB Defective			In door unit Fan Motor Defective			Outdoor Fan Motor Defective			Comp. taking High Current / Amp			Compressor Ground / Earth			Compressor Tripping due to High Temperature			Compressor tripping due to High Pressure			Indoor Unit MfgSw Defective			Outdoor Unit MfgSw Defective			Indoor Unit Transformer Faulty			Out door Unit Transformer Faulty			Fault of swing Motor			Defect of Drain Pump			Expansion Valve Body / Motor Defective			Defective Temperature Sensor of Indoor Unit			Defective Temperature Sensor of Outdoor Unit			Defective Current Sensor In Out door Unit			Gas Leakage at Indoor Unit			Gas Leakage at Outdoor Unit			Blower broken			Short Cycling of Air at Indoor Unit			Short Cycling of Air at Outdoor Unit			Defect in Drain piping System			Gas Leakage from Flare nut			Error in Transmission wiring			Product under capacity			Rat bite case			Less cooling problem due to dirty Airfilter			Remote setting changed			Clogged Condenser			Other - Pl. specify		
Fault Diagnosed		✓																																																																																																																
Power Failure																																																																																																																		
Phase Reversal																																																																																																																		
In door unit PCB Defective																																																																																																																		
Out door PCB Defective																																																																																																																		
In door unit Fan Motor Defective																																																																																																																		
Outdoor Fan Motor Defective																																																																																																																		
Comp. taking High Current / Amp																																																																																																																		
Compressor Ground / Earth																																																																																																																		
Compressor Tripping due to High Temperature																																																																																																																		
Compressor tripping due to High Pressure																																																																																																																		
Indoor Unit MfgSw Defective																																																																																																																		
Outdoor Unit MfgSw Defective																																																																																																																		
Indoor Unit Transformer Faulty																																																																																																																		
Out door Unit Transformer Faulty																																																																																																																		
Fault of swing Motor																																																																																																																		
Defect of Drain Pump																																																																																																																		
Expansion Valve Body / Motor Defective																																																																																																																		
Defective Temperature Sensor of Indoor Unit																																																																																																																		
Defective Temperature Sensor of Outdoor Unit																																																																																																																		
Defective Current Sensor In Out door Unit																																																																																																																		
Gas Leakage at Indoor Unit																																																																																																																		
Gas Leakage at Outdoor Unit																																																																																																																		
Blower broken																																																																																																																		
Short Cycling of Air at Indoor Unit																																																																																																																		
Short Cycling of Air at Outdoor Unit																																																																																																																		
Defect in Drain piping System																																																																																																																		
Gas Leakage from Flare nut																																																																																																																		
Error in Transmission wiring																																																																																																																		
Product under capacity																																																																																																																		
Rat bite case																																																																																																																		
Less cooling problem due to dirty Airfilter																																																																																																																		
Remote setting changed																																																																																																																		
Clogged Condenser																																																																																																																		
Other - Pl. specify																																																																																																																		
Daikin Invoice:		Date:		SP / T °C		psig/°C		psig/°C																																																																																																										
Dealer Invoice:		Date:		Current °C		Amps°C		Amps°C																																																																																																										
Type	Model No	Manufacturing No.		Voltage		Volts		Volts																																																																																																										
Outdoor unit /	<i>RK35UV16W</i>	<i>27026</i>		Indoor temperature																																																																																																														
Indoor unit	<i>FTK35UV16W</i>	<i>29126</i>		Suction		°C		°C																																																																																																										
Work Date	No. of S.E.	Work hours	Progress code	Details of the Repair Work		Discharge		°C																																																																																																										
<i>09/12/25</i>				<i>Installation done. calling good.</i>		Suction		°C																																																																																																										
						Discharge		°C																																																																																																										
						Work No / Parts No		City																																																																																																										
								Billing Amount																																																																																																										
Compressor manufacturing No.				Defective Compressor		Replacement Compressor																																																																																																												
Installed date		Warranty		AMC		Using with		Fault location																																																																																																										
						Stabilizer Cut off		Phenomena code																																																																																																										
Yes / No		Yes / No		Yes / No		Yes / No		Error code																																																																																																										
Service Engineer Remarks				Signature		Total																																																																																																												
<i>Umar</i>				<i>[Signature]</i>																																																																																																														
Customer Remarks				Signature		Customer Impression about Service																																																																																																												
<i>[Signature]</i>				<i>[Signature]</i>		(Please rate on scale of 1 poor, 2, 3, 4 & 5 excellent)																																																																																																												
						How is the behavior of visited engineer																																																																																																												
						What is the level of your satisfaction																																																																																																												
						How is the explanation by Engineer																																																																																																												
						a Simple Repair																																																																																																												
						b Part Replaced																																																																																																												
						c Part Repaired																																																																																																												
						d Gas Charging done																																																																																																												
						e Routine Service - Wet																																																																																																												
						f Routine Service - DRY																																																																																																												

Daikin Customer Care : Missed Call or SMS <DAIKIN> to 92101 88999 ; Toll Free Number : 1860 180 3900 / 1800 102 0300 ; cs@daikinindia.com / www.daikinindia.com



Scanned with OKEN Scanner

DAIKIN

DAIKIN AIRCONDITIONING INDIA PVT. LTD.

Service Completion Certificate



AEON AIRCONDITIONING SOLUTIONS

Office No. 108 & 109, Devanashree Garden, Commercial Complex,
H.W. Swarnam Marg, above Shastri Dalry, Pudu Park, Thane - 400 001.
Mob.: 9322334107 / 9322334109

1415

Subject

Installation

Registration No.		Request Date		Service Engineer		Scheduled Date/Time		Service Order																																																																					
				Umar SHAFERH.																																																																									
User: City Union Bank				Mobile:		Operation data (Ambient temp. °C)																																																																							
Customer Address: - Khar.						<table border="1"> <tr> <td></td> <td>Before repair</td> <td>After repair</td> </tr> <tr> <td>HP / T</td> <td>psig/</td> <td>psig/</td> </tr> <tr> <td>SP / T °C</td> <td>psig/°C</td> <td>psig/°C</td> </tr> <tr> <td>Current °C</td> <td>Amps°C</td> <td>Amps°C</td> </tr> <tr> <td>Voltage</td> <td>Volts</td> <td>Volts</td> </tr> </table>					Before repair	After repair	HP / T	psig/	psig/	SP / T °C	psig/°C	psig/°C	Current °C	Amps°C	Amps°C	Voltage	Volts	Volts																																																					
	Before repair	After repair																																																																											
HP / T	psig/	psig/																																																																											
SP / T °C	psig/°C	psig/°C																																																																											
Current °C	Amps°C	Amps°C																																																																											
Voltage	Volts	Volts																																																																											
Basic Address:						Fault Diagnosed																																																																							
Daikin Invoice:				Date:		<table border="1"> <tr> <td>Power Failure</td> <td></td> </tr> <tr> <td>Phase Reverse</td> <td></td> </tr> <tr> <td>In door unit PCB Defective</td> <td></td> </tr> <tr> <td>Out door PCB Defective</td> <td></td> </tr> <tr> <td>In door unit Fan Motor Defective</td> <td></td> </tr> <tr> <td>Outdoor Fan Motor Defective</td> <td></td> </tr> <tr> <td>Comp. taking High Current / Amp</td> <td></td> </tr> <tr> <td>Compressor Ground / Earth</td> <td></td> </tr> <tr> <td>Compressor Tripping due to High Temperature</td> <td></td> </tr> <tr> <td>Compressor tripping due to High Pressure</td> <td></td> </tr> <tr> <td>Indoor Unit MqSw Defective</td> <td></td> </tr> <tr> <td>Outdoor Unit MqSw Defective</td> <td></td> </tr> <tr> <td>Indoor Unit Transformer Faulty</td> <td></td> </tr> <tr> <td>Out door Unit Transformer Faulty</td> <td></td> </tr> <tr> <td>Fault of swing Motor</td> <td></td> </tr> <tr> <td>Defect of Drain Pump</td> <td></td> </tr> <tr> <td>Expansion Valve Body / Motor Defective</td> <td></td> </tr> <tr> <td>Defective Temperature Sensor of Indoor Unit</td> <td></td> </tr> <tr> <td>Defective Temperature Sensor of Outdoor Unit</td> <td></td> </tr> <tr> <td>Defective Current Sensor In Out door Unit</td> <td></td> </tr> <tr> <td>Gas Leakage at Indoor Unit</td> <td></td> </tr> <tr> <td>Gas Leakage at Outdoor Unit</td> <td></td> </tr> <tr> <td>Blower broken</td> <td></td> </tr> <tr> <td>Short Cycling of Air at Indoor Unit</td> <td></td> </tr> <tr> <td>Short Cycling of Air at Outdoor Unit</td> <td></td> </tr> <tr> <td>Defect in Drain piping System</td> <td></td> </tr> <tr> <td>Gas Leakage from Flare nut</td> <td></td> </tr> <tr> <td>Error in Transmission wiring</td> <td></td> </tr> <tr> <td>Product under capacity</td> <td></td> </tr> <tr> <td>Rat bite case</td> <td></td> </tr> <tr> <td>Less cooling problem due to dirty Airfilter</td> <td></td> </tr> <tr> <td>Remote setting changed</td> <td></td> </tr> <tr> <td>Clogged Condenser</td> <td></td> </tr> <tr> <td>Other - Pl. specify</td> <td></td> </tr> </table>				Power Failure		Phase Reverse		In door unit PCB Defective		Out door PCB Defective		In door unit Fan Motor Defective		Outdoor Fan Motor Defective		Comp. taking High Current / Amp		Compressor Ground / Earth		Compressor Tripping due to High Temperature		Compressor tripping due to High Pressure		Indoor Unit MqSw Defective		Outdoor Unit MqSw Defective		Indoor Unit Transformer Faulty		Out door Unit Transformer Faulty		Fault of swing Motor		Defect of Drain Pump		Expansion Valve Body / Motor Defective		Defective Temperature Sensor of Indoor Unit		Defective Temperature Sensor of Outdoor Unit		Defective Current Sensor In Out door Unit		Gas Leakage at Indoor Unit		Gas Leakage at Outdoor Unit		Blower broken		Short Cycling of Air at Indoor Unit		Short Cycling of Air at Outdoor Unit		Defect in Drain piping System		Gas Leakage from Flare nut		Error in Transmission wiring		Product under capacity		Rat bite case		Less cooling problem due to dirty Airfilter		Remote setting changed		Clogged Condenser		Other - Pl. specify	
Power Failure																																																																													
Phase Reverse																																																																													
In door unit PCB Defective																																																																													
Out door PCB Defective																																																																													
In door unit Fan Motor Defective																																																																													
Outdoor Fan Motor Defective																																																																													
Comp. taking High Current / Amp																																																																													
Compressor Ground / Earth																																																																													
Compressor Tripping due to High Temperature																																																																													
Compressor tripping due to High Pressure																																																																													
Indoor Unit MqSw Defective																																																																													
Outdoor Unit MqSw Defective																																																																													
Indoor Unit Transformer Faulty																																																																													
Out door Unit Transformer Faulty																																																																													
Fault of swing Motor																																																																													
Defect of Drain Pump																																																																													
Expansion Valve Body / Motor Defective																																																																													
Defective Temperature Sensor of Indoor Unit																																																																													
Defective Temperature Sensor of Outdoor Unit																																																																													
Defective Current Sensor In Out door Unit																																																																													
Gas Leakage at Indoor Unit																																																																													
Gas Leakage at Outdoor Unit																																																																													
Blower broken																																																																													
Short Cycling of Air at Indoor Unit																																																																													
Short Cycling of Air at Outdoor Unit																																																																													
Defect in Drain piping System																																																																													
Gas Leakage from Flare nut																																																																													
Error in Transmission wiring																																																																													
Product under capacity																																																																													
Rat bite case																																																																													
Less cooling problem due to dirty Airfilter																																																																													
Remote setting changed																																																																													
Clogged Condenser																																																																													
Other - Pl. specify																																																																													
Dealer Invoice:				Date:		<table border="1"> <tr> <td>Indoor temperature</td> <td></td> <td></td> </tr> <tr> <td>Suction</td> <td>°C</td> <td>°C</td> </tr> <tr> <td>Discharge</td> <td>°C</td> <td>°C</td> </tr> <tr> <td>Outdoor temperature</td> <td></td> <td></td> </tr> <tr> <td>Suction</td> <td>°C</td> <td>°C</td> </tr> <tr> <td>Discharge</td> <td>°C</td> <td>°C</td> </tr> </table>				Indoor temperature			Suction	°C	°C	Discharge	°C	°C	Outdoor temperature			Suction	°C	°C	Discharge	°C	°C																																																		
Indoor temperature																																																																													
Suction	°C	°C																																																																											
Discharge	°C	°C																																																																											
Outdoor temperature																																																																													
Suction	°C	°C																																																																											
Discharge	°C	°C																																																																											
Type		Model No		Manufacturing No.		<table border="1"> <tr> <td>Work No / Parts No</td> <td>Qty</td> <td>Billing Amount</td> </tr> <tr> <td></td> <td></td> <td></td> </tr> <tr> <td colspan="2">Total</td> <td></td> </tr> </table>				Work No / Parts No	Qty	Billing Amount				Total																																																													
Work No / Parts No	Qty	Billing Amount																																																																											
Total																																																																													
Outdoor unit /		RKC35CLV16W		27057																																																																									
Indoor unit		FTKC35UV16W		29127																																																																									
Work Date	No. of S.E.	Work hours	Progress code	Details of the Repair Work																																																																									
09/12/25				Installation done. Colling good.																																																																									
Compressor manufacturing No.		Defective Compressor		Replacement Compressor																																																																									
Installed date	Warranty	AMC	Using with	Fault location	Phenomena code	Error code																																																																							
	Yes / No	Yes / No	Stabilizer Cut off	Yes / No	Yes / No																																																																								
Service Engineer Remarks																																																																													
Umar						Signature																																																																							
Customer Remarks						Customer Impression about Service																																																																							
						(Please rate on scale of 1 poor, 2, 3, 4 & 5 excellent)																																																																							
						How is the behavior of visited engineer																																																																							
						What is the level of your satisfaction																																																																							
						How is the explanation by Engineer																																																																							
						<table border="1"> <tr> <td>a</td> <td>Simple Repair</td> <td></td> </tr> <tr> <td>b</td> <td>Part Replaced</td> <td></td> </tr> <tr> <td>c</td> <td>Part Repaired</td> <td></td> </tr> <tr> <td>d</td> <td>Gas Charging done</td> <td></td> </tr> <tr> <td>e</td> <td>Routine Service - Wet</td> <td></td> </tr> <tr> <td>f</td> <td>Routine Service - DRY</td> <td></td> </tr> </table>				a	Simple Repair		b	Part Replaced		c	Part Repaired		d	Gas Charging done		e	Routine Service - Wet		f	Routine Service - DRY																																																			
a	Simple Repair																																																																												
b	Part Replaced																																																																												
c	Part Repaired																																																																												
d	Gas Charging done																																																																												
e	Routine Service - Wet																																																																												
f	Routine Service - DRY																																																																												

Daikin Customer Care : Missed Call or SMS : DAIKIN to 92101 86999 ; Toll Free Number : 1860 180 3000 / 1800 102 9300 ; ca@daikinindia.com / www.daikinindia.com



Scanned with OKEN Scanner

DAIKIN

DAIKIN AIRCONDITIONING INDIA PVT. LTD.

Service Completion Certificate

1415



AEON AIRCONDITIONING SOLUTIONS

Office Nos. 108 & 109, Greenhouse Garden, Commercial Complex,
F.V.E. Swastik Marg, above Shantil Orya, Paldi Park, Thane - 400 001
Mob: 9322341107 / 9322341109

Subject: Installation

Registration No.		Request Date		Service Engineer		Scheduled Date/Time		Service Order	
				Umar.					
User: <u>City Union Bank</u>				Mobile:		Operation data (Ambient temp. °C)			
Customer Address: <u>- Khar</u>						Before repair		After repair	
Base Address:						HP / T		psig/ psig/	
Daikin Invoice:				Date:		SP / T °C		psig °C psig °C	
Dealer Invoice:				Date:		Current °C		Amps °C Amps °C	
Type		Model No		Manufacturing No.		Voltage		Volts Volts	
Outdoor unit /		RKC35UV1GW		27063		Suction		°C °C	
Indoor unit		FTKC35UV1GW		29136		Discharge		°C °C	
Work Date	No. of S.E.	Work hours	Progress code	Details of the Repair Work					
09/12/25				Installation done. Calling good.					
Compressor manufacturing No.		Defective Compressor		Replacement Compressor		Work No / Parts No		Qty Billing Amount	
Installed date	Warranty	AMC	Using with	Fault location	Phenomena code	Error code			
	Yes / No	Yes / No	Stabilizer Cut off						
Service Engineer Remarks							Total		
Name: <u>Umar</u>							Signature: <u>[Signature]</u>		
Customer Remarks							Customer Impression about Service		
							(Please rate on scale of 1 poor, 2, 3, 4 & 5 excellent)		
How is the behavior of visited engineer							a	Simple Repair	
What is the level of your satisfaction							b	Part Replaced	
How is the explanation by Engineer							c	Part Repaired	
							d	Gas Charging done	
							e	Routine Service - Wet	
							f	Routine Service - Dry	

Daikin Customer Care : Missed Call or SMS to 02101 869999 ; Toll Free Number : 1860 180 3900 / 1800 102 8300 ; cs@daikinindia.com / www.daikinindia.com



Scanned with OKEN Scanner