

DAIKIN

DAIKIN AIRCONDITIONING INDIA PVT. LTD.

Authorised Service Center

AEON AIRCONDITIONING SOLUTIONS

AEON HOUSE, SHOP NO. 6/7, BEHIND N CUBE CHINA TOWN

DR. AMBEDKAR ROAD, THANE W 400601 MAHARASHTRA. PHONE :- 02225370101 / 7900097007



PROJECT :- The cosmos co-op bank LTD Ichalkaranji branch Santa Chowk
Measurement Sheet


Sr. No.	Location	AC Type	Tonnage	Indoor Unit Details		Outdoor Unit Details		Copper In Rmt	Cable In Rmt	Drain In Rmt	ODU Stand
				Model No.	Sr. No.	Model No.	Sr. No.				
1	Reception	cassette	2	FCQF36ARV	0024984	RGVF36A	0025438	1	1.5	-	-
2	Area.	AC	TR	16		SV16					
3											
4	BM	cassette	2	FCQF36ARV	0024969	RGVF36A	0025441	1	1.5	-	-
5	Area.		TR	16		SV16					
6											
7	cast	cassette	2	FCQF36ARV	0024764	RGVF36AS	0025426	1	2	-	-
8	Counter		TR	16		NIG					

EXTRA ACTIVITY CARRIED OUT

CIVIL WORK	Stabilizer			TIMER	CASING CAPPING	CABLE TRAY	GAS CHARGING	DISMENTALING		RE-INSTALLATION
	3KVA	4KVA	5KVA					Hi Wall	Cassette	
	-	-	-	-	-	-	-		3 NOS.	

OTHERS Fabrication stand modification work

For Customer Details: <u>The cosmos Bank</u>					Vendor Details: <u>Aeon Airconditioning</u>				
Sign:					Signature:				
Name:					Technician Name:	<u>Vajid Shaikh</u>			
Date:	<u>20/03/2025</u>	Stamp:			Date:	<u>20/03/2025</u>			



3 NOS old AC Dismantle & 3 NOS cassette AC Installation
Done with Nitrogen leak testing Flushing, vacuuming
AC working & cooling ok

Subject :

DAIKIN AIRCONDITIONING INDIA PVT. LTD.
Service Completion Certificate



AEON AIRCONDITIONING SOLUTIONS

Shop No. 6 & 7, Aeon House, Dr. Ambedkar Rd., Thane (W)
Phone : 431 (505234107) 9922354109

[illegible]

DAIKIN

DAIKIN AIRCONDITIONING INDIA PVT. LTD.
Service Completion Certificate



AEON AIRCONDITIONING SOLUTIONS

Shop No. 6 & 7, Aeon House, Dr. Ambedkar Rd., Thane (W)
Phone : +91 (8322334197) 8322334195

Registration No.		Request Date		Service Engineer		Scheduled Date/Time		Service Order	
				Vijayl.		20/03/2025			
User: The cosmos Bank Customer Address: Ichalkaranji Branch. Branch Address:				Observation data (Ambient temp. °C)			Fault Diagnosed		
				Before repair After repair			Power Failure		
				HP / T psig/ psig/			Phase Reverse		
				SP / T °C psig/°C psig/°C			In door unit PCB Defective		
				Current °C Amps °C Amps °C			Out door PCB Defective		
				Voltage Volts Volts			In door unit Fan Motor Defective		
				Indoor temperature			Outdoor Fan Motor Defective		
				Discharge °C °C			Comp. lacking High Current / Amp		
				Suction °C °C			Compressor Ground / Earth		
				Discharge °C °C			Compressor Tripping due to High Temperature		
				Work No / Plans No Qty Billing Amount			Compressor tripping due to High Pressure		
							Indoor Unit Mfg. Defective		
							Outdoor Unit Mfg. Defective		
							Indoor Unit Transformer Faulty		
							Out door Unit Transformer Faulty		
							Fault of swing Motor		
							Defect of Drain Pump		
							Expansion Valve Body / Motor Defective		
							Defective Temperature Sensor of Indoor Unit		
							Defective Temperature Sensor of Outdoor Unit		
							Defective Current Sensor In Out door Unit		
							Gas Leakage at Indoor Unit		
							Gas Leakage at Outdoor Unit		
							Blower broken		
							Short Cycling of Air at Indoor Unit		
							Short Cycling of Air at Outdoor Unit		
							Defect in Drain piping System		
							Gas Leakage from Flare nut		
							Error in Transmission wiring		
							Product under capacity		
							Rpt btle case		
							Less cooling problem due to dirty Airfilter		
							Remote setting changed		
							Clogged Condenser		
							Other - Pl specify		
							Details of Repair Work Done		
							a Simple Repair		
							b Part Replaced		
							c Part Repaired		
							d Gas Charging done		
							e Routine Service - Yes		
							f Routine Service - No		
Service Engineer Remarks: Daikin cassette old Ac Dismantle A New Ac Reinstallation done ac ok.				Customer Impression about Service			(Please rate on scale of 1 poor, 2, 3, 4 & 5 excellent)		
Name: _____ Signature: <i>[Signature]</i>				How is the behavior of visited engineer?			What is the level of your satisfaction?		
Customer Remarks:				How is the explanation by Engineer?			(Please rate on scale of 1 poor, 2, 3, 4 & 5 excellent)		
Stamp:				9834101146			9834101146		

DAIKIN

DAIKIN AIRCONDITIONING INDIA PVT. LTD.
Service Completion Certificate

AEON AIRCONDITIONING SOLUTIONS

Shop No. 6 & 7, Aeon House, Dr. Ambedkar Rd., Thane (W)
Phone : +91 (9322334107) 9322334109

Subject :

Registration No.		Request Date		Service Engineer		Scheduled Date/Time		Service Order	
				Vojich		20/03/2025			
User: The Cosmos Bank				Mobile:		Fault Diagnosed			
Customer Address: Ichalkaranji branch									
1 Baro Address:									
Daikin Invoice:				Date:					
Dealer Invoice:				Date:					
Type	Model No.	Manufacturing No.		Operation data (Ambient temp. °C)					
Outdoor unit /	FCQF36ARV16	0024764		HP / T	psig/	psig/			
Indoor unit	PGVF36ASV16	0025426		SP / T °C	psig/°C	psig/°C			
Work Done	No. of S.E.	Work hours	Progress code	Current °C		Amps °C	Amps °C		
Details of the Repair Work				Voltage		Volts	Volts		
				Indoor temperature					
				Suction		°C	°C		
				Discharge		°C	°C		
				Outdoor temperature					
				Suction		°C	°C		
				Discharge		°C	°C		
				Work No / Parts No		Qty	Billing Amount		
Compressor manufacturing No.				Defective Compressor		Replacement Compressor			
Installed date	Warranty	AMC	Using with	Fault location	Phenomena code	Error code			
	Yes / No	Yes / No	Yes / No	Yes / No					
Service Engineer Remarks: Old AC Dismantle A new AC reinstallation Done AC working OK									
Name: Signature:									
Customer Remarks:									
Name: 9834101146									
Customer Impression about Service									
(Please rate on scale of 1 poor, 2, 3, 4 & 5 excellent)									
How is the behavior of visited engineer?									
What is the level of your satisfaction?									
How is the explanation by Engineer?									
a Simple Repair									
b Part Replaced									
c Part Repaired									
d Gas Charging done									
e Routine Service - Wet									
f Routine Service - DRY									
Details of Repair Work Done									